

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42728	Date	27/08/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: 1OI2IA Odo: 99438 Ref: 07/08/2026 Make/Model: TOYOTA HILUX Type: Ute Year: 2018 VIN: MR0KA3CD701220186 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 27/02/26 Kms: 109438

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.
90,000km service

Replaced engine oil and oil filter.
Replaced sump plug washer.
Replaced air and cabin filter.
Replaced wheel nuts. to be put on when comes in

DIESEL FUEL FILTER REPLACEMENT entailed removing any attached hardware, remove then replace filter ensuring leak proof see and bleeding system on completion.

REPLACED WIPER BLADES ensuring correct location in arms to ensure full contact with windscreen.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$218.18	\$218.18	\$21.82 GST	\$240.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W`screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.5	VANTAGE MV 5W-30	\$17.21	\$129.09	\$12.91 GST	\$142.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	FILTER - AIR	\$65.45	\$65.45	\$6.55 GST	\$72.00
1	FILTER - CABIN AIR	\$60.00	\$60.00	\$6.00 GST	\$66.00
24	WHEEL NUTS RAV4	\$5.99	\$143.64	\$14.36 GST	\$158.00
1	FUEL FILTER REPLACEMENT- DIESEL	\$59.09	\$59.09	\$5.91 GST	\$65.00
1	FILTER - FUEL	\$61.82	\$61.82	\$6.18 GST	\$68.00
1	WIPER BLADE REPLACEMENT x2	\$10.91	\$10.91	\$1.09 GST	\$12.00
1	R-BLADE FLAT BEAM-400MM-16IN	\$38.18	\$38.18	\$3.82 GST	\$42.00
1	R-BLADE FLAT BEAM-560MM-22IN	\$40.00	\$40.00	\$4.00 GST	\$44.00

Vehicle report

Approx Brake Lining Thickness - (3mm is low but still ok) Front 8mm, Rear 4mm

During repairs to this vehicle, these items were noted
Reported Fault Codes
IM: Immediate

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42728	Date	27/08/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

EA: Early attention

N: Next service

O: Monitor/Observation

O: Very minor brake shudder.

O: Rear shocks minor sweat.

Financial Summary

Total (Ex. Tax)	\$900.00	Terms	Cash on delivery
Tax Total	\$90.00	Paid	\$0.00
Total (Inc. Tax)	\$990.00	Balance	\$990.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	44305	Date	14/04/26	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: 1OI2IA Odo: 110630 Ref: 07/08/2026 Make/Model: TOYOTA HILUX Type: Ute Year: 2018 VIN: MR0KA3CD701220186 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 14/10/26 Kms: 120630

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work Done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.
210,000km service

Replaced oil and oil filter
Replaced sump plug washer
Replaced air and cabin filter

BRAKE DISC REPLACEMENT required raising vehicle and removing wheels and calliper assemblies, removing and replacing disc then reassembly and test on completion.

BRAKE PADS REPLACEMENT Removed wheels and disassembled callipers to ensure proper operation of calliper slides and reassembled then road tested.

BRAKE FLUID FLUSH Drained the fluid from the master cylinder. Cleaned the cap & reservoir. Refilled with fluid, then raised the vehicle and pressure bled the new fluid through the system, Removed any air and refilled the chamber. Rechecked operation.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$236.36	\$236.36	\$23.64 GST	\$260.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W`screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.5	VANTAGE MV 5W-30	\$17.21	\$129.09	\$12.91 GST	\$142.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	FILTER - AIR	\$65.45	\$65.45	\$6.55 GST	\$72.00
1	FILTER - CABIN AIR	\$60.00	\$60.00	\$6.00 GST	\$66.00
1	BRAKE FLUID FLUSH	\$54.55	\$54.55	\$5.45 GST	\$60.00
2.294	Brake / Clutch Fluid	\$15.45	\$35.45	\$3.55 GST	\$39.00
1	BRAKE DISCS REPLACEMENT - front	\$65.45	\$65.45	\$6.55 GST	\$72.00
2	REPCO ARMOUR BRAKE ROTOR	\$117.28	\$234.55	\$23.45 GST	\$258.00
1	BRAKE PAD REPLACEMENT- front	\$63.64	\$63.64	\$6.36 GST	\$70.00
1	PAD SET-DISC BRAKE	\$100.00	\$100.00	\$10.00 GST	\$110.00

Vehicle Report

Approx Brake Lining Thickness - (3mm is low but still ok) Front New Rear 4 mm

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	44305	Date	14/04/26	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

During repairs to this vehicle, these items were noted

Reported Fault Codes

IM: Immediate

EA: Early attention

N: Next service

O: Monitor/Observation

O: Rear shocks minor sweat.

Financial Summary

Total (Ex. Tax)	\$1,118.18	Terms	Cash on delivery
Tax Total	\$111.82	Paid	\$0.00
Total (Inc. Tax)	\$1,230.00	Balance	\$1,230.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com