

LR115.



Peter Kittle Toyota

TOYOTA

SERVICE TAX INVOICE

Peter Kittle Toyota
1459 Main North Road,
Para Hills West, SA 5096

T 08 8256 1212

peterkittletoyota.com.au

EMAIL ADDRESS

jarod.hosking@linctgroup.com.au

BSB: 035 000 ACC: 710 299
ABN: 91 620 982 694 ACN: 620 982 694
MVD: 284 343 ARC: AU44997

REPAIR ORDER/TAX INVOICE No JC34249107	PAGE: 1
C2 Alt. Cust 1 (Account)	

CUSTOMER: LINCT GROUP PTY LTD PO Box 444 Pakenham VIC 3810		DATE: 19/04/2023	TIME IN: 3:31 PM	TIME OUT: 4:30 PM	KILOMETERS: 197212	ADVISER: CO
VEHICLE: Hilux 4x2 SR 3.0L T Diesel Manual Double (					MONTH/YEAR 08/2014	AIR:
REG. No: S024CSF	STOCK No: LR115	SELLING DEALER:				
CUSTOMER No: 472236	VIN: MR0EZ12G204158331	ENGINE No: 1KDA553512				
CONTACT NAME: Linct Group Pty Ltd Jarod Hosking		COLOUR/TRIM Glacier White/Black			ORDER No: S024CSF	
CONTACT NUMBERS: M:0456729189		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	FIRST REG:

JOB DETAILS	PRICE	QTY/HRS	AMOUNT
JOB 1 CARRY OUT 120 MONTHS/200,000KM SERVICE AS PER HANDBOOK Carried out 120 months/200,000km service as per handbook. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected cooling system, hoses & connections. Inspected engine coolant. Inspected air cleaner element. Inspected valve clearances. Inspected battery electrolyte, cleanliness & security. Inspected water sedimenter & drained water trap. Replaced brake fluid. Inspected clutch fluid. Checked power steering fluid. Inspected brake booster vacuum pump & replaced blades. Inspected fuel cap, fuel lines & connections. Inspected diesel smoke. Replaced fuel filter. Inspected brake pads & discs. Inspected park brake linings & drums for wear. Checked brake pipes & hoses. Checked exhaust system for security & leaks. Inspected steering wheel, gear & linkages. Inspected front & rear suspension. Inspected ball joints & dust covers. Inspected manual transmission oil. Replaced rear differential oil. Tightened chassis & body bolts & nuts. Checked condition & pressures of all tyres including spare. Rotated wheels. Balanced front wheels. Checked brake pedal height & hand brake lever operation. Inspected all seat belts operation and condition. Checked lights, wiper/washers, horn & electrical systems. Cleaned air conditioning fresh air filter. Inspected air conditioner, including amount of refrigerant. Inspected driver's floor mat for correct fitment and retention. Road tested vehicle & reported any defects. BRAKES 4MM FRONT 3MM REAR			439.08
***** CONTINUED *****			

CASH ☐ CREDIT CARD ☐ FLEETLEASE ☐ REF.NO. _____

EFTPOS (DETAILS) _____ RECEIVED BY _____

Payment can be made electronically using the following bank account details:

Bank: Westpac Account Name: PKMC Adelaide P/L T/As Peter Kittle Toyota

BSB: 035-000 Account No: 710299

Please quote your account/invoice number as reference. Remittance advices to debtors@peterkittle.com.au



Peter Kittle Toyota

SERVICE TAX INVOICE

Peter Kittle Toyota
1459 Main North Road,
Para Hills West, SA 5096

T 08 8256 1212

peterkittletoyota.com.au

EMAIL ADDRESS

jarod.hosking@linctgroup.com.au

BSB: 035 000 ACC: 710 299
ABN: 91 620 982 694 ACN: 620 982 694
MVD: 284 343 ARC: AU44997

REPAIR ORDER/TAX INVOICE No
JC34249107

PAGE:
2

C2 Alt. Cust 1 (Account)

CUSTOMER: LINCT GROUP PTY LTD PO Box 444 Pakenham VIC 3810		DATE: 19/04/2023	TIME IN: 3:31 PM	TIME OUT: 4:30 PM	KILOMETERS: 197212	ADVISER: CO
VEHICLE: Hilux 4x2 SR 3.0L T Diesel Manual Double (					MONTH/YEAR 08/2014	AIR:
REG. No: S024CSF	STOCK No:	SELLING DEALER:				
CUSTOMER No: 472236	VIN: MR0EZ12G204158331	ENGINE No: 1KDA553512				
CONTACT NAME: Linct Group Pty Ltd Jarod Hosking		COLOUR/TRIM Glacier White/Black			ORDER No: S024CSF	
CONTACT NUMBERS: M:0456729189		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	FIRST REG:

JOB DETAILS			PRICE	QTY/HRS	AMOUNT
TYRES 5MM SPARE 6MM					
PRT	0882380220	BRAKEFLUID 500ML		1	10.51
PRT	0888800001C	ORD P/N 0888800001EP		1	.90
PRT	1121330021	GASKET CYLINDER		1	32.75
PRT	1215710010	GASKET DRAIN PLUG		2	3.36
PRT	233900L050	ELEMENT ASSY FUEL F		1	43.77
PRT	2368130010	SEAL NOZZLE HOLDER		4	19.16
PRT	2368230020	GASKET NOZZLE HOLDER		4	20.08
PRT	2933167020	BLADE A		5	169.20
PRT	2934258010	O-LING		1	14.99
PRT	2934267020	O-RING		1	10.54
PRT	2934268010	O-RING		2	7.02
PRT	2936466010	WASHER NIPPLE		1	9.08
PRT	9020114099	WASHER PLATE		2	7.60
PRT	9043012031	GASKET		1	1.95
PRT	9043018008	GASKET		1	2.11
PRT	90915YZZD2	OIL FILTER 75*85		1	22.01
CON	AUTO TRANS FLUID				63.68
CON	5W 30 DURABLEND ENGINE OIL				106.40
MIS	Environmental Levy				11.95
MIS	Workshop Sundries				12.95
JOB 1 SUBTOTAL					1,009.09
RECOMMENDATIONS					
***** CONTINUED *****					

CASH ☐ CREDIT CARD ☐ FLEETLEASE ☐ REF.NO. _____

EFTPOS (DETAILS) _____ RECEIVED BY _____

Payment can be made electronically using the following bank account details:

Bank: Westpac Account Name: PKMC Adelaide P/L T/As Peter Kittle Toyota

BSB: 035-000 Account No: 710299

Please quote your account/invoice number as reference. Remittance advices to debtors@peterkittle.com.au



Peter Kittle Toyota

SERVICE TAX INVOICE

Peter Kittle Toyota
1459 Main North Road,
Para Hills West, SA 5096

T 08 8256 1212

peterkittletoyota.com.au

EMAIL ADDRESS

jarod.hosking@linctgroup.com.au

BSB: 035 000 ACC: 710 299
ABN: 91 620 982 694 ACN: 620 982 694
MVD: 284 343 ARC: AU44997

REPAIR ORDER/TAX INVOICE No
JC34249107

PAGE:
3

C2 Alt. Cust 1 (Account)

CUSTOMER: LINCT GROUP PTY LTD PO Box 444 Pakenham VIC 3810		DATE: 19/04/2023	TIME IN: 3:31 PM	TIME OUT: 4:30 PM	KILOMETERS: 197212	ADVISER: CO
		VEHICLE: Hilux 4x2 SR 3.0L T Diesel Manual Double (			MONTH/YEAR 08/2014	AIR:
		REG. No: S024CSF	STOCK No:	SELLING DEALER:		
CUSTOMER No: 472236	VIN: MR0EZ12G204158331		ENGINE No: 1KDA553512			
CONTACT NAME: Linct Group Pty Ltd Jarod Hosking		COLOUR/TRIM Glacier White/Black			ORDER No: S024CSF	
CONTACT NUMBERS: M:0456729189		WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	FIRST REG:

JOB DETAILS

spare tyre missing
number plate light inop- non genuine LED

PRICE

QTY/HRS

AMOUNT

LABOUR	\$439.08
CONSUMABLES	\$170.08
PARTS	\$375.03
MISCELLANEOUS	\$24.90
SUBTOTAL	\$1,009.09
GST	\$100.91
TOTAL INCLUDES GST	\$1,110.00

PRINTED 08/05/23 10:44:24

CASH

☐

CREDIT CARD

☐

FLEETLEASE

☐

REF.NO.

EFTPOS (DETAILS)

RECEIVED BY

Payment can be made electronically using the following bank account details:

Bank: Westpac Account Name: PKMC Adelaide P/L T/As Peter Kittle Toyota

BSB: 035-000 Account No: 710299

Please quote your account/invoice number as reference.

Remittance advices to debtors@peterkittle.com.au

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42505	Date	23/07/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Client Details	Vehicle Details
Linct Group 2 / 4 Purton Road Pakenham VIC 3175	Rego: S024CSF Odo: 235743 Make/Model: TOYOTA HI-LUX Type: Ute Year: 2014 VIN: MR0EZ12G204158331 Next service: SCHEDULED SERVICE - LARGER VEHICLE Due: 23/01/26 Kms: 245743

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Work done

SCHEDULED SERVICE replacing parts as listed . Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.

Replaced engine oil and oil filter.
Replaced sump plug washer.
Replaced air and cabin filter.
Clean inside of R/H/R rim was full of dry mud

HEADLIGHT RECONDITIONING by following specific procedure to remove damaged outer layer on polycarbonate surface then replace using uv protective resin.

REPLACED WIPER BLADES ensuring correct location in arms to ensure full contact with windscreen.

PARK LAMP GLOBE REPLACEMENT,RHF-accessed globe holder, inspected condition, replaced globe, reassembled and checked operation.

Services, Parts & Labour

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$218.18	\$218.18	\$21.82 GST	\$240.00
1	Sundries- Inc` Small Quantities Grease, Top Up Fluids, W`screen washer additive ,Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Epa Levy , Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7.2	OIL-HPR DSL 10 10W40 ENVRBOX 20L	\$15.40	\$110.91	\$11.09 GST	\$122.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	Air Filter	\$70.91	\$70.91	\$7.09 GST	\$78.00
1	Cabin Air Filter	\$40.91	\$40.91	\$4.09 GST	\$45.00
1	HEADLIGHT RESTORATION	\$109.09	\$109.09	\$10.91 GST	\$120.00
1	WIPER BLADE REPLACEMENT x2	\$12.73	\$12.73	\$1.27 GST	\$14.00
2	Wiper Inserts 6mm 22inch	\$9.09	\$18.18	\$1.82 GST	\$20.00
1	PARK LAMP GLOBE REPLACEMENT RHF	\$7.27	\$7.27	\$0.73 GST	\$8.00
1	GLOBEWEDGE 5W 10X26MM	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	REMOTE BATTERY REPLACEMENT	\$7.27	\$7.27	\$0.73 GST	\$8.00
1	Remote Battery	\$8.18	\$8.18	\$0.82 GST	\$9.00

Vehicle report

Andrews Autos TA Weightman Automotive

Factory 3 / 30 Michael street
Pakenham VIC 3810
ABN 33 557 172 616
Tel: 03 5941 7450 Fax: 03 5941 7452
Email: ian@weightinvest.com.au
Website: www.andrewsautos.com.au
Rta no. Au47170



Tax Invoice

Inv. No.	42505	Date	23/07/25	Order No.	-	Sales ID	-
----------	-------	------	----------	-----------	---	----------	---

Approx Brake Lining Thickness - (3mm is low but still ok) Front 7.5mm, Rear 3mm

During repairs to this vehicle, these items were noted

Reported Fault Codes

IM: Immediate

EA: Early attention

N: Next service

O: Monitor/Observation

O: Battery 54%

O: Shackel bushes worn

O: Internal fault in head unit

O: Minor left hand rack end play.

O: R/H headlight is dirty inside and cob webs

Financial Summary

Total (Ex. Tax)	\$681.82	Terms	Cash on delivery
Tax Total	\$68.18	Paid	\$0.00
Total (Inc. Tax)	\$750.00	Balance	\$750.00

Andrews Autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com

LR115.

Andrews Autos TA Weightman

Factory 3 / 30 Michael Street
 Pakenham VIC 3810
 ABN 33 557 172 616
 Tel: 03 5941 7450 Fax: 03 5941 7452
 Email: info@aapakenham.com.au
 Website: www.andrewsautos.com.au
 Rta no. Au47170



9999
 Tax Invoice

32983
 ENTERED
 13/2/2014

Inv. No.	38,941	Date	9/2/24	Order No.	-	Sales ID	-
----------	--------	------	--------	-----------	---	----------	---

Client Details
Linct Group 2 / 4 Purton Road Pakenham Vic 3175

Vehicle Details
Registration: S024CSF Odo: 207028 Make/Model: TOYOTA HI-LUX Type: Ute Year: 2014 VIN#: MR0EZ12G204158331 Next service: SCHEDULED SERVICE - LARGER Due: 9/8/24 Kms: 217028

Account	11896	Home	-	Work	-	Mobile	0418140661
---------	-------	------	---	------	---	--------	------------

Services, Parts & Labour**Mechanical**

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	SCHEDULED SERVICE - LARGER VEHICLES	\$254.55	\$254.55	\$25.45 GST	\$280.00
1	Sundries- Inc' Small Quantities Grease, Top Up Fluids, W'screen washer additive, Sealants, Hardware.	\$18.18	\$18.18	\$1.82 GST	\$20.00
1	Engine oil flush treatment.	\$20.00	\$20.00	\$2.00 GST	\$22.00
1	Epa Levy, Waste Disposal Inc. Hazardous Waste.	\$9.09	\$9.09	\$0.91 GST	\$10.00
7	OIL-HPR DSL 10 10W40 ENVRBOX 20L	\$15.32	\$107.27	\$10.73 GST	\$118.00
1	Oil filter	\$20.91	\$20.91	\$2.09 GST	\$23.00
1	Sump Plug Washer	\$4.55	\$4.55	\$0.45 GST	\$5.00
1	Air Filter	\$80.00	\$80.00	\$8.00 GST	\$88.00
1	Cabin Air Filter	\$40.73	\$40.73	\$4.07 GST	\$44.80
1	FUEL FILTER REPLACEMENT- DIESEL	\$50.00	\$50.00	\$5.00 GST	\$55.00
1	Fuel Filter Cartridge	\$43.64	\$43.64	\$4.36 GST	\$48.00
1	WIPER BLADE REPLACEMENT x2	\$12.73	\$12.73	\$1.27 GST	\$14.00
2	Wiper Inserts 6mm 22inch	\$6.37	\$12.73	\$1.27 GST	\$14.00
			\$674.38	\$67.42	\$741.80

Work Done

SCHEDULED SERVICE replacing parts as listed. Checks include all fluid levels on top and underneath vehicle and their condition. General visual check of underbody components including steering, suspension, mountings and pipes. Checks of wiper/washer operation, lighting, battery and charge and other checks specific to the kms and age of vehicle. Road tested vehicle on completion of all works to ensure customer satisfaction.

Replaced engine oil and oil filter.
 Replaced sump plug washer.
 Replaced air and cabin filter.
 Adjust rear brake bias

DIESEL FUEL FILTER REPLACEMENT entailed removing

Vehicle Report

Approx Brake Lining Thickness - (3mm is low but still ok)
Front 3.5mm, Rear 3 mm

During repairs to this vehicle, these items were noted
 Reported Fault Codes

IM: Immediate
 EA: Early attention
 N: Next service
 O: Monitor/Observation

O:
 Shackel bushes worn
 RHR tyre wearing inner edge
 Internal fault in head unit

SCANNED

Work not working requires clock spring, price fitted \$740.00

any attached hardware, remove then replace filter ensuring leak proof seal and bleeding system on completion.

Horn not working, requires clock spring, price fitted \$740.00

REPLACED WIPER BLADES ensuring correct location in arms to ensure full contact with windscreen.

Financial Summary			
Total (Ex. Tax)	\$674.38	Terms	Cash on delivery
Tax Total	\$67.42	Paid	\$0.00
Total (Inc. Tax)	\$741.80	Balance	\$741.80

Andrews autos
Business account

Bsb 083 547 acc no 747698419

Our goods and services come with guarantees that cannot be excluded under the Australian consumer law. For major failures with the service, you are entitled: 1. To cancel your service contract with us; and 2. To a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done, you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service. For details visit repcoservice.com

**ABR REPAIRS**

LIGHT VEHICLE INSPECTION

Date: 23/01/2023

VIN:

Unit Number: LR115Mechanic: Harry ParkerRego Number: 1SO1ZS

Mechanic:

Service Type: Inspection

Serviceman:

Kilometres: 192710

Operator:

Hours:

Spotter:

INSPECTION SCHEDULE

The following inspections require having the engine running or machine moving. Use of an operator and spotter may be required.

IN CAB

No.	ACTION	CHECKS	S	US	N/A	Initial
1	Inspect	Door latches & seals	X			HP
2	Check	Operation of window winders & door handles	X			HP
3	Inspect	Seat belt for damage, fraying & anchor bolt security	X			HP
4	Check	Seat for correct operation, excessive movement, cover & cushion condition	X			HP
5	Check	Operation of ignition & security of key, instrument cluster, warning alarms, warning indicator lights & horn	X			HP
6	Check	Windscreen & other glass in the cab for chips or cracks	X			HP
7	Check	Wipers & Washers	X			HP
8	Check	Park lights, headlights, spot lights, indicators, brake lights, internal cab light, reverse camera & rotating beacon	X			HP
9	Check	Operation of AM / FM radio & UHF radio	X			HP
10	Check	Rear view mirrors & brackets for condition & operation	X			HP
11	Check	Operation of steering wheel (lock to lock), security of the column adjuster	X			HP
12	Check	Operation of air conditioner & heater	X			HP
13	Check	Clutch pedal free play operation / adjustment	X			HP
14	Check	Pedal rubbers are on & in good condition	X			HP
15	Check	For breakdown triangles, condition & complete set			X	HP
16	Check	For the wheel brace & jack	X			HP
17	Check	For a first aid kit, in date & complete			X	HP
18	Check	Operation of E-Stops			X	HP
19	Check	Fire extinguisher for safety ties, gauge in green, rotate a couple of times & tap bottom to release sediment		X		HP

RUNNING CHECKS

No.	ACTION	CHECKS	S	US	N/A	Initial
20	Check	For excessive exhaust smoke or abnormal noises / vibrations	X			HP
21	Test	The operation of all gears, ease of selection, ease of selection between 2WD & 4 x 4 High & low range	X			HP
22	Test	Operation of automatic transmission kick down, lock-up & neutral inhibitor switch			X	HP
23	Test	Service brake operation / adjustment	X			HP
24	Test	Park brake operation (test on a 10° slope)	X			HP

25	Test	For brake & park brake drag	X			HP
26	Test	Cruise control	X			HP
27	Test	Lane Assist & Front / Rear Traffic Alert systems			X	HP
28	Check	The general driving characteristics of vehicle	X			HP
29	Check	Using a scan tool, check for faults	X			HP
30	Check	DPF Status & conduct a manual burn if required			X	HP

FRAME & BODY

Park on level ground, Isolate generator, Fit body prop, Relieve all pressures, Start from front right hand side and work clockwise around generator checking each item below

No.	ACTION	CHECKS	S	US	N/A	Initial
31	Check	Cab mounts, bonnet release cable, operation of bonnet tilt struts / locking mechanism	X			HP
32	Check	For external body damage	X			HP
33	Check	Mudguards, mudflaps for condition & security	X			HP
34	Check	For metal fatigue in chassis rails, cross members, tow hitch frame & tow ball	X			HP
35	Inspect	Electrical harnesses / junction boxes for chaffing & dust sealing	X			HP
36	Inspect	Exhaust mufflers, piping & mounts for leaks & security	X			HP
37	Check	Hazard warning / component location Decals	X			HP
38	Inspect	All grease lines for damage / security & grease penetration			X	HP

UNDER BONNET / ENGINE BAY

No.	ACTION	CHECKS	S	US	N/A	Initial
39	Check / Clean	Check battery isolator, battery box, mountings, terminals, cables & electrolyte levels	X			HP
40	Inspect	Exhaust manifolds / covers, bolts, turbo, piping for any leaks & security	X			HP
41	Inspect / Tighten	Air induction boxes / hoses / piping / fittings for damage & presence of dusting	X			HP
42	Inspect	Fuel pump / pipes / hoses / clamps, for leakage & movement	X			HP
43	Inspect	Engine for oil leaks & damaged hoses	X			HP
44	Inspect	Engine mounts for wear & security	X			HP
45	Check	Water pump "tell tail" for leakage or blockage	X			HP
46	Inspect	Alternator pulley, mountings, bearings & idler pulleys	X			HP
47	Inspect	Air Conditioner compressor pulley, mountings, hose connections for leakage & movement	X			HP
48	Inspect	Fan, alternator, air conditioner belts for condition & tension	X			HP
49	Inspect	Fan blades for cracks, wear, damage & security	X			HP
50	Check	Radiator mountings, coolant leakage & air flow through radiator	X			HP
51	Inspect	Coolant / heater hoses / clamps for condition, leaks & tightness	X			HP
52	Inspect	Power steering reservoir, pump, hoses for leakage	X			HP
53	Inspect	Power steering box for oil leaks, excessive movement, security of steering column & drag link	X			HP
54	Inspect	Steering column universal joints, slip joint & mountings	X			HP
55	Inspect	Electrical harnesses / connections for damage & security	X			HP
56	Inspect	Engine bay is free of combustible materials i.e. leaves, sticks & rags for prevention of fire hazards	X			HP

POWER TRAIN & AXLES

Jack up all axles to check wheel bearings, steering linkages & kingpins

No.	ACTION	CHECKS	S	US	N/A	Initial
57	Inspect	Wheel rims for damage, cracks missing or loose wheel nuts	X			HP
58	Check	Front wheel bearings adjust or replace if necessary	X			HP
59	Check	Rear wheel bearings adjust or replace if necessary	X			HP

60	Inspect	Both front & rear drive shafts							X			HP	
61	Inspect	All brake linings, pads for thickness & adjustment, adjust if required							X			HP	
62	Check	Operation / wear of brake callipers							X			HP	
63	Inspect	For movement in both upper & lower ball joints, shocky tower security, steering linkages & ball joints							X			HP	
64	Inspect	All shackle pins, bushes, shock absorbers, U bolts, wear plates for wear, movement& tension							X			HP	
65		Universal joints, slip joints, centre bearings for movement & rubber deterioration, lubricate							X			HP	
66	Inspect	Torque rod arms, pins, bushes, mounting bolts for wear & tension							X			HP	
67	Inspect	Gearbox / Transmission for oil leaks, mounts & lubrication of pivot points							X			HP	
68		Differentials for oil leaks, excessive movement in input & output shafts							X			HP	
	Inspect	Tyres for damage, tread depth & pressure											
69	Depth / Damage	LHSF:	7	mm	LHSR:	7	mm	SPARE		X			HP
		RHSF:	7	mm	RHSR:	7	mm		mm				
70	Pressure	RHSF:	38	psi	RHSR:	38	psi	SPARE		X			HP
		LHSF:	38	psi	LHSR:	38	psi	38	psi				
71	Rotate	Tyres, including spare										X	HP

DEFECTS / COMENTS & PARTS TO BE ORDERED[illegible]

Garry Parker

Mechanic / Supervisor Signature

H Parker

Name of Mechanic / Supervisor

20.01.20

Service Completion Date