

B&H Equipment Ltd.
CELEBRATING 40 YEARS! 1979 - 2019
 C3, 19325 - 94th Avenue
 Surrey, BC V4N 4E6
 604-513-9728 Fax: 604-513-9714
 cheryl@bhequip.ca
 Tax #100502566

X10-7

Date In:	2024-10-02
Date Out:	2024-10-18
Service Order #:	25592
Page:	1

Ship To: DVC Communications Ltd. 5549 - 180 Street Surrey, BC V3S 5Y5

Unit #: 34 Plate #: VIN #: YJ524331 Alternate ID: Reference: Mileage: 28,413 km
--

Phone: 778-858-0233		Alternate Phone:		Terms:		
Service Rep:		Cust PO:		Status: CLOSED	Due Date: 2024-11-18	
Job #	Stock Code	Description	Indications/Work Performed	Quantity	Price	Extended

1 Technician:

1. Perform an annual aerial inspection;
2. Have an NDT performed;
3. Rebuild carburetor for generator, replace fuel hose and fuel pump, change oil and filter;
4. Repair wiring for extension drive;
5. Repair wiring to outrigger pump;
6. Replace safety decals;

	LABOR	20.00	125.00	2,500.00
NDT STEEL		1.00	455.00	455.00
H312	Fuel Hose	1.00	99.75	99.75
3023	Fuel Filter	1.00	27.55	27.55
FUEL FITTING KIT		1.00	17.37	17.37
146-0457	Carburetor Repair Kit	1.00	280.71	280.71
149-2333	Fuel filter	1.00	31.25	31.25
A064S971	Used Fuel Pump	1.00	236.48	236.48
GAS		1.00	20.00	20.00
15W40	Rotella CK4 Triple Pro Oil	3.50	6.60	23.10
1348	Oil Filter	1.00	9.70	9.70
67040179	Decal - Danger Electrical Hazards	3.00	6.96	20.88
67040229	Decal - Moving outrigger hazard	2.00	3.97	7.94
67040170	Decal - Danger Moving Outrigger Hazard	2.00	6.31	12.62
67040231	Decal - Electrical Hazard	1.00	8.54	8.54
67040174	Decal - Operating Instructions	1.00	6.74	6.74
67040172	Decal - Qualified Personnel Only	1.00	14.21	14.21
MISC MATERIAL & SS	Grease, lube, hardware, steel, paint, solvent	1.00	40.00	40.00

Total Parts:	1,311.84	Total Labor:	2,500.00	Total Sublet:	0.00	Total Disposal:	0.00
Shop Parts:	0.00			Pickup/Delivery:	0.00	Service Call:	0.00
						SubTotal:	3,811.84
						GST:	190.59
						Tax:	266.83
						Shipping:	0.00
						Total:	4,269.26
						Paid:	0.00
						Balance:	4,269.26

TERMS STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE B&H Equipment Ltd. does not assume responsibility whatsoever for vehicles or equipment left for repairs, storage or other purposes or for articles left in same vehicles driven by our employees at owner's risk. I hereby authorize the repair work to be done together with necessary materials and acknowledge my indebtedness to B&H Equipment Ltd. in the amount shown hereon.

DISCLAIMER OF WARRANTIES Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

FORMAL STRUCTURAL REPORT**B & H Equipment Ltd.**

19325 94th Avenue C3

Surrey, BC V4N 4E6

Attention: Mr. Mike Baertl

Owner: DVC Communications

Structural Inspection of a Telsta Aerial Lift**MODEL:** T36, **SERIAL:** 00380020, **UNIT:** DVC34**LOCATION:** B & H Equipment Ltd.**DATE OF INSPECTION:** October 2, 2024**PURCHASE ORDER:** DVC DVC34**OUR FILE:** V87393

Visual examinations and magnetic particle inspections were performed on the above-described equipment in accordance with Kova Engineering Inspection Plan (KSIP1-V87393). The specific items examined and our inspection findings were as follows:

1. Outriggers (2x) - no defects noted.
2. Main Frame - no defects noted.
3. Turret - no defects noted.
4. Boom Butt Section - no defects noted.
5. Boom Tip Extension - no defects noted.
6. Manbasket Adapter - no defects noted.
7. Manbasket - no defects noted.

THE EQUIPMENT IS JUDGED STRUCTURALLY SUITABLE FOR ITS INTENDED SERVICE.

Yours very truly,

KOVA ENGINEERING LTD.

the Crane Certification Bureau™



PN: 1001263

Barry Devlin, P. Eng.

BD:kbr

CERTIFICATION

Telsta Aerial Lift

MODEL: T36, SERIAL: 00380020, UNIT: DVC34

OWNER: DVC Communications

OUR FILE: V87393

CERTIFICATION DATE: October 2, 2024

The structural, mechanical and controls inspections were performed on the above-described equipment in reference to Kova Engineering Inspection Plans KMIP1-V87393 and KSIP1-V87393. The items as outlined in the reports were inspected and repaired where required.

Outriggers (2x)

Main Frame

Turret

Boom Butt Section

Boom Tip Extension

Manbasket Adapter

Manbasket

This certification is based on the details as set out in the assembled inspection reports and on reasonable assumptions and assessments. The equipment is judged safe for its intended use.

KOVA ENGINEERING LTD.
the Crane Certification Bureau™



PN: 1001263

Barry Devlin, P. Eng.

BD:kbr



Valley Auto Repair

17902 Roan Place

Surrey, BC V3S 5K1

Phone: 604 576 2824 ~ Fax: 604 576 2815

Email: valleyautorepair@telus.net

Website: Valleyautorepair.net

GST: R139603542

Invoice

Bill To DVC Communications
Communications, DVC
5549 180 St
Surrey, BC V3S 5Y5
Canada

Phone +1 (604) 579-0291
GURINDER +1 (604) 719-6221
Email dvc@shaw.ca

Invoice # 58811
Work Order # 69043
Service Advisor Andrew
Technician Cole

Plate BC BUCKETT
Description 2000 GMC C6500 Topkick C6H042 V8 7.4L
454CID VIN D
VIN 1GDJ6H1D5YJ524331
Odometer 28,402

Invoice Date 8/30/2024 5:27 PM
Appointment 7/25/2024 9:15 AM
Promised 7/25/2024 8:30 AM

Concern

Starting / Charging System Concern

Concern? = VEHICLE WILL NOT START, INSPECT AND ADVISE.

Conditions? =

Last Service? =

STARTED TO DIAGNOSE THE NO START. PUT A
BATTERY CHARGER ON THE ENGINE BATTERY. PUT 4
GAS CANS OF FRESH FUEL INTO THE FUEL TANK.
AFTER CRANKING OVER THE ENGINE SEVERAL TIMES
ATTEMPTING TO START THE ENGINE, WE FOUND FUEL
COMING OUT OF THE DOWN PIPE ON PASSENGER
SIDE FOR EXHAUST. SUSPECT INJECTOR OR
INJECTORS ARE STUCK OPEN, WILL NEED TO PULL
INJECTORS WITH RAIL AND FURTHER INSPECT FOR
LEAKS.

\$168.00 *E5GP

GASOLINE

1 Unit

\$141.27 / Unit

\$141.27 E5GP

Sub \$309.27

Accessories Concern

Concern? = CUSTOMER STATES THE GENERATOR HAS NOT RAN FOR A LONG TIME. THE GENERATOR IS NEEDED TO
RUN IN ORDER FOR THE BOOM TO WORK. TRY TO START AND RUN THE GENERATOR. IF IT STARTS THEN LET IT RUN
FOR A WHILE BEFORE OIL CHANGE SERVICE IS PERFORMED.

Conditions? =

Last Service? =

FOUND FUEL SUPPLY LINE FROM THE GENERATOR TO
THE FUEL TANK WAS REMOVED. UNKNOWN WHY. WE
ARE NOT ABLE TO WORK ON THE GENERATOR.
RECOMMEND VEHICLE GO TO A SMALL ENGINE
REPAIR SHOP OR A HEAVY DUTY REPAIR SHOP TO
WORK ON THE GENERATOR.

\$0.00 *GP

Sub \$0.00

Inspection

Thank you for Choosing Valley Auto & RV Repair Inc.
T/N

\$0.00 *GP

Sub \$0.00

Service

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.

Drive Shaft General Service - REINSTALL DRIVE SHAFT AFTER TOW-IN

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Service

\$84.00 *GP

Sub \$84.00

***** DRIVE SHAFT NOT CURRENTLY INSTALLED, DRIVE SHAFT BOLTS ON DRIVERS FLOOR *****

Fuel Injector

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Service

\$1,041.60 *GP

Fuel Injector

2 Unit \$288.54 / Unit \$577.08 GP

FUEL INJECTOR

2 Unit \$288.54 / Unit \$577.08 GP

FUEL INJECTOR

4 Unit \$288.54 / Unit \$1,154.16 GP

FUEL INJECTOR - seal kit

2 Unit \$12.64 / Unit \$25.28 GP

PLENUM GASKET SET

1 Unit \$72.78 / Unit \$72.78 GP

Sub \$3,447.98

EXTRA TIME REQUIRED DUE TO BOOM RUNNING INTERFERENCE WITH OPENING HOOD

PERFORM COMPLETE PHYSICAL

Service

\$252.00 *GP

Sub \$252.00

***** TOW-IN ***** CUSTOMER STATES VEHICLE HAS SAT FOR A VERY LONG TIME. DOES NOT START AND RUN *****

Fleet Maintenance Service Package

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complimentary visual vehicle inspection. Inspect and repair all lighting as required, lube all hinges and latches. Reset oil life monitor system. Install next service decal.

Service

\$69.95 *GP

ACDelco - ENGINE OIL - 5/30

7.5 Unit \$9.95 / Unit \$74.62 GP

Fram - OIL FILTER

1 Unit \$14.44 / Unit \$14.44 E1GP

Turbo Power - WINDSHIELD WASHER FLUID -35

3 Unit \$1.99 / Unit \$5.97 GP

Prestone Celsius - ANTI-FREEZE - LD Extended Life

4 Litre \$4.95 / Litre \$19.80 GP

Sub \$184.78

Battery General Service

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

BATTERY IS COMPLETELY DEAD. EVEN AFTER A FEW HOUR CHARGE IT WAS STILL DEAD. INSTALLED A NEW BATTERY IN ORDER TO DRIVE VEHICLE INTO THE SHOP AND DRIVE IT BACK OUTSIDE AFTER INSPECTION AND OIL CHANGE. RE INSTALLED OLD BATTERY AS THE CUSTOMER STATES THERE IS STILL WARRANTY ON THE BATTERY.

\$84.00 *GP

Sub \$84.00

Total Parts

\$2,662.48

Total Labor

\$1,699.55

Total Before Taxes & Miscellaneous Charges

\$4,362.03

(*) Materials, Consumables & Hazardous Waste

\$100.00 GP

(E1) Enviro/ Recycling/ Disposal - Oil Filter

\$2.00 Each \$2.00 GP

(E5) Electrical Supplies*

\$0.00 GP

(G) Canadian Goods and Services Tax (GST)

5 % \$223.20

(P) BC Provincial Sales Tax (PST)

7 % \$312.48

Grand Total

\$4,999.71

DVC Communications paid \$2,000.00 by Deposit (Visa)

DVC Communications charged \$2,999.71 to Account - 386 - DVC Communications - COD (Payment Due Upon Delivery)

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.

Thanks for the Business!
I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.



Valley Auto Repair

17902 Roan Place

Surrey, BC V3S 5K1

Phone: 604 576 2824 ~ Fax: 604 576 2815

Email: valleyautorepair@telus.net

Website: Valleyautorepair.net

GST: R139603542

Invoice

Bill To DVC Communications
Communications, DVC
5549 180 St
Surrey, BC V3S 5Y5
Canada

Phone +1 (604) 579-0291
GURINDER +1 (604) 719-6221
Email dvc@shaw.ca

Invoice # 58811
Work Order # 69043
Service Advisor Andrew
Technician Cole

Plate BC BUCKETT
Description 2000 GMC C6500 Topkick C6H042 V8 7.4L
454CID VIN D
VIN 1GDJ6H1D5YJ524331
Odometer 28,402

Invoice Date 8/30/2024 5:27 PM
Appointment 7/25/2024 9:15 AM
Promised 7/25/2024 8:30 AM

Concern

Starting / Charging System Concern

Concern? = VEHICLE WILL NOT START, INSPECT AND ADVISE.

Conditions? =

Last Service? =

STARTED TO DIAGNOSE THE NO START. PUT A
BATTERY CHARGER ON THE ENGINE BATTERY. PUT 4
GAS CANS OF FRESH FUEL INTO THE FUEL TANK.
AFTER CRANKING OVER THE ENGINE SEVERAL TIMES
ATTEMPTING TO START THE ENGINE, WE FOUND FUEL
COMING OUT OF THE DOWN PIPE ON PASSENGER
SIDE FOR EXHAUST. SUSPECT INJECTOR OR
INJECTORS ARE STUCK OPEN, WILL NEED TO PULL
INJECTORS WITH RAIL AND FURTHER INSPECT FOR
LEAKS.

\$168.00 *E5GP

GASOLINE

1 Unit	\$141.27 / Unit	\$141.27 E5GP
	Sub	\$309.27

Accessories Concern

Concern? = CUSTOMER STATES THE GENERATOR HAS NOT RAN FOR A LONG TIME. THE GENERATOR IS NEEDED TO
RUN IN ORDER FOR THE BOOM TO WORK. TRY TO START AND RUN THE GENERATOR. IF IT STARTS THEN LET IT RUN
FOR A WHILE BEFORE OIL CHANGE SERVICE IS PERFORMED.

Conditions? =

Last Service? =

FOUND FUEL SUPPLY LINE FROM THE GENERATOR TO
THE FUEL TANK WAS REMOVED. UNKNOWN WHY. WE
ARE NOT ABLE TO WORK ON THE GENERATOR.
RECOMMEND VEHICLE GO TO A SMALL ENGINE
REPAIR SHOP OR A HEAVY DUTY REPAIR SHOP TO
WORK ON THE GENERATOR.

\$0.00 *GP

Sub **\$0.00**

Inspection

Thank you for Choosing Valley Auto & RV Repair Inc.
T/N

Sub **\$0.00**

Service

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.

Drive Shaft General Service - REINSTALL DRIVE SHAFT AFTER TOW-IN

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Service

\$84.00 *GP

Sub \$84.00

***** DRIVE SHAFT NOT CURRENTLY INSTALLED, DRIVE SHAFT BOLTS ON DRIVERS FLOOR *****

Fuel Injector

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Service

\$1,041.60 *GP

Fuel Injector	2 Unit	\$288.54 / Unit	\$577.08 GP
FUEL INJECTOR	2 Unit	\$288.54 / Unit	\$577.08 GP
FUEL INJECTOR	4 Unit	\$288.54 / Unit	\$1,154.16 GP
FUEL INJECTOR - seal kit	2 Unit	\$12.64 / Unit	\$25.28 GP
PLENUM GASKET SET	1 Unit	\$72.78 / Unit	\$72.78 GP

Sub \$3,447.98

EXTRA TIME REQUIRED DUE TO BOOM RUNNING INTERFERENCE WITH OPENING HOOD

PERFORM COMPLETE PHYSICAL

Service

\$252.00 *GP

Sub \$252.00

***** TOW-IN ***** CUSTOMER STATES VEHICLE HAS SAT FOR A VERY LONG TIME. DOES NOT START AND RUN *****

Fleet Maintenance Service Package

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complimentary visual vehicle inspection. Inspect and repair all lighting as required, lube all hinges and latches. Reset oil life monitor system. Install next service decal.

Service

\$69.95 *GP

ACDelco - ENGINE OIL - 5/30	7.5 Unit	\$9.95 / Unit	\$74.62 GP
Fram - OIL FILTER	1 Unit	\$14.44 / Unit	\$14.44 E1GP
Turbo Power - WINDSHIELD WASHER FLUID -35	3 Unit	\$1.99 / Unit	\$5.97 GP
Prestone Celsius - ANTI-FREEZE - LD Extended Life	4 Litre	\$4.95 / Litre	\$19.80 GP

Sub \$184.78

Battery General Service

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

BATTERY IS COMPLETELY DEAD. EVEN AFTER A FEW HOUR CHARGE IT WAS STILL DEAD. INSTALLED A NEW BATTERY IN ORDER TO DRIVE VEHICLE INTO THE SHOP AND DRIVE IT BACK OUTSIDE AFTER INSPECTION AND OIL CHANGE. RE INSTALLED OLD BATTERY AS THE CUSTOMER STATES THERE IS STILL WARRANTY ON THE BATTERY.

\$84.00 *GP

Sub \$84.00

Total Parts	\$2,662.48
Total Labor	\$1,699.55
Total Before Taxes & Miscellaneous Charges	\$4,362.03

(*) Materials, Consumables & Hazardous Waste		\$100.00 GP
(E1) Enviro/ Recycling/ Disposal - Oil Filter	\$2.00 Each	\$2.00 GP
(E5) Electrical Supplies*		\$0.00 GP
(G) Canadian Goods and Services Tax (GST)	5 %	\$223.20
(P) BC Provincial Sales Tax (PST)	7 %	\$312.48
Grand Total		\$4,999.71

DVC Communications paid \$2,000.00 by Deposit (Visa)

DVC Communications charged \$2,999.71 to Account - 386 - DVC Communications - COD (Payment Due Upon Delivery)

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.

Thanks for the Business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: _____

Thank you for placing your trust in us! Valley Auto Repair warrants all operations performed in respect of defects in material and workmanship under normal use and service for a period of 18 months or 24,000 kilometres on service and materials supplied by Valley Auto Repair. There is no warranty expressed nor implied on any service where materials are supplied. Any warranty repairs must be approved by management in order for claim to be recognized. No warranty is extended to cover the loss of earnings, per diem expenses nor any other claim of any nature whatsoever. Indebtedness is hereby acknowledged in the sum stated.

APEX HD SERVICE CORP

PO BOX 75027 WHITE ROCK
SURREY, British Columbia V4A 0B1
CANADA

INVOICE

Invoice No.: 863
Date: 15/11/2024
Ship Date:
Page: 1
Re: Order No.

Sold to:

DVC COMMUNICATIONS LTD
5549 180 ST
SURREY, BC V3S 4K5

Ship to:

DVC COMMUNICATIONS LTD
5549 180 ST
SURREY, BC V3S 4K5

Business No.: 723989604

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
	34	58	NOV REPAIR FUEL SYSTEM / REPLACED FUEL PUMP REMOVE FUEL TANK AND CLEAN X 3 REPLACED FUEL FILTERS / FLUSH FUEL SYSTEM / REMOVE AND CLEAN SPARK PLUGS REMOVE ALL WHEELS AND REMOVE RUST FROM ROTORS / REPLACED FRONT BRAKES CLEAN AND SERVICE CALIPERS / REPLACED REAR BRAKES AND CALIPERS FLUSH BRAKE LINES . GREASED UNIT / TEST RUN / REPLACED ALTERNATOR AND FAN BELTS REPLACED MARKER LIGHTS / HEAD LIGHTS / INSTALL REFLECTOR TAPE / TOOK FOR CVI 2000 GMC C6500 28419MILES	GP	145.00	8,410.00
		1	ALTORNATER	GP	486.30	486.30
		1	FUEL PUMP	GP	425.60	425.60
		1	FRONT BRAKES	GP	299.00	299.00
		1	REAR BRAKES	GP	319.30	319.30
		2	REAR CALIPERS	GP	376.29	752.58
		8	OIL	GP	7.60	60.80
		1	OIL FILTER	GP	12.30	12.30
		4	BRAKE FLUID	GP	54.60	218.40
		20	TRANS OIL	GP	8.60	172.00
		120	FUEL	GP	1.86	223.20
		2	HEAD LIGHTS	GP	26.89	53.78
			Subtotal:			11,433.26
			GP - GST 5%, PST 7%			
			GST			571.68
			PST			800.32
Shipped By: Tracking Number:						
Comment:						Total Amount 12,805.26
Sold By:						

APEX HD SERVICE CORP

PO BOX 75027 WHITE ROCK
SURREY, British Columbia V4A 0B1
CANADA

INVOICE

Invoice No.: 863
Date: 15/11/2024
Ship Date:
Page: 1
Re: Order No.

Sold to:

DVC COMMUNICATIONS LTD
5549 180 ST
SURREY, BC V3S 4K5

Ship to:

DVC COMMUNICATIONS LTD
5549 180 ST
SURREY, BC V3S 4K5

Business No.: 723989604

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
	34	58	NOV REPAIR FUEL SYSTEM / REPLACED FUEL PUMP REMOVE FUEL TANK AND CLEAN X 3 REPLACED FUEL FILTERS / FLUSH FUEL SYSTEM / REMOVE AND CLEAN SPARK PLUGS REMOVE ALL WHEELS AND REMOVE RUST FROM ROTORS / REPLACED FRONT BRAKES CLEAN AND SERVICE CALIPERS / REPLACED REAR BRAKES AND CALIPERS FLUSH BRAKE LINES . GREASED UNIT / TEST RUN / REPLACED ALTERNATOR AND FAN BELTS REPLACED MARKER LIGHTS / HEAD LIGHTS / INSTALL REFLECTOR TAPE / TOOK FOR CVI 2000 GMC C6500 28419MILES	GP	145.00	8,410.00
		1	ALTERNATER	GP	486.30	486.30
		1	FUEL PUMP	GP	425.60	425.60
		1	FRONT BRAKES	GP	299.00	299.00
		1	REAR BRAKES	GP	319.30	319.30
		2	REAR CALIPERS	GP	376.29	752.58
		8	OIL	GP	7.60	60.80
		1	OIL FILTER	GP	12.30	12.30
		4	BRAKE FLUID	GP	54.60	218.40
		20	TRANS OIL	GP	8.60	172.00
		120	FUEL	GP	1.86	223.20
		2	HEAD LIGHTS	GP	26.89	53.78
			Subtotal:			11,433.26
			GP - GST 5%, PST 7%			
			GST			571.68
			PST			800.32
Shipped By: Tracking Number:					Total Amount	12,805.26
Comment:						
Sold By:						