

2011 GMC Duramax Truck

x13.2
Invoice No: 218681
INVOICE

Customer Number: 207898

ELDCAN FOREST PRODUCTS

40 1900 HUGH ALAN DR
KAMLOOPS, BC V1S 0A8
Home: 250-573-1900 Bus: 250-318-3103
Email: email|accounting@eldcan.com|home

BANNISTER

CHEVROLET KAMLOOPS

950 NOTRE DAME DR, KAMLOOPS, BC V2C 6J2
250.372.2551 | BannisterChevKamloops.com

GST # 792383614RT0001 PST # 1473-0243



Page 1 of 2

SERVICE ADVISOR: 4421 SARAH MCALEER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN / OUT	TAG
41U*BLACK	11	GMC TRUCK K350 CREW	1GT524C86BZ380758	1326HK	242898 / 242898	T2077
IN SERVICE DATE	WARRANTY	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
23JUN11			17:30 13MAR25	0.00	CASH	13MAR25
R.O. OPENED	READY	OPTIONS: DLR:120365 ENG:LML*6.6L-DURAMAX TRN:MW7*6-SPD-ALLISON 1)WSD 23 JUN 11 4)POWERTRAIN LIMITED WARRANTY 23/06/2011 (More...)				
08:04 13MAR25	13:16 13MAR25					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A INSPECT FOR CHECK ENGINE LIGHT							
4020350 GLOW PLUG REPLACEMENT							
	4396	CPD				526.50	526.50
	1	25945274	ELEMENT		74.86	74.86	74.86
	1	19433253	FLUID		41.24	41.24	41.24
	1	12639701	GLOW PLUG		53.76	53.76	53.76
	1	11601765	NUT		8.66	8.66	8.66
	4	7757	TIE STRAP		1.70	1.70	6.80
242898							
SCANNED CUSTOMER VEHICLE FOUND DTC'S SET FOR NOX CATALYST							
EFFICIENCY, DEF QUALITY, & FAILED GLOW PLUG, ENGINE AIR FILTER PLUGGED.							
REPLACED ENGINE AIR FILTER							
QUOTED ALL REPAIRS. (0.5)							
R&R CYLINDER 7 GLOW PLUG (1.0)							
ADDED JUG OF DEF TO CORRECT COMPOSITION (0.2)							
PERFORMED SERVICE REGEN (1.0)							
-----TOTAL							
(2.7) -----							
PREVAILED.							

Ad By Candace
w/credit card
\$1174.54
(Taxes
125.06)

Ad By Candace
w/credit card
\$1174.54
(TAXES 125.06)

B	DIESEL	TRUCK	SYNTHETIC	OIL CHANGE, 16 POINT INSPECTION, TOP UP FLUIDS, ADJUST TIRE PRESSURES \$224.99 - \$259.99 PLUS TAXES, \$3.85 ENVIRO, SHOP SUPPLIES,			
	DEXOSDS	DIESEL	TRUCK	SYNTHETIC OIL CHANGE, 16 POINT INSPECTION, TOP UP FLUIDS, ADJUST TIRE PRESSURES \$224.99 - \$259.99 PLUS TAXES, \$3.85 ENVIRO, SHOP SUPPLIES,			
			4057	CPT		43.49	43.49
	1	12691158	FILTER			3.85	3.85
	3	11247	15w40 syn		31.64	31.64	31.64
					60.31	60.31	180.93
242898	LOF	COMPLETE, FOUND OIL LEAK FROM OIL PAN AREA, NO OTHER LEAKS OR POINTS OF CONCERN, BRAKES AND TIRES GOOD, FLUIDS GOOD, ENGINE					

For Service: Mon-Fri 7:30 am to 5:00 pm Saturday 8:00 am to 4:00 pm Call (250) 377-3301 Most GM Parts & Labour Guaranteed For 12 months or 20,000 km Thank You for allowing us to service your vehicle.	AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.		DESCRIPTION	TOTALS
	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING THE TOTAL AMOUNT OR BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS WORK ORDER.		LABOUR AMOUNT	
	PRIVACY NOTICE: The personal information received from individuals relating to any transaction in this Dealership is collected in accordance with the Dealership's privacy policy. It's collection, use and disclosure is necessary for the purpose of purchase, sale, financing, lease, repair, service or testing of a vehicle (s) and related or other products and services of the Dealership and for providing information about other current and future products and services of this Dealership and its affiliates, the manufacturer of new vehicles for which this Dealership is franchised, any insurers or warranty providers and any applicable leasing or financing entity. If anyone would like further information on our privacy policy, please contact the dealership's privacy officer. BANNISTER CHEVROLET CADILLAC KAMLOOPS LTD. Kamloops, B.C.		PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS INSURANCE	
			TOTAL SALES TAXES	
	CUSTOMER SIGNATURE _____ DATE _____		PLEASE PAY THIS AMOUNT	

Customer Copy

Cust Number:207898

ELDCAN FOREST PRODUCTS

40 1900 HUGH ALAN DR
KAMLOOPS, BC V1S 0A8
Home: 250-573-1900 Bus: 250-318-3103
Email: email|accounting@eldcan.com|home

BANNISTER
CHEVROLET KAMLOOPS

950 NOTRE DAME DR, KAMLOOPS, BC V2C 6J2
250.372.2551 | BannisterChevKamloops.com

GST # 792383614RT0001 PST # 1473-0243

Invoice No: 218681

INVOICE

Page 2 of 2



SERVICE ADVISOR: 4421 SARAH MCALEER

SERVICE ADVISOR: 4421 SARAH MCALEER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN / OUT	TAG	
41U*BLACK_	11	GMC TRUCK K350 CREW	1GT524C86BZ380758	1326HK	242898 / 242898	T2077	
IN SERVICE DATE	WARRANTY	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE	
23JUN11			17:30 13MAR25	0.00	CASH	13MAR25	
R.O. OPENED	READY	OPTIONS: DLR:120365 ENG:LML*6.6L-DURAMAX TRN:MW7*6-SPD-ALLISON 1)WSD 23 JUN 11 4)POWERTRAIN LIMITED WARRANTY 23/06/2011 (More...)					
08:04 13MAR25	13:16 13MAR25						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
	AIR FILTER	GOOD					

C 250 318 3103
M000 NOTE FOR FILE :
4396 IPOL

(N/C)

Please return to the dealership to have your
wheels retorqued after 200km. Thank you again
for the opportunity to service your vehicle.

GST# 792383614RT0001
PST# 1473-0243

(#: GST R104893466)

52.45
73.41

For Service:
Mon-Fri 7:30 am to 5:00 pm
Saturday 8:00 am to 4:00 pm
Call (250) 377-3301

**Most GM Parts & Labour
Guaranteed
For 12 months or 20,000 km**

*Thank You
for allowing us to
service your vehicle.*

AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON
ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.
INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$
BEING THE TOTAL AMOUNT OR BALANCE OWING FOR REPAIRS, PARTS AND
ACCESSORIES DESCRIBED IN THIS WORK ORDER.
PRIVACY NOTICE: The personal information received from individuals relating to
any transaction in this Dealership is collected in accordance with the Dealership's
privacy policy. It's collection, use and disclosure is necessary for the purpose of
purchase, sale, financing, lease, repair, service or testing of a vehicle (s) and
related or other products and services of the Dealership and for providing
information about other current and future products and services of this
Dealership and its affiliates, the manufacturer of new vehicles for which this
Dealership is franchised, any insurers or warranty providers and any applicable
leasing or financing entity. If anyone would like further information on our privacy
policy, please contact the dealership's privacy officer.
BANNISTER CHEVROLET CADILLAC KAMLOOPS LTD.
Kamloops, B.C.

DESCRIPTION	TOTALS
LABOUR AMOUNT	\$ 569.99
PARTS AMOUNT	\$ 397.89
GAS, OIL, LUBE	\$ 0.00
SUBLET AMOUNT	\$ 0.00
MISC. CHARGES	\$ 80.80
TOTAL CHARGES	\$ 1048.68
LESS INSURANCE	\$ 0.00
TOTAL SALES TAXES	\$ 125.86
PLEASE PAY THIS AMOUNT	\$ 1174.54

CUSTOMER SIGNATURE

DATE

Customer Copy

Bannister



General Motors of Canada Company
500 Wentworth Street W
Oshawa, Ontario L1J 0C5



December 2024



SAFETY RECALL / RAPPEL DE SÉCURITÉ

N242469160 1GT59TEY8RF334962 14 0009871
TRUCK AND EQUIPMENT DOONAN
2957 SHUSWAP RD
KAMLOOPS BC V2H 1S9

LP# 000FG
Dads Truck

FRIDAY
11:00AM
march 7th

This notice applies to your vehicle, VIN: 1GT59TEY8RF334962.

Your vehicle is involved in **SAFETY RECALL** N242469160.
Transport Canada Recall # 2024-720

Tailgate

Dear Truck And Equipment Doonan:

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2024 model year GMC Sierra vehicles equipped with power-unlatching tailgates. As a result, GM is conducting a safety recall.

IMPORTANT

- Your vehicle is involved in GM recall N242469160.
- Schedule an appointment with your General Motors dealer.
- This service will be performed for you at **no charge**.
- Until the remedy is completed, owners should check that the tailgate closed and latched before driving.

Why is your vehicle being recalled?

Under certain conditions water may intrude into these vehicles' tailgates and come into contact with the electronic gate-release switch, potentially causing a short circuit. Due to this, the tailgate may inadvertently unlatch while the vehicle is in Park. If the driver does not manually close the gate before beginning a drive, cargo in the bed of the truck may exit the vehicle and become a road hazard, increasing the risk of a crash. Until the remedy is performed, owners should check that the tailgate closed and latched before driving.

What will we do?

Your General Motors dealer will replace the exterior touchpad switch assemblies. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 30 minutes.

What should you do?

You should contact your General Motors dealer to arrange a service appointment as soon as possible.

GMFTV241216002 0009871 01 of 02



0009239



Compagnie General Motors du Canada
500 rue Wentworth O
Oshawa (Ontario) L1J 0C5

Décembre 2024



N242469160 1GT59TEY8RF334962 14 0009871
TRUCK AND EQUIPMENT DOONAN
2957 SHUSWAP RD
KAMLOOPS BC V2H 1S9

Le présent avis concerne votre véhicule, NIV : 1GT59TEY8RF334962.

Votre véhicule est touché par le **RAPPEL DE SÉCURITÉ** N242469160.
Rappel de Transports Canada n° 2024-720

Dear Truck And Equipment Doonan:

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*. La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

General Motors a déterminé qu'un défaut relatif à la sécurité des véhicules automobiles existe sur certains véhicules GMC Sierra 2024 équipés de hayons à déverrouillage électrique. Par conséquent, GM effectue un rappel de ces véhicules pour des raisons de sécurité.

IMPORTANT

- Votre véhicule est touché par le rappel GM N242469160.
- Prenez rendez-vous auprès de votre concessionnaire General Motors.
- Ce travail sera effectué pour vous **sans frais**.
- Jusqu'à ce que le correctif soit effectué, les propriétaires doivent vérifier que le hayon est fermé et verrouillé avant de conduire.

Pourquoi votre véhicule fait-il l'objet d'un rappel?

Sous certaines conditions, l'eau peut s'infiltrer dans les hayons de ces véhicules et entrer en contact avec le contacteur électronique de déverrouillage du hayon, causant potentiellement un court-circuit. Pour cette raison, le hayon peut se déverrouiller par inadvertance lorsque le véhicule est en position P (stationnement). Si le conducteur ne ferme pas le hayon manuellement avant de commencer à conduire, le chargement de la caisse du camion peut sortir du véhicule et devenir un danger sur la route, augmentant le risque de collision. Jusqu'à ce que le correctif soit effectué, les propriétaires doivent vérifier que le hayon est fermé et verrouillé avant de conduire.

Quelles mesures allons-nous prendre?

Votre concessionnaire General Motors remplacera les assemblages de contacteurs de pavé tactile extérieur. Ce travail sera effectué pour vous **sans frais**. En raison d'une possibilité d'achalandage accru au service après-vente, votre concessionnaire devra probablement garder votre véhicule plus longtemps que la durée réelle d'un entretien correctif de 30 minutes.



VEHICLE DETAILS:	APPLICANT DETAILS:	BROKER DETAILS:
2024 GMC Sierra 3500HD SLE 4WD Double Cab 162" SLE	Doonan Truck & equipment Ltd	Westland Insurance Group Ltd. - Kamloops Columbia Place
Odometer: 10 km	BC V2H1S9	Agent Name: Madison Irmen
Condition: New	Phone:	Phone: (250) 371-5150
Vehicle Value: \$75,799.00 MSRP	Email:	Email: mirmen@westlandinsurance.ca
Purchase Method: None		

PRICE SUMMARY

Core Package

Total Loss Benefit:	\$627.00
Key FOB Reimbursement Benefit	Included

Optional Benefits

Partial Loss O.E.M. Benefit	\$107.00
Partial Loss Deductible Reimbursement Benefit	Declined
Rental Vehicle Reimbursement Benefit	Declined
Diminished Vehicle Value Benefit	Declined

Total Premium 1 Year Policy Term \$734.00

Please note: Premiums quoted are subject to change at any time. Should you have any questions regarding the Optiom Prime plan, please contact your Broker directly.

ACCEPT COVERAGE

Yes, I/we would like to purchase the Optiom Prime policy and I/we confirm that my vehicle is:

- Not for Commercial Use; and
- Not salvaged, rebuilt or modified; and
- Not more than 6,500 kg (14,330 lbs); and
- Not driven more than 50,000 km/year; and
- Insured under a primary auto insurer for collision and/or comprehensive and will continue to be for the duration of the term of this policy

	15/Nov/2024		15/Nov/2024
_____		_____	
1 st Applicant Signature	Date Signed	2 nd Applicant Signature	Date Signed

No coverage is in effect until a valid policy is issued by Optiom. Subject to the policy limitations and conditions. Your policy will be emailed to you immediately upon issuance.

DECLINE COVERAGE

No, I/we decline to purchase the Optiom Prime vehicle replacement insurance for the forementioned vehicle. By declining Optiom Prime, I/we understand that I/we will be entirely responsible to my lender/lessor under the terms of my loan or lease agreement for the financial impact of a total or partial loss to my vehicle.

	15/Nov/2024		15/Nov/2024
_____		_____	
1 st Applicant Signature	Date Signed	2 nd Applicant Signature	Date Signed