

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A30F ADT used 2012						
	45527	Tenkate upgrades 4771 Hrs, Pre Hire Inspection, install battery & start isolation switches, E-Stop, replace alternator, Pos. 3 & 4 suspension blocks, belt idler pulley, windscreen washer pump, gasket on transmission filler cap, A/C filterstop up coolant, sand guards for stone guard, silicone all gaps, fit grease lines, Stamp all rims, fit all safety stickers, non slip tape, Change engine oil & sample all compartments, fit fire extinguisher & bracket, wheel cocks & bracket, weld on tailgate ID numbers, replace flashing light, led brake light, repair cracked body floor dovetail plate	25/10/2018 1		Hours	.00	71.00	\$8706.85
	45546	Install High Sulfur Fuel Conversion Kit - 4771 hrs	7/11/2018 12:		Hours	.00	2.00	\$5811.23
	45820	1000 hr Service 4930 Hrs	7/12/2018 12:	4930.00	Hours	.00	8.25	\$1746.13
	45912	Off / Pre Hire 4931Hrs, Degrease all, bracket battery box, reseal windscreen, drop belly plates, grease all, adjust front struts to 295mm, pos 3 brake calliper seals,replace o-rings oil filter block,	21/12/2018 1		Hours	.00	32.50	\$2241.45
	46085	Repaired broken rear accumulator mounts + tightened loose dropbox diff lock selector plate at 5002 hrs	4/02/2019 12:		Hours	.00	3.00	\$775.16
	46161	C/O Pos 3 Tyre on Site 5133 Hrs. Remove Tyre F0J382370 & Rim TN8 4484 / Replace with Tyre F8A282406 & Rim TN8 3083	28/02/2019 1		Hours	.00	6.50	\$301.01
	46340	Repair load dump brake fault, trace to & replace faulty relay, re gas R/H front hydraulic strut lift to correct ride height - 5229 hrs, repair damaged seat side handle & refit, test operation, OK, re position hose rubbing on air temp sensor, top hydraulic tank, cooling system	3/04/2019 12:		Hours	.00	13.50	\$1362.84
	46390	SMU 5233 Off Hire Inspection / put belly plates up , bring machine up , test retarder brake etc RH strut leaking , LH step is bent , , oil residue is coming from bell housing drain hole ,	2/05/2019 12:		Hours	.00	.00	\$2181.16

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		pos bellows, struts are uneven , alt tensioner has no spray , changed transmission, drain valve on transmission topped up fluid level , Bolt on wheel					
46392	5232 hrs	Replace both front Axel Suspension Cylinders - remove both front struts and fitted new struts and pressurise L/H side, inspect tyres removed POS 1 and POS 2 replaced with new tyres and rims	2/05/2019 12:		Hours	.00 26.50	\$18308.72
46628		Repair seat switch button SMU 5242	14/06/2019 1		Hours	.00 4.00	\$208.00
46676		Off hire Inspection SMU 5291 , removed rocker cover and disconnected injector harness, reseal plug, refitted rocker cover , gasket and refitted injector harness	2/07/2019 12:		Hours	.00 13.50	\$1264.12
46931		Pre hire inspection , Put belly plates up replaced fire extinguisher from T76 to T314 mega fire , replaced bulb on work light	9/09/2019 12:		Hours	.00 3.50	\$205.50
47158		Trouble shot starting fault 5479 Hrs + Re soldered battery cable lug onto battery cable to the battery isolator	7/11/2019 12:		Hours	.00 2.00	\$189.13
47063	500 hr Service 5481 Hrs		8/11/2019 12:	5481.00	Hours	.00 2.50	\$912.97
47168		Overhaul Drop Box - 5481 hrs, install re build kit, replace all bearings, differential housing, slide gear, diff lock piston, sleeve, seals, adjust install, test, Found to be jumping out of diff lock when under high load, remove again strip down fully, check all parts Trouble shot air leak 5481 Hrs + found that drop box diff lock assembly bolts had walked out , Removed floor and made up drop box lifting frame for inside the cab + painted frame	5/02/2020 12:		Hours	.00 98.50	\$23024.56
47175		Off / Pre Hire 5486 Hrs, Repair bottom step, replace r/h parker, fix dicky seat belt, install ATC override switches, replace expansion tank. replaced Alt belt, replace all tyres & rims for straddie, dropped struts for straddie, fitted second hand KAB seat shocky, replaced beacon lock handle, straightened body up lock bar bracket. @ 5487 hrs	6/03/2020 12:		Hours	.00 53.00	\$5818.10
47576		Trouble shoot engine failure @ 5489 hrs	1/04/2020 12:		Hours	.00 25.00	\$4656.68
48171		Reseal bonnet lift pump @ 5489 hrs. inflated tyres to 65 psi, pumped struts up to 290mm	31/08/2020 1		Hours	.00 8.00	\$2369.91
48204		Pre Hire Inspection 5490 Hrs, Grease all, Check lights, adjust struts to 290mm,	31/08/2020 1		Hours	.00 7.00	\$775.47

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	48299	Replace blown hydraulic hose supply hose to brake relay valve on rear chassis - 5502 hrs (pirtek strathpine)	18/09/2020	1	Hours	.00	5.00	\$431.12
	48310	Off / Pre Hire 5516 Hrs, rectify engine miss, trace to loose plug on No.4 injector - 5510 hrs, tighten engine mounts, grease all, test machine, check tyres, refit belly plates,	25/09/2020	1	Hours	.00	8.50	\$1212.29
	48444	Replace leaking air fitting on hitch hoses - 5648 hrs [repaired by CJD]	10/12/2020	1	Hours	.00	.00	\$625.37
	47940	Engine Replacement - 5489 Hrs, fit reman cylinder head & turbo to new reman block, remove pumps - electrical harness - cross members - engine mounts - drain fluids, remove seat ,Strip engine down, clean parts, reassemble onto new block ,Fit new engine into truck, reconnect all pipes & pumps & Elecs, fill all fluids,	28/12/2020	1	Hours	.00	245.00	\$50902.53
	48621	Off Hire Inspection 5733 Hrs, replace seals in scavenge pump / pump drive unit, belt tensioners, blow out cab filters, replace inner cab filter, replace pos 3 bellow,	15/01/2021	1	Hours	.00	12.50	\$2146.29
	48743	Off / Pre Hire 5765 Hrs Grease all, check lights, replace fire ext,	5/02/2021	12:	Hours	.00	2.50	\$379.51
	48787	Trouble shot SE2702-4 error code, repair uniden UHF modes @ 5784 hrs	12/03/2021	1	Hours	.00	3.50	\$353.87
	48896	Off / Pre Hire - Hrs Straight to site	31/03/2021	1	Hours	.00	.00	\$0.00
	49083	Repair seat air line - 5978 hrs [CJD] Replace seat cushion pad sensor.	6/05/2021	12:	Hours	.00	7.00	\$815.00
	48965	4000 hr Service - 5996 hrs	13/05/2021	1	5996.00 Hours	.00	11.00	\$4790.53
	49243	Replace dowdy seals on remote engine oil filter housing pipes @ 6088 hrs	25/06/2021	1	Hours	.00	1.50	\$185.33
	49486	Repair hydraulic oil leaking from belly guards, found loose fittings on bottom of brake/fan solenoid, tightened & topped up oil - 6300 hrs	20/08/2021	1	Hours	.00	4.00	\$339.03
	49257	Check reported turbo error code, check turbo, re calibrate turbo actuator - hrs, late invoice costs relating to work order 48965	31/08/2021	1	Hours	.00	.00	\$1195.13
	49539	500 hr Service 6490 Hrs	23/09/2021	1	6496.00 Hours	.00	6.50	\$1101.41
	49698	Replace driveline from drop box to front diff - 6548 hrs (Remove Tailshaft from 1020),	7/10/2021	12:	Hours	.00	5.50	\$1193.81
	49967	Replace damaged parts - hrs [back charge Client Shadfoth],	1/03/2022	12:	Hours	.00	28.00	\$11541.68

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Remove front grill & frame & R/H bonnet panel, replace with new parts, change over headlights, Access damaged to front of unit - hrs					
50178		Off / Pre Hire - Hrs Test operation ,drop belly plates, grease all, degrease all, check tyres, replace a/c filter,	25/03/2022 1		Hours	.00 9.00	\$622.91
50301		Un blocked RH tailgate bearing bearing grease hose - 6671 hrs, topped up coolant	30/03/2022 1		Hours	.00 1.00	\$138.72
50442		Off hire inspection onsite 6819 Hrs so it can be taken directly to another BMD site - , fitted reco Alternator & belt, replace header tank, replace park brake switch.	3/06/2022 12:		Hours	.00 9.50	\$1820.49
50631		1000 hr Service 7008 Hrs	22/06/2022 1	6996.00	Hours	.00 11.00	\$1405.89
50674		Off / Pre Hire - 7044 Hrs, (Offhire inspection onsite for Rochdale BMD), topped up fluids, fitted new Alt belt, replace UHF mic	29/06/2022 1		Hours	.00 3.00	\$1047.47
50828		Replace secondary water pump, belt tensioner and replace rocker switch in dash 7124 Hrs, replace ignition barrel,	29/07/2022 1		Hours	.00 13.00	\$3030.46
50856		Off / Pre Hire - 7150 Hrs Fit new seat belt, fitted upgraded strut covers, replaced R/H indicator, swapped fire extinguisher	15/08/2022 1		Hours	.00 16.00	\$1548.19
50869		Remove wheels,remove bellows and drop diffs down, remove beams, used press to R&R to replace beam bearings + 1 spring - refit beams and wheels, torque all bolts to spec - 7150 hrs	29/08/2022 2:		Hours	.00 48.50	\$5300.08
50870		Replace both guard flares and R/H bonnet - damage back charge to client BMD (invoice #1247 sent 8/9/22)	4/10/2022 12:		Hours	.00 8.00	\$3311.68
51038		Off / Pre Hire - 7269 Hrs Grease all points, Carry out machine checks, wash machine, remove rear axle backing plates to clean excess dirt, replace steer rack bellows, grease machine	4/10/2022 12:		Hours	.00 14.00	\$818.77
51324		500 hr Service - 7478 hrs	5/12/2022 3:4	7478.00	Hours	.00 9.00	\$1295.82
51368		Replace cab door glass - client backcharge (MC Autoglass booked for 12pm 2/12/22) - (Inv #1281 sent 6/12/22)	6/12/2022 7:5		Hours	.00 1.00	\$575.00
51564		Replaced d-box to front diff tailshaft - 7586 hrs, replaced a/c control panel, rectify cooling hose leak, blew out a/c filters	25/01/2023 7:		Hours	.00 7.50	\$3371.68
51752		Off / Pre Hire - 7756 Hrs checked bellows, topped up coolant, check for leaks, checked fluid levels + tyre pressures and depths, replaced grease nipple on body pin + greased machine, replaced outer air filter, drained over full transmission	20/03/2023 2:		Hours	.00 9.00	\$1679.40

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		oil, gassed front LH strut to correct level						
	52006	Off / Pre Hire - 7858 Hrs - Replace Cab Mounts and Pos 5 Bellows. Swapped out seat.	8/05/2023 1:4		Hours	.00	.00	\$2459.89
	52218	Off / Pre Hire - 7947 Hrs - Replaced LH Headlight Bulb, Air seat not working - found kink in line, removed and tested all okay. Fitted new side shims to body pivots. Replaced fuel tank screen.	26/06/2023 7:		Hours	.00	.00	\$644.22
	51949	Rebuild seat - hrs - completed	26/06/2023 1		Hours	.00	4.00	\$973.51
	52178	4000 hr Service - 7948 hrs	27/06/2023 1	7948.00	Hours	.00	.00	\$5536.87
	52342	Replaced both N150 batteries - 7947 hrs, troubleshoot operators seat going down, replaced seat air valve, Replace RH tailgate bearing grease hose	10/07/2023 2:		Hours	.00	9.50	\$1816.10
	52442	Off / Pre Hire - 8063 Hrs - Checked all levels and inspected for leaks. Greased all points. Checked belt tensions and pulleys. Tested all lights and controls. Carried out driving tests.	31/08/2023 1		Hours	.00	6.00	\$376.25
	52672	Off / Pre Hire - 8279Hrs - Checked all levels, lights and controls. Rest tyre pressures and measured tread depth. Inspected body and tailgate. Greased machine. Checked for movement in articulation and steering. Inspected fire extinguisher. Performed operational checks and brake tested. Replaced dipstick tube O-rings. Replaced rear body rubbers. Cleaned out air filters. Fitted body lock. Straightened outriggers. Equalized strut heights. Replaced top RHS cab light lens.	6/11/2023 10:		Hours	.00	17.50	\$1119.77
	52918	Repair aircon - 8367 hrs - Millers - replace dryer + compressor + gas - test ok 12/12	19/12/2023 9:		Hours	.00	.50	\$1556.00
	52949	Off / Pre Hire - 8389Hrs - Checked all levels, belts and pulleys. Tested lights, and carried out operational checks. Reset tyre pressures and checked tread depths. Inspected body, tailgate, ropes and outriggers. Greased machine. Completed driving and brake tests. Relocated fire extinguisher to articulation. Fitted new guide plate and adjusted tub. Replaced bonnet lift pump.	24/01/2024 1		Hours	.00	15.50	\$2285.55
	53089	Change out POS 4 - 8390 hrs Remove tyre F9Y281731 + rim TN83049 and fit tyre S5S000201 + rim 722-226-P5	26/02/2024 9:		Hours	.00	7.00	\$1711.18
	53128	Replace missing body lock pins - hrs Replaced steering lock pin and rear body service lock pin	11/03/2024 9:		Hours	.00	1.00	\$660.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	53249	500hr Service - 8497 hrs	22/04/2024 1	8497.00	Hours	.00	10.00	\$1558.47
	53385	Onsite inspection @ Kinma Valley - 8615 hrs, checked belts, oil levels etc, repaired thread in belt guard mounting bracket, blew out a/c filters, inflated pos 3 tyre to 65 psi, took off hire pics for allocations, swap out 9kg fire extinguisher	10/06/2024 1		Hours	.00	5.50	\$502.35
	53395	Off / Pre Hire - 8616Hrs - Performed driving and brakes tests. Checked all levels, belts and pulleys. Tested lights, and carried out operational checks. Reset tyre pressures and checked tread depths. Inspected body, tailgate, ropes and outriggers. Greased machine. Fault find park brake issue. Replaced bolts in both tail lights. Replaced coolant pipe joining hose.	17/06/2024 1		Hours	.00	24.60	\$1181.31
	53485	Top up coolant requested by client, client had already topped up cooling system with water by the time i got to site.	8/07/2024 12:		Hours	.00	1.50	\$78.00
	53518	Inspected seat sensor - 8648hrs - No fault found, all working correctly.	29/07/2024 1		Hours	.00	.00	\$26.00
	53527	Replace Pos 5 Wheel Seal - 8663hrs - Attended site, replaced wheel seal, refilled system and bled, all okay.	30/07/2024 1		Hours	.00	.00	\$3055.52
	53578	C/O Pos 4 tyre/rim - 8716hrs - Removed S5S000201/772-226P and fitted S9KCU0108/722-226-P6	12/08/2024 8:		Hours	.00	.00	\$709.75
	53719	Replace Pos 6 wheel seal - 8860 hrs, (Waiting on CJD invoice)	9/10/2024 12:		Hours	.00	.00	\$2609.38
	53837	Off/Pre-Hire - 8917hrs - Completed off-hire inspection. Straightened LHS outrigger and replaced broken bolts. Replaced outer A/C & air filters. Replaced RH cab light bulb. Replaced Pos 1 & 2 wheel bearings, wheel seals, brakes pads and caliper seals. Replaced RHF brake pipes. Replaced LH LED clearance light. Resealed windscreen. Replaced tailgate buffers. Straightened LH outrigger and replaced bolts.	12/11/2024 3:		Hours	.00	.00	\$9287.44
	53919	1000hr Service - 8957hrs	20/11/2024 1	8997.00	Hours	.00	.00	\$1296.74
	53913	Off/Pre-Hire - 8947hrs - Replaced cab filters. Replaced LH top mirror. Cleaned air sensor plug. Replaced oil pressure sensor.	10/12/2024 8:		Hours	.00	.00	\$1009.55
	54024	Off/Pre-Hire - 8990hrs - Replaced Pos 3 bellow. Replaced Pos 6 wheel seal.	6/02/2025 3:2		Hours	.00	.00	\$3226.47
	54075	Trouble shoot Fuel surging Fault - 9038hrs - Replaced fuel filters, cleaned filter housing and lines, add fuel doctor and test, OK. Diagnosed algi in fuel system, drained fuel tank, cleaned tank, refilled tank and primed fuel system. Replaced	12/03/2025 7:		Hours	.00	.00	\$3157.76

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		wiper blades. Cleaned inline fuel filter.(AWE Invoice)					
	54121	Resample Drop box - 9146hrs	12/03/2025 3:	Hours	.00	.00	\$92.00
	54163	Replace Muffler - 9161hrs - Replaced blown air line under muffler.	1/04/2025 9:0	Hours	.00	.00	\$3593.74
	54177	C/O Pos 6 Tyre/Rim - 9185hrs Removed F7B482653/TN8 3059 and fitted S5S000201/TN8 4363.	30/05/2025 1	Hours	.00	.00	\$1028.20
	54450	Late Invoice for closed W/O 54177	30/06/2025 1	Hours	.00	.00	\$650.00
		: <u>77</u>	Asset Total:	1047	0.0	982.9	\$236,240.47
		: <u>77</u>	Parent Total:	TPH	0.0	982.9	\$236,240.47
		Grand Total <u><u>77</u></u>			0.0	982.9	\$236,240.47