

## Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Cat D5 LGP dozer used 2021						
	53364	Prepare for work - Tenkate upgrades - Carried out operational checks. Sampled fluids. Fitted safety stickers. Fabricated bracket and mounted flashing light. Filled track frames. Greased machine. Fitted starter isolator, lockout kit and GPS tracker(Millers).Fit seat cover	24/06/2024 3:		Hours	.00	31.10	\$6803.04
	53480	Off / Pre Hire - 207Hrs - Completed off-hire inspection. Replace UHF aerial. Fit stickers.	26/07/2024 8:		Hours	.00	.00	\$1212.79
	53661	Replace Japanese FM Radio with Australian radio + Replace Tenkate Stickers - 208 hrs, quick inspection before unit goes out on hire. Moved UHF to LH pillar	3/09/2024 4:0		Hours	.00	.00	\$913.70
	53467	Initial 250hr service - 263hrs - Adjusted track tensions	9/09/2024 12:		Hours	.00	.00	\$452.96
	53911	500hr Service - 454hrs	19/11/2024 1	500.00	Hours	.00	.00	\$1270.48
	53872	Off/Pre-Hire - 453hrs - Replaced hydraulic steer filter. Updated fire extinguisher.	4/12/2024 8:3		Hours	.00	.00	\$1787.34
	53516	Prep for GPS fitment - 456hrs	16/12/2024 3:		Hours	.00	.00	\$133.59
	54079	Off/Pre-Hire - 622hrs - Replaced alternator. Replaced bolts LHS of grouser plate. Removed GPS pole.	6/03/2025 9:1		Hours	.00	.00	\$1359.70
	54165	Off/Pre-Hire - 668hrs	20/03/2025 9:		Hours	.00	.00	\$256.23
	54220	Blade maintenance to all pivot points - hrs	11/04/2025 8:		Hours	.00	.00	\$6345.00
	54387	1000hr Service - 1025 Hrs	21/07/2025 1		Hours	.00	.00	\$3855.94
	54455	Off/Pre-Hire - 1025 hrs.Troubleshoot starting fault: Replaced 2x batteries - fault rectified.Adjusted track tension.	23/07/2025 1		Hours	.00	.00	\$1278.22
	54519	Onsite Pre / Hire Inspection - 1,149 Hrs. Blew out Primary ENG air filter and replaced Primary Cab air filter.	11/09/2025 1		Hours	.00	.00	\$529.16
	54736	Off/Pre-Hire Inspection - 1203 Hrs. - Adjusted tracks to spec- Remove R/H rear truck idler, refilled with oil & replaced bungs, refitted idler to track frame- Replaced damaged track link	24/10/2025 1		Hours	.00	.00	\$2459.40

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost		
		bungs- Replaced air filters							
54830		Sample final drives and engine oil - 1,204 Hrs.	30/11/2025	1	Hours	.00	.00	\$195.00	
54867		Replace L/H & R/H Final Drive oil due to Contamination - 1,205 Hrs.	21/01/2026	1	Hours	.00	.00	\$477.00	
55094		Off/Pre-Hire Inspection - 1,219 Hrs. - Replaced FRH track idler and track link master bolts	24/03/2026	1	Hours	.00	.00	\$3314.55	
		:		<u>17</u>	<b>Asset Total:</b>	<u>1129</u>	<u>0.0</u>	<u>31.1</u>	<u>\$32,644.10</u>
		:		<u>17</u>	<b>Parent Total:</b>	<u>TPH</u>	<u>0.0</u>	<u>31.1</u>	<u>\$32,644.10</u>
		<b>Grand Total</b>		<u><u>17</u></u>		<u><u>0.0</u></u>	<u><u>31.1</u></u>	<u><u>\$32,644.10</u></u>	