

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A30E ADT BMA Spec.						
	31869	BMA Spec upgrade, fit fire suppression system, fabricate & fit hand rails, repair steps sand blast and paint, BMA inspection/brake test	21/06/2012 1		Hours	.00	117.00	\$23729.38
	32281	Replace belt driven water pump, tensioners, belts, top up coolant	23/07/2012 1		Hours	.00	.00	\$2158.00
	32938	500 hr Service. 491 hrs	4/10/2012 12:	491.00	Hours	.00	15.50	\$1486.20
	33032	Repair A/C Fault, replace compressor, drier	31/10/2012 1		Hours	.00	.00	\$1819.00
	34170	1000 hr Service. - 896 hrs	27/03/2013 7:	896.00	Hours	.00	14.00	\$2278.67
	34478	Investigate oil leak. 896 hrs.	30/04/2013 1		Hours	.00	.00	\$557.00
	35266	Off hire inspection and Weed and seed. 956 hrs	31/07/2013 3:		Hours	.00	.00	\$1815.00
	36824	inspect truck after rollover. 1278 hrs	11/02/2014 1		Hours	.00	.00	\$542.00
	36499	Pre-hire inspection, weed and seed. 1132 hrs	31/03/2014 1		Hours	.00	4.00	\$366.00
	37247	Costs to set up site	4/04/2014 1:3		Hours	.00	.00	\$110.00
	36875	Repair Roll Over damage, Replace Engine, compressor, fuel pump, replace air cleaner box, left hand handrail, mirror, mirror bracket, R/H window complete, A/C repairs, replace A/C fan motors.	30/08/2014 1		Hours	.00	73.50	\$83422.80
	38164	off-hire inspection, repair seat, replace seat air valve, replace mudguard widener. - 1279hrs	31/08/2014 1		Hours	.00	43.50	\$3875.00
	38422	Late inv for 36875	30/09/2014 1		Hours	.00	.00	\$180.00
	38450	Prepare Bonnet & front lower sections & paint, replace with L/H upper side pannel. 1284 hrs	30/09/2014 1		Hours	.00	48.00	\$2699.88
	38652	Pre Hire Inspection, modify unit comply to BMA standards again, fabricate R/H BMA style handrail, certify Fire suppression system, replace rear tail light, fit tailgate - 1279	30/11/2014 1		Hours	.00	50.00	\$6288.95

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		hrs					
	39059	Replace alternator.	31/01/2015 1	Hours	.00	.00	\$717.00
	39615	Mechanical Inspection, check seat position switch. - 1364 hrs	30/06/2015 1	Hours	.00	3.00	\$368.00
	39977	Pre-hire Inspection, repair rubbed a/c wiring, replaced, seat belt, cracked LHS spotter mirror with one from 1019, BMA Inspection, fire system check.- 1365 hrs	31/07/2015 1	Hours	.00	.00	\$1791.00
	40435	Off hire inspection. - Dry Hire (client ACCM). Replace R/H high beam head light, adjust, repair wiring to reverse alarm, clean batteries & terminals, at 1550 hrs	24/09/2015 1	1550.00 Hours	.00	8.00	\$605.95
	40244	500 hr Service - 1435 hrs	30/09/2015 1	Hours	.00	4.50	\$1442.39
	40629	Replace seals in L/H Steering cylinder - 1553 hrs	21/10/2015 1	Hours	.00	3.50	\$182.00
	40627	Pre Hire Inspection - 1553 hrs	22/10/2015 1	Hours	.00	4.00	\$162.00
	40801	Replace Pos.1 wheel seal - 1612 hrs	19/11/2015 1	Hours	.00	4.00	\$859.90
	40797	Pre hire inspection. - 1612 hrs	20/11/2015 1	Hours	.00	2.00	\$882.00
	40686	Off hire Inpsection - 1611 hrs	30/11/2015 1	Hours	.00	5.00	\$160.00
	41061	Sample : Engine for monitoring. - 1834 hrs	27/01/2016 1	Hours	.00	.00	\$79.00
	41157	Adjusted labour hours for Anton Csik. (Work orders : 40686)	31/01/2016 1	Hours	.00	.00	\$246.00
	41281	2000 hr Service - 2006 hrs	8/03/2016 12:	2006.00 Hours	.00	.00	\$4633.00
	41619	Sample ENGINE oil for monitoring, matris download, replace fire extinguisher, removed arm rests. - 2261 hrs	17/05/2016 1	Hours	.00	13.50	\$827.50
	41635	Replace Pos.4 Wheel seal, wear ring, o-ring. Dry Hire Inspection at hrs, Replace 9kg fire extinguisher - 2261 hrs	17/05/2016 1	Hours	.00	22.00	\$2457.25
	41770	Off hire inspection. -Swap seat from 846. 2370 hrs	8/06/2016 12:	Hours	.00	13.50	\$872.30
	41780	Replace rear view mirror. - 2370 hrs. inv 924 created and sent to Kent.	8/06/2016 12:	Hours	.00	.00	\$123.52
	42057	500 hr Service. - 2440 hrs	9/09/2016 12:	2440.00 Hours	.00	11.00	\$1374.68
	42783	Replace longitudinal diff lock sleeve, piston, seals , remove & refit drop box at 2517 hrs Investigate drop box longitudinal lock operation. - 2517 hrs	1/03/2017 12:	Hours	.00	19.00	\$2084.00
	42524	Insurance Claimed - Rollover repairs at 2516 hrs, travel to site check over due the roll over & found large vibration when driving, trace to the hitch area , found through shaft bearings	14/03/2017 1	Hours	.00	40.50	\$38966.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		failure, unit returned to workshop, split machine in half, stripped down, measure hitch, found to be out of Volvo Specifications with 8 mm bend, striped down & measure through shaft found to have .2mm run out, Parts ordered form over seas, strip out steering bearings & other reusable parts & install into new hitch, install new hitch, joint the machine back together, adjust shimming to specified value, refit tail shafts, fit all hoses & guards, park brake disc, caliper & adjust, grease all bearings, check hitch for axial & radial movement, all within specs, test run unit						
	43079	Pre Hire Inspection at 2520 hrs, replace missing bolt Pos.4 caliper, UHF wiring, adjust tailgate ropes, glue rubber step thread on bonnet step back on,	6/04/2017 12:	2520.00	Hours	.00	3.50	\$311.32
	43099	Replace both Batteries at 2456 hrs	13/04/2017 1		Hours	.00	3.25	\$885.83
	43174	Off Hire - Pre Hire Inspection at 2594 hrs, BMA Compliance Inspections, replace faulty seat sensor, clean to weed & seed standard, clean cabin- 2594 hrs	4/05/2017 12:	2594.00	Hours	.00	6.00	\$985.40
	43192	Replace Pos.1 Wheel Seal & o-rings at 2594 hrs	6/05/2017 12:	2594.00	Hours	.00	7.50	\$376.54
	43441	Fire Suppression system 12 Monthly Inspection & Certification & 9Kg & 1.5 extingusiher	20/06/2017 1		Hours	.00	4.00	\$1752.63
	43498	Off - Pre Hire Inspection - 2760 hrs, replace reverse alarm, tighten loose tailgate bolts, clean unit, replace windscreen washer pump	1/08/2017 12:		Hours	.00	7.50	\$921.97
	43499	Bma Certification, fire supression checks Cert, BMB Inspection, brake test	1/08/2017 12:		Hours	.00	1.00	\$1081.04
	43710	Replace No.2 Cylinder EGR Rocker - 2919 hrs, check engine noise, remove tappet cover & found broken rocker & camshaft failure	1/09/2017 12:		Hours	.00	.00	\$3763.14
	43862	1000 hr Service at 2922 hrs, changed to AT102 Oil	30/09/2017 1	2940.00	Hours	.00	6.00	\$2326.28
	43752	Replace Wheel Seal Pos.2, - 2920 hrs, strip down & reassemble parts as required to complete this repair, replace 12 caliper bolts, replace brake pads pos 1 pos 2,	1/10/2017 12:		Hours	.00	18.00	\$2354.07
	43792	Off Hire / Pre Hire - 2922 hrs, weld numbers tailgate, fix a/c cable fault, replace seat slides	4/10/2017 12:		Hours	.00	12.25	\$1332.29
	43756	Replace Camshaft at 2919 hrs [warranty claimed for all parts] , fit 6 new EGR rockers to rocker shaft, cam bearings, change	1/11/2017 12:		Hours	.00	42.25	\$3104.50

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		over cam drive gear, replace cam mounting bolts, refit & tension cam & check clearance, rocker shaft, adjust all valves & rockers, fit injector harness, rocker cover, refit other components, test run engine assist with loading onto float, clean engine, move unit into shed,						
	44125	Off Dry Hire Inspection - 3052 hrs	8/01/2018 12:	3052.00	Hours	.00	4.00	\$414.80
	44131	Replace L/H steering cylinder seals, Pos.6 suspension block, Pos.1 shock absorbers - 3052 hrs	1/02/2018 12:		Hours	.00	8.00	\$2241.30
	44426	Off/Pre Hire 3158 Hrs, Inspect for bug in fuel tank, remove intercooler assly to gain access to fuel tank, clean out tank & reassemble intercooler, replace cab filters, replaced rhs body rubber,blow out air filter,	21/02/2018 1		Hours	.00	11.50	\$1787.29
	44525	Check A/C fan fault - 3200 hrs, traced to vent control selector was jamed between two settings, lubed cable to free it up	19/03/2018 1	3200.00	Hours	.00	1.00	\$65.25
	44656	Pre hire inspection 3320 Hrs, Replace pos 3 wheel seal & bearings, drop belly plates, remove seat & change back of seat, top up oils, replace fire Ext,	23/04/2018 1		Hours	.00	19.00	\$2224.91
	44771	Replace pos 6 wheel seal 3382 Hrs, Replace all wheel nuts & studs,	10/05/2018 1		Hours	.00	15.50	\$1525.13
	44955	Off / Pre Hire 3666 Hrs, replace Pos 3. rubber suspension block, Top up oils, blow out air cleaners, replace pos 6 caliper bolt, replace body rubber, check all tyres, degrease all,	26/06/2018 1		Hours	.00	24.50	\$3976.43
	44788	500 hr Service 3471 Hrs	29/06/2018 1	3471.00	Hours	.00	5.50	\$916.59
	45132	Late invoice for for labout costs for work order 44955	13/07/2018 1		Hours	.00	4.50	\$606.95
	45178	Late parts cost relating to work order 43756 - parts not covered under warranty for engine repairs	31/07/2018 8:		Hours	.00	.00	\$52.49
	45239	Off Hire - Pre Hire inspection - 3829 hrs, replace secondary water pump & idler pulley & belt tensioner	3/08/2018 12:		Hours	.00	13.50	\$4413.76
	45271	C/o pos 2 tyre on site Kippa Ring Hrs Details	7/08/2018 12:		Hours	.00	.00	\$156.00
	45566	4000 hr Service - 3968 Hrs	31/10/2018 1	4132.00	Hours	.00	5.00	\$4526.79
	45543	OFF Dry Hire Inspection - 3957 hrs . BMA brake test PBC, Air Tank & Fire Suppression Certification, replace seat sensor - 3968 hrs, oil sample rear diff - 4050 hrs, remove tailgate	1/11/2018 12:		Hours	.00	7.50	\$2148.28
	45833	Replace Batteries - 4313 hrs	13/12/2018 1		Hours	.00	1.00	\$651.76
	46006	500 hr Service - 4480 Hrs	7/02/2019 12:	4480.00	Hours	.00	7.00	\$1777.44

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	46097	Replace Pos.6 Wheel Seal - 4480 hrs, fit tailgate, fabricate spacers for tailgate retaining pins, replace bulbs	11/03/2019 1		Hours	.00	3.00	\$1609.84
	46254	Repair leaking caliper on Pos.1 wheel - 4667 hrs, strip, clean, re seal both calipers, fit new pistons as required, brake pads, bleed & test, found both front & one centre diff master cylinder bypassing, replace re bleed brakes & test, refit wheel, tension wheel nuts	1/04/2019 12:		Hours	.00	17.00	\$8574.34
	46298	Repair steering linkage failure - hrs, remove seat & floor panels on #1058 & supply steering linkage for easy fitment by client, install new one to 1058, replace wheel studs	1/04/2019 12:		Hours	.00	4.00	\$1320.72
	46351	Replace both Position 5 & 6 wheel seals - 4765 Hrs. replace wheel studs, replace brake pads on Pos.5 , drain rear diff, refill with oil, free up brake over stroke sensor, refit wheels, tension wheel nuts	3/04/2019 12:		Hours	.00	18.75	\$3014.33
	46352	Replace position 2 Brake air chamber - 4765 hrs, re kit both calipers on position 1, replace rear caliper brake pads, check brake system fault, trace to air chamber full of sand & rusted internally, holding brakes on, re fit wheel, tension nuts, parts on work order 46298	6/04/2019 12:		Hours	.00	15.75	\$1495.67
	46371	1000 hr Service - 4935 hrs	3/06/2019 12:	4935.00	Hours	.00	5.00	\$2798.68
	46458	Replace wheels as required - 4935 hrs. Replace Position 4 wheel	3/06/2019 12:		Hours	.00	11.00	\$1030.20
	46472	Replace rear walking beam bushes - 4935 Hrs, jack up machine remove wheels, walking beams, backing plates, remove old & install, press in new bushes, walking beams, refit other parts & wheels, repair rear tail light protection guard, drill out broken bolts, tap holes, refit guard, refit tailgate	3/06/2019 12:		Hours	.00	30.00	\$6147.05
	46481	Replace Position 2 brake disc - 4935 hrs, due to retaining bolt coming loose & jamming & wearing thought brake disc, reseal front brake caliper, refit components, bleed brakes, top up oil level front diff	3/06/2019 12:		Hours	.00	8.50	\$1685.27
	46668	Off Hire - Pre Hire Inspection - 5104 hrs, replace broken L/H side E-Stop, bulbs, top up coolant	2/07/2019 12:		Hours	.00	4.00	\$620.14
	46998	Check reported starting issue - 5267 hrs, trace to failed relay solenoid on starter motor, replace relay, test OK	25/09/2019 1		Hours	.00	8.50	\$1288.45
	47315	Replace broken mirror right side, missing engine oil filler cap, and wheel chocks [client Shadforth back charge] Invoice	18/12/2019 1		Hours	.00	.50	\$433.96

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		1085 sent 15/01/2020						
47305		Off Hire - Pre Hire Inspection -5629 hrs, replace Beacon, front brake fluid reservoir, blown bulbs, missing in panel covers, wiper blade, diff level bungs, top fluid levels, travel to & from site	16/01/2020 1		Hours	.00	9.50	\$1699.67
47205		500 hr Service - 5629 Hrs	17/01/2020 1	5629.00	Hours	.00	9.00	\$1826.58
47515		Replace blown seat air bag - hrs remove seat from 1019 to replace & repair 1020 seat	1/04/2020 12:		Hours	.00	.50	\$306.08
47750		Replace broken R/H Large mirror - 5833 hrs [Invoice 1116 sent 1/05/2020 12: 27/05/2020]			Hours	.00	.50	\$97.51
47751		Off Dry & Pre Dry Hire Inspection - 5833 hrs, Replace Position 4 wheel seal & suspension block, both R/H side front body pads, silaflex down rubber step threads on bonnet, fit strap to hose support chain. grease, clean machine, clean windows, fit new Tenkate decals	4/05/2020 12:		Hours	.00	11.50	\$1961.32
47905		6000 hr Service - 5953 hrs - changed Coolant, Completed Mackay Yard.	25/06/2020 1	5953.00	Hours	.00	12.00	\$4180.10
47994		Pre Hire Inspection - 5950 Hrs, replace belt idler pulley & tensioners, battery isolator, body rubbers, flush cooling system, clean machine, cab, windows	25/06/2020 1		Hours	.00	11.50	\$4142.52
48001		Position 3 brake caliper leak - 5952 Hrs, remove & strip, re kit caliper, reinstall, bleed brakes, test operation,	25/06/2020 1		Hours	.00	6.00	\$1438.59
48394		Replace starter switch, Deliver spare wheel to Haughton River site for NQ Excavations	2/11/2020 12:		Hours	.00	9.00	\$1484.54
48475		500 hr Service - 6551 hrs	19/11/2020 1	6551.00	Hours	.00	9.00	\$2461.40
48766		Off / Pre Hire - 6669 Hrs, replace A/C air filters, wiper blade, hydraulic hose to radiator cooling fan motor, missing out rigger mounting bolts, fit shims to front body guide, wiper head, by pass fire suppression system due to low pressure, grease & wash machine & clean cab	12/02/2021 1		Hours	.00	7.00	\$1222.34
49040		Off / Pre Hire - 6743 Hrs. Replace seals in R/H steering cylinder, centre diff pinion seal, Pos.3 suspension block, fuel tank screen, screws, R/H front windscreen section, air vents, refit steering rack bellows, check over unit, repair BMA alarm system, adjust gear selector micro switch, grease unit, install tags to fire extinguishers, fit new O-rings to hydraulic hose	6/05/2021 12:		Hours	.00	37.50	\$4174.67

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		fittings, grease nipple to L/H tailgate fitting, re fit belly guards, degrease engine & work areas, clean radiators,						
49181		Diagnose longitudinal diff fault - 6803 hrs, test all electrical circuits, found no feed voltage from VECU to MA4604	4/06/2021 12:		Hours	.00	7.50	\$6635.31
49240		Off / Pre Hire - 6816 Hrs (Remove Gear selector from 970 & install) , check & adjust tyre pressures, repair flashing light, replace park light bulbs, clean belly guards, full grease,	25/06/2021 1		Hours	.00	8.00	\$845.10
49361		1000 hr Service - 6929 Hrs	16/08/2021 1	7051.00	Hours	.00	6.00	\$1993.93
49613		Hitch repairs 7028 Hrs, Split Tractor unit from frame, remove lower bearings, clean & check, repack bearings, put back together, reconnect tractor with frame, fit steering rams,	21/09/2021 1		Hours	.00	26.00	\$3210.07
49594		Off / Pre Hire -7028 Hrs, grease all, blow out filters, check tyres, degrease all, check all operations,	23/09/2021 1		Hours	.00	14.00	\$792.00
49714		C/O Tyre TPH Yard Position 3 - 7031 Hrs, Remove Tyre F7L382454 & Rim TN8 3033 / Replace With Tyre F8S284069 & Rim 742-412-P1.	8/10/2021 12:		Hours	.00	4.00	\$263.10
49647		Rectify gear selection fault - 7028 hrs, trace to failed ECU, replace & testy all OK (Front tailshaft replaced from 1018)	1/11/2021 12:		Hours	.00	22.00	\$7774.34
49928		500 hr Service -7414 Hrs	10/01/2022 1	7414.00	Hours	.00	4.25	\$1244.81
50040		C/O Tyre's Mackay Yard -7414 Hrs, Remove Pos 3 Tyre F8S284069/Replace With Tyre CVA7882L8A -- Remove Pos 4 Tyre F0J282820/Replace With Tyre VVX0183V3A*** .TPH Yard Remove Pos 3 Tyre CVA7882L8A-Replace with Tyre F8S382667 / Remove pos 4 Tyre VVX0183V3A-Replace with F7J482555.	27/01/2022 1		Hours	.00	8.00	\$1503.06
50070		Off / Pre Hire -7416 Hrs, Test all operations, replace fire ext, drop belly plates, grease all, replace pos 5 suspension block, check tyres,	27/01/2022 1		Hours	.00	7.00	\$1369.87
50022		Repair broken tailgate grease line, E-Stop, repair air leak under cab - 7415 hrs, trace to build up of dirt around treadle valve, clean out dirt, refit fit floor & seat	10/02/2022 1		Hours	.00	4.00	\$514.70
50021		Replace Seals in R/H side steering cylinder - 7415 hrs	11/02/2022 1		Hours	.00	3.50	\$546.26
50185		Replace exhaust manifold centre section & gaskets - 7515 hrs (CJD BEN)	18/03/2022 1		Hours	.00	9.00	\$3188.44
50179		Off / Pre Hire -7515 Hrs, Drop belly plates, blow out filters, replace anti slip tape at front, trans oil decal, 2 belly plate bolts,	25/03/2022 1		Hours	.00	12.00	\$2266.59

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		alt & water pump belts, grease all, brake over stroke pos 2, replace gear selector gate, door strut, bleed brakes,					
	50717	Replace LH trans filter, top up trans oil - 7708 hrs	5/07/2022 12:		Hours	.00 6.00	\$610.69
	50950	4000 hr Service - 7898 hrs	12/09/2022 1	9414.00	Hours	.00 10.00	\$3511.35
	50850	Trouble shoot reported engine miss (CJD attended, replaced injector plugs, performed cold/hot valve set, performed cylinder cut out test, inspect error codes. No fault found)- 7786 hrs, replace pos #2 master cyl	12/09/2022 1		Hours	.00 4.00	\$2974.54
	50970	Off / Pre Hire - 7898 Hrs Checked belts, pulleys and air intake hoses. checked for oil leaks, inspected driveshafts, changed air filters, changed cab filters, checked/pumped tyres to 65psi, changed vent control wire, repair over stroke switch (sized) bleed rear brakes, remove R/H steer cylinder rod for replacement, reseal and fit recondition steer cylinder rod, test, fit roof panel	4/10/2022 12:		Hours	.00 54.00	\$5514.68
	51092	Topped up 5 lts hyd oil, replace both tailgate grease nipples - 7964 hrs	17/10/2022 1		Hours	.00 2.50	\$182.40
	51101	Check reported air con issue - 7942 hrs CJD attended, found faulty thermostat. Replaced and tested	14/11/2022 2:		Hours	.00 1.00	\$1037.64
	51277	rectify brake over stroke sensor fault on mid axle - 8143 hrs - replace master cylinder + reservoir - CJD	6/12/2022 10:		Hours	.00 4.50	\$1645.96
	51544	Off / Pre Hire - 8238 Hrs, Test all machine functions, bleed rear brakes, replace engine exhaust pipe section, brake pressure switch,	7/02/2023 7:4		Hours	.00 25.50	\$4767.61
	51573	Replace damaged rim flange - POS 1 -hrs - back charge client	20/03/2023 3:		Hours	.00 1.00	\$793.79
	51889	Replaced starter and battery isolators - 8514 hrs	28/03/2023 8:		Hours	.00 5.50	\$632.10
	51812	500 hr Service - 8514 hrs	4/04/2023 7:3	8514.00	Hours	.00 13.00	\$1513.38
	51911	Off / Pre Hire Inspection - 8515 Hrs. Fit new seatbelt. Replaced RHS tailgate bearing & bearing plate. Repair brake light issue - swapped brake light assembly from 968.	14/04/2023 1	8515.00	Hours	.00 23.00	\$3328.47
	52118	Off / Pre Hire - 8591 Hrs - Replaced exhaust stack.	31/05/2023 1		Hours	.00 11.50	\$1746.78
	52186	Line bore body locations + fit new bushes, seals and pins - 8592 hrs	26/06/2023 6:		Hours	.00 7.00	\$4347.29
	52312	Replace batteries - 8592hrs - Call out for Flat Battery Fault. Tested batteries to find faulty - replaced and tested, all okay.	5/07/2023 12:		Hours	.00 4.00	\$1168.85

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	52396	Off / Pre Hire - 8608 Hrs - trouble shoot machine not starting, replaced cracked fuel bowl. Replaced E-ECU (CJD). Replaced dipstick. Replaced brake master cylinder. Replaced brake line to Pos 1. Replaced steering bellows. Replaced LHS steer cylinder seals. Rebuilt fire suppression tank bracket. Replaced tailgate ropes. Replaced bonnet pump.	27/09/2023 1		Hours	.00	104.50	\$14200.74
	53152	Repair and repaint handrails - 8613hrs - Removed handrails, roof grab rails and mirror brackets. Prepped for painting, primed and painted. Refitted.	2/04/2024 1:2		Hours	.00	33.50	\$2539.90
	53248	Check reported air con issue - 8638hrs (CJD repaired) - Checked pressures and belt. Removed RH panel and inspected thermostat and evaporator. Filled system with 300g, compressor started cycling. Tested okay.	3/06/2024 11:		Hours	.00	1.00	\$1125.00
	53337	Check vandal damage - replace missing body lock bar and pins - hrs - Inspected machine & cleaned powder off engine.	10/06/2024 1		Hours	.00	6.60	\$444.30
	52974	Rebuild water tank and fit to #1020 - 8613hrs - Disassembled spray bar and inspected for damage. Removed and disassembled water pump to inspect for wear and tear. Disassembled hydraulic pump and inspected. Disassembled cannon and inspected. Rebuilt water pump and painted housing. Not continuing with the water tank rebuild at this stage - tank moved to yard	21/06/2024 2:		Hours	.00	67.50	\$13682.13
	53478	Off / Pre Hire - 8798hrs - Carried out on-site off hire inspection, Found Pos 3 wheel seal leaking - truck to return to workshop for repairs. Replaced bonnet latch and resealed bonnet pump.	18/07/2024 8:		Hours	.00	.00	\$733.05
	53511	Replaced Pos 3 wheel seal - 8798hrs - trouble shot hydraulic leak on suction pipe, replaced clamp.	18/07/2024 8:		Hours	.00	.00	\$2641.98
	53589	Off-hire inspection - 8852hrs - Completed off-hire inspection. Replaced air filters. Replaced tail shaft. Replaced LH upper mirror.	6/09/2024 3:3		Hours	.00	.00	\$2283.15
	53734	Off hire Inspection - 8909hrs - Completed off-hire inspection. Rebuilt tail shaft. Replaced main pulley hub and water pump belt. Replaced alternator.	11/10/2024 8:		Hours	.00	.00	\$3320.58
	53784	1000hr Service - 9002hrs	17/10/2024 8:	9414.00	Hours	.00	.00	\$2839.51
	54017	Rectify A/C not working - 9176 hrs - Replace a/c compressor and dryer, Repair wiring to RHS estop. Top up hyd oil(7litres), replace failed voltage converter and harness.	12/02/2025 2:		Hours	.00	.00	\$3559.20

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	54195	Rectify Uhf wiring fault - 9337 hrs, re wire UHF and FM radio power sources. Check reported Park Brake fault but couldn't fault.	7/04/2025 6:2		Hours	.00	.00	\$686.50
	54286	Off/Pre-Hire - 9372 hrs.Trouble shoot brake over stroke warning light, replaced front left brake master cylinder, bleed brakes, replace park brake solenoid, adjusted park brake to spec, repaired seat air line, tightened loose hand rails, replaced bonnet pump, resealed bonnet lift cylinder. swapped out fire ext.	20/06/2025 1		Hours	.00	.00	\$3190.94
	54470	Trouble shoot low power fault - 9586 hrs.Replaced fuel filters and blew out lines. Conducted stall test - maxed out at 1400 RPM.blew out fuel filter housing and conducted pressure test - 65psi. Replaced fuel filters and overflow valve.trouble shot brake over stroke fault - bled front right master cylinder and caliper. Identified blown flexi brake hoses on rear axle and middle axle - replaced lines and bled system.Replaced missing handrail bolts.Trouble shot boost leak, found intake heater bolt threads were striped, Repaired threads and refitted heater element.Re-conducted machine stall test - maxed at 1600 RPM.Repair UHF radio harness.Replaced failed Park brake pressure sensorReplaced battery isolator CJD sent to investigate low power. Stall speed test conducted - maxed out at 1100 RPM.No visible aeration in control circuit. Feed pressures SERV. Injector cutout test SERV. Inspected overflow valve and identified damage allowing air to blow through whilst conducting test. Additionally identified park brake pressure switch failed. replaced park brake pressure switch.	14/07/2025 1		Hours	.00	.00	\$6098.43
	54426	500 Hr service - 9494 Hrs	18/07/2025 1	9494.00	Hours	.00	.00	\$1463.00
	54770	Inspect truck after rear chassis roll over - 10023 hrs, - Replace both L/H Mirrors	15/10/2025 1		Hours	.00	.00	\$680.15
	54740	2,000 Hr Service - 10013 Hrs. - Replaced both L/H mirrors.	16/10/2025 1		Hours	.00	.00	\$4076.44
	54872	Trouble shoot intermittent a/c fault - 10,108 Hrs. - Blew out primary and secondary cab filters, Test OK- Troubleshoot fuel fault - 10,127 Hrs, founf primer pump was u/s, replaced fuel filter housing.- Replace failed middle axle flexi brake hose. bleed system, Test OK - Rectify coolant leak at back of water pump housing: replaced seal on pipe.	27/11/2025 1		Hours	.00	.00	\$2091.78

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	54913	Inspect vandal damage onsite at Shadforth Coomera - 10023 hrs- Replace both L/H rear view mirrors.(parts/labour costs on w/o 54770)- Back charge invoice included	28/11/2025	1	Hours	.00	.00	\$20.00
	54955	Inspect exhaust rattle at muffler - 10,194 Hrs. - Identified muffler was full of rocks. Removed debris and welded cracks. - Replaced failed muffler and clamps- Replaced air safety valve on front chassis air tank	16/12/2025	1	Hours	.00	.00	\$5186.53
	55005	Rectify air leak in operator's seat - 10,252 Hrs.- Replaced air line from seat to sidewall.- Replaced additional small air line under seat.	12/01/2026	1	Hours	.00	.00	\$927.02
	55137	Rectify hydraulic oil leak under cab - 10,488 Hrs- Tightening rear cover bolts for steering spool. Tested OK, degreased leak. - Rectified air leak at seat	5/03/2026	12:	Hours	.00	.00	\$1259.89
	55108	500 Hr Service - 10,478 Hrs.	6/03/2026	9:0	Hours	.00	.00	\$1689.40
		: <u>139</u>	Asset Total:		1020	<u>0.0</u>	<u>1527.6</u>	<u>\$432,518.20</u>
		: <u>139</u>	Parent Total:		TPH	<u>0.0</u>	<u>1527.6</u>	<u>\$432,518.20</u>
		Grand Total <u><u>139</u></u>				<u><u>0.0</u></u>	<u><u>1527.6</u></u>	<u><u>\$432,518.20</u></u>