

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Workshop 41 Izuzu FVY 1400 long Izuzu Module for #582					
	34456	400hr Service - 397 hrs. Swap fire extinguishers (done 05.07.13)	18/10/2013 8:		.00	6.00	\$849.00
	37435	replace oil pump filter and service tank air breathers.	30/06/2014 1		.00	3.00	\$891.00
	38140	rust repairs to near side top corner	31/08/2014 1		.00	21.00	\$1092.00
	38745	Repair oil leaks and re-fit doors, repair oil nozzle.	30/11/2014 1		.00	7.00	\$1309.00
	38901	Hydraulic Tank repair.	10/12/2014 1		.00	21.00	\$1897.00
	38995	Waste tank repair. sand blast & paint internal rusted side & roof sections	31/01/2015 1		.00	24.50	\$3154.00
	39221	Crane certification inspection	22/02/2015 1		.00	7.00	\$832.00
	39222	Repair hinges on doors. - 152000 kms	28/02/2015 1		.00	4.00	\$648.00
	39283	March repairs, repair rust in front top passenger side corner / RH rear door.	30/04/2015 1		.00	4.50	\$387.00
	39617	Replace engine oil pump. - 06/05/2015	31/05/2015 1		.00	5.00	\$1210.00
	39658	Investigate and repair rust issues in water tank, replace sight glasses and assoc. fittings. - 785 hrs	1/06/2015 12:		.00	46.50	\$4243.00
	39799	800hr service, replace toolbox slides, replace rusted bolts in door strut brackets. - 792 hrs	30/06/2015 1		.00	6.00	\$1446.00
	40144	Repair air leak to overflow protection valve on roof, replace hinge on fuel cap cover, replace 1 x P565183/ 3 x P565185 filters, repair 1 x oil pump, replace 1 x oil gun. - 169500 kms	30/09/2015 1		.00	24.00	\$3104.00
	40523	General tidy up of spares compartments, replace 4 x oil filters, repair 1 x oil pump (hydraulic), take to BARD engineering for rust repairs to front LH top corner of module. - (No. 4 attempt).	31/10/2015 1		.00	21.50	\$2158.00
	41003	Change out AGRIS oil pump, clean out, replace o-rings on air regulators.	1/02/2016 12:		.00	5.50	\$336.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	41280	Crane certification inspection	29/02/2016	1	.00	6.00	\$659.00
	42364	1000hr service on compressor. - 1012 hrs	31/10/2016	1	.00	1.00	\$361.00
	42876	Crane certification Inspection. - 224000 kms	15/02/2017	1	.00	13.00	\$1115.00
	42878	February repairs, repair oil leaks on oil pumps.	1/03/2017	12:	.00	3.00	\$512.00
	43090	April Repairs	1/06/2017	12:	.00	9.00	\$468.00
	43897	400 Hr Service at 1190 hrs	11/10/2017	1	.00	4.00	\$707.78
	43896	Re Seal oil pumps, engine oil & transmission oil pumps, 1190 Hrs,	13/10/2017	1	.00	23.50	\$1673.90
	44413	Reseal oil pumps, replace battery boxes on oil guns X 4, adjust oil pump seals,	28/02/2018	1	.00	11.50	\$1208.06
	44485	Re hinge all doors, reseal spare oil pump, replace seals in Engine oil pump	27/03/2018	1	.00	8.00	\$946.08
	46163	Replace fill point fittings & oil metering gun	27/02/2019	1	.00	8.00	\$3267.59
	46312	Crane certification - 300253 klm	26/03/2019	1	.00	2.75	\$664.10
	46382	Supply new Oil Pump & parts	26/06/2019	1	.00	10.50	\$1614.66
	46961	200 Hr Service	17/09/2019	1	.00	4.00	\$439.36
	47125	Replace door hinges as required , check compressor cooling fan,	4/12/2019	12:	.00	10.50	\$874.80
	48384	Replace Engraved signs for waste oil, Cat elc coolant, Volvo VCS Coolant, Volvo AT102 Trans Oil, 12 Volt , 24 Volt, replace oil gun battery cases, Test fire extinguishers	20/10/2020	1	.00	.00	\$718.29
	48532	Remove & Inspect Hyspin pump, Rekit Hyd Pump, replace L/H mid cabinet hinge, Suction hose on waste oil pump, supply Flomax couplings	4/02/2021	12:	.00	16.00	\$3479.79
	48729	Replace front pump compartment door Jamb & Hinge Panel 317220 Kms, Cut out top door jamb & rust out on L/H front door & replace with new jamb, cut out rust & repair in roof above 2nd door, replace tank hatch bolts, carry out small rust repairs to pod, prep & spray paint all repairs, refit all to pod,	4/02/2021	12:	.00	60.00	\$3480.90
	49085	Supply oil dispensing gun & parts to repair other guns, replace oil suction adaptor line, fit seals to 85 /140 oil pump	2/06/2021	12:	.00	15.50	\$4911.65
	49715	Replace Compressor air intake hose & Door struts - 1655 Hrs, supply parts for oil guns, SCVI-01250187V seals, MN7-097-5	1/12/2021	12:	.00	14.50	\$3085.67

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost			
		O rings, GC255197 battery modules, GC25694 Kit repair elec. SDP&SDP15								
	50084	Replace all delivery Oil Pumps, filters, door pinch rubbers , completed set up of tool boxes, install inverter and test.	30/03/2022	1	.00	94.50	\$18553.40			
	50528	Replace oil tank sight glasses	27/06/2022	1	.00	5.50	\$854.08			
	50851	Change in-line filters (back ordered since January) + service air compressor - 1755 hrs + replace hose + replace 1 x gun	5/10/2022	7:1	.00	7.00	\$5656.37			
	51505	Replace top cover on GO102 oil gun	17/01/2023	8:	.00	1.00	\$726.00			
	51628	Replace air supply hose to screw compressor & rubber hose in pump bay	13/02/2023	2:	.00	3.00	\$835.98			
	51676	Repair rust and replace door hinges + fit new stickers	29/03/2023	8:	.00	50.00	\$11306.93			
	51898	Replace all tank desiccant breather filters and the remain 5 old oil level sight glasses	18/04/2023	1	.00	4.00	\$2570.21			
	51989	Repair accident damage. Refit 3 x Toolbox Doors, replace damaged hinges and struts- 382000 klms	9/05/2023	11:	.00	6.50	\$772.82			
	52415	Check/ repair rear work lights - found rivet had broken wire. Replaced wire and test - ok	31/08/2023	1	.00	7.00	\$582.50			
	52603	Replace Gas Bottle Brackets	25/09/2023	2:	.00	8.00	\$1506.91			
	53139	Replace air hoses to oil tank valves	25/03/2024	9:	.00	27.00	\$2467.39			
	53222	Replace compressor hose - kms	22/04/2024	2:	.00	10.00	\$520.00			
	53410	Repair compressor - replace clutch, invertor and pressure switch	24/06/2024	3:	.00	41.00	\$3834.09			
	53477	Replace faulty oil guns and engine oil pump/evac hose couplers - 1988hrs	6/09/2024	3:2	.00	.00	\$8027.52			
	53595	Compressor Service and check for overheating - 1990hr - Diagnosed faulty cooler and cooler fan. Replaced both and tested all okay.	9/09/2024	2:5	.00	.00	\$2636.32			
	53977	Replace oxy cabinet door hinge - 476259 km	20/01/2025	8:	.00	.00	\$521.80			
	54256	Rectify Vmac Compressor power supply issue, rectify compressor not revving back engine when air pressure is at max pressure - 501281hrs	15/05/2025	8:	.00	.00	\$1209.10			
	54637	Replace failed engine oil gun.	23/10/2025	1	.00	.00	\$1810.60			
No of W/O for 582M			:	52	Asset Total:		582M	0.0	691.8	\$118,135.65

