

## Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A40F ADT						
	42397	1044 Prepare unit for work & fit, carry out Tenkate upgrades, fit UHF, spray protector coating under front guards & other areas. - 5 hrs	1/11/2016 12:		Hours	.00	30.50	\$2945.23
	42542	Check & cleaned coolant level, fixed the sensor fault, shortened UHF coax cable. - 133 hrs	1/12/2016 12:		Hours	.00	.00	\$242.93
	42656	Off hire inspection. - 236 hrs	21/12/2016 1		Hours	.00	4.00	\$234.00
	42698	Pre hire inspection. - 237 hrs	10/01/2017 1		Hours	.00	5.00	\$86.00
	42960	March Pre-starts, [check A/C replace filter - 408 hrs]	2/03/2017 12:	408.00	Hours	.00	2.00	\$110.86
	43074	500 hr Service at 1044 hrs	6/04/2017 12:	507.00	Hours	.00	9.50	\$1223.93
	43103	Off / Pre hire inspection. 507 Hrs	13/04/2017 1	507.00	Hours	.00	7.00	\$388.45
	43307	May repairs, check fuel refilling issue, replace tank breather filter - 626hrs	1/06/2017 12:		Hours	.00	4.00	\$268.91
	43402	Rectify oil leaks on remote oil filter piping - 701 hrs Replace dowdy seal	20/06/2017 1		Hours	.00	6.00	\$352.00
	43629	1000 hr Service at 958 hrs	18/08/2017 1	958.00	Hours	.00	9.00	\$1973.71
	43867	October prestarts. Blow out radiator & A/C condenser. Replace fuel tank breather.	28/11/2017 1		Hours	.00	2.00	\$172.06
	44002	November Pre Starts	29/11/2017 1		Hours	.00	5.50	\$321.70
	44584	500 hr Service 1515 Hrs,	6/04/2018 12:	1515.00	Hours	.00	3.00	\$888.35
	44710	Check fuel system warning alarm 1655 Hrs, change fuel filters, replaced fuel pressure sensor	9/05/2018 12:		Hours	.00	1.00	\$473.63
	44712	May Pre Starts, 1633 Hrs, Trouble shot SE 2301 error	30/05/2018 1		Hours	.00	3.00	\$156.00
	45094	C/O Pos 5 Tyre on site 1838 Hrs. Remove Tyre F5U584509 & Rim TN8 4510 / Replace with Tyre F6M283124 & Rim TN8 4428	12/07/2018 1		Hours	.00	9.00	\$517.99

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	45269	August prestarts, fit second hand sun visor, Major repair to Tyre F5U584509	16/08/2018 1		Hours	.00	3.00	\$702.00
	45247	2000 hr Service - 2016 Hrs	27/08/2018 4:	2016.00	Hours	.00	12.00	\$3292.60
	45507	Fitted GPS tracker unit #3138 + checked over unit from wet hire to dry hire for halls,	19/09/2018 1		Hours	.00	5.00	\$327.52
	45612	Off / Pre Hire Hrs, replace broken main water pump belt tensioner ,blow out air filters,drop belly plates & clean, grease all, inflate tyres, check oils top Hyd oil, ,	11/10/2018 1		Hours	.00	6.50	\$754.69
	45663	Off / Pre Hire - 2266 Hrs, Grease all, Degrease engine , blow out filters, check tyres, top up engine oil, drop belly plates, Upgrades for Bris Airport, make up handrails- reverse alarm-unit numbers, tyre pressures,	9/11/2018 12:		Hours	.00	28.00	\$1960.32
	45844	Fitted new UHF radio S/N 88000607, 2387 Hrs	7/12/2018 12:		Hours	.00	1.00	\$463.14
	45849	500 hr Service 2450 Hrs	13/12/2018 1	2450.00	Hours	.00	8.00	\$459.77
	45935	Fit manual longitudinal diff lock control switches - 2500 hrs, check intercooler fan high speed fault, trace to broken sensor SE2602, replace sensor , fire extinguisher	31/01/2019 1		Hours	.00	7.00	\$519.66
	46147	Febuary Pre Start checks & repairs - 2857 hrs	11/03/2019 1		Hours	.00	.50	\$20.00
	46198	1000 hr Service 2989 Hrs	14/03/2019 1	2989.00	Hours	.00	16.00	\$1687.49
	46585	Off hire Inspection , topped up oil level , coolant , blew out filters , remove rocker cover and injector harness and washed out with brake clean. Pumped injector harness full of RTU , tapped out belly guard bolt holes, changed drop box filler plug washer.Degrease engine, clean up,	11/06/2019 1		Hours	.00	.00	\$904.59
	46959	Off hire Inspection , changed fire extinguisher to T278	13/09/2019 1		Hours	.00	.00	\$113.00
	46890	Inspect truck for Oil leak - 3341 hrs, reseal injector harness, replace O-ring on fitting into head, degreased, deflate tyre to 50 PSI for beach work	1/10/2019 12:		Hours	.00	10.00	\$874.46
	47033	Off hire Inspection - 3386 hrs, check oils, lights, AC, seat and dump brake operation, Replace L/H AC pillar vent and R/H dash vent, Grease	2/10/2019 12:		Hours	.00	2.00	\$325.26
	47089	Inspect damage from sticky bonnet switch + repair bonnet with aluminium strips as a temporary fix till machine comes back to the workshop + replace bonnet switch @ 3392 hrs / 3413 Hrs ??	23/10/2019 1		Hours	.00	5.50	\$593.32

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	47085	500 hr Service - 3529 hrs	20/11/2019 1	3489.00	Hours	.00	4.50	\$749.11
	47214	Repair damage cause by hail storm 3529 Hrs, replace front windscreen, refit wiper arms, replace coolant header tank, replaced both RHS and LHS spot mirrors, mirror on top hand rail on front of cab @ 3529 hrs [ Invoice 1079 sent 10/12/19 }	25/11/2019 1		Hours	.00	16.50	\$3009.12
	47261	Off / Pre Hire 3567 Hrs, blow out air filters, check tyres & rims, replace pos 4 bellow,	5/12/2019 12:		Hours	.00	6.00	\$977.85
	47426	Check machine over for hire @ 3568 hrs	20/01/2020 1		Hours	.00	1.50	\$120.70
	47617	Final inspection before going out on hire, topped up engine oil, fitted 9 kg fire ext, repaired reverse camera @ 3569 hrs	19/03/2020 1	3569.00	Hours	.00	1.50	\$141.87
	47693	Off / Pre hire 3609 Hrs, service battery's, check tyres, blow out air filters, l/h tailgate bearing take grease, unseize artic lock pin, grease all, clean & wash evap-cond-intercooler-radiator, measure body blocks	7/05/2020 12:		Hours	.00	11.00	\$526.06
	47743	Replace Front Axle A-frame Bushes - 3610 Hrs	7/05/2020 12:		Hours	.00	26.00	\$2639.00
	48008	Check reported fault with hoist operation -3436 hrs, calibrate body sensor	26/06/2020 1		Hours	.00	1.50	\$244.13
	48391	Off / Pre Hire - 3888 Hrs, replace belts w/p idler pulley ,change coolant due to contamination ,grease all, degrease all, wash truck,	16/10/2020 1		Hours	.00	5.00	\$1621.05
	48392	4000 hr Service 3888 Hrs. Please change Transmission oil AT 102 / Diffs GO 102 / Hydraulic Tank Hyspin AWH 46 / Brake oil Agri As Trans Plus / Coolant Changed due to Contamination.	16/10/2020 1		Hours	.00	9.50	\$5006.17
	48466	Replace fuel tank breather filter - 3951 Hrs, coolant expansion Tank sensor	6/11/2020 12:		Hours	.00	4.00	\$648.93
	48526	Replace universal joint on hitch jack shaft 4017 Hrs, replaced coolant header tank @ 4062 Hrs, resealed rear windscreen	19/11/2020 1		Hours	.00	13.00	\$1748.83
	48830	Off / Pre Hire - 4160 Hrs, replace Pos.3 suspension block, rear diff pinion seal, windscreen washer pump, Top up gas level in A/C system. inflate tyres, rectify electrical fault in R/H mirror, clean out electric plug, test OK, clean out radiator & intercooler, check A/C system due to low efficiency, replace fire extinguisher	5/03/2021 12:		Hours	.00	21.00	\$2172.16
	49208	Late invoice relating to work order 48830 - A/C gas top up CJD	9/06/2021 12:		Hours	.00	2.00	\$221.25
	49169	500 hr Service 4536 Hrs	2/07/2021 12:	6489.00	Hours	.00	9.00	\$1022.60

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	49327	Check body sensor fault - 4558 hrs	31/08/2021 1		Hours	.00	.00	\$550.00
	49666	Check engine oil leak near filters - 4865 hrs	1/11/2021 12:		Hours	.00	8.00	\$2482.20
	49622	1000 hr Service - 4968 hrs	29/11/2021 1	.00	Hours	.00	11.00	\$2669.81
	50244	Replace all Brake Accumulators - 5187 hrs	22/03/2022 1		Hours	.00	10.00	\$8561.91
	50251	Trouble shoot brake cooling oil leak - 5192 hrs, tightened clamps on brake cooling oil hoses into oil cooler, top up Agri oil (15 ltrs), tightened brake wear indicator on pos 4 hub. Test run machine machine with operator for reports of a brake shudder (no problem found) machine had a slight shudder when first applying retarder but when fully applying retarder there isn't a problem (operator error).	23/03/2022 1	5192.00	Hours	.00	5.00	\$1231.57
	50245	Replace both Batteries - 5190 hrs, replace grease hose on LH tailgate bearing, Installed new body lock pin.	24/03/2022 1	.00	Hours	.00	6.00	\$1256.23
	50357	Check reported Body sensor fault - hrs, calibrate sensor	7/06/2022 9:3		Hours	.00	.00	\$876.18
	50569	Replace Pos.6 Wheel on site - 5438 Hrs, Remove Tyre F5U584460 & Rim TN8 4511 / Replaced with Tyre F7M483420 & Rim TN8 4435	8/06/2022 12:		Hours	.00	10.50	\$810.39
	50455	500 hr Service 5489 Hrs	16/06/2022 1	5468.00	Hours	.00	10.00	\$1364.72
	50667	C/O Tyre On Site Position 4 -5546 Hrs, Remove Tyre F5U582998 & Rim TN8 4509 / Replace With Tyre F7M483871 & Rim 322-205-P6 .	28/06/2022 1		Hours	.00	10.50	\$632.76
	50700	Check reported transmission oil leak - 5316 hrs, trace to broken oil filter housing on L/H side of transmission	1/07/2022 12:		Hours	.00	4.00	\$2263.23
	49949	Replace oil feed pipes to remote oil filter housing - hrs	6/07/2022 1:3		Hours	.00	.00	\$521.38
	51111	6000 hr Service - 5930 hrs	24/10/2022 8:	5930.00	Hours	.00	11.50	\$3686.79
	51184	Replace alternator belt, water pump belt, alternator tensioner, remote engine oil pipes, mounts, clamps seals, seat cushion sensor, mounting bolt for extinguisher, top up hydraulic oil, unblock RH tailgate bearing 5930 hrs	24/10/2022 9:		Hours	.00	5.00	\$871.44
	50872	C/O Pos 3 Tyre On Site 5740 Hrs - Remove Tyre F5U584459 & Rim TN8 4508 / Replace with Tyre F7M483870 & Rim 324-051-P6C/O POS 4 onsite - hrs Remove tyre & rim F7M483871 - 324-051-P6/ Replace with tyre & rim F6B284192 - 342-649-P5 AT 5860 HRS	1/11/2022 12:		Hours	.00	22.00	\$1277.25

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	51311	Sample centre diff oil for monitoring 6010 hrs	19/12/2022 9:		Hours	.00	3.00	\$208.00
	51315	Replace damaged rear tail shaft - back charge client - 6015 hrs - Travel to site and inspect rear tail shaft. Fit spare shaft and drop damaged one to Hardy Spicer. Hardy Spicer - retubed shaft, replaced uni joints and balanced shaft. - inv #1300 sent 12/1/23	12/01/2023 1		Hours	.00	6.50	\$1656.28
	51744	Check air con + reverse beeper issues - 6297 hrs CJD - fitted new reversing alarm and checked aircon - test ok	31/03/2023 8:		Hours	.00	1.00	\$3178.37
	51786	Off / Pre Hire - 6306 Hrs Wash machine and perform operational checks, reseal injection harness, modified fuel filler neck to stop fuel blow by, repair leaking hydraulic pump hose, change out reverse camera, adjust tyre pressures	4/04/2023 3:1		Hours	.00	40.50	\$8337.77
	51363	Repair damaged access ladder, Replace L/H engine cover + fit missing wheel chock, replace LH mudguard widener - inv #1321 + #1322 sent 18/4/23	18/04/2023 1		Hours	.00	6.00	\$7401.62
	52359	C/O All tyres - 6306 Hrs, Remove Tyres F2U584740, F5U582964, F7M483870, F6B284192, F6M283124, F7M483420 / Replace With Tyres F2N584471, F2N584025, F2A585651, F2N585575, F2N583728, S3R000697 .	24/07/2023 1		Hours	.00	26.50	\$30871.06
	51799	Inspect centre axle issue - very high iron on multiple oil samples - 6259hrs, remove and dismantle differential - found collapsed thrust washers + damaged hemisphere. Rebuild centre differential. Refitted diff, hubs and brakes. Filled up diff and brake cooling oils. Bled brake relay valve.	9/08/2023 2:4		Hours	.00	116.50	\$32388.07
	52578	Check and repair aircon fault - 6310 hrs - Diagnosed no gas - leaking compressor, replaced compressor and receiver drier.	19/09/2023 1		Hours	.00	1.00	\$1496.50
	52701	Off / Pre Hire - 6345Hrs - Top up engine oil, top up brake oil, top up hydraulic oil. Performed brake tests. Fitted lynch pin to body lock bar. Check fire extinguisher. Performed operational checks. Found and noted leaks, check Tyre depths, condition and pressures. Tighten mirror mountings. Checked body, body mounts and tailgate. Greased machine.	24/10/2023 9:		Hours	.00	5.00	\$424.50
	52938	500 hr Service - 6469 hrs	1/02/2024 9:1	6469.00	Hours	.00	12.50	\$2041.19
	53100	Off / Pre Hire - 6483Hrs - Performed driving and brake tests. Checked all levels. Inspected belts and pulleys. Blew out air filters. Tested lights, and carried out operational checks. Reset tyre pressures and checked tread depths. Greased machine.	4/03/2024 11:		Hours	.00	11.00	\$947.34

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Inspected body, tailgate, ropes and outriggers. Swapped out fire extinguisher. Replaced A/C vent. Replaced 2 x O-rings on front side of PTO pump.						
	53368	Check for site - hrs	10/06/2024 1		Hours	.00	1.00	\$0.00
	53393	Check grease issues + replace R/H tailgate rope - 6488hrs - Greased machine(no issues), Replaced broken RH tailgate rope and checked adjustment.	10/06/2024 1		Hours	.00	4.00	\$414.25
	53440	Diagnose engine oil leak - 6513 hrs, replace pump 3 and 5 mounting face orings.	24/06/2024 1:		Hours	.00	7.50	\$663.28
	53465	Check reported oil leak - POS 5 - 6549hrs - Inspected hub and found brake cooling fitting loose. Removed fitting and replaced o-ring. Tightened, topped up oil and tested.	2/07/2024 11:		Hours	.00	1.50	\$170.50
	53571	Replaced missing tailgate bearing grease lines - 6590hrs + Unblocked tailgate bearings	12/08/2024 8:		Hours	.00	.00	\$257.75
	53577	Replace Damaged Tyre - BACKCHARGE - C/O Pos 5 tyre/rim - 6603 hrs - Removed tyre/rim F2N583728/TN8 4428 and fitted F8N384204/342-420-P4	13/08/2024 1:		Hours	.00	.00	\$1291.48
	53653	Replace seized a/c compressor- 6686hrs - Replaced alternator and both belts + belt guard. Replaced 9kg fire extinguisher, replaced a/c control panel, remove reverse camera cover. Replaced failed compressor/receiver drier and re-gas system. Replaced UHF.	8/10/2024 12:		Hours	.00	.00	\$2812.91
	53991	Replaced LH tailgate rope - 6899 hrs + Replaced RH top rear view mirror	17/01/2025 2:		Hours	.00	.00	\$886.63
	54065	1000hr Service - 6937hrs	30/01/2025 1	6969.00	Hours	.00	.00	\$2468.74
	54053	Off/Pre-Hire - 6937hrs - Replaced air and cab filters. Update fire extinguisher. Replaced LH A/C vent. Replaced Pos 5 bellow. Resealed both front PTO pumps. Replaced RHS tailgate bearing grease hose. Replaced rotating beacon.	13/02/2025 9:		Hours	.00	.00	\$3162.87
	54118	Diagnose fuel issue - 6962hrs, Found fuel tank was empty, replaced fuel filters and fuel tank breather, client refilled fuel tank.	1/04/2025 8:0		Hours	.00	.00	\$808.67
	54485	Rectify coolant leak - 7376 HrsReplace coolant header tank.	14/07/2025 1		Hours	.00	.00	\$1294.34
	54537	500 Hr Service - 7,514 Hrs.	11/08/2025 1		Hours	.00	.00	\$2143.61
	54636	Diagnose a/c fault - 7634 Hrs. Replace faulty TX Valve (CJD)	11/09/2025 1		Hours	.00	.00	\$2965.82

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	54767	Off/Pre-Hire Inspection - 7,771 Hrs. - Replaced POS 3 & 4 bellows, parking light blubs, fire extinguisher + bag, wiper blade, LH mirror and rear differential breather. - Resealed POS 3 PTO pump. - Diagnosed UHF fault: repaired settings for channel 40. - Welded mirror frame mounting brackets and painted.	20/11/2025	1	Hours	.00	.00	\$5106.63
	55012	Late Invoice for w/o 54746	12/01/2026	1	Hours	.00	.00	\$645.00
	55099	Replace POS 5 O-ring - 7,778 Hrs.- Investigate error codes: EF8706-11 & EF8700-11. Replace leaking Evaporator core and drier.-Late AWE invoice for 54746	15/04/2026	1	Hours	.00	.00	\$2595.30
		:						<u>89</u>
			<b>Asset Total:</b>		<b>1044</b>	<b>0.0</b>	<b>694.0</b>	<b>\$189,896.72</b>
		:						<u>89</u>
			<b>Parent Total:</b>		<b>TPH</b>	<b>0.0</b>	<b>694.0</b>	<b>\$189,896.72</b>
		<b>Grand Total</b>				<u><b>0.0</b></u>	<u><b>694.0</b></u>	<u><b>\$189,896.72</b></u>