

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A40F ADT						
	32624	1026 A40F Serial No.52382 Tenkate upgrades Install, fit UHF, lockable battery Isolator, under guard protection ETC at hrs	31/10/2012 1		Hours	.00	6.00	\$2848.79
	33267	First 100hr service - 132hrs	13/11/2012 1		Hours	.00	.00	\$0.00
	33990	steering cylinder leak repaired under warranty.	28/02/2013 1		Hours	.00	.00	\$0.00
	34660	Pre - Hire Inspection. 180 hrs	31/05/2013 1		Hours	.00	.00	\$450.00
	34681	Wash & clean this Unit. 180 hrs	31/05/2013 1		Hours	.00	.00	\$500.00
	34644	April tyres	30/06/2013 1		Hours	.00	.00	\$0.00
	34981	June Pre Starts	30/06/2013 1		Hours	.00	2.00	\$944.00
	35229	500 HR Service. 675 hrs	22/08/2013 1	675.00	Hours	.00	6.50	\$1260.58
	35286	July pre-starts	22/08/2013 1		Hours	.00	.00	\$1360.00
	35389	August Pre-Starts. Replace pressure sensor	31/08/2013 1		Hours	.00	4.50	\$327.50
	35647	1000 HR Service. 930 hrs	23/09/2013 8:	930.00	Hours	.00	13.00	\$1798.56
	35717	September Pre-starts. 930 hrs	30/09/2013 1		Hours	.00	2.50	\$1557.00
	35982	October pre-starts. 1172 hrs	31/10/2013 1		Hours	.00	14.00	\$884.00
	36233	November pre-starts.	30/11/2013 1		Hours	.00	5.00	\$391.00
	36364	500 HR Service. 1536 hrs	30/11/2013 1	1536.00	Hours	.00	17.00	\$1661.00
	36452	December pre-starts	31/12/2013 1		Hours	.00	1.00	\$20.00
	37032	Mechanical inspection (pre-hire?) repiar RHS indicator wiring. relplace faulty lhs tailgate bearing grease line. weed and seed. 1909 hrs. inspect fire extinguisher.	5/03/2014 12:		Hours	.00	10.00	\$808.00
	36988	2000 hr Service - 1909 hrs	12/03/2014 7:	2036.00	Hours	.00	8.00	\$4530.71
	36968	Replace Pos 1 wheel rim due to damage from previous hire	31/03/2014 1		Hours	.00	.00	\$296.00
	37105	March pre start	31/03/2014 1		Hours	.00	1.50	\$183.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	37186	April Pre-start	30/04/2014 1		Hours	.00	.00	\$162.00
	37402	May pre-start. 2163 hrs. inspect rum marks on inside of pos #5 - measured - tyre has wrong offset 2196 hrs.	31/05/2014 1		Hours	.00	19.50	\$1195.50
	37680	Late invoice for 37402	18/06/2014 8:		Hours	.00	.00	\$1072.00
	37579	June Pre-start. 2229 hrs. Top up agri. recalibrate body angle sensor.	30/06/2014 1		Hours	.00	7.50	\$575.00
	37542	500 HR Service. 3491 hrs	21/07/2014 1		Hours	.00	12.00	\$1299.00
	37785	July Pre-start. 2391 hrs. replace fuel filters 2506 hrs	31/07/2014 1		Hours	.00	8.00	\$1192.45
	38082	August pre start. fit new fuel filters, put in fuel doctor.	31/08/2014 1		Hours	.00	8.00	\$883.60
	38305	September prestarts. top up engine and hydraulic oil. 2867 hrs. replace hoist hose over hitch.	30/09/2014 1		Hours	.00	8.00	\$1067.00
	38503	October prestart, topped up engine oil. - 2933 hrs	31/10/2014 1		Hours	.00	5.00	\$495.00
	38342	Upgrade to softwear (labour only due to out of 12 months warranty) - 3017 hrs	30/11/2014 1		Hours	.00	.00	\$640.00
	38570	1000 HR Service - 3016 hrs	30/11/2014 1		Hours	.00	11.00	\$1567.65
	38694	November Pre-Start	30/11/2014 1		Hours	.00	13.50	\$702.00
	38900	Off hire inspection - 3028 hrs	31/12/2014 1		Hours	.00	10.50	\$666.00
	38908	December Pre-starts	31/12/2014 1		Hours	.00	3.00	\$156.00
	39760	Prehire Inspection, replace 2 x batteries, repair hydraulic leak on control valve - 3030 hrs.	31/05/2015 1		Hours	.00	8.00	\$1131.00
	40044	Pre-hire Inspection. - 3137 hrs	31/07/2015 1		Hours	.00	2.00	\$691.00
	40700	Off hire Inspection - Dry Hire Client L & D Earthmoving. - 3413 hrs	4/11/2015 12:		Hours	.00	3.00	\$470.60
	40780	Pre hire inspection - 3414 hrs	17/11/2015 1	3414.00	Hours	.00	4.00	\$418.50
	40904	500 hr Service - 3505 hrs	9/12/2015 12:	3505.00	Hours	.00	10.00	\$1232.88
	40892	Recitfy fuel system - 3484 hrs	31/12/2015 1		Hours	.00	.00	\$382.00
	41187	Mechanical inspection, replace rear view mirror. - 3651 hrs	12/02/2016 1		Hours	.00	12.50	\$757.00
	41472	4000 hr Service - 3970 hrs	14/04/2016 1	3970.00	Hours	.00	17.50	\$6081.00
	41443	April Pre-starts	30/04/2016 1		Hours	.00	8.75	\$505.00
	41578	May Pre-starts. - 4056 hrs	31/05/2016 1		Hours	.00	6.00	\$336.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	41760	June Pre-starts - 4252 hrs	30/06/2016 1		Hours	.00	3.00	\$156.00
	41910	July Pre-starts [made up mud flap and fitted to Pos. 1 mudguard, trouble shot short in mirror circuit, fitted UHF antenna - 4363 hrs]	31/07/2016 1		Hours	.00	2.50	\$618.95
	42024	500 hr Service - 4476 hrs	5/08/2016 12:	4476.00	Hours	.00	8.50	\$1341.71
	42041	August Pre-starts, Rectify leak in air system. trace to & replace air fitting on exhaust brake, replace fuel cap, cover plate. - 4476 hrs	31/08/2016 1		Hours	.00	17.50	\$1653.40
	42179	September Pre-starts.	30/09/2016 1		Hours	.00	.00	\$162.00
	42315	October Pre-starts.	31/10/2016 1		Hours	.00	1.00	\$63.00
	42476	1000 hr Service - 5005 hrs	16/11/2016 1	5005.00	Hours	.00	12.50	\$2049.12
	42898	500 hr Service - 5499 hrs	1/03/2017 12:	5499.00	Hours	.00	10.00	\$1067.93
	43371	NIL	12/06/2017 7:		Hours	.00	.00	\$0.00
	43372	6000 hr Service Hrs 5957 change coolant, Changed to AT102 transmission oil at 5957 hrs	20/06/2017 1	5957.00	Hours	.00	12.00	\$5254.44
	43632	August General repairs, replace seized battery isolator switch - 6178 hrs	1/09/2017 12:		Hours	.00	3.00	\$376.85
	43874	500 hr Service - 6466 hrs	6/10/2017 12:	11157.00	Hours	.00	7.00	\$1096.35
	44316	1000 hr Service 6960 Hrs	8/02/2018 12:	6960.00	Hours	.00	8.00	\$1944.15
	44399	February Pre Starts, 6998 Hrs, Fit new UHF on site, grease machine, top up oils, get tailgate to take grease,	27/02/2018 1		Hours	.00	2.50	\$137.85
	44777	May Pre starts, 7290 Hrs, Replace flashing light, swap seat from #1002 into #1026, Check steering fault +repaired seat out of #1026 and fitted to #1002 7313 Hrs,	18/05/2018 1		Hours	.00	15.50	\$1032.77
	44921	500 hr Service 7462 Hrs,	22/06/2018 1	7462.00	Hours	.00	7.50	\$982.42
	45154	July prestarts, Replace engine oil pressure sensor(se2203), replace coolant header tank - 7509 hrs	16/07/2018 1		Hours	.00	4.50	\$907.82
	45249	Reseal steering dampner, fitted new coolant header tank, resealed intake manifold - 7667 Hrs,	7/08/2018 12:		Hours	.00	5.00	\$1375.60
	45314	Transmission Calibration - 7699 hrs , change Pos.4 tyre Old 0811NJ1481/tn84421 and fitted new 1CK0204GA/TN84230 - 7776 hrs	24/09/2018 1		Hours	.00	12.50	\$775.05
	45559	Fitted resealed steering damper 7911 Hrs	2/10/2018 12:		Hours	.00	2.00	\$39.60

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	45579	4000 hr Service 7934 Hrs	25/10/2018 1	7934.00	Hours	.00	11.25	\$5501.32
	45719	Trouble shot truck serging + trouble shot se4307-2 and se4209 -2 error codes 7971 Hrs, trace to failure in PWM2501 Solenoid, holding exhaust brake on, fit new solenoid, repair earth wiring,	9/11/2018 12:		Hours	.00	3.00	\$3307.06
	46133	Replaced seat cushion sensor , 8377 Hrs	15/02/2019 1		Hours	.00	2.00	\$110.25
	46183	500 hr Service 8501 Hrs	6/03/2019 12:	8501.00	Hours	.00	4.50	\$697.10
	46217	Replace centre diff front A-Frame bushes - 8512 Hrs. Fabricate puller jigs & bars to remove lower bush & collar	26/03/2019 1		Hours	.00	27.00	\$2772.91
	45938	Replace all rear suspension blocks + replaced Uniden uhf mic @ 8330 hrs	1/04/2019 12:		Hours	.00	21.75	\$4125.32
	46233	Off / Pre Hire Inspection - 8513 Hrs, install tracking unit, replace engine crankcase pressure sensor, steering wheel, r/h mirror, sump drain hose & o-ring, all belts, coolant bleed nipple, flashing light bulb, reseal injector wiring harness plug, fit dowdy seals oil filter pipes, repair broken bolt in rear transmission guard mounting frame, remove frame, drill out broke bolt, tap out threads, refit, broken fuel line brackets, coolant leak at pipe seals, Drop belly plates, degrease, blow out filters, refit guards, top up fluids, replace bulbs in headlights & flashing light, jump start machine	10/04/2019 1		Hours	.00	61.50	\$5255.47
	46497	Fitted 2 x N150 battery's @ 8514 hrs	16/05/2019 1		Hours	.00	1.50	\$1331.85
	46839	Onsite Inspection @ kipparing, replace 9kg fire ext @ 8669 hrs , Blew out radiator and AC filters , straightened belt guard brackets and topped up hydr leak , replaced wiper blade @ 8669 hrs	23/08/2019 1		Hours	.00	.00	\$518.62
	47064	1000 hr Service - 9029 hrs	7/11/2019 12:	9029.00	Hours	.00	8.50	\$1585.62
	47161	Replace blown hydraulic hose X 2 - 9029 Hrs,	7/11/2019 12:		Hours	.00	2.00	\$1149.71
	47557	Reseal steering dampener - 9238 hrs, installation was done at an earlier time	28/02/2020 1		Hours	.00	5.50	\$459.32
	47660	C/O Pos 6 Tyre on Site 9301 Hrs. Remove Pos 6 Tyre 0412NJ0485 & Rim TN8 4423 / Replace with Tyre AC4CDC531 & Rim 9101-P5.	6/04/2020 12:		Hours	.00	12.00	\$766.85
	47637	Replace battery isolator, Replace windscreen washer hose, Replace horn, Replace outside door handle and lock barrel @	10/04/2020 1		Hours	.00	15.00	\$1431.40

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		9285 hrs					
47809		Replaced RHS tailgate bearing 9444 Hrs, grease hose and got both tailgate bearings to take grease .	7/05/2020 12:		Hours	.00 2.50	\$254.10
47811		500 hr Service - 9471 Hrs	13/05/2020 1	9471.00	Hours	.00 9.50	\$1041.62
47875		Replace door glass [Client Shadforth back charge] Invoice 1115 sent 20-05-2020	19/05/2020 1		Hours	.00 2.00	\$400.00
47854		Replace air cleaner box - 9502 hrs, Fitted new uniden UHF radio s/n 98001842, Replaced A/C control panel, repaired 8 mm nylon airline to exhaust brake valve, Parts run to CSM for air box repairs and Bursons	21/05/2020 1	9502.00	Hours	.00 3.50	\$2143.38
47869		Repair A/C operation @ 9502 hrs, Replaced both a/c hoses from the a/c compressor + receiver dryer + regas the system	21/05/2020 1		Hours	.00 4.50	\$2836.86
48251		C/O Pos 5 Tyre On Site 9783 Hrs, Remove Tyre 0911NJ2492 & Rim TN8 4422 / Replace with Tyre F1A181830 & Rim TN8 4328	3/09/2020 12:		Hours	.00 3.50	\$634.01
48252		Replace Seat Shock, replace LHS step rope x 1 @ 9778 Hrs	3/09/2020 12:		Hours	.00 4.50	\$528.38
48366		Trouble shot horn and wipers not working, replace fuse 35 @ 9882 hrs	9/10/2020 12:		Hours	.00 1.50	\$118.00
48357		Replace all tyres - 9860 Hrs, Remove Pos 1 Tyre 0911NJ1807<>F9M583116/ POS 2 0811NJ1595<>F9M585470/POS 3 0412NJ0528<>F8N384204/POS 4 1CK0204G4A<>F9M585467/POS 5 F1A181830<>F8N384213/POS 6 ACACDC531<>F9M585067. Changed on site Kippa Ring Bridgestone.	21/10/2020 1		Hours	.00 6.00	\$29881.20
48376		2000 hr Service - 9943 Hrs	6/11/2020 12:	9971.00	Hours	.00 13.00	\$4561.31
48522		Replace Park brake switch - 10018 hrs, replaced wiper blade, re mounted E-stop onto LH fender, (replaced grease line on RH lift cyl top bearing, topped up 3 lts coolant @ 10060 hrs)	19/11/2020 1		Hours	.00 4.50	\$641.74
49095		Replaced RH tailgate bearing and bearing plate @ 10408 hrs	7/05/2021 12:		Hours	.00 8.50	\$1588.00
49157		Replaced both tailgate ropes (1120mm) @ 10500 hrs	2/06/2021 12:		Hours	.00 3.00	\$645.49
49028		500 hr Service 10518 Hrs	4/06/2021 12:	10518.00	Hours	.00 6.00	\$853.10
49158		Replace muffler @ 10518 hrs, replace battery box latch	4/06/2021 12:		Hours	.00 8.00	\$2173.50
49392		Replace dowdy seal on SE9102 sensor on control valve - 10650 hr	23/07/2021 1		Hours	.00 2.50	\$368.35

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	49860	Repair A/C Operation - 10,920 hrs - no fault found	12/01/2022 8:		Hours	.00	5.50	\$905.75
	49724	1000 hr Service - 10962 hrs	18/02/2022 1	10971.00	Hours	.00	9.00	\$1591.77
	50083	Replace brake accumulators - 10962 hrs, replaced brake cooling hose over hitch.	18/02/2022 1		Hours	.00	15.50	\$9500.76
	50236	Trouble shoot load dump brake fault, replace SE5203 sensor - 10987 hrs, repair airline to operators seat, unseized park brake pivot pin, adjusted park brake, un blocked both tailgate grease ports and replaced both tailgate grease hoses - 10997 hrs	30/03/2022 1		Hours	.00	6.00	\$1380.76
	50343	Check reported steering fault -11001 hrs, trace to seized universal on steering rack, fitted 2nd hand uni, replaced rack boots, test OK, unseize door hinges, 11000 Hrs . replace door strut, hose clamps on lift cyls, R/H LED parker, . Check fuel warning, drain bowl and treat 11036hrs .	28/04/2022 1		Hours	.00	10.50	\$2842.53
	50472	Replace batteries, engine crankcase pressure sensor - 11091 Hrs expansion tank, all belts, coolant pipe & seals, windscreen washer pump, adapter harness, fit second hand seat base from 1062 & new slides, remove broken fuel line bracket L/H/S, repair & refit, hose clamp on hydro breather, unblock R/H tailgate, top up brake cooling and hydraulic	31/05/2022 1		Hours	.00	19.00	\$3166.01
	50600	Repair brake cooling leak - 11135 Hrs ,replace rear suction elbow - o-rings - hose clamps - bolts - drain & refill cooling tank, top up & bleed, re-fit fuel leak back line & replace hose clamp	16/06/2022 1		Hours	.00	11.50	\$708.28
	50677	Replace L/H transmission oil filter housing, oil & filters - 11203 hrs, Replaced LH tailgate bearing and bearing plate.	29/06/2022 1		Hours	.00	15.00	\$3170.85
	50827	Off / Pre Hire -11249 Hrs check fault accelerate pedal, tidy up wiring rear body pivot, fit air cleaner clamps, replace pos 3 & 5 bellow, reset body sensor, replace steering control linkage & rack boots,	19/09/2022 1		Hours	.00	34.00	\$1866.18
	50857	Remove body pins, lift body and block. Remove bushings, Line bore dump body mounts, remove blocks and fit body, clean up burrs left post welding, replace pins and bushes - 11250 hrs replace front hydraulic pipe, , replace exhaust clamp + isolator mounts. Remove exhaust shields and L/H step for rust repairs, replace control rod, reset body sensor, repair and paint rust patch on front bumper, reseal injection harness,	19/10/2022 9:		Hours	.00	148.00	\$16126.27

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		repair rust on L/H guard, remove rock guard & sand blast & paint, cut up and repair step treads, replace bonnet grills						
	51164	Replace mirrors - 11253 hrs, front, reseal PTO box mounting flange, drop box drain bung & oil, cabin filters & hose out AC evaporator, straighten R/H bottom step, R/H guide plate, nutserts in stone guard, re stamp all rims, unseize artic lock, Replace both top lift cyl bearings and pins (parts booked to W/O 50857) fit new grip tape on nose of machine, replace SE2203 sensor, replace tailgate guides, replace rear hydraulic return pipe, degrease engine bay and transmission area, remove all pumps and PTO drive. Replace mount orings, fitted belly plates, topped up hydraulic oil, replace tailgate buffers	14/11/2022 1		Hours	.00	45.00	\$3583.73
	51402	Replace drop box filler cap + 6x6 diff lock switch - 11277 hrs	12/12/2022 1		Hours	.00	3.50	\$284.42
	51533	C/O tyre/rim pos #5 - 11363 hrs, removed tyre/rim F8N384213/TN84328 and fitted tyre/rim F8M181264/TN84436	17/01/2023 7:		Hours	.00	8.50	\$674.95
	51522	remove bent tailgate from truck - 11363 hrs flat packed and brought back to yard	17/01/2023 7:		Hours	.00	9.00	\$1978.74
	51572	Replace UHF with S/N 18001354 - 11384 hrs,	23/01/2023 1		Hours	.00	3.00	\$497.64
	51562	Replace damaged grease hoses x 2 - 11376 hrs	23/01/2023 1		Hours	.00	2.00	\$354.00
	51435	Repair rock guard	13/02/2023 1:		Hours	.00	1.00	\$1652.50
	51692	Replace park brake pads and un-seize park brake caliper slides - 11405 hrs, replace stepped idler belt pulley 11471 hrs	13/03/2023 9:		Hours	.00	12.00	\$1766.82
	51827	Replace turbo flex pipe - 11485 hrs	20/03/2023 2:		Hours	.00	7.00	\$1328.69
	51711	500 hr Service - 11485 hrs	20/03/2023 3:	11485.00	Hours	.00	9.00	\$1302.02
	51803	Check bonnet issue - hrs	29/03/2023 8:		Hours	.00	1.00	\$82.46
	51982	Late Invoice relating to W/O 50827 - Supply return pipe	13/04/2023 1		Hours	.00	.00	\$987.21
	52060	Replace Brake cooling hose to pos #6 hub - 11771 hrs [Pirtek Sunshine Coast] top up 30 lts Agri oil	15/05/2023 7:		Hours	.00	2.00	\$1227.96
	52159	Inspect + pics for possible sale - 11825 hrs	13/06/2023 1		Hours	.00	2.00	\$104.00
	52223	6000 Hr Service - 12011 hrs	6/07/2023 9:3	12011.00	Hours	.00	12.00	\$4904.72
	52300	Reseal rear diff pinion seal - 12011 hrs, replaced wiper blade, reseal plate on side of engine block LHS. replace R/H outer indicator bulb	4/09/2023 9:4		Hours	.00	9.50	\$1057.95

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	52380	Off / Pre Hire - 12054hrs - Carried out off-hire inspection. Replaced fire extinguisher.. Re-stamped rims. Reinforced top step. Straightened tailgate and tailgate arms. Replaced RH tailgate bearing plate. Replaced tailgate grease lines. Refitted tailgate.	3/10/2023 12:		Hours	.00	64.00	\$5381.44
	52800	Sand blast and paint - 12055 hrs - Dismantle machine for blasting. Repair access steps RWS, Reassembled machine and checked operation. Fit safety stickers. + Travel & Accommodation.	17/01/2024 1:		Hours	.00	51.50	\$24091.11
	53346	Check/repair PTO oil leak - 12061hrs - Replaced suction pipe for hydraulic pump, tested okay.	3/06/2024 12:		Hours	.00	5.60	\$629.83
	54027	Check for leak on front axle - 12064hrs, Replace oring on brake cooling hose fitting on front axle	6/02/2025 8:3		Hours	.00	.00	\$222.08
	54119	Inspect Machine & Rust Repairs + 1025 repairs - 12064hrs - Disassembled and removed rusted parts and panels. Sandblasted and painted bonnet frame. Prepped and painted inner front guards, belly guards, crossmembers, driveshaft, engine front post. Reassembled machine. Replaced alternator belt tensioner. Replaced LH circle park light and both indicator bulbs. Replaced headlight clips. Replaced LH spotter mirror. Repair RH headlight wiring to plug(corroded). Replaced valve stem and O-ring. Replaced 4 x wheel nuts.	11/03/2025 3:		Hours	.00	.00	\$9595.78
	54275	Late Invoice - W/O 54119	29/04/2025 1		Hours	.00	.00	\$359.25
	54326	Adjustment Note For work order 54119	23/06/2025 1		Hours	.00	.00	-\$790.36
	54663	Replaced both N150 batteries - 12,065 Hrs. - Replaced water pump idler pulley.	5/09/2025 12:		Hours	.00	.00	\$995.72
	55087	Prepare vehicle for third party inspection (Pre sale) - 12054 Hrs.- Investigate issue with park brake: internal workings of electrical actuator jamming. Stripped, cleaned and reassembled. System checked OK.	13/02/2026 1			.00	.00	\$648.00
	54976	Rectify hydraulic oil leak - 12,068 hrs	14/04/2026 1		Hours	.00	.00	\$630.75
		: 130		Asset Total:	1026	0.0	1183.4	\$247,025.70
		: 130		Parent Total:	TPH	0.0	1183.4	\$247,025.70

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Grand Total		130	0.0	1183.4	\$247,025.70