

## Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A25F ADT						
	48611	500 hr Service, 9557 Hrs. Please change Transmission oil & Drop Box Oil,	11/12/2020 1	9558.00	Hours	.00	3.00	\$1342.03
	48485	Off / Pre Hire Tenkate upgrades - 9557 Hrs, Replace all suspension blocks, ignition & door locks to standard key, A/C control panel, Drop belly plates & clean, Collect all oil samples, grease all, stamp all rims, reposition fire extinguisher, Drain front struts oil - make up fittings for re-oiling struts & fill, degrease all,	18/12/2020 1		Hours	.00	38.50	\$7226.82
	49061	Trouble shoot overheating fault 9798 Hrs , Check radiator fan not spinning - PWM 2602 - 2601 swap around, check error codes history, found brake circuit pressure issue oil supply fan 3, Found servo pressure for load dump brake to be at fault, Replace pilot filter in brake circuit.	3/05/2021 12:		Hours	.00	16.50	\$1896.63
	49182	4000 hr Service - 9963 Hrs	12/06/2021 1	9961.00	Hours	.00	11.00	\$4632.17
	49297	Replaced UHF arial and base @ 10020 hrs	2/07/2021 12:		Hours	.00	1.50	\$233.17
	49328	Replace Brake system pilot filter housing @ hrs, repair air leak on air hose over hitch @ 10090 hrs	29/07/2021 1		Hours	.00	8.00	\$1101.58
	49455	Replace seat cushion sensor @ 10130 hrs , check reported park brake fault, trace to failed seat sensor	13/08/2021 1		Hours	.00	3.00	\$388.17
	49514	Replace seat sensor 10176 Hrs, Trouble shot Alt putting out 28.6 Volts 10183 Hrs, Replace with Reco Alt, Replace both belly plate bolts, replace coolant header tank	1/09/2021 12:		Hours	.00	11.50	\$2356.96
	49704	Off / Pre Hire -10361 Hrs, replace aux water pump, belt tensioner, fire extinguisher, w/p belt, x-rings, straighten & weld damaged lower steps x2, Blow out filters, grease all, check tyres, hose out a/c, re seal all windscreens, re route eng breather, coolant overflow & unblock	13/10/2021 1		Hours	.00	27.50	\$3750.49
	49792	Off Dry Hire Inspection - 10,402 hrs, clean cab , take photos, check oil levels. tvre pressures. list defects	1/12/2021 12:		Hours	.00	3.75	\$359.50

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	49826	Check Pos.1 wheel hub for possible oil leaks - 10435 hrs. inspection , clean cab & windows, grease, wash	1/12/2021 12:		Hours	.00	4.00	\$407.33
	49908	Off / Pre Hire - 10435 Hrs	6/12/2021 12:		Hours	.00	3.00	\$233.10
	49813	500 hr Service - 10435 hrs	8/12/2021 12:	10435.00	Hours	.00	5.00	\$1122.87
	50264	Replace Position 5 wheel seal -10785 hrs, Remove Pos 6 tyre and rim clean out brake caliper and clean out dirt from hub Refit wheel, fit new LED beacon.	24/03/2022 1	10785.00	Hours	.00	19.00	\$1718.39
	50271	Off / Pre Hire Inspection - 10785 Hrs Please note all grease points were very dry. Test Machine & check functions.	24/03/2022 1	10785.00	Hours	.00	8.00	\$449.85
	50456	1000 hr Service 11033 Hrs	16/06/2022 1	10935.00	Hours	.00	13.00	\$1789.04
	50769	Diagnose failed trans front oil seal - 11174 Hrs, Remove transmission, set transmission upright, remove torque convertor and replace seal and oring, refit torque convertor, replace rear crankshaft seal, fit transmission and torque convertor bolts and bellhousing bolts to spec, complete transmission test and calibration - CJD	6/09/2022 10:		Hours	.00	99.50	\$8692.96
	50938	Off / Pre Hire -11174 Hrs,(Tim M), Check wheel seals, greased machine, checked tyre pressures and wear, blew filters out	6/09/2022 10:		Hours	.00	6.50	\$619.75
	50940	Replace wheel seals- POS 1 and 6.Replace cab mounts - 11171 Hrs Replace bearing and seal - POS 2 final drive	19/09/2022 3:		Hours	.00	37.50	\$5344.79
	50984	Replace both front struts install upgraded units - 11171 hrs	19/09/2022 3:		Hours	.00	16.00	\$10672.15
	51056	Check trans shift fault onsite - found convertor seal had failed again and lost 10-15 ltrs of oil 11202hrs	5/10/2022 7:1		Hours	.00	8.00	\$416.00
	51179	Fit guards to suit upgraded front struts - 11202 hrs, Replace pos 1 brake pads, Replace stolen seat strut. Refitted wiring for dump brake & refitted dash. Fitted new shock to seat and bolted floor back in. Refitted exhaust and guard. Replaced battery isolator. Checked all fluid levels. Greased machine.	24/07/2023 9:		Hours	.00	43.50	\$6815.58
	52513	Off / Pre Hire - 11203 Hrs - Replaced windscreen wiper arm. Replaced seatbelt.	4/09/2023 9:5		Hours	.00	2.00	\$1985.31
	52417	Remove transmission to rectify torque convertor leak - 11203 hrs - Removed transmission. Replaced torque convertor input seal and plate. Refitted transmission and all components. Tested, failed, suspect cracked torque convertor.	9/10/2024 8:5		Hours	.00	.00	\$11898.76
	54054	Remove Transmission & Inspect for oil leak - 11208hrs - Disassembled cab and removed steering column Drained	7/04/2025 8:3		Hours	.00	.00	\$16413.84

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Disassembled cab and removed steering column. Drained fluids and disassembled all connecting components and wiring. Inspected for leaks, replaced rubbing hoses while transmission is out, found torque converter leaking from centre weld. Sent Transmission away to DAMET for torque converter to be repaired. found torque converter retaining clamp loose and the converter had slipped forward. Removed torque converter from transmission, Removed front transmission sealing plate and replaced seal and o-ring. Reassembled and refit all components. Carry out recalibration and testing. Started fitting upgraded to front mud guards backing plates.						
	54218	Off/Pre-Hire - 11208 hrs Fit front mudguard upgraded backing plates. Replace failed a/c compressor, replace failed horn, refitted mirror pivot springs, replaced park brake switch, fit retaining strap to wheel chock holder, (70% of backing plate parts are on w/o 54054) Rust proofed LHS inner wheel arches. Replaced beacon bracket handle.	1/05/2025 11:		Hours	.00	.00	\$4195.35
	54463	Rectify hydraulic oil leak on rear chassis - 11,249 KmReplaced hydraulic hose from rear chassis accumulator bank to relay valve, bleed brakes on both rear axles, top up hydraulic oil, engine oil & coolant.	7/07/2025 12:		Hours	.00	.00	\$969.41
	54552	Off/Pre-Hire Inspection - 11,354 Hrs. Resealed RH lift cylinder, Replace both lift cylinder top bearings, LHF HYD pump o-ring, primary and secondary cabin air filters and primary and secondary ENG filters.Resealed leaking timing cover and oil/fuel scavenger pump.	20/10/2025 1		Hours	.00	.00	\$6473.28
	54925	Rectify seat height issue - 11,408 Hrs. - Identified and replaced leaking seat valve.	8/12/2025 12:		Hours	.00	.00	\$279.10
	54584	Troubleshoot brake pressure issue with park brake coming on intermittently - 11,354 Hrs. (AWE)- Replaced hydraulic cartridge valve in L&D brake block with upgraded cartridge.- Fitted 2nd hand brake treadle valve out of unit 1047 as it was leaking.	5/01/2026 12:		Hours	.00	.00	\$4887.60
	54989	500 Hr Service - 11,496 Hrs.	6/02/2026 11:		Hours	.00	.00	\$1563.96
	55176	Rectify Bonnet pump fault - 11,617 Hrs. - Replaced Mega fuses and cleaned area: rectified- Replaced 2x grease nipples	26/03/2026 1		Hours	.00	.00	\$305.62
		:		<b>Asset Total:</b>	<b>1077</b>	<b>0.0</b>	<b>389.3</b>	<b>\$110,541.54</b>

