

Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A35E Artic Water Truck BMA Spec.						
	27287	Prepare unit to work status and fit all upgrades, fit exhaust stack , fire exts , wheel chocks and bracket , pad locks , air filter , h/light globes , 220hrs	23/09/2010 1		Hours	.00	21.50	\$3706.80
	27314	1000 Hr Service 220hrs A35D	24/09/2010 1	220.00	Hours	.00	10.00	\$2523.61
	27446	Repair A/C fault - regas system and test operation, paint bonnet	12/10/2010 1		Hours	.00	1.00	\$773.00
	27485	October pre start checks & drain fuel tank and filter fuel and add fuel doctor at 267 hrsOperate this truck from 11/10/10 to the 14/10/10 as requested by Gibbo	30/10/2010 1		Hours	.00	14.50	\$2439.80
	27882	500 HR Service 482 hrs & fit A/C switch	18/12/2010 1	482.00	Hours	.00	5.50	\$1231.09
	28607	1000 HR Service 944 hrs	2/04/2011 12:	944.00	Hours	.00	12.50	\$3299.50
	29006	June Pre-Start Checks & repair windscreen joints at 1365 hrs Clean to Weed and Seed Stanard and inspectionInspection nsd repaired mirrors and beacon at 1288 hrs Shim body	30/06/2011 1		Hours	.00	.00	\$1604.00
	29483	500 HR Service 1500 hrs	29/07/2011 1	1500.00	Hours	.00	3.00	\$1228.60
	29514	August Pre-Start Checks at 1500 hrs	5/08/2011 12:		Hours	.00	8.50	\$1421.50
	30076	September Pre-starts- 1731hrs, remove diff lock switch	30/09/2011 1		Hours	.00	2.00	\$670.00
	30422	2000 hr Service- 1955hrs	5/11/2011 12:	1955.00	Hours	.00	7.50	\$4877.60
	30491	November pre-starts	30/11/2011 1		Hours	.00	.50	\$92.00
	31052	January pre-starts, replace bonnet gas strut	27/01/2012 1		Hours	.00	2.50	\$591.00
	30810	Replace Muffler- 2114hrs	21/02/2012 2:		Hours	.00	3.50	\$1774.00
	31352	March pre-starts- 2207hrs, replace front gas strut on grille	22/02/2012 1		Hours	.00	1.50	\$98.00
	32337	Mechanical Inspection- 2260hrs, replace fire extinguishers, remove wiring plug out of engine block	31/07/2012 1		Hours	.00	.00	\$2189.00
	32345	Weed and Seed	31/07/2012 1		Hours	.00	.00	\$1166.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost	
	32769	2000 hr Service at 2559hrs	14/09/2012	1	2559.00	Hours	.00	8.00	\$5804.81
	33091	Replace turbo & gaskets, studs	30/11/2012	1		Hours	.00	.00	\$3533.00
	33530	1000 HR Service. - 2988 hrs	19/12/2012	1	2988.00	Hours	.00	.00	\$1587.15
	33149	Replace Pos.2 tyre	31/01/2013	4:		Hours	.00	.00	\$1091.00
	33799	Repair drop box oil leaks, replace bushes in rear stabliser bars & lower drop box mounting, replace steering linkage ball joints, tappet cover seal, sump gasket	20/02/2013	1		Hours	.00	.00	\$6570.00
	33755	Off Dry Hire Inspection & computer download, replace fault accelerator pedal. 3010 hrs	27/03/2013	2:		Hours	.00	.00	\$1465.00
	36508	mechanical inspection - 3015 hrs	31/12/2013	1		Hours	.00	1.00	\$1528.47
	37214	Pre Hire Inspection, paint lower front panels & bonnet, remove & refit bonnet assembly. stamp rims 3019 hrs. change engine oil.	30/04/2014	1		Hours	.00	28.50	\$2245.15
	37962	Pre-hire inspection. 3020 hrs	31/07/2014	1		Hours	.00	23.00	\$1410.80
	37965	Replace all tyres - 3020 hrs	31/08/2014	1		Hours	.00	.00	\$26932.00
	38069	August pre start	31/08/2014	1		Hours	.00	10.00	\$520.00
	38292	September prestarts. top up brake oil and hydraulic oil. adjust belts. topped up coolant. 3355 hrs	30/09/2014	1		Hours	.00	5.00	\$468.25
	38490	October prestart. Replaced beacon.3456hrs.	31/10/2014	1		Hours	.00	6.50	\$944.50
	38571	500 HR Service - 3486 hrs	30/11/2014	1		Hours	.00	22.50	\$1983.85
	38677	November Pre-Start, rotate tyres to 1032.	30/11/2014	1		Hours	.00	10.00	\$1254.00
	39076	Mechanical inspection, rotate tyres - 3490 hrs	28/02/2015	1		Hours	.00	11.00	\$928.80
	39241	Pre-hire inspection - 3490 hrs	28/02/2015	1		Hours	.00	4.00	\$785.77
	39322	Pre hire inspection. - 3503 hrs	31/03/2015	1		Hours	.00	6.00	\$451.40
	39350	Replace leaking seat air valve. - 3541 hrs	31/03/2015	1		Hours	.00	1.00	\$520.00
	39648	Sample transmission for monitoring. - 3812 hrs	31/05/2015	1		Hours	.00	4.00	\$201.00
	39661	Replace missing wheel nuts and damaged wheel studs on Pos. 6. - 3698 hrs	31/05/2015	1		Hours	.00	6.50	\$580.04
	40040	4000 hr Service - 3964 hrs	31/07/2015	1		Hours	.00	11.50	\$5810.92
	40179	August Pre-starts - 4070 hrs	31/08/2015	1		Hours	.00	3.00	\$256.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	40315	September Pre-starts. - 4205 hrs. Replace hydraulic return pipe.	30/09/2015	1	Hours	.00	19.50	\$2667.00
	40660	Pre hire inspection. - 4392 hrs	29/10/2015	1	Hours	.00	6.00	\$741.68
	40515	October Pre-starts - 4387 hrs	31/10/2015	1	Hours	.00	1.00	\$256.00
	40792	500 hr Service - 4470 hrs	27/11/2015	1	4470.00 Hours	.00	8.00	\$1428.85
	40933	Off hire inspection. - 4503 hrs	15/12/2015	1	Hours	.00	6.00	\$582.38
	40657	Modify A35 tailgate to fit. Replace 1 wheel stud pos 6.	31/12/2015	1	Hours	.00	42.00	\$2369.90
	41203	Pre- Hire Inspection - 4504 hrs	16/02/2016	1	Hours	.00	8.00	\$294.00
	41375	Fit fire extinguisher, replace Pos. 6 wheel studs. - 4517 hrs	18/03/2016	1	Hours	.00	11.00	\$1194.18
	41664	Mechanical Inspection, install UHF bracket. - 4556 hrs, Fit dicky seat - 4558 hrs	20/05/2016	1	Hours	.00	1.50	\$905.35
	42037	Unjammed twisted seat belt, inspected faulty load counter, fit new UHF. - 4635 hrs	30/09/2016	1	Hours	.00	7.50	\$839.84
	42321	Upgrade to BMA Standard, modify handrails, Fit fire suppression, fitted new e-stop on RHS and fitted insulated terminal to starter isolator circuit, freed up canon joints. - 4705 hrsPaint handrails, modify & install mirrors, fit handrails	14/10/2016	1	Hours	.00	35.50	\$8280.11
	42324	Fit water tank and controls, Free seized up pump, clean up pump housing & impellor and re-fitted, free up seized cannon, heatup pivot points, greased, fitted new auto greasers, stripped RHS and MID sprays down to unseize . - 4708 hrs	20/10/2016	1	4708.00 Hours	.00	92.50	\$8079.76
	42327	Mechanical inspection, fit new sump gasket, 2 x o-rings to front pumps, fitted o-rings to gerota pump. - 4705 hrs	20/10/2016	1	Hours	.00	15.50	\$1639.08
	42554	Fit handrails back onto # 986 were removed & fitted to this unit on work order 42321	29/11/2016	1	Hours	.00	13.50	\$806.50
	42563	Late invoice for 42327 - Mechanical inspection, fit new sump gasket, 2 x o-rings to front pumps, fitted o-rings to gerota pump. - 4705 hrs	30/11/2016	1	Hours	.00	.00	\$80.00
	42510	Off-hire Inspection, replace beacon, replace middle diff cross stay bearings, replace rocker cover gasket.	12/12/2016	1	Hours	.00	18.00	\$2677.40
	42641	Late invoice for 42321 - Upgrade to BMA Standard, modify handrails, Fit fire suppression, new e-stop on RHS, insulated terminal to starter isolator circuit, freed up canon joints. - 4705 hrsPaint handrails, modify & install mirrors, fit handrails	15/12/2016	1	Hours	.00	.00	\$612.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	42782	Off Hire Inspection. - 4734 hrs	1/03/2017 12:		Hours	.00	5.50	\$480.45
	43056	Off Hire Inspection, 4782 Hrs, Replace Rubber Bearing in centre axel torque rod.	5/04/2017 12:	4782.00	Hours	.00	20.50	\$1502.31
	43314	Fit s/h muffler.	1/07/2017 12:		Hours	.00	.00	\$1591.65
	43522	Off Hire Pre Hire Inspection - 4842 hrs, replace all rubber suspension blocks, repair oil leaks on filter housing, replace seals & gaskets	14/07/2017 1	4842.00	Hours	.00	14.50	\$2893.17
	43318	Repair water cannon. Elevation seized. Butterfly valve not shutting off. Dismantle pump to replace impeller, mechanical seal. - 4956 hrs	19/07/2017 1		Hours	.00	53.00	\$3475.79
	43542	Replace bulk water tank pump, - 4968 hrs, fit southern cross pump & motor, modify mounting frame, suction & discharge piping, fit suction intake screen, Paint modified areas & pump, adjust pump speed, test operation	2/08/2017 12:		Hours	.00	63.00	\$7043.20
	43558	1000 hr Service at 4968 hrs. AT 102 Transmission oil installed	25/08/2017 1	4970.00	Hours	.00	6.00	\$2032.47
	43726	Repair hydraulic oil leak, replace O-rings for hoses on hydraulic diversion block on rear hitch, CJD to site fuel error on display, change filters bleed system,	21/09/2017 1		Hours	.00	.00	\$573.76
	43991	Off hire/Pre Hire inspection - 5258 Hrs, replace seals in both steering cylinders, diagnose park brake fault, replace park brake control solenoid valve, repair rear lights & wiring, test sprays	14/11/2017 1	5258.00	Hours	.00	85.50	\$5968.78
	44068	BMA Inspection & Certification, brake test, fire suppression test & service	16/11/2017 1		Hours	.00	1.00	\$577.50
	44225	500 hr Service 5512 Hrs,	29/01/2018 1	5512.00	Hours	.00	10.00	\$1272.73
	44312	January service run, restamp rims X 6, tighten pos 1 wheel arch, top up Hyd oil X 22Ltrs, tighten hose clamps return pipe Hyd oil,5512 Hrs,	31/01/2018 1		Hours	.00	1.00	\$153.91
	44667	6000 hr Service 5916 Hrs AT 102 Oil installed	29/04/2018 1	5916.00	Hours	.00	13.50	\$5611.46
	44704	May service run (Scott) 5916 Hrs, Replace L/H bulb headlight (H7), Remove step & covers to fix Hyd leak on return pipe to tank, top Hyd oil 35 Ltrs,	30/04/2018 1		Hours	.00	2.00	\$232.65
	44732	Rust repair to cab panels, AT	3/05/2018 12:		Hours	.00	.00	\$2900.00
	45165	BMA Compliance & Inspections 6073 hrs Fire Suppression System test & Certification and extinguisher test	18/07/2018 1		Hours	.00	.00	\$731.46

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	45146	Check hydraulic oil leak on tank front return pipe, tighten hose clamps - 6073 hrs, found pipe rusted through, replace pipe, front body pads, install blue flashing light, clean machine	21/07/2018 1		Hours	.00	7.00	\$5161.28
	45254	Rectify fault with hydraulic control solenoid for water pump speed, replace batteries	7/08/2018 12:		Hours	.00	6.00	\$2523.81
	45619	Off Hire - Pre Hire inspection - 6330 hrs, remove & replace rounded off belly guard bolts, grease pods on water cannon, fit turbo blanket, green beacon, call sign, test water tank operation, repair leaking L/H rear spray valve, clean to weed & seed standard Back charged a BMA Triangle I.D. Signage,	11/10/2018 1		Hours	.00	11.50	\$2457.63
	45735	BMA & Fire Suppression Certification - hrs, Brake Test - client back charge [Inv.1017 sent 07/12/18]	17/10/2018 1		Hours	.00	.00	\$1682.52
	45781	Off Hire - Pre Hire inspection - 6455 hrs - check error PWM9102-5, trace corroded terminal on solenoid, replace solenoid, repair wiring, fit new lower step rubbers, change flashing light over to blue type on cab & tank, clean to weed & seed standard	26/11/2018 1		Hours	.00	10.75	\$1175.01
	45716	500 hr Service - 6455 hrs	30/11/2018 1	6416.00	Hours	.00	3.00	\$804.74
	45974	Replace fuel sensor & filters if required - 6468 hrs, repair water & hydraulic oil leaks at cannon, replace mounting bolts, hydraulic hoses, test OK	17/01/2019 1		Hours	.00	11.25	\$2529.56
	46337	Replace broken E.G.R. Rocker arm & tappet cover - 6908 hrs, 3/06/2019 12:			Hours	.00	1.00	\$3037.32
	46412	Replace the hydraulic slew & fit cylinders for the water cannon	3/06/2019 12:		Hours	.00	1.00	\$893.00
	46683	Fire Suppression foam change over, upgrade to F3 foam	16/07/2019 1		Hours	.00	2.00	\$2546.80
	46692	Replace broken headlight [client back charge to AE Group - invoice 1058 sent 28/08/19]	30/08/2019 1		Hours	.00	.50	\$197.69
	46703	Replace engine bonnet pump - 6939 hrs, due to the control valve is bypassing inside the hand pump section, test operation, replace water cannon slew cylinder	2/09/2019 12:		Hours	.00	7.00	\$3019.50
	46696	Repair the damage to the inter cooler fan and grill, cowling - 6939 hrs [back charge to AE Group - Invoice 1061 sent 01/10/19] remove damaged parts, install new parts, repair bonnet damage, replace broken seat air control valve, headlight & bulbs	19/09/2019 1		Hours	.00	6.75	\$4035.31
	46917	Pre hire and BMA inspections - 6939 hrs, Fire Suppression bottle change over, repair fire suppression bottle retaining	19/09/2019 1		Hours	.00	5.50	\$2196.70

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		strap, repair water cannon, clean swivel joints, fit new seals, ball bearings, grease, fit cylinders, auto greaser canisters, install cannon, test operation					
	47069	Replace hydraulic & brake cooling hoses over hitch area & R/H steering cylinder rear hose - 6940 hrs, battery box lid latch, exhaust stack, repair spray heads on rear of tank, replace tank drain valve, re stamp wheels, change over reverse camera, fit pre ordered fuel filter housing, second hand blue beacon, clean repair areas, weed & seed Late Invoices for work order 46917	14/10/2019 1		Hours	.00 14.50	\$7730.13
	46579	1000 hr Service - 6940 hrs	15/10/2019 1	6940.00	Hours	.00 4.00	\$1658.27
	47359	Pre Hire Inspection -- no costs Craig	1/01/2020 12:		Hours	.00 .00	\$0.00
	47429	Client back charge, All Roads, replace broken large mirror left side [Invoice 1091 sent 29/01/2020]	20/01/2020 1		Hours	.00 .00	\$118.01
	47449	Replace rear diff tailshaft - 7338 Hrs, check for roll over damage, remove centre diff rear output flange, bearing, through shaft, found shaft to be bent, remove though shaft & cut flange retaining nut as it was seized, remove old seals & bearing, fit new ones, install middle torque rod from 979, all rear suspension blocks	2/03/2020 12:		Hours	.00 23.50	\$15214.54
	47569	Pre Hire Inspection - 7339 hrs, replace exhaust brake air cylinder, BMA & UHF Radios, bulbs, repair water entry to roof area, trace aerial cable entry & seal up, clean radiators, cab, windows, machine, fit new cam lock fittings	5/03/2020 12:		Hours	.00 6.50	\$803.50
	47579	Replace ladder section of front grill - 7339 hrs, change over wiring & steps, latches, grill & fit to new ladder, adjust as required, check rear spray fault on water tank, trace to seized, remove dismantle all spray heads, free up, refit & test - 7340 hrs	1/05/2020 12:		Hours	.00 5.25	\$2360.62
	47675	Replace seal in R/H steering cylinder, replace cracked hydraulic hoses from main pump & L/H lower steering, singal LS, hoses, check steering fault & trace to blocked orifice in LS signal block, strip down & clean, weld hole in hydraulic suction pipe Check fuel alarms & excess fuel usage, trace to failed check valve in fuel filter housing, replace housing	1/05/2020 12:		Hours	.00 11.50	\$2236.95
	47738	BMA Certification & tests - 7375 hrs, check cannon movement, grease swivel joints, adjust working pressures to cylinders,	5/05/2020 12:		Hours	.00 14.00	\$3011.69

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		adjust water spray heads, replace clamp on water supply pipe, check park brake fault, trace to seized clevis pin in brake caliper lever, free up, lube, adjust, test operation, install side mounted indicator lights to sides of bonnet, clean to weed & seed standard, clean cab & windows					
	47789	Replace Position 4 tyre and repair costs	30/05/2020 1		Hours	.00 1.50	\$1870.00
	47926	Replace exhaust engine pipe to muffler - 7445 Hrs, remove air cleaner box, R/H mud guard, remove exhaust & clamps ,mounts ,heat shield, L/H/F inner guard, hose out all engine bay, remove broken bolts exhaust clamp, reassemble + late invoice relating to 47738 work order - extinguisher test	1/07/2020 12:		Hours	.00 19.00	\$3525.89
	47726	500 hr Service 7445 Hrs Changed Trans AT102 CB	29/07/2020 1	7445.00	Hours	.00 4.00	\$1649.45
	48091	BMA Brake test - 7445 hrs, fit side indicators, clean to weed & seed standard	1/08/2020 12:		Hours	.00 8.00	\$1437.05
	48157	Replace Position 4 tyre - 7445 hrs. Remove Pos 4 Tyre F7R283183 & Replace with Tyre F7Y582934/ From W/O 47789. Remove Pos 3 Tyre F7R283185 & replace with Tyre F6K183957.	5/08/2020 12:		Hours	.00 .00	\$388.50
	48090	Pre Hire - 7445 Hrs, check SE4307-3 error codes, replace hydraulic tank slight glass, fit nylon washer spacers to L/H rear steering cylinder rod yoke, 3" inch ball valve to spray bar, fabricate & fit 4.5 fire extinguisher bracket, replace decals on controls for water tank,	31/08/2020 1		Hours	.00 12.00	\$1450.50
	48414	BMA updates, brake test & certify fire suppression system	5/01/2021 12:		Hours	.00 2.50	\$983.88
	48479	4000 hr Service 7993 Hrs. Engine Valve Set, Please change diffs to GO 102	5/01/2021 12:	.00	Hours	.00 19.00	\$7358.12
	48682	Repair Hydraulic oil leaks on Main Control valve - 7993 hrs, replace O-rings on all hoses & check valves, two body rubbers, degrease valve & repair area, clean unit	5/01/2021 12:		Hours	.00 16.50	\$3388.53
	48910	Pre Hire Inspection - 7997 Hrs, replace east air line, unseize water cannon pivots	1/04/2021 12:		Hours	.00 5.00	\$459.28
	48959	Replace muffler & Tailpipe & clamps - 8009 hrs, repair error code defect, trace o broken wire to PWM9102-5, repair, test OK	1/04/2021 12:		Hours	.00 5.75	\$2709.52
	48994	Check A/C Fault - 8029 hrs, Replace A/C thermostat	13/04/2021 1		Hours	.00 3.50	\$427.19
	48914	Replace blown hydraulic return hose from water tank & main	26/04/2021 1		Hours	.00 10.75	\$3980.80

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Hydraulic return pipe - 7998 hrs, strip out floor section, panels & replace hydraulic hoses, pressure lines to and from servo control unit x 5, brake activation pressure hose from pedal to relay valve x 1, top up oil level, bleed brakes, reinstall floor, seat, panels					
49578		Replace brake Accumulators - hrs, remove panels to allow replacement of brake accumulators, reassemble, test OK	9/09/2021 12:	Hours	.00	3.50	\$7111.33
49579		Repair Water Tank Piping to Cannon - 8052 hrs, measure & plan cannon mounting & plumbing for installation of Magnum cannon, modify electric wiring & control switches to suit, . fit gate valve to cannon, grease canisters, test operation of water tank & cannon	15/09/2021 1	Hours	.00	20.00	\$3703.36
49575		Pre Hire Inspection - 8052 hrs, replace batteries, Am/Fm radio, windscreen wiper blade, fit new O-ring to Pos.5 tyre, top up oil levels, fill tank & teat operation, remove cannon to repair rusted supply pipe, check hydraulic oil leaks, clean to weed & seed standard	29/09/2021 1	Hours	.00	9.25	\$2317.92
49824		Off / Pre Hire - 8105 Hrs, replace batteries, repair step tread plates, patch roof holes with Alloy tape, grease unit, check flat battery fault, trace to short in battery isolator due to dirt build up behind it, clean area,	18/11/2021 1	Hours	.00	21.50	\$2517.65
49871		Rectify rear spray faults - 8113 hrs, fitted new exhaust valves to all rear sprays, removed rocks from suction manifold and refitted suction screen in the correct way, fit new quick release valves to both outer spray heads - 8113 hrs	25/11/2021 1	Hours	.00	11.00	\$1144.60
49686		Replace water tank spray heads - (Sent from Craig) , check faulty sprays valve	14/01/2022 1	Hours	.00	.00	\$1929.97
50055		Replace all 3 rear sprays Re D Gibson. (with fully rebuilt spray heads) - 8182 hrs	21/02/2022 1	Hours	.00	9.50	\$2472.10
50135		Repair spray bar mounts -8208 hrs Centre & RH sprays leaking tightened nuts and added locknuts, Found fire bracket U/S, repaired passenger seat back rest, check engine oil as per operators request. 8213 Hrs cut off LHS stauff clamp and replaced with new clamp, manufactured up support & welded onto spray bar ,prepped & painted.	1/04/2022 12:	Hours	.00	12.50	\$1143.34
50256		Repair A/C operation - 8208 hrs, trace to fault thermostat. replaced, test OK	1/04/2022 12:	Hours	.00	5.50	\$1383.23

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	50373	Replace Flashing light on rear of tank, 8231 Hrs, adjust L & R sprays to fan outwards more.	13/04/2022 1		Hours	.00	3.00	\$442.00
	50487	Off / Pre Hire -8305 Hrs, drop belly plates, replace fire suppression bottle bracket, r/h low beam H7 bulb, both A/C filters,washer motor pump, blow out outer air filter, top up oils, replaced water tank sight glass, replace both toolbox handles. replace air box, test sprays,	20/05/2022 1		Hours	.00	21.50	\$2779.05
	50583	Off / Pre Hire -8333 Hrs, grease all, check operations, repair door latch,	10/06/2022 1		Hours	.00	8.50	\$481.97
	50647	Repair R/H spray fault - 8340hrs Remove rock from spray, troubleshoot water output fault & fit new screen, replace coolant header tank - hrs	24/06/2022 1		Hours	.00	6.00	\$1090.81
	50746	Off / Pre Hire -8366 Hrs, test all operations, replace coolant, grease all, blow out filters,	15/07/2022 1		Hours	.00	17.50	\$1629.38
	50878	Remove handrails, mirror mounts and roof sign mount. Repair handrails, mirror brackets and roof bracket. Replace roof panel. Fire suppression system inspection -8366 hrs replace battery master switch and lockout bracket, fit turbo lagging, swap roof sign from #963 to #967, needle gun rims and fit wheel nut indicators, repair r/h spray head, replace rear beacon with blue beacon	28/09/2022 9:		Hours	.00	41.00	\$5540.52
	51027	Repair bonnet cylinder - hrs. Remove, inspect, reseal and re-fit bonnet cylinder	18/10/2022 8:		Hours	.00	3.00	\$497.24
	51145	Check coolant loss issue - hrs	1/11/2022 1:4		Hours	.00	1.00	\$164.67
	50945	500 hr Service - 8526 hrs [Serviced by Callcorr]	8/11/2022 12:	8526.00	Hours	.00	3.00	\$751.48
	51238	Prep for site - Callcorr - Clean wheels and remove rust, repair lights, fit call sign and flashing light	14/11/2022 3:		Hours	.00	1.00	\$910.00
	51474	Repair aircon - replace a/c compressor and dryer - tested ok	20/12/2022 1		Hours	.00	1.00	\$1259.43
	51932	Fire suppression service - Callcorr completed 25/1/23	29/03/2023 2:		Hours	.00	1.00	\$1522.92
	52053	Water Tank repairs - 8933 hrs, replace rusted internal pressure feed piping & hydraulic cooling pipes , replace damaged hoses, epoxy coat inside tank where weld repairs were	12/05/2023 1		Hours	.00	26.00	\$3019.49
	52079	Off / Pre Hire - 8934 Hrs - Diagnose & Repair PTO leak. Repair/Replace Seat Base. Remove POS 6 tyre to be repaired - tyre repaired and refitted - Allcoast tyre	15/05/2023 7:		Hours	.00	56.00	\$5199.16

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	52201	Check battery fault - 8935 hrs (CJD) Replaced batteries + test - ok	19/06/2023 1		Hours	.00	1.00	\$655.00
	51645	1000 hr Service - 8937 hrs	27/06/2023 8:	8937.00	Hours	.00	.00	\$3845.88
	52250	Off / Pre Hire - 8938Hrs - Straightened LH step and fit new bolts, Reseal Pos 4 brake pipe, Replaced cabin roof panel.	5/07/2023 12:		Hours	.00	20.00	\$3653.51
	52112	Re-Shoe + replace all 6 rims- 8938 hrs - Removed all tyre assemblies from machine and took off valve stems, Proceeded to strip tyres from rims and load rims on pallets for transport. Transported to Reid Engineering. Reassembled rims and tyres and fitted to machine.	1/08/2023 11:		Hours	.00	23.50	\$16739.03
	52627	Re rod steer cylinders + check rear spray heads - 8937hrs - Remove L/H steer cylinder and dismantle - drop rod to BT hydraulics. Pick up rod and assemble with new seal + fit back in=to truck. Position and remove R/H steer cylinder + dismantle + drop rod to BT hydraulics. Fitted seat cover, glued loose dash panels, converted hitch from oil to grease. Replaced tank site glass tube. Replaced bonnet step tread plates.	10/10/2023 1		Hours	.00	42.00	\$4894.41
	52705	Fit registration plates - 8937 hrs	16/10/2023 1:		Hours	.00	2.50	\$132.00
	52842	Replaced LHS and centre sprays - 9127 hrs, replaced both a/c filters, fitted new UHF s/n 18004070, Replace hydraulic oil filter recess plate on top of hydraulic tank, replace both fresh air flap a/c control cables, replace a/c filter backing plate and cover, striped mid and left rear sprays and flipped the sealing balls + reassemble both sprays + adjusted both spray opening heights. - 9277 hrs, replaced LH rear spray, replaced middle spray quick release valve and exhaust hose. replace cracked Victaulic coupling on rear spray bar.	24/01/2024 1		Hours	.00	36.50	\$6474.46
	53011	Replace Stauff clamps on rear of tank for wiring to tail lights - 9331 hrs, replace M6 push fit air fitting on middle spray	1/02/2024 9:0		Hours	.00	1.50	\$595.80
	53025	Replace 3 x rear sprays with SV-205 type - 9335 hrs, fit quick drop valves to all rear sprays	14/02/2024 2:		Hours	.00	1.00	\$140.07
	53045	Off / Pre Hire - 9335Hrs - Checked all levels, belts and pulleys. Tested lights, and carried out operational checks. Inspected tank, plumbing and sprayer. Reset tyre pressures and checked tread depths. Greased machine. Completed driving and brake tests. Replaced bonnet lift cylinder hose. Changed out fire	14/02/2024 2:		Hours	.00	23.50	\$3445.20

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		extinguisher. Replaced 3 sprayers & 1 spray bar clamp. Removed client stickers. Fitted asset stickers						
	53221	500hr Service - 9489hrs	22/04/2024 1	9489.00	Hours	.00	10.50	\$2437.88
	53267	Replace all 3 rear spray head diaphragms with magnum parts - 9489 hrs, onsite inspection while machine was getting serviced	22/04/2024 1		Hours	.00	4.00	\$827.67
	53307	Off / Pre Hire - 9542hrs - Took transmission oil sample. Performed brake and driving tests. Tested lights and carried out operational checks. Checked movement in steering, hoist cylinders and body pivot pins. Reset tyre pressures and checked tread depths. Checked all levels, belts and pulleys. Greased machine. Rotate RH steer cylinder 180 degrees. Fit new safety stickers.	30/05/2024 6:		Hours	.00	16.50	\$2764.34
	53134	Replace water pump return hose - (Holcim organized Hasting Deering to complete) - hrs? No response from client or Hastings for an invoice 21/6/24 AH	21/06/2024 2:		Hours	.00	1.00	\$575.08
	53568	Replaced brake cooling hose on rear axle - 9576 hrs, replaced LH rear spray internal seal, fitted 4 inch 90 degree camlock adaptor to fill water tank	12/08/2024 9:		Hours	.00	.00	\$1115.45
	53581	Replace middle spray air switch - 9646hrs	28/08/2024 3:		Hours	.00	.00	\$409.07
	53727	Off Hire Inspection - 9682hrs - Completed off-hire inspection. Replaced LH steer cylinder rod and seals. Replaced door strut. Replaced O-rings of front PTO pumps. Updated fire extinguisher.	15/10/2024 9:		Hours	.00	.00	\$2152.79
	53755	Fit Reman brake stacker pump complete assembly - 9682hrs - Replaced stacker box. Replaced O-rings in hydraulic hose fittings. Replaced water pump seal and missing input shaft collar.	15/10/2024 2:		Hours	.00	.00	\$6580.15
	53722	LH Steer Cylinder Rod Repair -9682hrs - Tig repair damaged rod & linish as required.	15/10/2024 3:		Hours	.00	.00	\$431.37
	53835	Repair windscreen chip- 9687hrs	13/11/2024 7:		Hours	.00	.00	\$72.73
	53959	Off/Pre-Hire - 9815hrs - Replaced top lip seal in stacker pump. Replace front windscreen. Replace cab door lock barrel, replace LH sliding window latch.	11/12/2024 2:		Hours	.00	.00	\$1917.74
	54120	2000hr Service - 10016hrs - Replaced victaulic coupler on RH rear spray bar. Replaced wiper blade.	28/02/2025 2:	9989.00	Hours	.00	.00	\$6841.41

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	54132	Rectify Truck Surging issue - 9973 hrs, replaced fuel filters, blew out filter housing and fuel lines.	13/03/2025	1	Hours	.00	.00	\$517.20
	54261	Replace fuel filters - 10202hrs - Added fuel doctor. Rectify cannon spraying water	30/04/2025	7:	Hours	.00	.00	\$1610.14
	54453	Troubleshooting hydraulic oil leak - 10431 Hrs.Traced leak to rusted return pipe. Replaced pipe.Fault code 'SE2302-4' - Active water in fuel sensor wiring fault. Rectified.Replaced reversing camera loom due to damage.Conducted stall test - SERV. Identified dirt in fuel bowl. Cleaned out bowl and blew out fuel lines. Dirt identified in fuel tank - Advised customer to keep fuel tank fluid level above 1/4 capacity.Identified jelly substance in fuel filter bowl. Cleaned bowl. Tested SERV.	24/07/2025	1	Hours	.00	.00	\$4277.57
	54548	500 Hr Service - 10,481 Hrs. Replaced fuel water separator bowl due to damaged wires. Topped up coolant.	18/08/2025	1	Hours	.00	.00	\$2052.76
	54606	Rectified hydraulic oil leaks - 10502, tightened loose hydraulic hose fittings on pump hydraulic motor, replace both brake cooling feed hoses for middle axle, topped up brake cooling oil.	28/08/2025	1	Hours	.00	.00	\$1525.91
	54669	Trouble shoot low power fault - 10579 hrs, couldn't fault machine while onsite.	22/09/2025	1	Hours	.00	.00	\$1706.00
	54675	- Off/Pre-Hire Inspection - 10,549 Hrs.- Investigate fuel pressure issues: Cleaned low pressure fuel assembly, all fuel lines and fuel tank. Installed new fuel filters, replaced overflow valve in head.- Resealed hydraulic drive motor for the water tank pump. - Resealed brake cooling system water pump. - Resealed LH steer cylinder and installed 2nd hand gland. - Replaced ENG oil sump gasket. - Replaced all torque rod bushes in 2nd & 3rd axles, alternator, LHR sprayer clamp & body pad rubbers. - Replaced brass bung on water pump/HYD stacker. - Replaced wiper blades. - Repaired cracked on body pad mount. - Fit new o-ring to brake cooling hose.- Replaced crankcase pressure sensor.	13/10/2025	1	Hours	.00	.00	\$15243.90
	54747	Rectify a/c fault - 10607 hrs, awaiting AWE invoice - Trouble shoot reverse camera fault, adjusted reverse cam setting, test OK- Replaced failed a/c compressor, TX valve, dryer and thermostat.- Found blown engine oil hose, travel to Pirtek to get hose made, Fitted new hose from gear pump to engine oil filter housing.- Extracted broken belly guard bolt. - Topped up brake cooling oil 5L- Rectify starting issue 24/10/25, replaced	10/11/2025	1	Hours	.00	.00	\$8282.88

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost		
		faulty relay for V-ECU, replace faulty E-stop.							
54829		Off / Pre Hire - 10,675 Hrs. - Resealed ENG sump pan. - Replaced 2x HYD hoses and UHF antenna. - Replaced Cabin primary and secondary filters. - Cleaned ENG primary filter. - Replaced missing VECU fuse. - Replaced 2x battery's. - trouble shoot steering squeel, Check steering linkage position: Ok. Cleaned LS block tested OK - Adjusted ALT belt tension- Replaced cracked lower L/H mirror	20/01/2026	1	Hours	.00	.00	\$4684.99	
54857		Rebuild old brake cooling stacker pump - 10748 hrs	16/02/2026	1	Hours	.00	.00	\$4647.00	
55068		Replace failed #5 exhaust rocker arm & Cam Shaft + bearings - 10,824 Hrs - Recovered machine from site due to not being able to start engine	6/03/2026	12:	Hours	.00	.00	\$14547.06	
		:		<u>165</u>	Asset Total:	<u>967</u>	<u>0.0</u>	<u>1542.3</u>	<u>\$436,884.05</u>
		:		<u>165</u>	Parent Total:	<u>TPH</u>	<u>0.0</u>	<u>1542.3</u>	<u>\$436,884.05</u>
		Grand Total		<u><u>165</u></u>		<u><u>0.0</u></u>	<u><u>1542.3</u></u>	<u><u>\$436,884.05</u></u>	