

## Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A40F ADT BMA Spec. used 2012						
	44952	Fit Fire Suppression systems - 74 hrs & BMA Upgrades All, Fabricate new handrails, paint, install fluids decals & safety stickers, modify fire suppression mounting position	1/07/2018 12:		Hours	.00	40.75	\$18730.92
	44951	Tenkate Upgrades All, remove body heat exhaust, stamp rims, fit bma stickers, paint all stone gaurd, rust proof all hoses & pipes, fit turbo blanket, fit TPH stickers, Top up oils, Replace air filters & A/C, Replace fire ext & bracket, mounted wheel chocks, fit new grease lines Exts, Fit tailgate & outriggers,	2/07/2018 12:		Hours	.00	51.25	\$5334.32
	45587	500 hr Service - 524 Hrs	16/11/2018 1	616.00	Hours	.00	.00	\$811.02
	46314	Pre Hire Inspection - 659 hrs, replace belt tensioner, brake pressure sensor, SE 5204-3 error code	28/03/2019 1		Hours	.00	2.00	\$632.74
	46535	BMA Certification & Inspections - 695 hrs, repair rear muffler guard, straighten due to impact with fire suppression Bottle, touch up paint, refit grease lines	3/06/2019 12:		Hours	.00	14.00	\$1891.53
	46596	Check reported steering pressure warning light fault - 747 hrs. replace faulty SE 9102 sensor	26/06/2019 1		Hours	.00	5.00	\$906.80
	46742	1000 hr Service - 1051 hrs	1/10/2019 12:	.00	Hours	.00	10.50	\$4246.62
	47361	Replace batteries 1480 Hrs. Relocate fire suppression by 80mm & paint, clean out body,	6/01/2020 12:		Hours	.00	5.50	\$1144.93
	47369	500 hr Service 1480 Hrs	8/01/2020 12:	1551.00	Hours	.00	3.00	\$980.42
	47512	Dry Hire Pre & BMA Inspection & certifications - 1481 Hrs, fitted new alt belt tensioner ,	2/03/2020 12:		Hours	.00	10.50	\$2052.88
	47914	Pre Hire Inspection 1720 Hrs, Replace hand rail brackets & clamps, clean cab & windows,	8/06/2020 12:		Hours	.00	7.00	\$1686.01
	48099	BMA Brake test & weed & seed - Hrs, fire suppression system 6 month & extinguishers service	10/08/2020 1		Hours	.00	1.00	\$4410.41
	48098	Pre Hire - 1800 Hrs, replace Position 3 & 4 suspension blocks, repair work lights, wire up starter isolator correctly, install VHF	20/08/2020 1		Hours	.00	19.00	\$2972.05

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		radio, antenna, power cable, extra indicator to mirror brackets, fit second fire extinguisher on hitch area, reflective tape, clean out body, grease unit, clean to weed & seed standard,					
48519		Pre Hire Inspection - 1883 hrs, repair seat air line	11/01/2021 1		Hours	.00 2.00	\$240.00
48648		2000 hr Service - 2005 Hrs Engine Oil only	5/02/2021 12:		Hours	.00 9.00	\$4365.78
48749		Replace seals in bonnet pump due to no pressure been generated - 2005 hrs , install reman pump, wash unit	24/02/2021 1		Hours	.00 5.50	\$1035.99
48832		BMA Certification & Inspections - 2025 hrs, 12 month Fire Suppression system service, replace centre diff pinion seals, fit safety decals, Clean unit to Weed & seed standard, clean out body, detail cab,	26/02/2021 1		Hours	.00 10.50	\$3145.61
48804		Repair leaking middle axle pinion seal Hrs	30/04/2021 1		Hours	.00 .00	\$0.00
49164		Check reported damage to position 3 tyre - no issue found	29/06/2021 1		Hours	.00 .00	\$0.00
49499		Pre Hire Inspection - 2470 hrs - re seal injector wiring plug, repair oil leaks at hydraulic return pipe hose clamps, replace door gas spring, blown bulbs, full grease, re seal rear window joints, refit yoke to exhaust brake actuator cylinder, break up compacted dirt in body, clean machine, cab & windows	2/09/2021 12:		Hours	.00 4.50	\$491.38
49366		500 hr Service - 2474 Hrs	9/09/2021 12:	2474.00	Hours	.00 8.25	\$1332.49
49651		Off / Pre Hire -2476 Hrs (Pos 6 tyre has been changed up north Ultima updated), Fit tailgate , grease all, check tyres, blow out filters,(Tim Martin Inv) weld tailgate numbers,	24/09/2021 1		Hours	.00 11.50	\$800.01
49767		C/O pos 1 tyre - 2546 hrs, remove CVX7946A8A/TN84111 and fitted F7N284148/TN84150	25/10/2021 1		Hours	.00 7.00	\$479.13
49827		Pre /Off Hire inspection - 2581 hrs, Fire Suppression L2 Service, replace seat air control switch, straighten R/H lower step, clean air filters, adjust tyre pressures	1/12/2021 12:		Hours	.00 3.50	\$1916.81
49963		Check unit for brake system failure Ma5503-4 error code - 2588 hrs, remove floor panels, check wiring, test coil, found coil had failed, replace coil & hydraulic cartridge, teat operation, refit floor	21/12/2021 1		Hours	.00 13.50	\$2986.88
50066		Replace broken the park brake switch - 2675 hrs, Check reported rough ride, train operator how to adjust seat air pressure - 2611 hrs	2/03/2022 12:		Hours	.00 3.75	\$560.62
50217		1000 hr Service 2936 Hrs	7/04/2022 12:	2974.00	Hours	.00 7.00	\$2444.90

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	50652	Replace lost bonnet control spanner - 3230 hr [client CMC ISSAC Downs back charge invoice 1216 sent 1/07/2022]	29/06/2022 1		Hours	.00	.00	\$119.35
	50538	Replace battery isolator switch	6/07/2022 1:4		Hours	.00	.00	\$295.30
	50727	Repair coolant leak	3/08/2022 3:5		Hours	.00	1.00	\$501.97
	50842	500 hr Service - 3523 hrs	23/08/2022 2:	3523.00	Hours	.00	4.50	\$1332.98
	50910	Replace belt tensioner and pulley + replace oring and tighten fitting on main control valve - 3523 hrs	29/08/2022 1		Hours	.00	2.25	\$660.21
	50936	Off / Pre Hire, repair work lights, wash machine, clean cab, report POS 2 tyre damage, operator training - 3524 Hrs, replace wheel chocks - (Back charge CMC - Invoice #1242 sent 5/9/22)	6/09/2022 3:0		Hours	.00	9.00	\$1502.77
	50968	Change POS 3 tyre - (Tyrepower Moranbah) - hrs	15/09/2022 8:		Hours	.00	1.00	\$419.09
	51100	Replace door window - back charge client (Quarrico Grosvenor) - 3677 hrs (Inv #1253 sent 11/10/22)	18/10/2022 6:		Hours	.00	1.00	\$810.06
	50992	Re-shoe - hrs	20/10/2022 8:		Hours	.00	1.00	\$36801.92
	51115	Prep and mine spec - 3677 hrs Replace R/H Front Park light assembly, straighten R/H step, remove and replace tensioners, clean windows and detail cab, replace missing bolts on R/H cover, refit belly guards, manufacture wheel chock brackets, fit new wheel chocks, fit 4.5 kg extinguisher bracket, Remove BMA radio, Install Foxleigh radio	6/12/2022 12:		Hours	.00	27.00	\$4936.15
	51489	Late invoice for fire system inspection and 12 month service - 11/10/22 - Chubb	4/01/2023 7:4		Hours	.00	1.00	\$1352.27
	51816	4000 hr Service - 3917 hrs	4/04/2023 7:2	3917.00	Hours	.00	14.00	\$9245.24
	52021	Pre hire clean - 3917 hrs Replace bonnet raise witch, repair door switch, repair wheel chock bracket,	9/05/2023 3:4		Hours	.00	17.00	\$1445.00
	52104	Reseal L/H steer cylinder + replace door strut - 3984 hrs	13/06/2023 1		Hours	.00	11.00	\$1403.05
	52011	Replace R/H console - hrs (supplied parts only)	15/06/2023 1		Hours	.00	1.00	\$57.58
	52666	Off / Pre Hire - 3988Hrs - Carried out off hire inspection. Fitted wheel nut indicators. Replaced hitch hose. Replaced work light. Detailed.	16/10/2023 3:		Hours	.00	15.00	\$1910.21
	52819	Replace UHF - JRT - 4030 hrs	4/12/2023 1:1		Hours	.00	1.00	\$237.78
	52923	Replace flashing light - 4212hrs -	19/12/2023 9:		Hours	.00	1.00	\$322.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	53095	500hr Service - 4503hrs	4/03/2024 11:	4503.00	Hours	.00	17.00	\$1915.84
	53102	Replace fire extinguisher - 4503 hrs	4/03/2024 11:		Hours	.00	1.00	\$220.00
	53273	Replace air filters - 4817 hrs + top up coolant + repair air leak in seat base + clean out tailgate bearings	7/05/2024 1:5		Hours	.00	7.00	\$692.83
	53262	Replace fuel filters - hrs (JRT)	16/05/2024 3:		Hours	.00	1.00	\$409.99
	53316	Replace RH E-stop - 4866 hrs + replace fuel filters - test ok	20/05/2024 3:		Hours	.00	21.00	\$1392.70
	53335	1000 hr Service - 4919 hrs	10/06/2024 1	4919.00	Hours	.00	16.50	\$3093.91
	53295	Replace coolant header tank - 4919 hrs	10/06/2024 1		Hours	.00	2.00	\$853.63
	53343	Check recuring fuel fault - 4878 hrs Cleaned filter heads and fuel tank + replaced fuel filters - test ok (15-5-24) Clean tank and test ok - (28-5-24)	10/06/2024 1		Hours	.00	17.00	\$2185.00
	53344	Check truck after roll over - back charge client - 4900 hrs - Checked all levels, all within spec. Checked hoses in articulation for damage, none. Inspected fire suppression for damage, all okay. Checked middle and rear diff breathers, both have oil in breathers. Checked outriggers for damage, none found. Inspected tailgate to find RHS arm damaged and contacting tub. Removed tailgate. Checked tyres, found POS 5 to have cut in sidewall. Straightened bent tailgate arm and replaced bracing strip. Reassembled RHS tailgate arm, replaced bearings and bearing plates before refitting to machine. Adjusted tailgate ropes. Inv #1400 sent 21/6/24 Removed pos 5 tyre CCO0046V9A/TN8 4115 and fitted DVY1808M4A/322-812 P3	21/06/2024 2:		Hours	.00	92.75	\$5166.88
	53562	Trouble shot low power fault - 5176 hrs, found algi in fuel system, drained fuel tank, blew out all fuel lines and filter housing, removed RH handrail and fender cover to gain access to hatch plate on fuel tank, removed fuel tank top hatch plate, cleaned fuel tank out, refilled fuel tank, replaced both fuel filters, bleed fuel system, added fuel dr to tank.	30/07/2024 1		Hours	.00	.00	\$1621.98
	53558	Replace engine oil pressure sensor - 5176 hrs	30/07/2024 1		Hours	.00	.00	\$241.42
	53707	500hr Service - 5555hrs	23/09/2024 1	5419.00	Hours	.00	.00	\$1482.79
	53714	Check for Algae in fuel sight glass - 5469hrs - Replaced fuel filters and add fuel doctor. Replace front grill gas strut.	9/10/2024 12:		Hours	.00	.00	\$1230.97

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost		
	53831	Replaced main isolator - JRT Mechanical	13/11/2024	1	Hours	.00	.00	\$709.24	
	53974	Top up hydraulic oil level(20lts) - 5810hrs - JRT Mechanical	13/12/2024	8:	Hours	.00	.00	\$221.44	
	54094	Off/Pre-Hire - 5836hrs - Replaced belt tensioners. Cleaned machine. Replaced seized battery isolator. Replaced LH indicator on mirror bracket. Replaced broken Volvo emblem on grill. Replaced door strut. Replaced work light bulbs. Replaced reverse beeper. Replaced Pos 2,3,1 suspension blocks. Repaired cracks in hand rails. Straightened RH access ladder. Replaced washer pump. Unblocked washer jets. Replaced batteries. Removed tailgate and arms.	28/02/2025	3:	Hours	.00	.00	\$9619.86	
	54062	Repair bent rear light sub frames and tail light backing plates - 5835hrs - Replace 1 x tail light, replace 1 x rear indicator, repair both tail light outer grills, prep and paint repaired subframe and tail light backing plates.	4/03/2025	3:5	Hours	.00	.00	\$1725.61	
	53968	C/O Pos 5 tyre - Removed tyre DVY1808M4A and fitted tyre IVY2512M0A.	14/03/2025	7:	Hours	.00	.00	\$45.00	
	54176	6000hr Service - 6052 hrs	7/04/2025	8:5	5919.00	Hours	.00	.00	\$7986.59
	54148	Replace blown hydraulic hose - 5908 hrs (JRT Completed this repair)	2/06/2025	12:	Hours	.00	.00	\$0.00	
	54520	Pre / Hire Inspection - 6080 hrs, Fit tailgate to truck, clean & detail truck.	28/07/2025	1	Hours	.00	.00	\$2688.88	
	54614	Sample front differential and transmission for monitoring - 6,271 Hrs.	28/08/2025	1	Hours	.00	.00	\$300.00	
	54691	Troubleshoot EF5203-1 error code - 6342 hrs Replace Brake pressure sensor. (McCosker to complete repairs)	29/09/2025	1	Hours	.00	.00	\$862.13	
	54754	500 Hr Service - 6,571 Hrs.	28/11/2025	1	Hours	.00	.00	\$2933.34	
	54886	Off/Pre-Hire Inspection - 6600 Hrs. - Replace Alternator belt tensioner. - Replaced FM radio. - Replace POS 3 bellow. - Replaced both tailgate bearings. - Straightened R/H step treads + prep & paint. - Replace reverse alarm. - Investigate heavy steering sounds: identified seized ball joint on tie rod under cab flooring. Rectified with lubrication.- Replace damaged POS 1 fender flare and retaining plate (client supplied parts)	23/02/2026	1	Hours	.00	.00	\$4653.01	
	55222	Late Invoice for WO 54148	4/05/2026	12:	Hours	.00	.00	\$2014.66	

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	:			71				
			<b>Asset Total:</b>		1060	0.0	538.5	\$183,220.86
	:			71				
			<b>Parent Total:</b>		TPH	0.0	538.5	\$183,220.86
		<b>Grand Total</b>		71		0.0	538.5	\$183,220.86