

## Work Order History Report

22-May-2026

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		Plant Hire 51 Volvo A30F ADT						
	31950	1006- serial number- 52086, Fit all Tenkate Upgrades	18/05/2012 1		Hours	.00	22.50	\$2414.29
	32211	Replace mirror glass	30/06/2012 1		Hours	.00	.00	\$265.00
	32537	Inspect fault with diff lock, found faulty switch- 491hrs	31/08/2012 1		Hours	.00	6.00	\$484.00
	32588	500 hr Service- 452hrs	10/09/2012 1	452.00	Hours	.00	5.00	\$987.65
	33563	1000 hr Service. 1024 hrs	9/01/2013 7:5	952.00	Hours	.00	.00	\$624.00
	34055	Costs not issued to 33563	22/02/2013 3:		Hours	.00	.00	\$1433.00
	34303	500 hr Service - 1451 hrs	31/05/2013 3:	1571.00	Hours	.00	9.00	\$1811.15
	34938	2000 hr Service. 1984 hrs	23/07/2013 1:	1984.00	Hours	.00	13.50	\$4824.97
	36123	Recharge front Hydro suspension, set to correct ride height. 2382 hrs. CJD- Investigate suspension issues, found both struts gas less, recharge, if leaking again will need to reseal.	30/11/2013 1		Hours	.00	.00	\$1190.00
	36257	500 hr Service - 2422 hrs, replace flashing light.	30/11/2013 4:	2502.00	Hours	.00	9.50	\$1699.25
	36707	replace flashing light. 2693 hrs	25/02/2014 1		Hours	.00	2.50	\$280.49
	37139	Inspect air con. replave TX, receiver drier, o-rings and cabin filter. regas system.	26/03/2014 1		Hours	.00	4.00	\$1842.00
	37046	1000 hr Service. 2980 hrs	26/03/2014 1	3024.00	Hours	.00	9.50	\$1836.20
	36913	Rectify Coolant leaks, replace secondary water pump. 2994hrs	31/05/2014 1		Hours	.00	2.00	\$4383.00
	37254	Warranty Replacment Pos.1 hydraulic suspension Strut at 2994 hrsRegassed for the second time at 2856. warranty claim put forward -TRAVEL COSTS ONLY	1/06/2014 3:3		Hours	.00	.00	\$476.00
	37726	500 hr Service. 3478 hrs. repair L/H headlight, remove mine aerial.	2/07/2014 8:2		Hours	.00	7.00	\$1479.82
	38555	Check & Adjust Front Suspension Strut heightsTravel costs for replacement of Pos. 1 strut.	31/10/2014 1		Hours	.00	.00	\$315.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	38580	Mechanical Inspection - 3620 hrs	31/10/2014	1	Hours	.00	2.50	\$228.00
	38728	Rectify fault with body up sensor locking in low gear , install softwear upgrade, tighten loose body bolts, repair rear light wiring earth fault, fit new UHF aerial. replace air fitting - 3715 hrs	31/01/2015	1	Hours	.00	.50	\$1058.00
	38952	4000 hr Service - 4014 hrs	31/01/2015	1	Hours	.00	18.50	\$5628.30
	39174	Spare tyre repairs	28/02/2015	1	Hours	.00	.00	\$234.00
	39293	Replace hydraulic hose from Pump 1 to fan. - 4254 hrs	31/03/2015	1	Hours	.00	11.00	\$924.00
	39397	Mechanical Inspection. Replace timing cover seal. Reseal scavange pump. - 4299 hrs	31/03/2015	1	Hours	.00	37.50	\$2294.64
	39583	Off-hire inspection, replace washer pump. - 4328 hrs	30/04/2015	1	Hours	.00	2.00	\$278.00
	39588	Replace secondary water pump. - 4328 hrs	30/04/2015	1	Hours	.00	24.50	\$2541.00
	39497	Replace Pos.6 tyre. - 4306 hrs	31/05/2015	1	Hours	.00	7.50	\$1361.00
	39662	Pre-hire Inspection. - 4330 hrs	31/05/2015	1	Hours	.00	10.00	\$732.00
	40055	500 hr Service - 4478 hrs	14/08/2015	9:	Hours	.00	8.00	\$1331.82
	40184	August Pre-starts - 4476 hrs	25/08/2015	1	Hours	.00	4.00	\$208.00
	40142	July Pre-starts - 6724 hrs	31/08/2015	1	Hours	.00	2.50	\$180.00
	40363	Recover unit from site roll over. - 4615 hrs	11/09/2015	1	4615.00 Hours	.00	18.50	\$1087.00
	40312	September Pre-starts. - 4615 hrs	30/09/2015	1	Hours	.00	5.00	\$260.00
	40415	Repair damage to machine after rollover. Strip cab down, remove, check damage, send to QMW for repairs, strip down engine , check big end & main bearings, replace damaged L/H mirrors, brackets, panels, lights, cab lid, crack testcab mounts, Check chassis alignments, check & cut open all engine , transmission, hydraulic oil filters, check oil pressures, check hydraulic pumps, motors, pressures, replace all breather filters, cab air filters, inspect & check hitch for movement, repair error defects on start upUnit Recovery Reassemble cab, fit to machine hook up & re fit all panels, mirrors , brackets etc	30/10/2015	1	Hours	.00	128.00	\$59698.92
	40463	Replace vertical hitch bearings - 4612 hrs	31/10/2015	1	Hours	.00	9.00	\$568.00
	40703	Pre hire inspection. - 4615 hrs	4/11/2015	12:	4615.00 Hours	.00	4.00	\$551.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	40830	Troubleshoot coolant leak. - 4640 hrs	30/11/2015 1	Hours	.00	2.50	\$180.00
	40911	Adjust cab door lock mechanism. Take engine oil sample. - 4682 hrs	9/12/2015 12:	4682.00 Hours	.00	4.00	\$183.00
	40948	Pre hire inspection. - 4683 hrs	18/12/2015 1	4683.00 Hours	.00	7.00	\$431.40
	41027	Sample : Engine, Transmission, Hydraulic for monitoring. - 4723 hrs	14/01/2016 1	Hours	.00	1.00	\$217.00
	41028	Pre-hire Inspection - 4723 hrs	14/01/2016 1	4723.00 Hours	.00	10.00	\$578.00
	41247	1000 hr Service - 4953 hrs	16/03/2016 1	4953.00 Hours	.00	8.00	\$1889.20
	41324	Fitted joiner to middle diff lock, looked at cab not sealing. - 4953 hrs	21/03/2016 1	Hours	.00	10.00	\$570.00
	41382	Pre-hire Inspection. - 4954 hrs	4/04/2016 12:	4954.00 Hours	.00	2.00	\$314.20
	41588	Matris download. - 5057 hrs	5/05/2016 12:	5057.00 Hours	.00	1.50	\$78.00
	41813	Pre hire inspection. - 5076 hrs	16/06/2016 1	5076.00 Hours	.00	7.00	\$414.00
	41915	July Pre-starts. - 5106 hrs	31/07/2016 1	Hours	.00	.00	\$50.00
	42198	Pre hire inspection. - 5145 hrs	6/09/2016 12:	Hours	.00	7.00	\$414.00
	42224	Check reported hydraulic low level warning code fault - 5153 hrs	14/09/2016 1	Hours	.00	4.50	\$305.20
	41863	Warranty Front Suspension Struts Replacement. - Percentage of the Claim Agreed on. - 5211 hrs	30/11/2016 1	Hours	.00	9.00	\$6649.00
	42513	November repairs, [change out fire extinguisher, top up engine oil. - 5249 hrs]	30/11/2016 1	Hours	.00	4.00	\$418.50
	42579	Pre- Hire Inspection - 5263 hrs, secondary water pump costs	2/12/2016 12:	Hours	.00	2.50	\$1252.18
	42670	Offhire Inspection. - 5315 hrs	21/12/2016 1	Hours	.00	2.00	\$130.00
	42773	January repairs, [calibrated body angle sensor - 5428 hrs]	20/01/2017 1	Hours	.00	2.50	\$180.00
	42838	Replace Pos.5 Wheel on site at Petrie. - 5527 hrs	7/02/2017 12:	5527.00 Hours	.00	8.50	\$492.00
	42801	500 hr Service. - 5541 hrs	9/02/2017 12:	5541.00 Hours	.00	4.00	\$970.54
	42848	Off hire/ Pre hire inspection. C/o pos 6 wheel / tyre assy, fit Pos. 3/4 rubber suspension blocks, supply fit battery isolator, cables to suit, emergency stop. - 5541 hrs	9/02/2017 12:	5541.00 Hours	.00	12.00	\$2339.37
	43076	Off / pre hire inspection. replace Pos.5 wheel, 5610 hrs, replace secondary water pump supplied os work order 42579,	10/04/2017 1	5640.00 Hours	.00	6.50	\$757.07

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		Replace Belt, 5640 klms						
	43171	Change Pos.5 wheel at 5754 hrs, remove tyre FIB481370 & Rim TN8 2510 install tyre F1N584006 & rim TN8 4364	4/05/2017 12:	5754.00	Hours	.00	7.00	\$400.07
	43233	Off / Pre hire inspection. 5798 hrs	16/05/2017 1	5798.00	Hours	.00	6.50	\$380.91
	43178	Repair 23.5 x25 Tyre No. FIB481370 at 5798 hrs	29/05/2017 1		Hours	.00	1.00	\$722.00
	43358	Change out Pos 5 tyre on site at Coomera - 5891 hrs. Removed FIN584006, Rim TN8 4364, Tyre was scrapped, Fitted VLT F1R484506, Rim TN8 2510.	8/06/2017 12:	5891.00	Hours	.00	9.50	\$580.66
	43462	6000 hr Service at 6000 hrs Transmission oil changed to AT102	8/07/2017 12:	6000.00	Hours	.00	17.00	\$5605.88
	43576	Repair hydraulic oil leak, CJD to site MCV hose repair , labour and inspect truck.	1/08/2017 12:		Hours	.00	4.00	\$2391.24
	43626	Replace Batteries	10/08/2017 1		Hours	.00	3.50	\$765.11
	43670	Replace blown transmission hose, top oil - 6191 hrs + repaired air fitting over hitch	21/08/2017 1		Hours	.00	27.00	\$2379.97
	43818	September Pre starts, Body up sensor staying on (CJD)	30/10/2017 1		Hours	.00	.00	\$1697.78
	43995	500 hr Service. 6487 Hrs,	3/11/2017 12:	6487.00	Hours	.00	10.00	\$1247.94
	44012	October prestarts, replace alt belt tensioner + replace aux water pump belt tensioner, clean out grease tracks in tailgate bearings, grease bearings, Inflate Pos.3 tyre, re calibrate body position sensor - 6498 hrs	9/11/2017 12:		Hours	.00	4.50	\$1072.31
	44121	Change out pos 3 tyre on site Hope Island 6586 Hrs. Remove tyre F1N482326 & Rim TN83040. Replace with Tyre F3E181161 & Rim TN82511.	30/11/2017 1		Hours	.00	6.50	\$543.72
	44200	Off Dry Hire Inspection 6670 Hrs, tapped new thread to bell housing, fitted rear main upgrade, tailgate bearings to take grease, repair seat belt buckle, reseal middle diff input seal, replace hose from pump 6,replace brake fan valve, replace wiring LHS taillight, removed seized rear belly plate pins,	3/01/2018 12:	6670.00	Hours	.00	18.50	\$1486.81
	44428	Off Hire/ Pre Hire 6902 Hrs, fit cab filters, top up coolant,	21/02/2018 1		Hours	.00	4.50	\$332.44
	44452	1000 hr Service at 6952 hrs	31/03/2018 1	6952.00	Hours	.00	4.00	\$1609.19
	44544	Pre hire inspection - 6952 hrs, top up oils, drop belly plates, replace cab filter, degrease engine bay,	31/03/2018 1		Hours	.00	6.50	\$506.58
	44643	Replace faulty body sensor - 6963 hrs, fit new sensor, adjust, test operation.	30/04/2018 1		Hours	.00	4.50	\$1144.84

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		see operation,						
	44672	Replace pos 3 on site rangeview station (Craig) Remove Tyre F3E 181161 & Rim TN8 2511(Tyre & Rim to come back to caloundra yard) / Replace with Tyre F1B481370 & Rim TN8 4364	3/05/2018 9:3		Hours	.00	.00	\$78.00
	44839	Repair tailgate due to roll over of the rear body - 7125 Hrs [back charge to Client Inv. 993 sent 1/06/18], travel to site check & adjust body up sensor, sensor kept going out of calibration traced to bent tailgate arm & due to this the body would not settle into position, remove R/H tailgate arm, check for other possible damage, travel to & from site, press & straighten tailgate arm, load into trailer, travel, refit to unit & adjust	23/05/2018 1		Hours	.00	10.25	\$1584.71
	44877	C/o Pos 5 tyre at Mackay Yard, Remove Pos 5 Tyre F1R484506 & Replace with Tyre F2S282043.	31/05/2018 1		Hours	.00	.00	\$366.00
	44906	Off Hire / Pre Hire - 7147 hrs, replace centre diff input seals & pinion nut, windscreen washer pump, rear body pivot bushes, Shim up rear mounts & front body side plates, tighten hose clamps, wash machine clean cab	30/06/2018 1		Hours	.00	23.75	\$2608.55
	45108	Trembath Tyre Repairs to closed W/O 44672	11/07/2018 1		Hours	.00	.00	\$512.00
	45079	C/O Pos 1 Tyre on Site 7265 Hrs,Remove Tyre F1N581258 & Rim TN8 3038 / Replace with Tyre F6A482359 & Rim TN8 4273	20/07/2018 1		Hours	.00	.00	\$660.40
	45191	Fitted new battery isolator and red lock out kit 7412 Hrs	22/07/2018 1		Hours	.00	1.50	\$193.46
	45209	Replaced rhs low beam light bulb + recalibrated tub sensor - 7485 hrs	27/07/2018 1		Hours	.00	2.00	\$139.90
	45227	C/O Tyre on Site Pos 4 - 7522 Hrs. Remove Tyre F1N581255 & Rim TN8 3041 / Replace Tyre with F2R483052 & Rim TN8 4465	30/07/2018 1		Hours	.00	.00	\$586.50
	45195	500 hr Service 7555 Hrs.	31/07/2018 1	7555.00	Hours	.00	6.00	\$936.97
	45265	August prestarts 7573 Hrs+ fitted T245 fire ext,	1/08/2018 12:		Hours	.00	1.00	\$292.00
	45297	C/o Tyre on site Pos 3 , 7638 Hrs. Remove Tyre F1B481370 & Rim TN8 4364 / replace with Tyre F1R484461 & Rim TN8 3041	9/08/2018 12:		Hours	.00	6.50	\$382.26
	45350	Off / Pre Hire - 7649 Hrs, replace Pos.5 suspension block, calibrate body sensor, rotate tyres from #982 & on machine,	24/08/2018 1		Hours	.00	36.50	\$2607.69

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		check fluid levels, clean radiators, all air filters, fit safety stickers, squawker reverse alarm, paint tow points, side of body for ID decal, fit 80 channel UHF, upgrade handrail to site specs.						
45466		Assess RHS tailgate bearing failure + removed damaged RHS tailgate bearing plate + drilled grease hole in second hand bearing plate - replace both bearings - 7737 Hrs	13/09/2018 1	7737.00	Hours	.00	19.00	\$1258.89
45554		Major Tyre Repair Costs to F1B481370	27/09/2018 1		Hours	.00	.00	\$812.00
45640		Replace Pos 1 Tyre On Site 7876 Hrs, Remove Tyre F2E384365 & Rim TN8 2527, Replace with Tyre F8B381247 & Rim TN8 3051.	23/10/2018 1		Hours	.00	23.00	\$1257.47
45681		Replace tub body pads X 4 on site - 7894hrs, replace missing body lock pin & retaining lock	1/11/2018 12:		Hours	.00	3.00	\$448.94
45522		Check for possible engine boost pressure loss, trace to leaking flexible hose from turbo to intercooler pipes, replace hose & clamps	8/11/2018 12:		Hours	.00	10.00	\$625.85
45674		4000 hr Service 8009 Hrs	21/11/2018 1	8009.00	Hours	.00	28.50	\$5160.43
45756		Fitted new LED beacon 7972 Hrs, remove & repaired front grill hinges, lubed up seat linkages, replace grease gun, check all tyre pressures, 8050 Hrs reset body up sensor, tailgate to take grease,	28/11/2018 1		Hours	.00	18.00	\$1330.75
46347		Replace Pos.4 wheel - 8145 Hrs. remove tyre F2R483052 & Rim TN8 2529 & fit tyre F7M583581 & rim TN8 2014, re stamp rim	9/04/2019 12:		Hours	.00	14.00	\$1146.97
46393		Replace Pos.3 wheel Fit and strip stock 14/ 3045 / F7R481502 / Scrap ECUJ032754A / strip tyre F7M583581	18/04/2019 1		Hours	.00	.00	\$856.08
46403		Replace Position 3 wheel , SMU 8218	24/04/2019 1		Hours	.00	6.50	\$424.20
46444		SMU 8262 Change POS 4 tyre at airport	3/05/2019 3:0		Hours	.00	.00	\$341.60
46493		Replace Pos.4 wheel , strip and refit for stock Rim no 2058 / tyre # F7L281835 , restamp rim 2058, scrap tyre # F7L281835 SMU 8328 Replace POS 3 tyre YOKOHAMA HTPGDD054 / TN8 3059 REPLACE WITH BRIDGESTONES F8A383270/TN82014	16/05/2019 1		Hours	.00	7.50	\$519.84
46529		Replace position 1 wheel -8371 hrs	3/06/2019 12:		Hours	.00	.00	\$476.60
46592		Change POS 3 tyre BRIDGESTONE F8A383270 TN8 2014 TD 16 TO TYRE #18	6/06/2019 12:		Hours	.00	7.00	\$386.47

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		BRIDGESTONE F7R383964 RIM NO 2523 TREAD DEPTH 18 SMU 8484						
46578	500 hr Service	SMU 8521	11/06/2019	1 8521.00	Hours	.00	7.00	\$1104.75
46641	Change flat tyre pos 4 @ 8614 hrs take off POS 4 tyre fit up new wheel rim no 2014 tyre no F8A383530 ( 48) scrap F8A383270, Pump up flat tyre and identified leak , moved machine to hard ground , inflated POS 3 from 45PSI to 50PSI and fitted new valve cap to POS 1. fitted new tyre to pos 4 @ 8614 hrs (F3E181190/TN83045) + Lubricated seat roller and linkages		20/06/2019	1	Hours	.00	.00	\$1344.34
46781	Change Position 6 tyre - hrs, fit tyre , send 2 tyres to Trembath for major repair F8B381247 BRIDGESTONE AND F3A181803 BRIDGESTONE		30/07/2019	1	Hours	.00	2.00	\$1153.87
46758	Off Hire Inspection SMU 8649 , topped up engine oil , replaced tensioner for AC belt , replaced drop box filler plug , drained oil from drop box and replaced drain plug , refilled drop box. Replaced X rings on remote oil filter , replaced O rings on PTO cover LH rear and removed LH pump , fitted new Oring and pump, fitted rear LH cover and Oring, ytest ran until oil was hot and checked for leaks, tested OK . Removed dipstick and dipstick tube, replaced tube and reassemble , washed and degreased , found oil leak in oil linefor upgradewas loose and leaking.Replaced steer bearing on RH side , restamped all rims and painted,topped up hydraulic oil , replaced beacon light handle. LH side tailgate bearing not taking grease, picked out old grease from nipple and pumped enerpack through it to free up then grease.Jacked up RH side of truck , removed wheels and RH bellow , prepare to remove bellow		27/08/2019	1	Hours	.00	.00	\$2117.36
46879	Replace walking beam bushes, Pos. bellows SMU 8649, Remove walking beams, pressed out bush , pressed in new bushes, fit tyres and torque wheel nuts		27/08/2019	1 8649.00	Hours	.00	15.50	\$2160.59
47038	Late invoice from CJD invoice no . 1912053		4/10/2019	12:	Hours	.00	.00	\$626.74
47101	inspected machine to go out on hire, fitted T322 fire ext to truck, topped up engine oil, adjusted tyre pressures @ 8650 hrs		18/10/2019	1 8650.00	Hours	.00	1.00	\$392.03
47326	Off / Pre Hire 8736 Hrs, drop belly plates, check tyres & rims, check lights, check belts, grease all, replace bonnet switch,		16/12/2019	1	Hours	.00	8.00	\$1027.32

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	47412	Replace exhaust flex from turbo to engine pipe, steering rack boot, Tighten Door strut, coolant leak - heater core - 8738 Hrs, top up oils, blow out filters	17/01/2020	1	Hours	.00	9.50	\$2632.90
	47462	Tyre Repair Trembath X 3 .Tyre No F1N482892 18-04-2019 + F3E181188 25-09-2019+ F7R481502 20-06-2019.	29/01/2020	1	Hours	.00	.00	\$1736.00
	47614	Replace all wheels - 8739 hrs, swap with wheel from 929, restamp rims fit to Pos.1 TN8 4274 + J495O-17, Pos.2 TN8 4063, J0152O-17, Pos.3 TN8 4255, J3994R-17, Pos.4 TN8 4261, J4969O-17, Pos.5 TN8 4360, J2383R-17, Pos.6 TN8 2528, J3057R-17Remove , Pos.1 TN8 2529, F7R482281, Pos.2 TN8 2530, F2R381141, Pos.3 TN8 2523, F7R383964, Pos.4 TN8 3045, F3E181190, Pos.5 TN8 2510, F2S282043, Pos.6 TN8 2546, F6E481926	19/03/2020	1	8739.00 Hours	.00	18.00	\$1077.85
	47615	Replace batteries - 8739 hrs, muffler bottom blanking cap, check air leak in seat, replace window catch & fuel screen [removed from #1028] final inspection, grease unit	20/03/2020	1	8739.00 Hours	.00	9.00	\$1774.80
	47853	Off / Pre Hire - 8803 Hrs, check park & exhaust brake operation, replace alt belt tensioner, seat slides, front steering rack bellow, O-ring on transmission breather pipe, fire extinguisher, unseize park brake caliper linkage clevis pin & adjust, clean all air filters, wash evaporator, repair air leaks, coolant leaks, fit new tailgate guide bushes to side of body, degrease, refit guards & panels	29/05/2020	1	Hours	.00	24.00	\$2405.19
	47880	Replace drive shaft to front diff - 8803 hrs, remove lower drop box mounting bolts to allow removal of seized driveshaft, fit new shaft, reassemble	10/06/2020	1	Hours	.00	3.50	\$205.97
	47996	Off / Pre Hire 8819 Hrs, Test operation, check oil leak l/h lift cylinder, replaced exhaust brake cylinder (second hand), grease all,	25/06/2020	1	Hours	.00	11.50	\$625.10
	48081	1000 hr Service 8959 Hrs	26/08/2020	1	9021.00 Hours	.00	7.00	\$1472.89
	48447	Off / Pre Hire 9045 Hrs blow out cab filters, change fire ext, replace LHS H1 bulb, check tyres,	11/11/2020	1	Hours	.00	4.00	\$343.01
	48566	Off / Pre Hire - 9079 Hrs, Replace Pos 5 suspension block ,Check fluids, belts, drop belly plates, grease all, blow out filters,	2/12/2020	12:	Hours	.00	7.00	\$963.05
	48677	Check seat fault - 9130 hrs, replace air seat control valve (CJD)	31/01/2021	1	Hours	.00	.00	\$1397.43

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	48741	Off / Pre Hire 9230 Hrs, replace exhaust brake actuator cylinder, L/H steering bearing & seals, grease all, replace l/h rear & front body pads, inner a/c filter, wiper blade,	12/02/2021 1		Hours	.00	14.50	\$2659.72
	48751	Replace Exhaust pipes, clamps, mounts -9230 Hrs,	12/02/2021 1		Hours	.00	6.00	\$2441.79
	48752	Replace A/C Evaporator & Heater cores -9230 Hrs, recover gas, pressure test system, replace receiver drier, regas system, test operation	12/02/2021 1		Hours	.00	4.00	\$2263.57
	49010	500 hr Service - 9474 hrs	6/05/2021 12:	9474.00	Hours	.00	3.50	\$994.31
	49404	Replace LS line from AUX pump to LS block - 9833 Hrs (Pirtek), Reset body angle sensor x 3 - 9883 hrs, 9903 hrs, 9910 hrs	27/07/2021 1		Hours	.00	7.50	\$1116.71
	49469	2000 hr Service 9989 Hrs	26/08/2021 1	9974.00	Hours	.00	4.50	\$3679.60
	49496	Line Bore the bores in body pivot mounts - 9990 hrs, replace bushes, body pivot pins, seals	30/08/2021 1		Hours	.00	8.00	\$4329.26
	49511	Off / Pre Hire -9990 Hrs , Fit Expansion Tank, grease all, blow out filters, replace fire ext, primary water pump tensioner, Alt Aux w/p belts, top up coolant, check tyres, Replace load dump brake solenoid coil, repair l/h step tread, drop belly plates, remove pos 5 & 6 wheels check brake pads, replace o-ring rear diff housing,	30/08/2021 1		Hours	.00	18.50	\$2908.29
	49557	Replace Pos 5 & 6 Wheel Seals -10071 Hrs, replace wheel seals, spacer rings, bearings, o-rings,	21/09/2021 1		Hours	.00	11.50	\$7070.04
	49614	Off / Pre Hire -10071 Hrs, re-seal l/h lift cylinder, replace l/h tailgate grease hose, l/h front body pad, fix wiring to l/h mirror, drop belly plates, grease all, blow out filters,	1/11/2021 12:		Hours	.00	13.00	\$1448.60
	49776	Off / Pre Hire - 10,143 Hrs, Install Pos.5 & 6 Sun Gears, top up diff oils, replace UHF mic holder	8/11/2021 12:		Hours	.00	6.00	\$548.81
	49939	Off / Pre Hire - 10,186 Hrs , check seat movement & diagnose/recall, top up oils, grease, replace park light bulbs on bonnet	30/12/2021 1		Hours	.00	11.00	\$1066.43
	50106	Replace battery and starter isolators - 10287 hrs, late invoice for seat repair costs	18/02/2022 1		Hours	.00	2.50	\$927.71
	50181	Replace R/H rear body pad 10396 Hrs, check over before commencing at new site	22/02/2022 1		Hours	.00	3.00	\$607.86
	50258	Off / Pre Hire -10,405 Hrs change out fire extinguisher T321 off to T400 on.	23/03/2022 1	10405.00	Hours	.00	12.00	\$682.07

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	50172	500 hr Service - 10405 Hrs	30/03/2022 1		Hours	.00	7.50	\$1029.79
	50609	Off / Pre Hire -10581 Hrs, grease all, check operations, blow out filters, replace Alt,	17/06/2022 1		Hours	.00	13.00	\$630.76
	51140	1000 hr Service - 10948 hrs	14/11/2022 1	10974.00	Hours	.00	.00	\$1559.77
	51429	Off / Pre Hire - 11084 Hrs perform operational checks, clean out belly guards, grease machine, replace grease nipples in hitch pivots, check tyres and rims, blow out filters and replace air con outer filter, dismantle POS 6 tyre + replace valve stem and adaptor - assemble and inflate	19/12/2022 1		Hours	.00	18.00	\$1053.53
	51553	Off / Pre Hire - 11153 Hrs Perform driving tests, checked tailgate, checked lights, checked vee belts and pulleys, inspected tub, inspect fluid levels, checked cab funstions, inspect drive shafts, checked tyres + rims, checked bellows + walking beams, inspected belts + pulleys, add fuel doctor to fuel tank, relpace body rubbers, replaced seat belt	23/01/2023 1		Hours	.00	15.50	\$2017.11
	51790	C/O pos 1 tyre/rim - 11325 hrs, Remove tyre/rim J49540-17/TN84274 and fitted tyre/rim F5J282888/TN84357	20/03/2023 1:		Hours	.00	8.00	\$681.00
	51870	Diagnose air leak on air dryer - 11368 hrs, replaced air dryer filter and oring	28/03/2023 8:		Hours	.00	2.00	\$328.30
	51948	500 hr Service - 11464 hrs	24/04/2023 2:	11464.00	Hours	.00	5.00	\$1246.96
	51960	Off / Pre Hire - 11464 Hrs - Tested brakes, all pins and bushes for movement, found water pump has failed - replaced. Replaced collars and springs in mirror frames, removed tailgate	23/05/2023 7:		Hours	.00	25.00	\$2271.70
	52194	Replace park brake feed air line over the hitch - 11532 hrs	9/06/2023 8:2		Hours	.00	.00	\$398.35
	52327	Replace 90 degree coolant elbows from thermostat housing - 11684hrs, topped up 4ltrs VCS. Replace FM radio Ariel assembly, replace all belts	24/07/2023 1		Hours	.00	18.50	\$1963.41
	52321	C/O Tyre On Site Position 5 - 11684Hrs, Remove Tyre J2383R -17 & Rim TN8 4360 / Replace With Tyre S5JCK0022 & Rim TN8 4256.	1/08/2023 11:		Hours	.00	11.50	\$717.60
	52668	Off / Pre Hire - 11775Hrs - Carried out off hire inspection checking all levels, lights and controls. Inspected fire extinguisher. Checked tyre depths and pressures. Inspected body mounts and tailgate. Greased machine. Performed operational checks and brake tested. Replaced all belts. Cut	23/10/2023 2:		Hours	.00	10.50	\$880.52

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
		old steps off both sides, fabricated new runs, painted and fitted to machine with new wire straps.						
	52899	Fit tailgate number A30F 24 - 11775 hrs - Fitted tailgate to machine, adjusted ropes and tested.	19/12/2023 7:		Hours	.00	7.00	\$2702.17
	53001	Replace UHF radio, fitted S/N 18004144 - 11821 hrs, re calibrate body angle sensor.	1/02/2024 2:4		Hours	.00	2.50	\$449.00
	52667	6000hr Service - 11971 hrs	17/06/2024 1	11971.00	Hours	.00	12.00	\$4908.28
	53554	Off / Pre Hire - 12003hrs - Completed off-hire inspection	9/08/2024 3:4		Hours	.00	.00	\$249.85
	53627	Off / Pre Hire - 12019hrs - Completed off-hire inspection. Replace front PTO pump O-ring. Replace pump suction hose barb fitting on rear of hyd tank and filled(30L).	9/09/2024 11:		Hours	.00	.00	\$1124.48
	53743	Off Hire Inspection - 12045hrs - Completed off-hire inspection. Replaced RHS steer cylinder bearing. Replaced door strut.	11/10/2024 8:		Hours	.00	.00	\$960.33
	53829	Hydraulic leak under belly guards - 12144hrs - Replaced hose from P2 to control valve.	13/11/2024 1		Hours	.00	.00	\$858.54
	53893	Off/Pre-Hire - 12195hrs - Resealed LH steer cylinder, bled system and tested. Replaced LHF PTO O-ring. Replaced turbo drain O-rings.	6/12/2024 2:4		Hours	.00	.00	\$812.50
	54125	C/O Pos 3 tyre/rim - hrs, Removed J3994R-17/TN8 4255 and fitted ECJ0261S0A/322-032-P6, tyre only lasted for 1 hour, removed ECJ0261S0A/322-032-P6 and fitted F8S382035/TN8 4273	13/03/2025 1		Hours	.00	.00	\$931.88
	54281	Off/Pre-Hire - 12483hrs - Trouble shoot & Repaired broken seat switch harness. Replaced reverse light bulb. Replace 2 x idler pulleys	29/05/2025 2:		Hours	.00	.00	\$1201.52
	54244	500hr Service - 12484 hrs, replaced seat air line joiner.	29/05/2025 3:	12471.00	Hours	.00	.00	\$1425.18
	54285	Replace Cab Door Glass -12483 hrs (Back Charge Shadforth Joyner)	9/06/2025 12:		Hours	.00	.00	\$545.50
	54400	Off/Pre-Hire - 12554 hrs. unblocked grease hoses on tailgate, blew out a/c filters.	23/06/2025 1		Hours	.00	.00	\$172.74
	54789	1,000 Hr Service - 13,013 Hrs. - Reset body sensors. - Repaired air leak under seat. - Replaced grease hose on LH tailgate bearing.	28/10/2025 1	13013.00	Hours	.00	.00	\$2763.30
	54945	Replace worn out Dovetail plate in body - 13,061 Hrs	19/01/2026 1		Hours	.00	.00	\$3136.02
	54914	Off/Pre-Hire Inspection - 13,061 Hrs. - Replaced POS 3 bellow. - Replaced RH circle LED liiht. - Replaced RHS lift	2/02/2026 12:		Hours	.00	.00	\$6079.91

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		cylinder bearing. - Replaced alternator tensioner. - Replaced A/C primary and secondary air filters. - Cleaned windscreen washer jets and top up washer fluid. - Replaced reverse beepers. - Repaired damage taillight wires. - Striped floor and seat to remove smell from cabin from last hire.- Removed/ refit hub backing plates for cleaning - Replaced a/c compressor and receiver dryer due to leakage - work conducted by Millers.					
	:	<u>164</u>	<b>Asset Total:</b>	<b>1006</b>	<u>0.0</u>	<u>1266.0</u>	<u>\$273,590.06</u>
	:	<u>164</u>	<b>Parent Total:</b>	<b>TPH</b>	<u>0.0</u>	<u>1266.0</u>	<u>\$273,590.06</u>
		<b>Grand Total</b>			<u>0.0</u>	<u>1266.0</u>	<u>\$273,590.06</u>