

Ford Fleet Care – Repair Summary

Vehicle Information

VIN: 1FMCU9GX3FUB01703

Unit Number: 291X8402

License Plate: UXB2923

Model: 2015 Ford Escape 1.6L

Repair Section 1

Valve Assembly – \$59.80

Labor – \$495.00

Transmission Repair

Automatic Transmission Assembly – \$3,144.84

Transmission Oil – \$41.31

Oil Cooler Assembly – \$60.33

Labor – \$2,475.00

Dealer Discount – -\$2,860.74

Total Cost: \$3,415.54

Repair Notes

Fault code P26B7 traced to coolant bypass valve. Replaced valve.

Transmission failure identified with metal in fluid.

Transmission and cooler replaced. Vehicle tested and verified.