



VEHICLE MAINTENANCE RECORD

Fleet Number	072
Registration Number	XN 76 FP
Engine Number	9061100206535
Chassis Number	WDB9702782K593700

Vehicle Make	2001 Mercedes Benz Atego 1223
Registration Due	25th November
Vehicle Type	Rigid

[illegible]

MURPHY TRANSPORT SOLUTIONS PTY LTD

Vehicle Maintenance Record

Fleet Number 72.

Vehicle Make MERCEDES

Registration Number XN 76 FP.

Date Registration Due 25-11

Engine Number

Date E.A. License Due

Chassis Number WDB9702782K593700.

Vehicle Type 6x4 ATEGO.

Date	Mileage	Work Performed	Mechanic	Approx Time
27.10-20		Replace LHS wiper blade.		
8-10-20		Fit up new RHS window winder handle		
3-11-20.		Crowhurst call in inv 278586. Heater fan not working found faulty fan speed resistors		
		fit new resistors. Fan motor drawing too much current replace faulty motor.		
30.11.20		Bridgestone 2950176878. TYRE	299-78	
16.12.20.		Coolant leak. Replace breather hose between top of radiator and header tank and from header tank to top front of motor		
		top up coolant pressure test (ok)		
6.1-21.		Breakdown Kingsgrove noise in RHS steer wheel truck towed to. Hi torque		
7.1-21.		Hi TORQUE INVOICE NO 687742		
		Check wheel bearing on steer axle fit new wheel bearings as required.		
		Carry out B service		
		Replace brake pads drive (2) axle and 3rd axle		
		Replace steer axle sway bar bushes		
28-1-21	Jack up	Check out steering movement. Pressure test cooling system for leaks		
17-2-21		Repair broken wiring clearance light LHS between rear axles.		
25-3-21		RMS. Defect brackets for both sides of pumper broken. headlights moving around make up brackets and fit		
		Check steer axle u-bolts LHS		
		remove RHS steer u-bolt nuts. replace with harden washers. PRO		

Date	Mileage	Work Performed	Mechanic	Approx Time
		tighten with air gun then with strong bar and pipe. take to C & S, to clear defect		
8-4-20		Check out for coolant leak, leaking from cabin heater hose to header, tank tighten hose clamp. Pressure test and stop leak.		
14-4-20		RHS. SPOTTER MIRROR glass. knocked out by truck passing. fit up new glass. adjust mirror.		
11-3-21		REPLACE BLOWN GLOBE IN LHS BRAKE LIGHT.		
20-4-21		REPAIRS TO RHS. BOTTOM STEP.		
16-6-21		REPLACE RUBBER HEATER HOSES BETWEEN FIREWALL & RADIATOR HEADER TANK.		
26-10-21		CHECK & ADJUST TYRE PRESSURES.		
11-11-21		REGO CHECK. FIT NEW EXHAUST BREATHER FILTER TO AIR DRYER. REPLACE AIR TANK DRAIN VALVE.		
16-11-21	80992.	FIT NEW CLUTCH & BRAKE PEDAL RUBBERS.		
17-11-21		REGO INSPECTION. MAKE UP FLOOR MAT RIVERSIDE.		
19/11/21		FIT NEW POLE & HANDLE TO O/S/F. CURTAIN. CROWHURST LOOKED AT AIR CON.		
23/11/21		ENGINE CHECK & CHASSIS LUBE		
20/11/21		REGO PAYMENT. BILLING # 26423273.		
21/1/22		New radio, remove & supply, fit new battery terminal #280782		
16/3/22		New batteries, supply & fit #281258		
27/4/22		Tyre replacement POS 2 #2720089312		
6/6/22		Tyre replacement POS 5,6,7,8 #87846281		
6/9/22		Air con fix #282089		
8/11/22		Tyre replacement POS 11,12 #88655213		
27/5/22		B Service New centre bearing #700149		
23/9/22		3rd axel R/H air bag replaced #50822		
25/10/22		P/steer line leak, air bag reset #703482		
17/11/22		3rd axel L/S excess movement #703977		
25/1/23		Radiator and hose replacement #57114		
14/12/22		Air bag rod replacement #XA940011012		
9/3/23		B Service, driver seat replacement. #706238		

Vehicle Maintenance Record

Vehicle Type 6x4 ATECO

[illegible]