

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3584	TYRE	18/03/2026	18/03/2026	117,211		0		Internal Workshop Fitted two new steer rims (old ones didn't sit properly on the hub and caused a vibration) with two new tyres and two balance bags Replaced two broken tarp feet on trailer last pole Found and repaired major air leak on drawbar	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3583	hub seal	23/02/2026	04/03/2026	111,135		0		Internal Workshop Replaced leaking hub seal on passenger side second drive, inspected bearings (okay), washed down all contaminated parts, torqued preset bearing to spec, torqued axle to spec, fitted new brake shoes and brake drum, fitted fresh hub oil Replaced to drive tyres on passenger side second drive Completed A service Fitted mud flap to trailer	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3067	ABS light, air leak, Mudflaps, Tarp, TYRE	11/12/2025	12/12/2025	94,239		0		Internal Workshop Fitted 2 new trailer tyres to 3rd axle passenger side Repaired broken tarp cable Repaired broken ABS wiring harness Fitted 2 new drive mudflaps Fitted bolt to passenger mudguard Repaired 3 air leaks at draw bar Repaired air leak at hoist Inspected diff sensors and plugs	\$0.00
S-1842	A - 10k	12/12/2025	12/12/2025	92,083 10,583	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1841	A - 10k	16/10/2025	16/10/2025	81,500 10,372	0	0		Internal Workshop Completed "A" service.	\$0.00
R-2786	TYRE	04/08/2025	04/08/2025	76,714	0	0		Internal Workshop PLUGGED TYRE 1 X PLUG	\$0.00
S-1839	A - 10k	17/03/2026	04/06/2025	71,128 8,930	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1017	A - 10k	02/04/2025	02/04/2025	62,198 9,806	0	0		Internal Workshop -A service completed	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1787	TYRE	13/02/2025	13/02/2025	56,718	0	0		Internal Workshop found 5 different holes in steer tyres in tread and on sidewall, Replace steer tyre with second hand steer tyre in shed scrap 1x steer tyre due to sidewall puncture	\$0.00
R-1616	tarp cable	21/01/2025	20/01/2025	54,641	0	0		Internal Workshop Loosen Tarp tensioner. Refit tarp bows to correct position. Remove snapped tarp cable bracket Tension tarp cable and ensure correct Operation.	\$0.00
R-1599	trailer connector	20/01/2025	16/01/2025	54,100	0	0		Internal Workshop Replace Tpin trailer plug Replace Tpin Trailer socket	\$0.00
S-1840	B - 50k	07/01/2025	07/01/2025	50,039 19,036	0	0		Internal Workshop Completed "B" service.	\$0.00
S-1016	A - 10k	07/01/2025	07/01/2025	50,039 9,039	0	0		Internal Workshop A service completed	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1258	Mudflaps	04/12/2024	04/12/2024	47,498	0	0		Internal Workshop Put mudflap back on replaced hose clamp	\$0.00
R-1153	OIL LEAKS	19/11/2024	28/11/2024	46,549	0	0	473	Internal Workshop - Checked tightness of power steer reservoir cap... found to be loose. - Tighten cap + clean entire reservoir - Check for leaks all okay	\$0.00
R-1154	Mudflaps	19/11/2024	27/11/2024	46,483	0	0	474	Internal Workshop - Replace missing RHR drive mudflap with new.	\$0.00
R-1155	hoses	19/11/2024	19/11/2024	44,039	0	0	475		\$0.00
S-1514	A - 10k	19/11/2024	19/11/2024	41,000 9,997		0		Ely Cameron	\$0.00
R-969	mudflap	10/10/2024	10/10/2024	35,669		0		Riley Watters Replace missing LHR mudflap with new	\$0.00
S-814	C - 100k	28/09/2024	28/09/2024	31,003	0	0		Internal Workshop C Service Carried out A Service Checked all Levels. All ok	\$0.00