

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3690	airbag	16/04/2026	10/04/2026	1,111,989	0	0		Internal Workshop replaced L/H 2nd axle airbag	\$0.00
R-3697	tyres	30/03/2026	30/03/2026	1,108,484	0	0		Internal Workshop fit 4x drive tyre to L/H axle 1&2 fit 1x trailer tyre & rim to R/H 3rd axle	\$0.00
R-3594	Airbag	26/03/2026	13/03/2026	1,000,000	0	0		Internal Workshop Diagnosed blown airbag on dolly Found one in truckline marulan stock Replaced blown airbag Checked for air leaks All okay	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3411	Air System	02/03/2026	02/03/2026	1,087,664	0	0		Internal Workshop Inspected truck for air leaks, found faulty governor valve leaking air through exhaust port. Found D/S 1st drive brake booster to have a faulty service diaphragm. Checked all components for serviceability - all in working condition.	\$0.00
R-3593	Breakdown	27/02/2026	27/02/2026	1,000,000		0		Internal Workshop Breakdown call out getting hot Found broken coolant hose Replaced broken coolant hose Refilled missing coolant, got engine hot, checked for leaks, all okay Rechecked level and topped up Fitted to grain locks to trailer Repaired puncture on drive tyre	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3421	Air System	12/02/2026	12/02/2026	1,087,664	0	0		Internal Workshop Removed and repaired melted air lines that were rubbing on exhaust, cut out damaged sections, installed joiners and relocated to an optimal position. Checked all components for serviceability - all in working condition.	\$0.00
R-3715	air leak, tyres	10/02/2026	10/02/2026	1,087,664	0	0		Internal Workshop 2x tyre R/H 1st axle replacement major air leak repaired	\$0.00
R-3717	diff leak, water pump	06/02/2026	06/02/2026	1,000,000	0	0		Internal Workshop replace water pump replace first diff pin on seal	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3417	Cooling system, Driveline	06/02/2026	06/02/2026	1,087,664	0	0		<p>Internal Workshop Drained coolant from system, removed belts and surrounding hardware, removed water pump and cleaned mating surfaces. Installed new water pump and seals, re-fit belt and surrounding hardware, cycled engine to operating temperature and observed for any leaks - none found. Disconnected tail shaft, removed yolk and nut, removed input pinion seal cleaned area and installed new seal, installed yolk and nut and torque cap end bolts to spec, reconnected tail shaft and torqued bolts to OEM specification. Tested all components for serviceability - all in working condition.</p>	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3719	air compressor, air leak, Brake Booster, mudguard, TYRE	04/02/2026	04/02/2026	1,000,000	0	0		Internal Workshop replaced faulty governor valve replaced faulty brake booster 2x trailer tyres R/H 2x trailer tyres L/H replaced damaged guards checked for air leaks	\$0.00
R-3721	airleak, Radiator	02/02/2026	02/02/2026	1,000,000	0	0		Internal Workshop repaired broken draw plug re check air leaks @compressor discharge hose and remove	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3415	Air System, Cooling system	02/02/2026	02/02/2026	1,087,664	0	0		Internal Workshop Removed seized drain plug from bottom radiator elbow and installed new one, filled cooling system with coolant and pressure tested - all successful. Inspected truck for air leaks and found compressor main discharge line to be faulty, removed failed parts and had new hose made. Installed new parts and tested all for serviceability - all in working condition.	\$0.00
S-1936	A - 10k	19/01/2026	19/01/2026	1,083,540 10,528	0	0		Internal Workshop Completed "A" service.	\$0.00
R-3108	ELECTRICAL, Mudflaps	17/01/2026	17/01/2026	1,082,914	0	0		Internal Workshop Replaced mudflaps, replaced and re-wired trailer plug.	\$0.00
S-1932	A - 10k	30/11/2025	30/11/2025	1,073,012 9,967	0	0		Internal Workshop Completed "A" service.	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3547	wheel nut indicators	28/10/2025	22/10/2025	1,063,752	0	0		Internal Workshop took to sparkys to get alarm fitted, fitted wheel nut indicators	\$0.00
S-1928	A - 10k	28/09/2025	28/09/2025	1,063,045 10,034	0	0		Internal Workshop Completed "A" service.	\$0.00
S-1927	A - 10k	08/08/2025	08/08/2025	1,053,011 9,915	0	0		Internal Workshop Completed "A" service.	\$0.00
R-3595	mudguard	17/07/2025	17/07/2025	1,052,931	0	0		Internal Workshop fitted new mud guard, tightened all mug guards, fixed bent locking tooth	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3502	Brakes, ELECTRICAL, hubseal, Mudflaps	30/06/2025	30/06/2025	1,043,515	0	0		Internal Workshop Removed wheels on both drive axles, stripped foundation brakes and hubs to stub axles. Inspected bearings and hubs - found worn bearing cones and bearings. Replaced bearing cones and bearings and fit new hub seals, installed new brake linings and supporting hardware and fit hubs, fit new brakes drums and adjusted bearings to specification - filled with oil. Re-fit wheels and torqued wheel nuts to specification. Repeated process on steer axles. Fit new mudflaps to truck, inspected damaged wiring loom at drawbar and replaced damaged parts, cable tied hoses and loom.	\$0.00