

# Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-461	Puncture	04/02/2026	04/02/2026	108,195		0		Removed puncture and plugged tyre on 5th axle lhs inner. Parts used: tyre plug Parts from: NJ Ashton's stock	\$0.00
T-459	Puncture	06/02/2026	04/02/2026	108,546		0		Removed nail and plugged 5th axle inner lhs tyre. Parts used: tyre plug Parts from: NJ Ashton's stock	\$0.00
S-1695	C - 100k	20/11/2025	20/11/2025 499	99,782		0			\$0.00
S-1638	A - 10k	18/09/2025	18/09/2025	87,950 29,997	0	0		Internal Workshop	\$0.00
S-1694	B - 50k	01/09/2025	01/09/2025	90,735 66,544		0			\$0.00
S-1704	A - 10k	13/08/2025	13/08/2025	81,275 19,443		0			\$0.00
R-2595	mudguard	02/07/2025	02/07/2025			0	1645		\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-2756	TYRE	12/06/2025	12/06/2025	78,836	0	0		Internal Workshop replace drive Tyre with runout due to sidewall damage. Tension wheel nuts 1 x runout drive tyre 11RX22.5	\$0.00
R-2342	fuel	11/06/2025	11/06/2025	78,480	0	0	1502	issued truck with fuel tag	\$0.00
R-2346	mudflap	13/05/2025	13/05/2025	74,831	0	0	1338	replaced damaged mudflap truck sent away to get crack in tipper body welded	\$0.00
R-2324	TYRE	13/05/2025	13/05/2025	74,831	0	0	1337	replaced 1 steer tyre running low on tread	\$0.00
R-2313	beacon	13/05/2025	13/05/2025	74,831	0	0	1336	found faulty beacon light. Replace with new. Test ok	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-2305	tarp cable	13/05/2025	13/05/2025	74,831	0	0	1339	found frayed tarp cable. Removed old cable and replaced with new	\$0.00
T-400	Drive	29/04/2025	29/04/2025	72,283		0		Orkhan Combe Replace LH 2nd drive outer tyre with runout + tension	\$0.00
R-2148	shock absorber	28/04/2025	28/04/2025	72,283		0		Ely Cameron Remove + replace shock absorber with new	\$0.00
R-2137	Tarp	22/04/2025	22/04/2025	71,265		0		Replace chain master link + re-tension gearbox pulley	\$0.00
S-1693	A - 10k	20/03/2025	20/03/2025	61,832 3,879		0			\$0.00
S-1402	A - 10k	19/02/2025	19/02/2025	57,953 21,877	0	0		Internal Workshop A service due	\$0.00
S-1010	A - 10k	19/02/2025	19/02/2025	57,953 21,877	0	0		Internal Workshop A service	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1608	Tarp	17/01/2025	17/01/2025	53,454	0	0		Internal Workshop Remove old snapped tarp cable Refit new tarp cable Adjust tarp cable and ensure correct operation	\$0.00

Generated at: 29/05/2026, 1:42:11 pm