

81314	XS10DQ / L	Spare / Tim B			replace both LH & RH Windscreens	Obrien's / Murray Bridge	4/07/2025		
81212	XS10DQ / L	Tim B	A	775946 km	check all fluid levels , grease and brake adjust , top up auto greaser , clutch adjustment , replaced mud guard LHS drive axle found bearing to be worn remove and replaced ,	Glen Artney	6/06/2025	Inv - 80099	1 x MG620.DB BK blue mudguard , 4 x mud guard brackets , 1 x Kenworth mud flap , 1 x 6201 bearing , 1 x reinforcement mud flap , 1 x K036-235 clutch pedal bell crank bearing , 1 x 1/2"nut , 4 x Gr8 bolt & nuts & washers & body washers ,
80360	XS10DQ / L	Tim B		762860 km	remove old clutch and fit new as found broken spring in bottom of bell housing / remove exhaust , belly bar , all wiring, and hoses , remove clutch and fly wheel , remove gear box , replaced rear main seal , fit machined fly wheel, fit new Eaton clutch install kit , adjust clutch, and take for test drive	Glen Artney	24-May-25	Inv - 79236	1 x CP25RPLS1 uni joint , 1 x 4965569 rear main seal , 2 x 2866337 Cummins 5"exhaust gasket , 1 x HM gem machine flywheel , 8 x CSC82052 bolt drive line , 1 x 3/4x2-1/2xunf , 1 x 3/4 unf nyloc nut , 2 x 3/4 flat washer , 1 x 308935-531 PAC EP ADV clutch , 1 x K-4450-PAC clutch kit inc KW x shafts ,

80686	XS10DQ / L	Tim B	B	762847 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , check turn table adjustment , top up auto greaser , check all other fluid levels , check all lights work - any problems please call / found broken spring in bottom of bell housing - ??? / Replaced all drive shocks , replaced brake LHS , tighten all loose mud guard bolts , replace through shaft seal ,	Glen Artney	24-May-25	Inv - 79259	1 x R945008 seal through shaft , 1 x KIT2637 nut through shaft , 1 x 2210V7536FW Meritor RH drive S-cam , 1 x KIT8042 meritor S/cam repair kit , 1 x KSMA3124707QP Meritor Q plus brake shoe , 1 x 101289 manual slack adjuster , 4 x C71-1006 koni shockers , 1 x 47693S drive wheel seal , 2 ltr x diff oil 85W/140 , 2 ltr x ATF oil , 45 ltr x engine oil , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element , 1 x AS2474 air oil separator , 1 x UF110 AdBlue filter , 1 x 25189011 filter pollen ,
80689	XS10DQ / L	Tim B			plug in and check ECM Cummins calibration	Cummins / Tamworth	23-May-25		
80433	XS10DQ / L	Tim B			2 x wiper blades , 1 x 20 ltr truck wash	brown & Hurley / Tamworth	2-May-25	Inv - 3522036	
80252	XS10DQ / L	Tim B		743057 km	front diff pinion seal leaking , exhaust flex has hole ?? / Replaced pinion seal , tighten clamp on exhaust flex , replaced LHF shock , top up diff oil ,	Glen Artney	12-Apr-25	Inv - 78363	1 x R945007 pinion input seal , 1 x KIT2638 pinion nut , 1 x R945008 seal through shaft , 1 x KIT2637 nut through shaft , 1 x KWK374-38KIT drive shock air glide 400/460

80177	XS10DQ / L	Tim B		737076 km	custom air wouldn't start , check oil was low top up still not running need to look at it later , replace through shaft seal , remove diff breather hoses as worn - fit new & fittings , remove and replace height control valve , air dryer leaking , remove and replace with new , LH steer axle wheel seal leaking , remove bearings and clen hub , replaced anchor pin bushes , replace brake shoes & brake drum , fit new hub cap gasket , check brakes and adjust ,	Glen Artney	4-Apr-25	Inv - 78249	1 x R945008 seal through shaft , 1 x H00600P height control valve , 1 x 620300 turbo 2000 air dryer , 1 x 43764 steer wheel seal , 1 x KSMA2124715QP steer brake shoe , 1 x 453795CR (330.3067STM) hub cap gasket , .5 ltr turbo 40 oil , 1 ltr x diff oil 85w/140 ,
78879	XS10DQ / L	Simon	C	726416 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , check other fluid levels , top up auto greaser , adjust turn table , service custom air , remove tail shaft and replace uni joint new , replaced P-clamp on compressor hose , replace custom air mounts , fit tap to air dryer and replace filter , change diff oil & filter , change air filters	CHM Shed	18-Mar-25	CHM - 12281	40 ltr x diff oil 85W/140 , 49 ltr x engine oil , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron filter , 1 x UF110 replacement element AdBlue , 1 x X011623 air cleaner element , 1 x 637 oil filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 5 x SU-TM custom air rubber bushes , 2 mt x 80377 air brake hose 1/2" , 1 x T224 air dryer cartridge , 1 x CP25RPLS1 uni joint , 1 x 231721-08 1/2 ball valve , 1 x PGXLVITAL 20 ltr coolant , 1 x 0892333 windscreen cleaner , 1 x auto grease , 1 x 25189011 A?C filter , 1 x P14362-028 cushioned 3/4"clamp
78865	XS10DQ / L	Simon			AdBlue line broken / melted between pump and the injector	Glen Artney	16-Mar-25		

80015	XS10DQ / L	Simon		724674 km	inspected adblue issue , found adblue injector hose damaged , refit injector , inspect issue with steering - jack up front end , check steer bearings & kingpins & all steering joints all OK , replaced bolt in pitman arm as it was loose ,	Glen Artney	16-Mar-25	Inv - 77810	
80301	XS10DQ / L	Simon			1 x 22 ltr truck wash , 2 x connector 1/4 - 3mm	Brown & Hurley / Tamworth	15-Mar-25	Inv - 3478170	
78484	XS10DQ / L	Simon	Call Out	703700 km	Travel to Blayney - truck want build up air - only build to about 200/300 PSI - on inspection air compressor had failed , so replaced with new and replaced governor valve as well ,	Inland Trucks / Orange	10-Feb-25	Inv - S204922	1 x 3690864RX recon air compressor , 1 x 4988280 gasket hydraulic pump , 1 x 5440813 gasket ACC drive support , 2 x 3627695 seal O-ring , 2 x 3046201 seal O-ring , 1 x 275707 valve governor ,
78422	XS10DQ / L	Simon	A	702458 km	check all fluid levels , grease and brake adjust , check all lights work , top up auto greaser (DON'T OVER FILL) , repaired wiring for LHS taillight , replaced all 4 x battery with new , removed and replace idler pulley , also found bearing in alternator failing , so fit new alternator ,	Glen Artney	8-Feb-25	Inv - 77107	1 x 3689465 idler pulley , 1 x 6PK1590 belt (3103233) , 1 x LBP2189GH alternator LN 160A pad mount , 4 x 122112 century battery's (N70ZZHX) , 3 ltr x engine oil ,
78183	XS10DQ / L	Simon			1 x blue mudguard & 2 x mudflaps	Gilbert & roach / Tamworth	11-Jan-25	Inv - 3428895	1 x K127-1116-09A mudguard , 2 x LS2417-WRCKW mudflap-lowspray

78106	XS10DQ / L	Simon			1 x light lead	Inland trucks / Dubbo	6-Jan-25	Inv - 1025560	
78966	XS10DQ / L	Simon	B2	673539 km	change engine oil & filters , grease and brake adjust , top up auto greaser - DON'T OVER FILL , check all lights work , check all other fluids , check turn table adjustment / replaced AdBlue injector fitting , tighten up belly bar bolts , replaced rear drive shock rubbers , repaired wiring to tank lights , adjust clutch , replaced fan belt tensioner , rekit horton fan ,	Glen Artney	8-Dec-24	Inv - 75928	1 x LF14000NN oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter , 1 x AS2474 air /oil separator , 1 x UF110 AdBlue filter , 1 x 25189011 filter pollen , 1 x windscreen cleaner , 1 x F35008OB ht/s outback upgrade kit , 6 x 3/8 unf nyloc nut , 1 x 715-8016-006 AdBlue connector elbow , 4 x K066-310 shock mount bush , 1 x NAR56452 2 way male connector waterproof , 1 x NAR56462 2 wat female connector waterproof , 2 x NAR56231 terminal w-pack male , 2 x NAR56230 terminal pins , 45.88 ltr x engine oil
78813	XS10DQ / L	Simon			1 x 22 ltr truck wash , 1 x TRP38WS sponge bug dual	Brown & Hurley / Tamworth	20-Nov-24	Inv - 3383880	
78528	XS10DQ / L	Simon	B2	650905 km	change engine oil & filters , change fuel filters , grease and brake adjust , top up auto , check other fuilid levels , check over , check diff oil , check turn table adjustment	Glen Artney	26-Oct-24		replaced blown dash globes , replaced RHF anchor pins & bushes & shimmed S-cam , repacked wheel bearings , fit new gasket , removed tail shaft - remove and replace seal & new uni bolts , replaced RHR slack adjuster ,
78426	XS10DQ / L	Simon			possible coolant leak behind turbo ??	Cummins / Tamworth	11-Oct-24		

78415	XS10DQ / L	Simon			1 x coolant , 1 x engine oil	Glen Artney	11-Oct-24		
78303	XS10DQ / L	Simon			1 x 22 ltr truck wash , 1 x 2361hella jumbo led lamp , 2 x 95968500 rim-S/Steel suit , 10 x 001851 lug nut covers , 1 x TRP38WS sponge bug dual	Brown & Hurley / Tamworth	19-Sep-24	Inv - 3325611	
77879	XS10DQ / L	Simon		620076 km	check speed sensor / wiring and change the RPM setting	Cummins / Tamworth	22-Aug-24	Inv - 1367419	found broken wire in VSS sensor - repaired and reset parameters
77835	XS10DQ / L	Simon		616089 km	still Derated and want go over 1500RPM	Central West Diesel / Forbes	14-Aug-24	Inv - S28595	reset sensor gap for VSS , got truck going but will need to rewire VSS / need to get ruck booked into Cummins to rectify issue
77825	XS10DQ / L	Simon			truck want go over 1500 RPM - was speed sensor	Inland trucks / Dubbo	14-Aug-24		
77684	XS10DQ / L	Simon	B	614814 km	change engine oil & filters , top up auto greaser , check all lights work , check and adjust turn table , clutch adjustment	Glen Artney	3-Aug-24	Inv - 73556	remove and replace steering box , bleed system and top up , remove and replace indicator on bonnet , replace exhaust rubber mounts , replace LHS drive axle front axle , tighten loose drive shocks , replace blown dash globes , remove, and replace LHR clearance lights ,
77285	XS10DQ / L	Simon		591722 km	lacking power - tune up and possible turbo / waste gate	Cummins / Tamworth	21-Jun-24	Inv - 1283034	checked turbo and waste gate all OK , flush doser both wet & air side all OK , replaced solenoid , also found loose earth to clutch pedal position switch

77177	XS10DQ / L	Simon			1 x gasket , 1 x clamp 5"V-band , 2 x rim stainless steel	Brown & Hurley / Tamworth	24-May-24	Inv - 3213856	
76968	XS10DQ / L	Simon	B2	573657 km	change engine oil & filters , change fuel filters , grease and brake adjust , top up auto , check other fluid levels , check over , check diff oil	Glen Artney	17-May-24	Inv - 72049	replaced fan belt & A/C belt , replace both front and rear engine mounts , tighten radiator X brace , replace middle steering uni , repositioned shoe in drum , retrieved s-cam and shim and adjust brake , replaced wiper blades , replaced front diff oil , replaced governor valve , top up coolant & oil bottles ,
76805	XS10DQ / L	Simon	Call Out	556864 km	oil leaking -	Cummins / Tamworth	22-Apr-24	Inv - 1232125	front cover bolts were loose
76950	XS10DQ / L	Simon			Ice Pac repair - remove engine to strip down and repair , refit engine , Regas , run and test , replaced alternator ,	Mick Collyer	20-Apr-24	Inv - 3244	
76758	XS10DQ / L	Simon			LH mirror bracket & 4 x lug nut covers	Brown & Hurley / Tamworth	18-Apr-24	Inv - 3181714	
76810	XS10DQ / L	Simon			top up auto greaser	Superior Diesel / Tamworth	9-Apr-24	Inv - SDM71	

76479	XS10DQ / L	Simon	Call Out	543833 km	clutch linkage fallen off	Port Augusta / Andrew	2-Apr-24	Inv - 0863	Meet driver at the OTR at Port Augusta , discovered adjustment arm for clutch had fallen off , replaced with new one and adjust clutch
76446	XS10DQ / L	Simon	A	534635 km	check fluid levels . Grease and brake adjust , top up auto greaser , check all lights work , replace dash globe , tighten earth wire on alternator , replace drive shock	Glen Artney	8-Mar-24	Inv - 70897	
76405	XS10DQ / L	Simon			1 x 20 ltr truck wash	Brown & Hurley / Tamworth	21-Feb-24	Inv - 3129979	
76172	XS10DQ / L	Simon			2 x 1/2"air hose , 1 x front marker light , 1 x trailer socket	Truckline - Tamworth	2-Feb-24	Inv - 7682993	
76221	XS10DQ / L	Simon	B2	502160 km	change engine oil & filters , grease and brake adjust , check all lights work , replace front indicator on bull bar , fit 2 x new shock RHF side drive axle , replaced wheel seal LHF side drive axle , replaced S-cam bushes & shims , replaced pitman arm bolt ,	Glen Artney	29-Jan-24	Inv - 70130	
75956	XS10DQ / L	Simon		499527 km	top up engine oil & oil bottle x 10 ltr , 1 x 5 ltr coolant	Glen Artney	3-Jan-24	Inv - 69753	

75974	XS10DQ / L	Simon			8 x screw on nut covers , 1 x 22 ltr truck wash	Brown & Hurley / Tamworth	21-Dec-23	Inv - 3080611	
75872	XS10DQ / L	Simon	Call Out	487827 km	Travel to Coolah Hill - failed alternator ,	Inland Trucks / Dubbo	12-Dec-23	Inv - 872275	replaced with new alternator and new belts & new pulley & new belt tensioner
75835	XS10DQ / L	Simon	Call Out	484061 km	after treatment light on & truck has derated	Broken Hill Truck Center	5-Dec-23	Inv - 355599	on inspection found code for air temp sender , remove and replace with new , flushed doser pump and flush injector clear codes
75840	XS10DQ / L	Simon			1 x chrome hubcap	Brown & Hurley / Tamworth	2-Dec-23	Inv - 3063752	
75636	XS10DQ / L	Simon	A	473856 km	check all fluids , grease and brake adjust , check lights work , ice pack not working ??	Glen Artney	18-Nov-23	Inv - 69193	remove and replace power steering pump with new and top up with oil and bleed , change diff oil filter ,
75629	XS10DQ / L	Simon		469966 km	maybe leaking wheel seal LH front drive axle ? - replace brake drum & brake shoes , wash bearings refit with new seals fit wheels and tension , also had to fit new indicator on bull bar , faulty 7 pin plug remove and replace with new plug and test all OK	Glen Artney	10-Nov-23	Inv - 69106	

75507	XS10DQ / L	Simon			2 x rim/Stainless steel , 1 x 22 ltr truck wash	Brown & Hurley / Tamworth	20-Oct-23	Inv - 3022748	
75391	XS10DQ / L	Simon	C	452307 km	change engine oil & filters , grease and brake adjust , top up auto greaser , check all lights work , change diff oil (Synthetic oil) & filter , change air filters , change gear box oil & filter , replace air dryer filter , replace dash light , adjust RH drive wheel bearings and replace gasket , replace leaking through shaft seal , replace drain cocks on air tanks , fit new pinion nut ,	Glen Artney	14-Oct-23	Inv - 68681	
75071	XS10DQ / L	Simon		419140 km	truck boosting to 260 , engine light coming on and off ?? / Remove and replace turbo	Cummins / Tamworth	15-Aug-23	Inv - 9898905	waste gate leaking air - remove turbo replace with new turbo and set waste gate / 1 x 5607734RX recon turbocharger kit , 4 x 4298242 stud , 4 x 4298975 nut lock , 2 x 3922794 seal O-ring ,
74275	XS10DQ / L	Simon	B	410076 km	change engine oil & filters , grease and braker adjust , check all lights work , top up auto greaser	Glen Artney	29-Jul-23	Inv - 67353	repair LH hub cap & fit new gasket , carried out clutch adjustment , inspect turn table , replaced windscreens
74957	XS10DQ / L	Simon			1 x truck wash 22 ltr , 2 x spray fender support / 2 x mud flaps	Brown & Hurley / Tamworth Brown & Hurley / Tamworth	26-Jul-23	Inv - 2942215 - 2945509	Inv

74371	XS10DQ / L	Simon			1 x set of wiper blades	Brown & Hurley / Tamworth	5-Jun-23	Inv - 2892360	
74147	XS10DQ / L	Simon	A	380126 km	check fluid levels , grease and brake adjust ,	Glen Artney	27-May-23	Inv - 66241	
74071	XS10DQ / L	Simon	B2	358519 km	change engine oil & filters , grease and brake adjust , replace fuel filters ,	Glen Artney	19-Apr-23	Inv - 65548	
73744	XS10DQ / L	Simon			1 x mud flap	Brown & Hurley / Tamworth	31-Mar-23	Inv - 2822023	
73475	XS10DQ / L	Simon			1 x connector elbow 1/4 x 3mm	Brown & Hurley / Tamworth	10-Feb-23	Inv - 2761743	
73347	XS10DQ / L	Simon	A	314446 km	check fluid levels , grease and brake adjust , top up coolant 10 ltrs , replace with new radiator cap - all clamps were tight , top up engine oil , service ice Pac (? Hrs) , repair auto grease line	Josh , Luke , Scott	3-Feb-23	CHM - 6483	1 x AE9976132 radiator cap , 1 x AF25550 air filter , 1 x FF5018 fuel filter , 1 x LF637 oil filter

72937	XS10DQ / L	Simon		? km	RH steer seal leaking	Glen Artney	14-Dec-22	Inv - 63391	checked wheel bearing - replaced bearing , replace gasket and seal fill with new oil and tension bearing
72797	XS10DQ / L	Simon	B	290486 km	change engine oil & filters , grease and brake adjust , top up auto greaser	Glen Artney	10-Dec-22	Inv - 63274	
72240	XS10DQ / L	Simon	B	248428 km	change engine oil & filters , grease and brake adjust , check other fluid levels , check all lights work	Glen Artney	7-Oct-22	Inv - replaced 5 blown dash globes ,	
72140	XS10DQ / L	Marty		? Km	truck want rev past 1500 RPM , found speed sensor not reading , check wiring all Ok , replaced speed sensor	Scott	23-Sep-22		
71947	XS10DQ / L	Simon		231584 km	check engine light on	Cummins / Tamworth	1-Sep-22	Inv - 9501238	on inspection found broken earth wire at starter motor
71599	XS10DQ / L	Simon	B	215000 km	change engine oil & filters , grease and brake adjust , check all lights work	Glen Artney	30-Jul-22	Inv - 61446	top up 5 ltr oil drum ,
71264	XS10DQ / L	Simon	A	198921 km	check fluid levels , grease and brake adjust	Glen Artry	18-Jun-22	Inv - 60904	top up engine oil 3 ltr

70959	XS10DQ / L	Wayne S	B	179277 km	change engine oil & filters , grease and brake adjust , check all lights work , adjust clutch	Josh , Mike	6-May-22		
70644	XS10DQ / L	Noah		158747 km	repair broken wire in speedo as it wasn't working	Sam	29-Mar-22	CHm - 4701	1 x 12162188 A/C plug , 2 x 12048074 terminal
70594	XS10DQ / L	Noah	A	158206 km	check fluid levels , grease and brake adjust , check all lights work ,	Luke , Blake	23-Mar-22		
70450	XS10DQ / L	Noah	C	140142 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter , change air filters , found AdBlue hose had popped off refit , check nozzle wasn't blocked	Josh , Josh , Luke	25-Feb-22	CHM - 4561	1 x LF14000NN engine oil filter , 1 x FS19764-10-micron fuel filter , 1 x A3380W1687 filter , 1 x AS2474 air filter , 1 x LF637 oil filter , 1 x UF110 AdBlue filter , 2 x X011623 air cleaner element , 1 x BS.230.N70 diff filter O-ring , 1 x LF3335 fleet guard filter oil , 1 x 25189011 A/C filter
70234	XS10DQ / L	Noah	A	129972 km	check fluid levels , grease and brake adjust , drain both front steer axle oil and replace with new , flush AdBlue lines test all OK ,	Josh	12-Feb-22		
69978	XS10DQ / L	Noah	B	110411 km	change engine oil & filters , grease and brake adjust , top up auto greaser , tune up	Sam , Josh	10-Jan-22	CHM - 4092 - 4277	CHM 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10-micron fuel filter

69638	XS10DQ / L	Noah		104259 km	remove and replace 4 battery , refit ice Pac alternator & new belt , replace missing reflector	Beetle Battery's	Bridge Beaurepairs	Sam	30-Dec-21	Inv - 22-00002010 6412383134 - 4161 040215	Inv - CHM SC -	4 x XN70EX Battery / 1 x XN70EX Bridge battery / 2 x 13A0775 Dayco belts , 1 x SP-2160 ice Pac alternator / 1 x EL84036 reflector amber
69808	XS10DQ / L	Noah	B	92983 km	change engine oil & filters , grease and brake adjust , top up auto greaser ,	Josh , Andrew			3-Dec-21			
69788	XS10DQ / L	Noah	A	77423 km	check fluid levels , grease and brake adjust	Luke , Josh			12-Nov-21			
69318	XS10DQ / L	Noah		61130 km	adjust clutch	Josh G			18-Oct-21			
69298	XS10DQ / L	Bruce N	B	61130 km	change engine oil & filters , grease and brake adjust , top up auto greaser , adjust bonnet hinges	Sam , Scott , Josh G			15-Oct-21	CHM - 3714		1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10-micron fuel filter
68254	XS10DQ / L	Bruce		10300 km	First service ,	Inland Truck / Dubbo			2-Jul-21	Inv - 867230 867229	Inv -	