

80732	XS20CJ / L	Spare		948406 km	plug in and check ECM Cummins calibration ,	Cummins / Adelaide	27-May-25	Inv - 1622292	
81093	XS20CJ / L	Spare /	C	959719 km	change engine oil & filters & fuel filters , change air filters , change diff oil & filter , replace power steering cap washer/seal with new , replace missing fuel rail , replaced leaking fitting on Horton , tighten ice pack mounts , replaced gear stick boot , replaced LH track rod bushes , replaced joiner on leaking gearbox supply hose , carry out tune up & check waste gate , repaired rubbed line behind gear box , replaced P-clamp on compressor feed hose , replaced fan belt tensioner , replaced 2 PPI valves , replaced 2 x guard poles , tighten indicator stalk , ABS fault - found rubbed wire on RH wheel speed sensor	CHM - Shed	20/05/2025	CHM - 12880	40 ltr x 85W/140 diff oil , 39 ltr x engine oil , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter , 1 x HHW0116 AdBlue suction filter , 1 x AS2474 air filter , 1 x LF637 oil filter , 1 x LF3335 fleet guard filter oil , 1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring , 1 x 25189011 A/C filter , 2 x AF351KM air filter , 1 x ATF trans fluid , 2 x 90555396 valve pressure prote , 1 x 37.1869X4X4S dot 1/4x1/4 male , 1 x K042-79 gear boot stick boot , 1 x K042-80 boot shift lever , 1 x 89440 Dayco HD auto belt tensioner , 2 x 839310 track rod bushes , 1 x 62NTA-6 fittings , 1 x 32M03-0604-M3 6mm x 1/4"male connection , 1 x 012503E elbow 1/4 x 1/4 M/F , 2 x CA5452C mud guard pole
80489	XS20CJ / L	Josh		952560 km	after treatment light on / remove and replace 4 x new battery's / tested alternator and was putting out 14V & 13.5V at battery's , tested all 4 battery's 2 were faulty and the other 2 not good	Cummins / Tamworth	7-May-25	Inv - 1615523	4 x 5563486 battery's
80938	XS20CJ / L	Josh		928491 km	lost prime - unblock injector , replaced tilt cable for steering wheel , adjust steering wheel , free up seized deck	CHM Shed	4/04/2025	CHM - 12419	1 x 450205F steering cable
80271	XS20CJ / L	Spare / Beetle			replaced both LH ( KW1647 ) & RH ( KW1648 )windscreens	Obrien's / Windscreen	28-Mar-25	Inv - 1354	
78809	XS20CJ / L	Beetle		922476 km	after treatment light on ! - found active fault for fuel pump actuator / had no parts	CHM Shed	13-Mar-25	CHM - 12281	

78818	XS20CJ / L	Beetle			2 x mud flaps bull bar , 2 x white rear mudflaps	CMV / Adelaide	12-Mar-25	Inv - I31132315	
78694	XS20CJ / L	Spare / Jamie H			fit new inverter & battery both supplied by TAL , run wiring & fit DC-DC battery charger	Ryans Auto	10-Feb-25	Inv - 0535	1 x DC-DC battery charger 25A
78784	XS20CJ / L	Jamie H / Spare	B	905186 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , check turn table adjustment , top up auto greaser , change bottom heater tap , replace through shaft seal , clean diff breathers , replace LH mudflap	Glen Artney	6-Feb-25	CHM - 11871	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron , 1 x LS2417 mud flap KW , 1 x A1-1205Y2729 diff pinion seal , 49 ltr x engine oil ,
78950	XS20CJ / L	Marty			replace faulty fuel pressure relief valve	Cummins / Tamworth	4-Dec-24		
78882	XS20CJ / L	Dan / Marty			leaking hub steer - driver picking parts up and will do it	Inland Trucks / Dubbo	29-Nov-24	Inv - 1024626	1 x T04-4031CR hub cap CR1643 6 hole T , 1 x 90001-hub hub oil 1 ltr , 1 x CRC05073 degreaser 500G
78604	XS20CJ / L	Ian	B2	893701 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , check turn table adjustment , top up auto greaser , did clutch adjustment , did welding repairs to front diff housing , replaced worn alternator belts , replaced RHS gasket , tighten LHS hub bolts ,	Glen Artney	16-Nov-24	Inv - 75472	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element , 1 x AS2474 air/oil separator , 1 x windscreen cleaner , 1 x NAR56484 P-clamp 22mm , 1 x 6PK1590 belt ( 3103233 ) , 1 x 453795CR ( 330.3067STM ) hub cap gasket , 48 ltr x engine oil , 4 ltr x 80W/140
78464	XS20CJ / L	Spare		874511 km	40 x nut covers , 2 x headlight surround , 2 x drive hub caps / remove old tracker and replace with new / replace clutch - remove RH side gear box & all accessories , reseal rear housing , fit new rear main seal , machined fly wheel , input shaft to gearbox , replace all accessories to gear box , new hemi joints , bell crank bearing , road test	Hy-Way Truck accessories Auto Ryans CHM Shed	15-Oct-24	Inv - 1504742 - 0437 - 11027 Inv CHM	Paid Lou : Trans credit card / 1 x kit clutch installation , 1 x 308938.583PAC clutch , 1 x shaft input RTL022918 , 1 x ISX fly wheel housing gasket , 1 x K160-2353 clutch control lever , 1 x lever , 1 x E55-1128 clutch control lever , 1 x 4965569 kit seal , 2 x K066-421 rear snubber bar , 4 x rod end bearing , 1 x K036-235 bell crank bearing

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

77991	XS20CJ / L	Dave		861003 km	wheel seal leaking RHF drive axle plus need S/Steel guard , check diff oil level	Glen Artney	30-Aug-24	Inv - 73983	inspect RHF wheel seal damaged , replaced S-cams & new bushes , new brake shoes , replaced bearings , fill with oil , refit wheel and tension , check diff oil level , replace stainless steel guard
77812	XS20CJ / L	Dave S	C	854919 km	Change engine oil & fuel filters & oil filters , change air filters , grease and brake adjust , top up auto greaser , change diff oil & filter , check all lights work , check all other fluid levels , change gear box oil & filter , carry out tune up , temporary repair to grill , replaced leaking cab shockers , replaced worn steering shocks , found oil leak at turbo drain - tighten loose pipe , refit intake pipe to turbo , replaced blown dash lights ,	Glen Artney	17-Aug-24	Inv - 73646	1 x LF14000NN engine oil filter , 1 x F5776 fuel filter , 1 x FS19764 element , 1 x AS2474 air oil separator filter , 1 x HHW0116 AdBlue filter , 1 x 25189011 filter pollen , 1 x LF3501 diff oil filter , 1 x LF637 power steering oil filter , 1 x WF2127 coolant filter , 2 x AF351KM air filter , 1 x 6518 oil sample , 1 x LF3335 oil filter gear box , 2 x 43764 steer wheel seal , 2 x 453795OR hub cap gasket , 49.5 ltr engine oil , 35 ltr synthetic gear oil 80W/140 , 14.2 ltr syn trans 50 synthetic oil , 2 x 090-2209SP3 Koni steer shocks ,
77792	XS20CJ / L	Dave S		851944 km	Air compressor failed - made it to workshop remove and replaced with new compressor & gasket , fitted new governor valve , topped up coolant , gave driver spare governor valve	Swan Hill Trucks	10-Aug-24	Inv - 60745	1 x 3163075 paint , 1 x F4HZ3K506C power steering pump gasket , 2 x 275707N Bendix governor valve D-2 , 1 x 8010-29BSPP M tip 1/2 BSPP F ball 9 DIV ) , 1 x FF5776 fuel filter , 1 x consumables , 1 x 3690864RX recon air compressor E5/X15 , 1 x 3685614 E5 air comp gasket ,
77731	XS20CJ / L	Dave			1 x 7 pin light lead , 1 x 1/2"female coupling , 1 x 1/2"male adaptor	Glen Artney	25-Jul-24	Inv - 73241	

77559	XS20CJ / L	Dave			has no lights on trailers - Could be plug / fuse / lead	TTT	17-Jul-24		
77424	XS20CJ / L	Dave	A	831918 km	check fluid levels . Grease and brake adjust , check all lights work ,	Glen Artney	5-Jul-24	Inv - 72866	replace leaking brake release valve , tighten loose mud guard brackets , replace blown dash globes
76971	XS20CJ / L	Dave S	B2	808197 km	change engine oil & filters , change fuel filters , grease and brake adjust , top up auto , check other fluid levels , check over , check diff oil	Glen Artney	17-May-24	Inv - 72026	topped up oil & coolant bottles , couldn't get custom air to start , replaced missing bolt in spot light , fit new bug deflector , tighten output shaft on front diff , remove and replace LHF wheel seal , remove and replace S-cam & slack adjuster
76598	XS20CJ / L	Dave S			check batteries ?? - tested battery's and they failed , replace with 4 x new battery	Glen Artney	25-Mar-24	Inv - 71103	4 x N70ZZHX Century battery
76444	XS20CJ / L	Dave			top up oil bottle 5 ltr engine oil , top up coolant bottle 5 ltr	Glen Artney	8-Mar-24	Inv - 70856	
76457	XS20CJ / L	Dave	A	764515 km	grease and brake adjust , check all lights work , resealed rear diff - replaced gasket and top up with oil , carry out clutch adjustment , remove and fit new torque rod bush's , refit and tension uni joint on jackshaft	Glen Artney	29-Feb-24	Inv - 70699	
76230	XS20CJ / L	Dave S	Call Out	756996 km	suspected air compressor failed ?	Cummins / Tamworth	15-Feb-24	Inv - 1152313	on inspection found main charge line disconnected under LH side of cab , - line from steel tube to braided hose had come apart - rejoin and tighten
76249	XS20CJ / L	Dave	Call Out		Horsham - golf course road - blown drive air bag , remove and replace with new	Wimmera Trucks / Horsham	5-Feb-24	Inv - HKFSH1202	

75992	XS20CJ / L	Dave	B2	742190 km	change engine oil & filters , check all lights work , and just have a good look over it please	Cummins / Tamworth	12-Jan-24	Inv - 70073	replaced front & rear engine mounts , resealed rear diff , repair LH rear & RH front drive wheels seals leaking rebushed S-cams , replaced brake drum , repaired broken auto grease line , retention wheel bearings & wheel nuts , replaced broken brake booster , , repair RH rear brake light , replace RH rear slack adjuster , adjust clutch , relined RH rear brakes
75578	XS20CJ / L	Dave S	Call Out	696230 km	Tow truck from Larras Lee back to Inland Trucks Dubbo / on inspection failed front diff - remove and replace with new diff centre & seals , fill with new oil & filter , replaced wheel bearings & seals , refit drive shaft , hubs and axles , fit wheels and adjust brakes test all OK	Tow Truck Dubbo / Heavy Haul Inland Trucks / Dubbo	1-Nov-23	Inv - 13229 - 871939 Inv	1 x MP160430 drive head MP 4.30 ratio , 2 x WBK3DCRV kit-W/BRG drive oil CR , 1 x A3380W1687 filter , 2 x 20 ltr 85/140 gear oil , 1 x K1T2638 kit pinion nut , 2 x 2208S1215 gasket axle shaft ,
75812	XS20CJ / L	Dave	B	685911 km	change engine oil & filters , grease and brake adjust , replaced bottom mounts with new , replaced boost clamps	CHM Shed	9-Oct-23	CHM - 8417	1 x FS19764 element 10 micron fuel filter euro 5 , 1 x FF5776 fuel filter , 1 x LF14000NN engine oil filter , 2 x K077-372-66 clamp , 4 x custom air rubber bush 2PC , 1 x LF689 diff filter , 1 x AF25221 air filter , 55 ltr engine oil plus fill spare bottle , 10 ltr 85W/140 diff oil , 5 c 0954.250 green oem advanced 05 rtu 20 ltr

75427	XS20CJ / L	Dave	Call Out		truck want build up air , suspected governor vale / travel to Tocomwal	Grinter's Mechanical / Shepparton	6-Oct-23		Gave credit card details - Lou
75246	XS20CJ / L	Dave		669374 km	front diff weeping oil - cleaned sensor on diff & check oil level all OK ( will need to book truck in for oil leak repair on front diff )	Glen Artney	25-Aug-23	Inv - 67785	
74787	XS20CJ / L	Dave	C	651565 km	change engine oil & filters , grease and brake adjust , check all lights work , change diff oil & filter , change air filters , replaced heater tap , replaced LHR s-cam , refit slack adjuster , replace oil thermostat , replaced starter motor , repair coolant draw down bracket	Reece , Corey	19-Jul-23	CHM - 7556	1 x S16255 ring retaining , 1 x 3336204 seal O-ring , 1 x 4386527 thermostat , 1 x D61-1004-003 starter Paccar DP60 KWA , 0.30 x DCT110H1RW-10P double zip ties , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x LF637 oil filter , 1 x LF3335 fleet guard filter oil , 1 x V404P-10-6 heater tap , 2 x AF351KM air filters , 1 x TRPCAF0001 filter , 1 x HHW0116 AdBlue suction filter , 1 x PGXL 20 ltr coolant
74886	XS20CJ / L	Dave S			3 x prime mover wash	Glen Artney	17-Jul-23	Inv - 00009661	
73845	XS20CJ / L	Dave S	B	604287 km	change engine oil & filters , greaser and brake adjust , check all lights work , top up auto greaser , fit alternator on ice Pac	Glen Artney	21-Apr-23	Inv - 65765	adjusted clutch , fit new charge hose & clamps , LHR axle replaced bushes & seals , install new S-cam and grease , repacked wheel bearings , tension bearing nuts , fit new axle gasket , refit brake shoes &

									brake drum , fit new slack adjuster ,
73844	XS20CJ / L	Dave S		598888 km	remove old cab air bag and replace with new , 1 x 5 ltr engine oil	Glen Artney	19-Apr-23	Inv - 65462	
73221	XS20CJ / L	Dave		558810 km	finish off C service - only had to drop diff oil & filter , change air filters , grease and brake adjust , adjust turn table , replace 4 x new battery , order in alternator for ice pack / remove and replace RH / remove RH side eye bolt & LH side for bonnet spring and replace both with new as one was broken	Glen Artney Glen Artney	3-Feb-23	Inv - 64151 64465 Inv -	replace 4 x shockers
73195	XS20CJ / L	Dave S	B	558631 km	change engine oil & filters , check alternator charge ?	Cummins / Tamworth	27-Jan-23	Inv - 9691299	replace inline air filter for doser unit , replace A/C belt , replaced 1 x boost clamp ,
72944	XS20CJ / L	Dave S			2 x new steer tyres	Bridgestone / Jamestown	19-Dec-22		



72789	XS20CJ / L	Dave		517710 km	Warranty - low liner repair & replace boost hose & clamp , replace intake gasket and fit assembly , replace leaking front crankshaft seal , replace 2 x timing gear idler shafts , adjust waste on turbo , top up coolant and engine oil ,	Cummins / Tamworth	1-Dec-22	Inv - 9597130	replaced engine oil & filters
72705	XS20CJ / L	Dave	Call Out	513708 km	travel to break down at Birriwa , replace alternator and check charge ,	Double R equipment / Mudgee	12-Nov-22	M782858	
72704	XS20CJ / L	Dave	Call Out		1 x alternator -	Glen Artney	12-Nov-22	Inv - 62820	
72195	XS20CJ / L	Dave	C	481873 km	change engine oil & filters , change air filters , change diff oil & filter , grease and brake adjust , check all lights work , replace all drive shockers , replace centre bearing , replace front engine mounts , adjust clutch	Josh , Mike , Scott , Luke , Corey	29-Sep-22	CHM - 5696	1 x LF3335 fleet guard filter oil , 2 x AF351KM air filter , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x BS.230.N70 diff filter O-ring , 1 x FS19764-10 micron fuel filter , 1 x LF637 oil filter , 1 x HHW0116 AdBlue suction filter , 1 x A3380W1687 filter , 1 x AS2474 air filter , 1 x 25189011 A/C filter , 0.25 PGXLVITAL 20 ltr coolant , 2 x K066-405 ISX front engine mounts , 2 x K066-404 front engine mounts , 1 x 5003323PAC centre bearing , 4 x C71-1006 shock absorber-rear SU , 2 x N85-1112 reinforcement mud flaps

71133	XS20CJ / L	Dave	B	419223 km	change engine oil & filters , grease and brake adjust , check all lights work , replace diff filter & O-ring , clean out diff breathers , adjust clutch , replace all new wheel bearings , brake shoes , brake drums & seals , replace S-cams & bushes front drive axle , replace speed sensor , replace oil pressure light sensor , adjust clutch / replace LH KW1647 & RH KW1648 819133	Josh , Mike , Reece , Luke O'Brien's Windscreen / M-Bridge	23-May-22	Inv - 142243 - 4992	CHM	1 x FF5776 fuel filter , 1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring , 1 x 2210W7537FW-KW left S-cam , 1 x 2210V7536FW-KW right S-cam , 1 x K1T9078 kit , 2 x WBK3DCRV drive wheel bearing kit , 2 x DB017TRP-TRP 16.5 x 7 steel jacket , 2 x KSMA3124707QP drive brake shoe kit , 1 x 1745-2334-oil pressure switch , 2 x K077-372-66 clamp , 1 x Q21-6004 duel speedo / tacho sensor
70232	XS20CJ / L	Dave S		370369 km	warranty check over - driver reported speedo not working - check over test drive all OK	Brown & Hurley / Tamworth	22-Feb-22	Inv - 2409666		
70238	XS20CJ / L	Dave S	C	366826 km	change engine oil & filters , grease and brake adjust , top up auto greaser , replace fan belt & tensioner , replace ECM speed sensor , replace coolant drain down hose , rotate steer tyres with another set , replace LH wheel seal drums & brake shoes , replace LH front shocker , repair broken wire from ice Pac to alternator , check winch charge , replace AdBlue filter	Josh , / Adelaide CMV	7-Feb-22	CHM - 4427 I31033315	Inv -	1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter , 1 x FF5776 fuel filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x LF637 oil filter , 1 x 25189011 A/C filter , 1 x BS.230.N70 diff filter )-ring , 1 x D84-1000-3122380 belt fan drive , 1 x HHW0116 AdBlue suction filter , 1 x 89440 Dayco belt tensioner , 1 x 92216 Dayco automotive clamp , 1 x KSMA3124707QP drive brake shoe kit , 1 x DB17TRP - TRP 16.5 x 7 steel jacket , 1 x 47693S wheel seal , 1 x K374-38Kit Paccar drive shock absorber / 1 x HHW0116 AdBlue filter & O-ring

69546	XS20CJ / L	Dave		339638 km	remove LH rear guard , remove LH front air bag and replace with new & refit guard	Glen Artney	26-Nov-21	Inv - 58165	1 x C81-1005 10.5"air bag Ag460
69411	XS20CJ / L	Dave	A	326311 km	check fluid levels , grease and brake adjust , top up auto greaser , replace fan belt	Luke , Josh G	2-Nov-21		
69840	XS20CJ / L	Dave		318436 km	radiator repairs were covered under WARRANTY , other parts weren't covered like hoses & clamps , weld cracks around cross brace & fan shroud , replaced both intercooler hoses , fill with new coolant	Brown & Hurley / Tamworth	10-Oct-21	Inv - 2326879	
69100	XS20CJ / L	Dave	B2	315834 km	change engine oil & filters , grease & brake adjust	Glen Artney	9-Oct-21	Inv - 57449	replaced dash globes ,
68736	XS20CJ / L	Dave		294884 km	front steer and drive alignment	Big Wheels / Tamworth	24-Aug-21	Inv - 14111764	Paid Lou : trans credit card
68735	XS20CJ / L	Dave		294880 km	1 x steering linkage	Brown & Hurley / Tamworth	24-Aug-21	Inv - 2297620	1 x tie rod end A1-3102Q4541

68772	XS20CJ / L	Dave	A	292016 km	check fluid levels , grease and brake adjust , remove steering arm and straighten replace 1 tie rod end and refit , replace wiper blades	Josh G , Josh B	20-Aug-21	CHM - 3590	1 x R230073 tie rod end , 2 x WW610R6 wiper blades
68497	XS20CJ / L	Dave S	C	274846 km	change engine oil & filters , grease and brake adjust , top up auto freezer , change diff oil & filter , change air filters , tune up , remove and replace fan belt and A/C belt , add 3 ltr coolant , adjust waste gate	Sam , Luke , Josh G , Josh B	21-Jul-21	CHM - 3254	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x HHW0116 AdBlue suction filter , 1 x LF637 power steering filter , 1 x 17237 Eaton gear box filter , 2 x AF351KM air filter , 1 x 25189011 A/C filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring , 1 x D84-1000-3122380 fan belt , 1 x 3103233 Fan belt
68163	XS20CJ / L	Dave S		253957 km	had vibration in front end - inspect kingpins for movement , RH rear wheel bearing had slight movement , otherwise everything looked ok	Glen Artney	8-Jun-21	Inv - 55602	
67774	XS20CJ / L	Dave S			truck wash	Glen Artney	23-Apr-21	Inv - 00006018	
67562	XS20CJ / L	Dave S	B	229970 km	change engine oil & filters , grease and brake adjust , check all lights work	Glen Artney	23-Apr-21	Inv - 54742	adjust clutch , drained coolant and replace with new & filter ,

67042	XS20CJ / L	Dave S	B	190696 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser , remove LH front guard pole - cut & straighten , refit and tighten chassis bolt	Luke , Josh G	8-Feb-21	SC - 023108 2652	CHM -	1 x CA5452C bracket chrome chassis / 1 x FS19764 10 micron fuel filter , 1 x FF5776 fuel filter , 1 x LF14000NN engine oil filter
61566	XS20CJ / L	Dave S	A	166407 km	grease and brake adjust , top up auto greaser , check all fluid levels , check all lights work	Josh G , Josh B , Luke	4-Dec-20			
61275	XS20CJ / L	Dave S			1 x Engel cord DC	Jacksons 4 x 4	9-Nov-20	Inv - 107125		Paid Lou : trans credit card
61297	XS20CJ / L	Dave S	C	148691 km	change engine oil and filters , grease and brake adjust , toip up auto greaser , change diff oil & filter , change air filters , remove CAC wash out and wash out radiator	Josh B , Josh G , Luke , Sam	9-Nov-20	CHM - 2334		1 x LF14000NN engine oil filter , 1 x FS19764 10 micron fuel filter , 1 x FF5776 fuel filter , 1 x LF637 oil filter , 1 x AS2474 air filter , 1 x 17237 gear box filter , 1 x HHW0116 AdBlue suction filter , 1 x BS.230.N70 diff filter O-ring , 2 x AF351KM air filter
60810	XS20CJ / L	Craig			1 x pacgen elc40 premix 5 ltr	Inland Trucks / Dubbo	19-Sep-20	Inv - 975647		
60722	XS20CJ / L	Dave S	A	113553 km	grease and brake adjust , check all lights work , check fluid levels , replace RH windscreen	Glen Artney	11-Sep-20	Inv - 51071		adjust clutch , top up coolant , replace 1 blown bulb dash light

60505	XS20CJ / L	Dave S			1 x road train sign	Glen Artney	21-Aug-20	Inv - 50653	
60544	XS20CJ / L	Dave S	B	96506 km	change engine oil and filters , grease and brake adjust , top up auto greaser , check all lights work	Sam , Luke , Ivan	17-Aug-20	CHM - 2008	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10 micron fuel filter
60028	XS20CJ / L	Dave Somerville	A	68007 km	grease and brake adjust , top up auto greaser , tighten up loose belly bar	Glen Artney	29-May-20	Inv - 49234	
59612	XS20CJ / L	Dave Somerville	B	54889 km	change engine oil and filters grease and brake adjust , top up auto greaser , check all lights work , clutch adjustment	Glen Artney	9-May-20	Inv - 48844	
59311	XS20CJ / L	Dave Somerville	A	32472 km	grease and brake adjust , top up auto greaser , check all fluids	Beetle	30-Mar-20		
59122	XS20CJ / L	Dave Somerville	B	15588 km	First Service	Inland trucks / Dubbo	9-Mar-20	Inv - 864690	broken AdBlue fitting had been hit ?? / rang and queried it