

81268	XS62BJ / L	Spare			12 x 1 x 1-7/8 x 1/8 nylon washer , 12 x 1 x 1-7/8 flat washer	United Fasteners / Wingfield	1/07/2025	Inv - 2544049	Paid Lou : Trans Credit Card
81384	XS62BJ / L	Spare			2 x eye bolt to make new bull bar pin , 2 x zinc silver guard spray	East side Bearings	27/06/2025	Inv - 10500636	Have ordered 2 x M27 x 170 bolts
81120	XS62BJ / L	Spare / Robbo		1166612 km	replace RH wind screen & chip repair LH	Obrien's Murray Bridge	23/06/2025		
81042	XS62BJ / L	Robbo	A	1161769 km	grease and brake adjust , check all lights work , check all other fluid levels , tighten bulbar mounting bolts , load test battery's all OK , top up engine oil 5 ltr	Glen Artney	8/06/2025	Inv - 79795	5 ltr x engine oil , top up auto greaser
80643	XS62BJ / L	Robbo		1139171 km	replaced A/C compressor and receiver dryer on custom air , vac down and Regas	Glen Artney	1-Jun-25	Inv - 79586	1 x F37-1022-200 dryer , 1 x SD5H09 Sanden A/C compressor ,
80629	XS62BJ / L	Robbo	C	1143252 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , check turn table adjustment , top up auto greaser , check all other fluid levels , change diff oil & filter , change air filters , check all lights work ,	CHM Shed	16-May-25	CHM - 12726	40 ltr x 85W/140 diff oil , 49 ltr x engine oil , 2 x AF351KM air filter , 1 x FF5776 fuel filter , 1 x LF14000NN engine oil filter , 1 x A3380W1687 filter , 1 x LF3335 fleet guard filter oil , 1 x HHW0116 AdBlue suction filter , 1 x FS19764 element 10 micron fuel filter , 1 x LF637 oil filter , 1 x 25189011 A/C filter , 2 ltr x extended life red coolant

					weld KW plate back on , replaced blown fuse for crate charge				
80363	XS62BJ / L	Robbo	A	1127057 km	check all fluid levels , grease and brake adjust , top up auto greaser (don't over fill) , check all lights work , turn table adjustment & grease	Glen Artney	26-Apr-25	Inv - 78645	repairs done - RH front indicator , front drive shaft uni , front diff cover leaking , ride height rose joint worn , radiator bracket loose
80405	XS62BJ / L	Robbo		1127057 km	repaired broken wire behind headlight , replaced front drive shaft uni , replaced nuts on centre bearing , reseal front diff & fill with new oil & filter , replaced worn rose joint RH side height rod , tighten loose tighten loose radiator shroud , repaired A/C hose , fit new A/C compressor & receiver dryer ,	Glen Artney	24-Apr-25	Inv - 78636	2 x VF5G-8 ball joint rose , 1 x CP25RPLS1 uni joint , 1 x A-3380W1687 diff filter , 18 ltr x synthetic gear oil 80W/140 ,
80520	XS62BJ / L	Robbo		1120275 km	replaced head light , replaced new reverse buzzer , replaced broken mudguard bracket on drivers' side , removed jack shaft & install new through shaft bearing carrier , replaced 2 steering unis , replaced mud guard pole bolt , replaced leaking RHF hub gasket , reshimmed all drive S-cams , replaced all custom air belts ,	Glen Artney	11-Apr-25	Inv - 78427	1 x T-bolt clamp , 4 x SSBK-1 mud guard bracket , 1 x NAR72600 reverse alarm , 1 x 0556951 led head lamp , 1 x 453795CR hub cap gasket , 1 x 5.130X steering uni joint kit , 1 x A2-3226T1112S cage & thru shaft assembly , different assorted bolts & nuts & washers , 3 x KIT8015 S-cam washer kit ,

80144	XS62BJ / L	Robbo	B	1113193 km	change engine oil & filters & fuel filters , grease and brake adjust , top up auto greaser (DON'T OVER FILL) , grease & adjust turn table , check all other fluid levels - good check over , adjusted belts on custom air , replaced both leaking air bags on 2nd drive , replaced broken UHF aerial	Glen Artney	5-Apr-25	Inv - 78250	1 x LF14000NN oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10-micron , 1 x AS2474 air/oil separator , 1 x HHW0116 AdBlue filter , 1 x AE4012 S/Steel UHF , 2 x W01-358-9541 10.5"air bag Ag460 , 46 lt x engine oil ,
78850	XS62BJ / L	Robbo	A	1098477 km	check all fluid levels , grease and brake adjust , check turn table adjustment , top up auto greaser (DON'T OVER FILL) , chek all lights work	Glen Artney	15-Mar-25	Inv - 77798	Any problems please call
78708	XS62BJ / L	Robbo		1093486 km	remove and replace A/C compressor on custom air , fill system with 800 g ,	Glen Artney	7-Mar-25	Inv - 77604	1 x SD5H09 Sanden A/C compressor , 1 x 13A0775 v-belt , 1 x 13A0685 v-belt , 0.80 refrigerant gas , 0.05 A/C oil ,

78575	XS62BJ / L	Robbo	B2	1074915 km	change engine oil & filters & fuel filters , grease and brake adjust , top up auto greaser (DON'T OVER FILL) , grease & adjust turn table , check all other fluid levels - good check over , fit new wheel seal to RH front steer , replace anchor bushes , replaced brake shoes & refit brake drum , remove RHS drive wheels replaced hub seal , set wheel bearings , refit and tension & brake adjust , jack up rear diff - replaced brake shoes & brake drums on both sides , remove jack shaft and tighten yoke nut , remove and replaced seal , tighten filter pipe in front diff ,	Glen Artney	21-Feb-25	Inv - 77403	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element , 1 x AS2474 air oil separator filter , 1 x HHW0116 adblue filter , 1 x SS-500B glass sight radiator tank , 1 x 43764 steer wheel seal , 1 x 453795CR (330.3067STM) hub cap gasket , 3 x KSMA3124707QP Meritor Q plus brake shoe , 1 x 47693S drive wheel seal , 1 x 03-01568 axle gasket , 1 x CM10037991 drum brake steer , 1 x R945008 through shaft seal , 1 x KiT2637 nut through shaft , 2 x 55.190CF 10 stud brake drum , 1 x KSMA3124715QP Q plus 16.5"x 6"steer axle ,
78532	XS62BJ / L	Robbo		1077348 km	aftertreatment light on ! , active code 3569 , carry out pump override test , only collected 75ml below spec , clean nozzle and carry out wet flush & air side flush , retest all OK back up to 95ml	Cummins Tamworth	14-Feb-25	Inv - 1533376	
78436	XS62BJ / L	Spare / Robbo			make 2 x bull bar bolts ,	Lou Bearings Eastside	3-Feb-25	Inv - 10484036	2 x bolt , 2 x flat washer , 2 x eye lift nut

78392	XS62BJ / L	Spare / Robbo			remove and replace starter motor on custom air , also replaced rubber mounts top and bottom / service engine (3806 hrs)& replace oil & air filter & oil filter & fuel filter , clean evaporator filter	Ryans Auto	3-Feb-25	Inv - 0531	1 x starter motor , 5 x top engine mounts , 1 x fuel/water separator , 1 x sleep air oil filter , 1 x air filter
78454	XS62BJ / L	Spare / Robbo			replace RH windscreen (KW1648) , chip repair on LH side / replace PBR fittings	Obrien's Windscreen / M-Bridge / Lou	28-Jan-25	Inv - 1125 - 058673	SC 2 x AB1400 coupling 1/2"female
78093	XS62BJ / L	Shawn			repairs to bonnet	Truck Factory	2-Dec-24	Inv - 21165	
78759	XS62BJ / L	Spare		1065706 km	jobs carried out - repaired wiring on custom air as starter was cranking and the A/C not working - test and all working , repair front and rear diff leaks , fill both diffs new oil	BMG	27-Nov-24	Inv - KWFT387842	
78772	XS62BJ / L	Spare / Shawn			remove old tracker and upgrade with new 5G tracker	Evolution Auto fit / Troy	21-Nov-24		

78674	XS62BJ / L	Shawn		1063291 km	front diff - either pinion seal leaking or will need a diff reseal ?? , please check oil level in rear diff - replaced front axle LH & RH drive brakes shoe & drums & s-cams & bushes , also replace pinion seal , carry out brake adjustment , replace diff oil	Glen Artney	11-Nov-24	Inv - 75592	1 x LSG392 kit oil pump , 1 x K1T2638 pinion nut , 1 x R945008 seal through shaft , 2 x 47693S drive wheel seal , 2 x set403 Timken 592A/5*94A bearing set , 2 x set401 Timken 572/580 bearing set , 2 x 03-01568 axle gasket , 1 x 2210V7536FW Meritor RH drive S cam , 1 x 2210W7537FW Meritor LH drive S cam , 1 x K1T8042 S/cam repair , 2 x KSMA3124707QP Meritor Q plus brake shoe & lining kit , 2 x DB017TRP brake drum 55.190CF , 10 ltr x 85W/140 diff oil ,
78533	XS62BJ / L	Shawn			1 x 32 ltr fridge	BMG	26-Oct-24	Inv - 620788	
78411	XS62BJ / L	Joshua	Call Out / B	1054020 km	Travel to Mount Gambier sale yards - truck has pushed out all its coolant , suspected dropped liner ! Cummins provided new style block & Additional parts & Labour , install crank with new bearings & oil pump , fit new liners & pistons & piston cooling nozzles , install new cylinder head with new head bolts , refit front & rear housing & timing gear , install air compressor & governor & new water pump , replace oil & coolant thermostat , replaced front engine mounts & damage exhaust flex , clean radiator & CAC , fit new fan belt , fit all new filters , tune engine , carry out dyno run in , replace turbo charger	Mount Gambier / Cummins	9-Oct-24	Inv - 1422626	1 x 5607734RX recon turbocharger , 1 x 6305091RX recon water pump , 1 x FS19764 element , 1 x 5680039RX recon lube pump ISX , 1 x 3084879 seal thermostat , 3 x 2866337 gasket AFM device , 2 x 3391271 lubricate 105 grease , 1 x 3688113 plug gear cover , 1 x 4386527 thermostat , 2 x V404P-10-6 valve , 1 x 5633631 kit main bearing , 1 x 6438633 kit overhaul , 1 x 6489732RX recon cylinder head , 50 ltr engine oil , 7 x 3678506 screw flange head , 4 x 3963991 washer sealing , 1 x 12PK2370 Dayco blue label belt , 1 x WF2127 coolant filter , 2 x AF351KM air filters , 65 ltr LGXL coolant , 1 x 5531410 front engine mount , 1 x 5531576 exhaust flex
78329	XS62BJ / L	Joshua	A	1047156 km	check all fluid levels , grease and brake adjust , top up auto greaser , check all lights work , top up engine oil	CHM - Shed	30-Sep-24	CHM - 10943	Need to get back : input seal weeping , rear diff wet , fan shroud needs re bracing , sump gasket wet / 5 ltr x engine oil ,

78977	XS62BJ / L	Beetle		1040632 km	adjust ride height , replace clock spring fuse	CHM Shed	13-Sep-24		
78073	XS62BJ / L	Josh		1034800 km	LH side levelling valve on prime mover , zipped tied up , will need replacing	TTT	11-Sep-24	Inv - 298783-00	NOTED - front diff weeping , buttons on steering wheel not working
81116	XS62BJ / L	Spare / beetle	C	1029375 km	change engine oil & filters & fuel filters , grease and brake adjust , check all lights work , change diff oil & filter , change air filter , replace power steering fluid & filter , weld new exhaust flange on at turbo outlet , replaced exhaust mounts and pyro sensor , remove and replace clock spring ,	CHM Shed	26/08/2024	CHM - 10683	2 x K066-338 bushing anti vibration , 1 x P21-1027 pyrometer sensor , 1 x 2866337 gasket AFM service , 2 x AF351KM air filter , 1 x 25189011 A/C filter , 1 x clock spring , 1 x LF14000NN engine oil filter , 1 x FS19764 element 10 micron filter fuel , 1 x FF5776 fuel filter , 1 x fleet guard filter oil , 1 x LF637 oil filter , 1 x AS2474 air filter , 49 ltr x engine oil , 40 ltr x 85W/140 diff oil , 1 x HHW0116 AdBlue suction filter , 1 x Dayco HD auto belt tensioner ,
77486	XS62BJ / L	Spare / Beetle		1006721 km	loose guard pole , steering column want go up or down replace steering cable & steering column gas strut , tighten mudguard pole , after treat light on , replace boost hose clamp ,	CHM Shed	10-Jul-24	CHM - 10208	1 x K077-372-66 clamp , 1 x 450205F steering cable , 1 x tilt lock-gas strut gen 2
78117	XS62BJ / L	Beetle			change out PBR fitting ,fit new turn table cord	Beetle , Lou	4-Jul-24	SC - 053895	1 x AB0149 adaptor 1/2"female , 1 x TT8819G cord latch
77472	XS62BJ / L	Beetle			S/Steel / Alloy polish	Repco / Murray bridge	1-Jul-24	Inv - 3870173691	Paid Lou : trans credit card

77277	XS62BJ / L	Spare / Beetle	A	1002630 km	check all fluid levels , grease and brake adjust , check all lights work , turn table adjustment , replace power divider O-ring , remove RHF drive wheel and replace S-cam & re-shim S-cam	CHM Shed	18-Jun-24	CHM - 10126	1 x R824004 slack adjuster FS , 2 x 5 x 1327 power divider O-ring
76999	XS62BJ / L	Bucko			fit new clutch linkage arm & grease	Glen Artney	21-May-24	Inv - 72198	replaced both LHS & RHS marker lights ,
76983	XS62BJ / L	Bucko	Call Out	990338 km	bolt fallen out of clutch assembly / couldn't get bearing , so made up brass bush , adjust clutch	Black trucks / Moree	20-May-24	Inv - 1848301	Paid Lou : Trans credit Card
77183	XS62BJ / L	Bucko	Call Out	987562 km	truck derated - found active codes 2772,2773,3569,3548 , was blocked AdBlue injector , replace AdBlue filter & new line , carry out test all OK	Inland Trucks / Dubbo	17-May-24	Inv - 873373	
76902	XS62BJ / L	Edan / Shawn	B	983020 km	change engine oil & filters , change fuel filters , grease and brake adjust , top up auto , check other fluid levels , check over , check diff oil , remove radiator and clean and replace bottom radiator bushes & radiator cap , replace with new coolant , change gear box oil & filter & replace gear box cooler hoses , replace wiper blades , check and adjust turn table , carry out tune up , replace LH steer wheel seal , reseal radiator site glass , tie up loose wiring , replace boost hose ,	CHM Shed	7-May-24	CHM - 9978	1 x WW460R125 wiper refill , 1 x fleet guard filter oil , 60 ltr coolant red , 1 x LF14000NN engine oil filter , 1 x FF577 fuel filter , 1 x AE9976132 radiator cap , 2 x R5JF-14-10-10C5-10RFJSX90 , 1 x R5JF-14-10 fitting 5/8 , 1 x hose hump 4"x4.5"x7", 2 x K077-372-66 clamp , 2 x K077-372-73 charge air clamp , 4 x M200-70EP bushing radiator , 4 x mount radiator OE rubber , 6 x B9228-0275B clamp , 1 x kit brake shoe steer 16 , 1 x 43764S wheel seal , 1 x M-IS0A-08-08-P 1/2 BSPP male coupling , 1 x TRP brake drum 16-1/2 x 6 , 1 x AS0182 joiner 8mm , 0.60 K342-974-12Y/10RL hose hydraulic 10m roll , 15 ltr 3416169 Castrol transmax gear box oil

76882	XS62BJ / L	Spare / Edan	B		service and jobs , also has derated - possible doser pump or needs a flush	CHM Shed	7-May-24		
77740	XS62BJ / L	Spare / Bucko			30 ltr engine oil	Glen Artney	4-May-24	Inv - 71720	
77077	XS62BJ / L	Shawn	Call Out	966130 km	travel to sale yards - jump start truck , test battery's one had failed , replace 4 x battery's , also repair alternator wire broken on custom air	Glen Artney	7-Apr-24	Inv - 71274	
76676	XS62BJ / L	Shawn		966100 km	reseal front diff , replaced 4 x batterys	Glen Artney	6-Apr-24	Inv - 71343	fit new axle gasket , replace diff oil & filter ,
76538	XS62BJ / L	Shawn		950472 km	fan controller not working in cab ??	Glen Artney	19-Mar-24	Inv - 71019	on inspection found blower motor unserviceable - remove and replace with new
76414	XS62BJ / L	Shawn		940489 km	loose oil filter , replace with new oil filter and top up engine oil 4.65 ltr	Glen Artney	4-Mar-24	Inv - 70765	
76346	XS62BJ / L	Shawn	Call Out	927475 km	travel to Warracknabeal - replaced centre bearing	Wimmera Trucks / Horsham	7-Feb-24	Inv - HKFSH1203	1 x KW5003323PAC centre bearing

76504	XS62BJ / L	Shawn	A	908257 km	check fluid levels , grease and brake adjust , top up auto greaser , repair AdBlue leak , replace fitting and nut on injector , repair broken speedo wiring , fitted uploader kit to air dryer , drain coolant and replace compressor with new , and refill coolant ,	CHM Shed	4-Jan-24	CHM - 9242	1 x 715-8016-006 connector 1/4 elbow , 1 x nut tube Q67335 , 1 x 6 hole injector doser euro 5 , 1 x 3690067 belt tensioner , 1 x 5413204 belt , 4 x B9228-0275B clamp , 0.50 x 5581-250 hose silicone , 2.5ID RA , 2 x P3-0806 hose tail male , 2 x 92208 Dayco automotive clamp , 1 x kit-unloader air dryer , 2 x 275707 valve governor 105-125 PSI , 1 x 3690864RX recon air compressor ISX , 1 x 5440813 A/C gasket , 1 x 4988280 hydraulic pump gasket , 2 x 3678786 O-ring , 1 x 3627695 seal O-ring
75882	XS62BJ / L	Shawn	B	883450 km	change engine oil & filters , grease and brake adjust , replace AdBlue injector hose , fit new top mount , remove LH front drive wheel , replaced brake drum and brake shoes , replace RH drive S-cam , replace new bearing cups and seals , refit hub and fill with oil , install axle and adjust all brakes , repaired wiring on RHS headlight , reassembled new through shaft assembly ,	Glen Artney	8-Dec-23	Inv - 69355	
75826	XS62BJ / L	Shawn	A	899770 km	check fluid levels , grease and brake adjust , check all lights work	Glen Artney	8-Dec-23	Inv - 69467	replaced 2 ball joints (rose joint)
75871	XS62BJ / L	Shawn			1 x drivers side seat cover	CMV / Adelaide	6-Dec-23	Inv - I31085870	
75631	XS62BJ / L	Shawn			possible treadle valve ??	Glen Artney	10-Nov-23	Inv - 69018	found all drive brakes over 90 , adjusted all drive brakes , cleaned out slack adjusters , locks full of dirt , - MONITOR LH drive wheel seal wet ???

75411	XS62BJ / L	Shawn		854137 km	low boost ? , replace both LH & RH windscreen	TTT	3-Oct-23	Inv - 292723-00	replaced NOX sensor
75691	XS62BJ / L	Shawn			replace rod end on ride height valve	CHM Shed	26-Sep-23	CHM - 8415	1 x VF5G-8 hemi joint
75321	XS62BJ / L	Shawn		842942 km	check and carry out clutch adjustment - noted that clutch is at end of its life	Bendigo Truck centre	12-Sep-23	Inv - 343078	Paid Lou : Trans Credit Card
75536	XS62BJ / L	Shawn	B	843505 km	change engine oil & filter , refit wheel housing with new gasket , rear main seal and sump with new gasket , machined fly wheel , fit new clutch , kit input shaft, bell crank bearings and hind joints , refit gear box and accessories , tail shaft & exhaust , road test and check over all OK	CHM Shed	11-Sep-23	CHM - 8134	1 x 4393176-ISX fly wheel gasket , 1 x K-4450 PAC suits 14 spline KW clutch , 1 x seal O-ring , 1 x 4965569 kit seal , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x LF14000NN engine oil filter , 1 x 1287013003 oil temperature plug , 1 x switch pressure , 1 x 2866337 gasket AFM device , 1 x 308938583 clutch kit 14 spline EP advantage , 2 x 85W140 diff oil , 49 ltr engine oil , 4 x VF5G-8 Heim joint , 1 x 4026684 ISX sump gasket
74940	XS62BJ / L	Shawn	B	824217 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser , replace dash globes , repair wiring for indicators	Luke , Tom	1-Aug-23	CHM - 7709	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10-micron fuel filter euro 5 ,
74949	XS62BJ / L	Shawn			truck wheel alignment front & rear	L & A wheel Alignment , Shepparton	25-Jul-23	Inv - 0029	

74540	XS62BJ / L	Shawn			6 x S/Steel hinge butt	Bunnings	26-Jun-23	Ref : 115553	Paid Lou : Trans Australia Credit Card
74795	XS62BJ / L	Shawn	A	808729 km	check all fluid levels , grease and brake adjust , top up auto greaser , replace mud flaps ,	Josh , Corey	26-Jun-23		
74314	XS62BJ / L	Shawn			1 x D202-Aero - 302 dark blue insert (Bug Deflector)	CMV / Adelaide	6-Jun-23	Inv - I31066618	
74302	XS62BJ / L	Shawn			clean out plug and spread pins	Josh , Reece	1-Jun-23		
74329	XS62BJ / L	Shawn	C	795189	change engine oil & filters , grease and brake adjust , top up auto greaser , change air filters , change diff oils & filter , check all lights work , fit new washer to auto greaser , replaced front engine mounts , replaced RH front and rear track rod bushes , tighten top mount bolts on ice pac , repair wiring issue in stop/tail lights , replace blown fuse , check turn table adjustment , replace governor valve , repair exhaust outlet	Tom , Reece , Josh ,	25-May-23	CHM - 7165	4 x 839310 track rod bush , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x 275707 governor valve , 2 x K066-404 bushing front engine , 2 x K066-405 ISX front engine mounts yellow , 1 x TRPCAF0001 filter , 1 x LF3335 fleet guard filter oil , 1 x AS2474 air filter , 1 x LF637 oil filter , 1 x A3380W1687 filter , 1 x HHW0116 AdBlue suction filter , 2 x AF351KM air filter , 1 x 5 ltr premium blue oil , 2 x SB2430CCAUS - 24/30 brake chamber , 9 x 92208 Dayco automotive clamp , 1 x 2306/JW-5"lipped flange

73707	XS62BJ / L	Shawn	B	763935 km	change engine oil & filters , grease and brake adjust , check all lights work , fit new bug deflector , replace A/C idler bearing & fan belt , Through shaft seal slight weep	Luke , Corey	20-Mar-23	CHM - 6819	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x belt fan drive , 1 x FS19764-10-micron fuel filter , 1 x 6303-2RSH idler bearing ,
72714	XS62BJ / L			708523 km	top up engine oil 8 ltr , replace wiper blades , replace boost clamp	Sam , Josh	21-Feb-23		
77267	XS62BJ / L	Shawn	C	932290 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change air filters , change diff oils & filter , check all lights work , replace cabin ride height rod & valve , replaced centre bearing , replace LH rear track rod bush , service ice Pac , replace alternator , replace all 4 drive shockers , replace rear mud guards	CHM Shed	19-Feb-23	CHM - 9319	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x AS2474 air filter , 1 x LF637 oil filter , 1 x A3380W1687 filter , 1 x HHW0116 AdBlue suction filter , 2 x AF351KM air filter , 49 lt premium blue oil , 1 x fleet guard filter oil , 1 x BS.230.N70 diff filter Oring , 40 ltr x diff oil , 1 x auto grease , 1 x 1350-0111 assembly height control valve , 1 x linkage assy height valve , 1 x SU-ALT60 alternator kit 60amp , 1 x FF5018 fuel filter , 1 x LF689 diff filter , 1 x 25189011 A/C filter , 2 x 090-2209SP3B Koni front shockers , 2 x 839310 track rod bush , 4 x C71-1006 shock absorber rear SU
73308	XS62BJ / L	Shawn			1 x D202-Aero - 302 dark blue insert (Bug Deflector)	CMV / Adelaide	8-Feb-23	Inv - I31056679	
73326	XS62BJ / L	Shawn	A	744414 km	check fluid levels , grease and brake adjust , check lights work , top up auto greaser	Scott	6-Feb-23		
73158	XS62BJ / L	Shawn	A	736515 km	check all fluid levels , grease and brake adjust , tighten up clutch linkage , top up auto greaser	Josh B , Reece	19-Jan-23		

72898	XS62BJ / L	Shawn	Call Out	723663 km	clutch linkage fallen off ??	Inland Trucks / Dubbo	13-Dec-22	Inv - 869876	found clutch rod adjuster rod missing - fit new lever and adjust clutch set up
72896	XS62BJ / L	Shawn	B	721040 km	change engine oil & filters , grease and brake adjust , fit new S-cam bushes , slack adjuster , brake shoe , clean hub & bearings , refit fill with oil tension wheel bearing to spec , fit new gasket , fit new brake drum refit wheels & tension to spec - LH rear drive	Glen Artney	8-Dec-22	Inv - 63273	
72693	XS62BJ / L	Shawn			2 x nuts & washers	Bridge bearings	22-Nov-22	Inv - 405268	
72651	XS62BJ / L	Shawn	A		check fluid levels , grease and brake adjust , check all lights work ,	Sam	22-Nov-22		
72716	XS62BJ / L	Shawn	A	709306 km	check all fluid levels , grease and brake adjust , tighten front diff output yoke , replace top shocker mount , replace wiper blades & boost clamp	Corey , Scott	21-Nov-22	CHM - 6015	1 x WW460R125 wiper refill 460 x 12.5mm , 1 x K077-372-66 clamp , 1 x B11-1161 shock absorber bracket
72443	XS62BJ / L	Shawn		688347 km	replace faulty speed sensor , clean off pick up	Scott	21-Oct-22	CHM - 5848	1 x Q21-6004 dual speedo / tacho sensor

72235	XS62BJ / L	Shawn	Break Down		jack shaft & parts / top & bottom gusset , torque rod assy , bolts & washers	CMV / Adelaide / Adelaide	CMV	7-Oct-22	Inv - I31042779 - I31042815	Inv	1 x 20RHM080C156H RPL20 I/A D/line 398mm col , 1 x 20WYS32-2P yoke RPL20 luo , 1 x 20WYS38-3A yoke RPL20 rui x 8 x CSC82052 bolts , 1 x R945008 seal pinion unitised , 1 x R845010 seal pinion unitised , 1 x K1T2637 pinion nut 160 , 1 x K1T2638 kit pinion nut / 1 x K140-2468 gusset AG200 upper , 1 x K140-2480 gusset AG200 lower , 1 x K195-474 torque rod assy , 2 x FS8512 bolts 5/8 , 2 x 58NF5ZPNYLN 5/8 nyloc nut , 12 x 58ZYHTW 5/8 x 1-5/16 x 4.5mm washers
72281	XS62BJ / L	Shawn	C	676999 km	change engine oil & filters , grease and brake adjust , check all lights work , change diff oil & filter , change air filters , tighten belly bar behind engine , replace jack shaft & yolk on rear diff with new seal , fit new track rod top plate and new track rod bar - tighten everything up , refit turn table , free up seized solenoid on ice pack , load test battery's all OK , replace USB outlet in cab ,	Josh , Mike , Sam , Reece		7-Oct-22	CHM - 5695 - 5768	CHM	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , / 1 x 25189011 A/C filter , 1 x LF637 oil filter , 1 x LF14000NN engine oil filter , 1 x A3380W1687 filter , 1 x LF3335 fleet guard filter oil , 1 x AS2474 air filter , 1 x FF5776 fuel filter , 1 x HHW0116 AdBlue suction filter , 1 x BS.230.N70 diff filter O-ring , 1 x A2297D5334 filter screen , 1 x 47693S wheel seal , 1 x KSMA3124707QP drive brake shoe kit , 1 x breather stauuff SPB3 3 , 1 x K1T9078 kit , 1 x DB017TRP brake drum , 1 x A1-1205A2731 rear diff input seal
72011	XS62BJ / L	Shawn	B	660317 km	change engine oil & filters , tighten loose mud guards , load test battery's , change wiring on alternator , replace USB port in cab , free up solenoid on ice Pac ?	Luke , Cory , Scott , Mike		5-Sep-22			
71983	XS62BJ / L	Shawn			1 x USB port switch	Richards Auto		5-Sep-22	Inv - 55198		
71709	XS62BJ / L	Shawn		647108 km	check exhaust leak - replace gasket and reclamp	Josh		9-Aug-22	CHM - 5572		1 x 2866337 gasket

71743	XS62BJ / L	Shawn		639991 km	replace LH steer bearing cap & fill with oil	Beetle	28-Jul-22		
71624	XS62BJ / L	Shawn	A	638272 km	check fluid levels , grease and brake adjust , check all lights work , replace rear diff input seal , replace LHR & RHF shocker rubbers	Mike , Reece , Josh	25-Jul-22	CHM - 5403	1 x A1-1205A2731 rear diff input seal , 4 x K066-310 bush rubber
71507	XS62BJ / L	Shawn	Call Out	? Km	truck want start - Horsham saleyards	Daryl Robertson / Horsham	18-Jul-22	Inv - 94412	Change out Alternator
71415	XS62BJ / L	Shawn	B	621462 km	Change engine oil & filters , grease and brake adjust , top up auto greaser , replace heater tap , top up coolant 8 ltr , replace LH wheel seal wash brake drum & shoes	Luke , Mike , Reece , Corey	20-Jun-22	CHM - 5148	1 x FS19764-10-micron fuel filter , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x 43764S wheel seal , 1 x V404P-10-6 heater tap , 1 x HG4009 hub cap gasket , 0.50 PGXLVITAL 20 ltr coolant
71235	XS62BJ / L	Shawn	A	613149 km	check all fluids , grease and brake adjust , change out PPI valve , replace wiper blades , replace boost hose , change dash globes	Luke , Josh	2-Jun-22	CHM - 5146	1 x TRPN15759BA-PP1 pressure protection valve , 2 x WW460B15 wiper blade 460mm x 15mm , 1 x HE8761XL hose hump 4"x4.5"x7" , 2 x K077-372-66 clamp , 2 x K077-372-73 charge air clamp , 1 x 800005002 globe holder
71001	XS62BJ / L YN73DO / L	Shawn		? km	replace plug on truck , replace 7 pin socket on trailer ,	Auto elec / Shepparton	16-May-22	Inv - 17774	replaced 7 pin base socket , replace 7 pin male plug ,
70923	XS62BJ / L	Shawn	B	598012 km	chang engine oil & filters , grease and brake adjust , check all lights work , replaced RH & LH drive wheel seals - replaced new brake drums & new brake shoes	Josh , Mike	29-Apr-22	CHM - 4844	1 x LF9070 oil filter , 1 x FF5776 fuel filter , 2 x KSMA3124707QP drive brake shoe kit , 2 x DB017TRP - TRP 16.5 x 7 brake drum , 2 x 47693S wheel seal

70460	XS62BJ / L	Shawn	A	573048 km	check fluid levels , grease and brake adjust , replace boost clamp , tighten diff filter strainer as it was loose , top up coolant	Mike , Sam	7-Mar-22	CHM - 4595	1 x K077-372-66 clamp , .50 x PGXLVITAL 20 ltr PGXL Vital AD
70360	XS62BJ / L	Shawn	C	566556 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filters , change air filters , replace LH front mud guard brackets	Sam , Luke , Josh	21-Feb-22	CHM - 4561	1 x 25189011 A/C filter , 1 x A3380W1687 filter , 1 x P550222 hydraulic spin on , 1 x HHW0116 AdBlue suction filter , 1 x LF637 oil filter , 1 x BS.230.N70 diff filter O-ring , 1 x 25185926 A/C filter cover , 2 x AF351KM air filter , 20 ltr x 3416169 Castrol transmax gear box oil
70110	XS62BJ / L	Shawn		555921 km	defect on front diff ?	Glen Artney	4-Feb-22	Inv - 59049	front drive diff leaking - saved old oil and topped up with new , found oil leaking from seal carrier remove deck plate remove both diff breathers and replace with new also cleaned out lines , fit new seal & O-rings , refit yoke and new nut ,
70017	XS62BJ / L	Shawn		543717 km	remove RH front wheel - found bearing had got hot and found filings in oil , remove RH steer bearings and replace with new bearings & seal and fill with new oil , tension bearing and fit wheel all OK	Brett	12-Jan-22	CHM - 4277	1 x 43764S wheel seal . 1 x 552AT1M bearing cup , 1 x 555ST1M steer bearing cone , 1 x 6420T1M bearing cup , 1 x 6461AT1M steer bearing cone , 0.25 x PGXL vital coolant 20 lt (red) , 1 x R002659 locking washer
69989	XS62BJ / L	Shawn			had bung come out of front steer hub cover , top up oil and replace bung	Auto electrical / Edenhope	11-Jan-22	Inv - 18076	Paid Lou : Trans credit card
69954	XS62BJ / L	Shawn	A	540346 km	check fluid levels , grease and brake adjust , top up auto greaser , remove and replace diff filter & O-ring and tighten diff housing bolts - monitor oil leak , top up diff oil	Brett , Josh	5-Jan-22	CHM - 4161	1 x BS.230.N70 diff filter Oring , 1 x A3380W1687 filter

69799	XS62BJ / L	Shawn	Call Out	531445 km	starter motor ??	Brown & Hurley / Tamworth	14-Dec-21	Inv - 2360499	remove and replace starter motor Paccar DP60 ,
61581	XS62BJ / L	Shawn	B	527351 km	repair pressurizing under warranty - new rings & liners & cylinder head , remove radiator and wash out & CAC , replace thermostat , replace leaking waste gate actuator , carry out tune up , replace oil & filters and new coolant	Cummins / Mt Gambier	14-Dec-21	Inv - 9190947	1 x 4318947 thermostat , 1 x 4034356 kit turbocharger actuator
69821	XS62BJ / L	Shawn		527475 km	reattach bunk lining - Velcro had come off , refit door trim tightens all bolts and ensure everything secure , air leak at drier exhaust - replace unloader valve unservicable so replace with new	BMG	8-Dec-21	Inv - KWFT343098	
69739	XS62BJ / L	Shawn		518535 km	replace cab air bags	Josh , Josh	15-Nov-21	CHM - 4020	2 x 1102-A08 air bag
69158	XS62BJ / L	Shawn	B	506000 km	change engine oil & filters , grease & brake adjust , top up auto greaser , remove and replace 4 x battery's , remove and replace engine mounts , retention front diff bolts - monitor may need to reseal next C service , service ice pac @ 2437 hrs	Josh G , Josh B , Beetle Beau repairs / M-Bridge	8-Oct-21	CHM - 3713 Inv - 6412264950	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10-micron fuel filter , 2 x K066-404 front engine mounts , 2 x K066-405 ISX front engine mounts (yellow) , 1 x LF689 diff filter , 1 x FF5018 fuel filter , 1 x AF25221 air filter , / 4 x XN70EX battery

68823	XS62BJ / L	Shawn	A	493014 km	grease and brake adjust , check fluid levels , add 5 ltr engine oil , replace ride height valves - Monitor front diff starting to weep	Sam , Luke	27-Aug-21	CHM - 3591	2 x H00500C ride height valve
68460	XS62BJ / L	Shawn M	A	461144 km	check all fluid levels , grease and brake adjust , top up auto greaser	Sam , Josh , Luke	12-Jul-21		
68218	XS62BJ / L	Shawn	C	446931 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter , change air filters , change gear box oil & filter , replace fan belt & A/C belt , replace RH steer wheel seal	Luke , Josh , Beetle	16-Jun-21	CHM - 3252	1 x LF14000NN engine oil filter , 1 x FS19764 - 10 micron fuel filter , 1 x FF5776 fuel filter , 1 x 17237 gear box filter , 1 x LF637 power steering filter , 1 x AS2474 air filter , 1 x HHW0116 AdBlue suction filter , 1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring , 1 x D84-1000-3122380 fan belt , 1 x 5413204 belt , 1 x KSMA3124715QP steer brake shoes , 2 x AF351KM air filter , 1 x 43764S wheel seal
68129	XS62BJ / L	Shawn			2 x wiper blades	Kenworth / Shepparton	8-Jun-21		
67627	XS62BJ / L	Shaun	B	418702 km	engine oil change & filters , grease and brake adjust , change globes in dash , bunk lining coming away , brake pedal leaking air , replace LH rear drive axle wheel seal , re- pack bearings , tension and fit new gasket , and adjust brakes	Glen Artney	21-Apr-21	Inv - 54925	
67619	XS62BJ / L	Shawn			patch hole in bonnet - tree branch fell on bonnet	Mackin Forklifts	13-Mar-21	Inv - 31515	L x P Mackin , 83 Drummond Rd , Shepperton Vic 3630 / 03 58215221

67380	XS62BJ / L	Winga	A	392108 km	grease and brake adjust , adjust clutch , replace diff filter and O-ring	Sam ,Josh B	11-Mar-21	CHM - 2867	1 x BS.230.N70 Diff filter O-ring , 1 x A3380W1687 filter
67173	XS62BJ / L	Winga		378756 km	replace wiper blades	Luke	15-Feb-21	CHM - 2718	2 x WW610R6-20 wiper blades
67118	XS62BJ / L	Winga	B	378741 km	service ice Pac @ 824 hrs (2245 hrs ??) , replace LH steer brake shoes & drum , replace LH & RH bull bar indicator lights	Josh G , Luke	12-Feb-21	CHM - 2652	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 10-micron fuel filter , 1 x KSMA3124715QP steer brake shoes , 1 x FF5018 fuel filter , 1 x AF25221 air filter , 1 x SU-OPS-Pil pressure sensor
61941	XS62BJ / L	Winga			2 x bull bar indicators	Richard's auto	2-Feb-21	Inv - 45299	2 x 235A-12 led 12v mount lights
61894	XS62BJ / L	Winga	A	371003 km	grease and brake adjust , check all lights work , (need to order RH bull bar blinker light , replace LH front wheel seal	Sam , Josh B	1-Feb-21	CHM - 2611	1 x 43764S wheel seal , 1 x 1613CR steer hub cap
61987	XS62BJ / L	Winga		352797 km	gave to driver as spares (3 x PBR air fittings) , replace foot throttle sensor and lube	Beetle	4-Jan-21	SC - 022367 CHM - 2567	1 x AB1397 coupling 1/2"male , 1 x AB1400 coupling 1/2"female , 1 x AB0149 adaptor 1/2"female / 1 x 400755 harness , 1 x 402890 sensor
61714	XS62BJ / L	Winga	B	352777 km	change engine oil & filters , grease and brake adjust , top up auto greaser , top up battery's , check all lights work	Luke , Beetle	29-Dec-20	CHM - 2566	1 x LF14000NN engine oil filter , 1 x FS19764- 10-micron fuel filter , 1 x FF5776 fuel filter

61880	XS62BJ / L	Winga			service ice Pac ? . 1 x hub cap	Sam	31/11/2020	CHM - 2432	1 x RT1209A6 hub cap
61555	XS62BJ / L	Winga			LH front axle wheel seal	Glen Artney	11-Dec-20		
?	XS62BJ / L	Winga	A	? km	check fluid levels , grease and brake adjust , adjust clutch , remove CAC, and wash out & radiator washed out	Beetle , Josh	17-Nov-20	CHM - 2530	1 x HE8761XL 4'x 4.5"boost hose
61302	XS62BJ / L	Winga		326262 km	1 x new steer hub cap	Josh G	9-Nov-20	CHM - 2334	1 x RT1209A6 aluminium hub cap
61180	XS62BJ / L	Winga	C	316795 km	change engine oil and filters , change diff oil and filter , check all lights work , change air filters , top up auto greaser , grease and brake adjust , change out blown dash globes	Luke , Sam	22-Oct-20	CHM - 2153	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10-micron fuel filter , 1 x A3380W1687 filter , 1 x HHW0116 AdBlue suction filter , 1 x 17237 Eaton gear box filter , 1 x LF637 oil filter , 1 x AS2474 air filter , 1 x 25189011 A/C filter , 1 x BS.230.N70 diff filter O-ring , 2 x AF351KM air filter ,
61083	XS62BJ / L	Winga		302139 km	remove and replace RH front drive guard , fit new brackets , tighten mud guard pole ,	Hamilton Diesel , Hamilton	1-Oct-20	Inv - 62677	
60844	XS62BJ / L	Winga	A	300089 km	grease and brake adjust , check all fluid levels , all lights work	Luke , Beetle , Josh G	25-Sep-20		
60607	XS62BJ / L	Winga	B	282124 km	engine oil change and filters , grease and brake adjust , check all lights work , top up auto greaser , add 3 ltr coolant , adjust clutch	Luke , Beetle , sam	28-Aug-20	CHM - 1997	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10-micron fuel filter , .25 x PGXL vital coolant red 20 ltr

60241	XS62BJ / L	Winga			leaking power steering pump	Cummins / Tamworth	22-Jul-20		warranty
60169	XS62BJ / L	Winga	A	256708 km	grease and brake adjust , check all lights work , add 3 ltr engine oil	Beetle	13-Jul-20		
59965	XS62BJ / L	Winga	B	238502 km	change engine oil and filters , grease and brake adjust , top up auto greaser , check all lights work	Luke , Brett , Josh , Sam	5-Jun-20	CHM - 1683	1 x LF14000 engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10-micron fuel filter
76976	XS62BJ / L	Bucko			1 x truck jack	Truckline / Tamworth	17-May-20	Inv - 9305538	
59693	XS62BJ / L	Winga	A	221374 km	grease and brake adjust ,	Beetle	7-May-20		
59707	XS62BJ / L	Winga	C	211374 km	change engine oil and filters , grease and brake adjust , change diff oil and filter , change air filters	Luke , Josh , Beetle , Josh	23-Apr-20	CHM - 1555	1 x LF14000NN engine oil filter , 1 x FS19764 10-micron fuel filter , 1 x LF689 diff filter , 1 x FF5776 fuel filter , 1 x LF637 power steering filter , 1 x AS2474 air filter , 1 x 17237 Eaton gear box filter , 1 x 6303-2RSH idler bearing , 1 x BS.230.N70 diff filter O-ring , 1 x HHW0116 AdBlue suction filter ,
59469	XS62BJ / L	Winga	A	202868 km	grease and brake adjust , top up auto greaser , check all lights work	Sam , Luke	10-Apr-20		

59201	XS62BJ / L	Winga	B	181306 km	change engine oil and filter , grease and brake adjust , adjust clutch , top up auto greaser ,	Josh , Luke , Bettie	13-Mar-20	CHM - 1455	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10-micron fuel filter ,
59024	XS62BJ / L	Winga	A		grease and brake adjust , top up auto greaser , found fault in throttle position sensor - remove and replace with new	Sam , Josh	24-Feb-20	CHM - 1396	1 x 132034 throttle position sensor
58741	XS62BJ / L	Winga	B	142249 km	change engine oil and filters , grease and brake adjust	Sam	17-Jan-20	CHM - 1266	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10-micron fuel filter ,
58561	XS62BJ / L	Winga	A	127395 km	grease and brake adjust , check all lights work , service ice Pac 611 hrs	Luke , Beetle	24-Dec-19	CHM - 1220	1 x LF689 oil filter , 1 x AF25221 air filter , 1 x FF5018 fuel filter
58404	XS62BJ / L	Winga	C	112138 km	engine oil and filter change , drop diff oil and change filter , top up auto greaser , grease and brake adjust ,	Josh , beetle	9-Dec-19	CHM - 1209	1 x LF14000NN engine oil filter , 1 x FS19764 - 10-micron fuel filter , 1 x FF5776 fuel filter , 1 x LF689 diff filter , 1 x 17237 Eaton gear box filter , 1 x LF637 power steering filter , 1 x BS.230.N70 diff filter Oring, 1 x HHW0116 AdBlue suction filter
58206	XS62BJ / L	Winga		101600 km	broken down - between Ouyen - Manangatang	Cummins /Swan Hill	14-Nov-19		new motor put in truck (Warranty)
57895	XS62BJ / L	Winga	B	79070 km	top up auto greaser , grease and brake adjust , engine oil change and filter	Josh , Sam	10-Oct-19	CHM - 0999	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 - 10-micron fuel filter

57564	XS62BJ / L	Winga			1 x long vehicle sign banner	Murray lands fire & safety	5-Sep-19	Rec - 034100	
57547	XS62BJ / L	Winga	B	51563 km	engine oil / filters changed , top up auto greaser , brake adjust , check all lights work	Sam , Beetle , Josh	2-Sep-19	CHM - 0922	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10-micron fuel filter
57425	XS62BJ / L	Winga	A	40741 km	added 2 ltrs engine oil , top up auto greaser , remove and replace front wheel seals LH & RH side , also brake shoes , cleaned brake drums, and refitted	Josh , Sam , Beetle	16-Aug-19		took photos sent through to Gibbo & Jacinta @ BMG - Warranty , order number given from BMG 1S82645 - Sam CHM did job
57155	XS62BJ / L	Winga	B	19614 km	first service	Sam , Josh ,	16-Jul-19	CHM - 0811 SC - 009562	1 x AB7625 ball valve 1/2" / 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 10-micron fuel filter , 1 x LF689 diff filter , 1 x LF637 power steering filter , 1 x 17237 Eaton gear box filter , 1 x HHW0116 AdBlue suction filter , 18 ltrs of 3416169 gear box oil / change diff oil ,