

81318	XS79CZ / L	Spare / Lindsay			replace both LH & RH Windscreens	Obrien's / Murray Bridge	4/07/2025		
81054	XS79CZ / L	Lindsay	B	975009 km	change engine oil & fuel filters , grease and brake adjust , check all lights work , top up auto greaser , check all other fluid levels , replaced pitman arm with new , replaced broken hose on RHS front booster , top up front diff oil ,	CHM Shed	18/06/2025	CHM - 13025	49 ltr x engine oil , 1 x LF14000NN engine oil , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter , 1 x A273-8R hose repair kit , 1 x 76RB-3/4-6 adaptor , 1 x K029-280 arm pitman , 4 ltr x PG red coolant , 2.5 ltr x 85w/140 diff oil ,
80601	XS79CZ / L	Lindsay		949956 km	possibly will need 4 x battery's - removed and replaced	CHM Shed	12-May-25	CHM - 12726	4 x XPN70ZZMF explorer 85ah battery
80531	XS79CZ / L	Lindsay		948351 km	RH steer hub weeping - remove and replaced gasket , fit new screen and O-ring to hub & fill with oil ,	BMG	9-May-25	KWFT394625	1 x KW359-5995 hub cap with window kit , 1 x KW453795CR gasket hub cap
80506	XS79CZ / L	Lindsay	Call Out	946950 km	front RH steer hub weeping oil but still has oil in sight glass , but very hot to touch , inspect bearing signs of been pitted , remove old bearings replaced with new , adjust bearing and fill up with hub oil ,	Central West Diesel / Forbes	7-May-25	Inv - S33399	1 x CR43764 steel seal , 1 x KIT104 bearing kit(set423-set-424) , 1 x BP4024 hub cap gasket , 1 x brake cleaner , 1 x degreaser , 2 x 1 ltr hub oil moreys ,
80454	XS79CZ / L	Lindsay	Call Out	944698 km	Travel to Tabbita - failed alternator / replaced with new alternator	Inland Trucks / Griffith	5-May-25	Inv - I604614	1 x LBP2189GH alternator 12V 160A pad mount
80663	XS79CZ / L	Lindsay	B	940890 km	change engine oil & filters & fuel filters , grease and brake adjust , replaced uni joints on rear half of tail shaft , tighten loose coolant clamps , service custom air 3659 hrs , repair light fault in RHM light rear ,	CHM Shed	30-Apr-25	CHM - 12671	49 ltr x engine oil , 1 x auto grease , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter , 2 x CP25RPLS1 uni joint , 1 x LF689 diff filter , 1 x FF5018 fuel filter , 1 x P21-1038-U control turn signal ,
80162	XS79CZ / L	Lindsay		922895 km	remove tail shaft and replace power divider O-rings , remove and replace 2 x cab air bags ,	CHM Shed	31-Mar-25	CHM - 12419	2 x 5 x 1327 power divider O-ring , 2 x 1102-1001 air bag spring

					adjust clutch , clean diff breathers				
80024	XS79CZ / L	Lindsay	A	916610 km	check all fluid levels , grease and brake adjust , check all lights work , check over , tighten rubber mounts on custom air , replace cab ride height valve , adjust waste gate , check for boost leaks , replace guard bracket , adjust turn table ,	CHM Shed	21-Mar-25	CHM - 12281	1 x 1350-0111 assembly height control valve , 1 x CA5506 mud guard bracket , 1 x auto grease
78711	XS79CZ / L	Lindsay			service custom air & replaced starter motor & replaced belts & fit new sump plug & gauze , replace LHR drive axle air bag ,	Heavy Diesel / Burton	4-Mar-25	Inv - 1828	1 x air bag AG460 , 1 x air filter housing , 1 x oil filter , 1 x fuel filter , 1 x starter motor - custom air , 1 x belt , 1 x belt , 1 x oil drain plug , 3 ltr x turbo 40 oil ,
78538	XS79CZ / L	Lindsay		883172 km	possible low liner repair - lost coolant & compression lock , tow truck from TFI Lobethal / fitted new clutch / on repairs fitted new turbo , air filter , belt tensioner , idler pulley , OEM parts and radiator , engine mounts , exhaust supports & machined fly wheel & hose pack / strip engine , carry out rebuild fill with new oil and adjust clutch ,	Cummins / Adelaide CMV / Adelaide Cummins / Adelaide	13-Feb-25	Inv - I31130720 Inv - 1560352 Inv - 1616897	1 x 308938.583PAC Paccar genuine ADV clutch / 1 x 5607734RX recon turbo charger , 2 x AF4197 air filters , 1 x 3690067 tensioner belt , 1 x 3689465 pulley idler , 1 x 5551572 OEM parts , 1 x 5552145 machine flywheel , 1 x hose pack / 1 x 6489732RX recon cylinder head , 1 x 6438633 kit overhaul , 1 x 100328 seal O-ring , 1 x 4903514 seal O-ring , 2 x 3102109 seal O-ring , 3 x 3824541 disk surface condition , 1 x 5484100 shaft idler , 1 x 3164067 sealant silicone , 1 x 3689630 gear idler , 1 x 3690868 damper vibration VSCS , 1 x 4059172 seal O-ring , 1 x 5719759 core water pump , 3 x 2866337 gasket AFM , 1 x 3684384 seal O-ring , 65 ltr x PGXL coolant , 55 ltr x premium blue engine oil , 1 x 3104119 gasket cover plate , 1 x 4988280 gasket hydraulic pump , 1 x 3680260 shaft idler , 1 x 3686018 shaft idler ,
78442	XS79CZ / L	Lindsay		903198 km	air leak in truck ?? / replaced 2 pressure protection valves & 3 new fittings , replace air dryer cartridge and gasket , replace PBR fittings on Suzi coil	CHM Shed	6-Feb-25	CHM - 11871	1 x AB1397 female/male PBR fitting , 2 x TRPN15759BA pressure protection valve , 1 x TRP109914 valve ST4 , 1 x T224P air dryer cartridge , 1 x 68NTA-4-2 fitting , 1 x K129-232-0608 fitting male 45deg , 1 x 012503E elbow 1/4 x 1/4 M/F

78397	XS79CZ / L	Lindsay			travel to Naracoorte saleyards - had to replace Suzi coil air lines , replace 7 pin plug , replace PBR male/female air fittings	Poss Haulmark / Adelaide	4-Feb-25	Inv - 86004	1 x 200203 long tail suzi coils , 2 x 33A85 coupling male 1/2", 2 x 33A20 adaptor male 1/2", 1 x 4911bulk metal trailer plug
78348	XS79CZ / L	Lindsay	C	896744 km	change engine oil & filters & fuel filters , , grease and brake adjust , change air filters , check all lights work , change diff oil & filters , change air filters , top up auto greaser , replace bottom heater tap , replace inner cab shock absorber , replace leaking diff filter , replace icepack mounts , replace side light with new , replace LH steer hub cap	CHM Shed	29-Jan-25	CHM - 11871	1 x 2073 red/amber side marker , 1 x SU-TM custom air rubber bush , 1 x SPB-S-3-10-B12-A breather , 1 x LF14000NN engine oil filter , 1 x LF3335 fleet guard filter oil , 1 x FS19764 element 10 micron , 1 x A3380W168 filter , 1 x UF110 replacement element , 1 x FF5776 fuel filter , 1 x 25189011 A/C filter , 1 x AS2474 air filter , 49 ltr x engine oil , 38 ltr x 85W/140 diff oil , 1 x LF637 lube filter , 1 x 343-4046 hub cap , 1 x V404P-10-6 heater tap , 1 x BS.230.N70 diff filter O-ring , 1 x CB0260 cab shock absorber
78151	XS79CZ / L	Lindsay			1 x BGK1T2M-1/4 blow air gun hose for cab	Brown & Hurley / Tamworth	8-Jan-25	Inv - 3426033	
78970	XS79CZ / L	Lindsay		873310 km	Regas custom air - gas was OK , found rubbed wire and blown fuse , repaired all OK	CHM Shed	9-Dec-24	CHM - 11495	
78925	XS79CZ / L	Lindsay			remove and fit new alternator to custom air	Mick Collyer Auto Electrical / Tamworth	3-Dec-24	Inv - 6335	1 x alternator DXA4122 , 1 x 10mm battery lug , 1 x 2pin QC plug ACX2681
78912	XS79CZ / L	Lindsay			check custom air orange light on - after inspection found that it will need a new alternator	Glen Artney	30-Nov-24	Inv - 75833	
78867	XS79CZ / L	Lindsay	A	867062 km	check all fluid levels , grease and brake adjust , top up auto greaser - do not over fill , check all lights work , top up diff oil & engine oil , replace engine fan & A/C belt , replace bull bar indicator	Glen Artney	29-Nov-24	Inv - 75818	1 x 12PK2290 Dayco poly ribbed belt , 1 x 6PK1625 V belt ribbed , 1 x ATS235CA12 recessed amber indicator 235mm ,
78595	XS79CZ / L	Lindsay	B	847955 km	change engine oil & filters , grease and brake adjust , check all lights work , reconnect wire to custom air starter motor & replace earth wire	CHM Shed	31-Oct-24	CHM - 11162	1 x element 10 micron fuel filter euro 5 , 1 x engine oil filter , 1 x fuel filter , 49 ltr x engine oil , 1 x S16-1023-601 interior sun visor clip , 1 x S/motor suit Kubota icepack , 1 x air filter , 1 x diff filter , 1 x fuel filter ,

78550	XS79CZ / L	Lindsay			remove old tracker and fit new tracker	Ryans Auto	25-Oct-24	Inv - 0450	
78315	XS79CZ / L	Lindsay	B	828455 km	change engine oil & filters , change fuel filters , grease and brake adjust , check all lights work , top up auto greaser , check other fluid levels , replace Deutsch plug & reseal front diff	CHM - Shed	30-Sep-24	CHM - 10943	Need to get back - will need to change out front spring pack as has movement / 1 x engine oil filter , 1 x element 10 micron fuel filter euro 5 , 1 x fuel filter , 1 x A3380W1687 filter , 1 x 2208A1197 gasket , 2 x Narva terminal male Deutsch , 1 x Narva 2 way Deutsch female connector , 49 ltr engine oil , 2 x 839310 track rod bush , 1 x 14894 blue max Loctite
78304	XS79CZ / L	Lindsay			1 x LL040201AU TRP front indicator lamp	CMV / Adelaide	18-Sep-24	Inv - I31113961	
78713	XS79CZ / L	Lindsay		817441 km	remove and replace sun visor clip / supply driver with governor valve	CHM Shed	12-Sep-24	CHM - 10799	1 x 275707 valve governor 105-125 PSI , 1 x S16- 1023-601 interior sun visor clip
78098	XS79CZ / L	Lindsay			sun visor clip , spare governor valve	CHM Shed	12-Sep-24		
77974	XS79CZ / L	Lindsay			replaced drive air bag LH rear drive axle	Corey - CHM	28-Aug-24	CHM - 10683	1 x C81-1005 air bag MAF9541AU
78109	XS79CZ / L	Lindsay			1 x P28-1055 radio AM/FM alpine	BMG	27-Aug-24	Inv - 616557	
78173	XS79CZ / L	Lindsay	C	796475 km	change engine oil & filters , grease and brake adjust , check all lights work , change diff oil & filter , change air filters , carry out tune up , repaired broken wire on custom air , repair auto grease line leak , change air filters ,	CHM Shed	13-Aug-24	CHM - 10562	1 x 25189011 A/C filter , 18 ltr 3416169 Castrol transmax gear box oil , 1 x coupling olive double acting , 3 x P708-1/2" barb joiner , 6 x 92208 Dayco automotive clamp , 49 ltr engine oil , 40 ltr x 85W/140 diff oil , 1 x auto grease , 1 x BS.230.N70 diff filter Oring , 1 x LF14000NN engine oil filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x fleet guard filter oil , 1 x LF637 oil filter , 1 x UF110 replacement element inline

77605	XS79CZ / L	Lindsay		783632 km	leaking brake booster	Anthony Morris / Warrnambool	23-Jul-24	Inv - 111541	remove and replace RHF drive axle brake booster 30/30
77412	XS79CZ / L	Lindsay	B	774562 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser , replace RHS wheel seal , replace belt tensioner	CHM Shed	3-Jul-24	CHM - 10208	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 49 ltr engine oil , 1 x auto grease , 1 x 89440 Dayco belt tensioner , 1 x HG4009 hub cap gasket , 1 x 43764S wheel seal , 1 x 343-4046 hub cap ,
77162	XS79CZ / L	Lindsay	A	754545 km	check fluid levels , grease and brake adjust , top up auto greaser , check all lights work	CHM Shed	31-May-24		
77935	XS79CZ / L	Lindsay	B	740820 km	change engine oil & filters , grease and brake adjust , top up auto greaser , check all lights on , replaced front engine mounts , replaced indicator stalk , replace steer shock absorbers , tighten through shaft yolk , replace exhaust flex under engine	CHM Shed	10-May-24	CHM - 9978	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 2 x 090-2209SP3B Koni front shocks , 1 x SSFBKEN127-440-V2 exhaust flex , 3 x 2866337 gasket AFM service , 49 ltr engine oil , 1 x auto grease
77622	XS79CZ / L	Lindsay	A	717930 km	check fluid levels , grease and brake adjust , top up auto greaser , check all lights work , remove and replace LF brake shoe , reshim S-cam , faulty stalk	CHM Shed	10-Apr-24	CHM - 9929	1 x kit brake shoe steer 16 ,

76594	XS79CZ / L	Lindsay	B	708495 km	change engine oil & filters , grease and brake adjust , top up auto greaser , check all lights on , change air cleaners , fit new sun visor clip . Replace LH wheel seal , replace custom air stop solenoid	CHM Shed	25-Mar-24	CHM - 9759	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x 43764S wheel seal , 1 x stop solenoid OC60 , 1 x HG4009 hub cap gasket
76503	XS79CZ / L	Lindsay			replace sun visor clip , change air filters , replace solenoid on custom air	CHM Shed	14-Mar-24		
77056	XS79CZ / L	Lindsay	C	675348 km	change engine oil & filters , grease and brake adjust , check all lights work , change diff oil & filter , AdBlue fault - flush lines and replace injector , service icepack @ 2773 hrs , replace rear diff sensor , check turn table adjustment , replaced 4 x battery's , top up auto greaser	CHM Shed	9-Feb-24	CHM - 9247	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x fleet guard oil filter , 1 x UF110 replacement element inline , 1 x LF637 oil filter , 1 x A3380W1687 filter , 1 x AS2474 air filter , 1 x BS.230.N70 diff filter O-ring , 49 ltr engine oil , 40 ltr diff oil , 1 x injector doser Q67376 (4 hole) , 1 x LF689 diff filter , 1 x FF5018 fuel filter , 1 x AF25550 air filter , 4 x battery Explorer 85AH
76370	XS79CZ / L	Lindsay	B	634624 km	change engine oil & filters , grease and brake adjust , top up auto greaser , replace pitman arm bolt with new , replace A/C belt tensioner with new , top up ice Pac gas	CHM - Shed	5-Dec-23	CHM - 8884	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 49 ltr engine oil , 1 x 3690067 belt tensioner , 0.50 R134A air conditioning gas , auto grease
76036	XS79CZ /L	Lindsay	A	613258 km	replaced leaking water pump , replace A/C belt , Regas ice Pac , check fluid levels , grease and brake adjust , top up auto greaser ,	CHM - Shed	8-Nov-23	CHM - 8745	1 x 3687045P water pump ISX E5 , 1 x 5413204 belt , 1.30 x R134A air conditioning gas

75722	XS79CZ / L	Lindsay			inspect boost leak - found broken clamp replace with new	CHM - Shed	29-Sep-23	CHM - 8415	6 x K077-372-66 clamp , 1 x HE8701 hump hose 4"x4"x8"
75516	XS79CZ / L	Lindsay	A	582988 km	change engine oil & filters , grease and brake adjust , top up auto greaser , check all lights work , clear airline and replace doser unit injector , replace fan belt , replace boost clamp	CHM Shed	4-Sep-23	CHM - 8068	2 x WW460R125 wiper refill , 1 x K077-372-66 clamp , 1 x 6 hole injector doser euro 5 , 1 x 3100189 belt
75267	XS79CZ / L	Lindsay	A	582988 km	check fluid levels , grease and brake adjust , replace wiper blades , replace broken boost clamp , replace fan belt , replace AdBlue injector ,	Corey , Reece	4-Sep-23		
75084	XS79CZ / L	Lindsay			1 x R11-2541 LH mirror bracket	BMG	29-Aug-23	Inv - 596730	
75021	XS79CZ / L	Lindsay	C	563346 km	change engine oil & filters , grease and brake adjust , check all lights work , change diff oil & filter , service ice Pac @ 2212 hrs , carry out tune up , fit LH KW1647 & RH KW1648 819133 windscreens	Josh , Tom , Obrien's Windscreens / Murray Bridge	8-Aug-23	Inv - 144253 CHM - 7804	1 x AS2474 air filter , 1 x LF637 oil filter , 1 x FS19764 element 10 micron fuel filter euro 5 , 1 x FF5776 fuel filter , 1 x A3380W1687 filter , 1 x LF3335 fleet guard filter oil , 1 x LF14000NN engine oil filter , 1 x BS.230.N70 diff filter O-ring , 1 x FF5018 fuel filter , 1 x AF25550 air filter , 1 x LF689 diff filter
74916	XS79CZ / L	Lindsay			check over truck for any air leaks	Tom , Corey	27-Jul-23		
74717	XS79CZ / L	Lindsay	A	545112 km	check fluid levels , grease and brake adjust , check for air leaks , fit unloader kit in air dryer , tighten boost hoses	Reece , Corey , Tom	4-Jul-23	CHM - 7396	1 x 235 kit unloader air dryer

74421	XS79CZ / L	Lindsay		534399 km	found active faults 3569 / 3575 , AdBlue blockage - replace nozzle and carry out wet flush , faults gone inactive , clear codes	Cummins / Mt Gambier	14-Jun-23	Inv - 9821167	1 x A034L833 - 6 hole injector doser
74390	XS79CZ / L	Lindsay	B	527722 km	change engine oil & filters , grease and brake adjust , top up auto greaser , replace bull bar mud flaps , change alternator wiring , replace speed sensor , fit new air blower in cab behind driver's seat , adjust governor valve - gave driver spare governor valve & CAC clamps	Tom , Luke	8-Jun-23	CHM - 7168	1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter , 1 x FF5776 fuel filter , 1 x Q21-6004 duel speedo / tachometer sensor , 4 x 92208 Dayco automotive clamp , 2 x B9228-0275B clamp , 2 x K077-372-73 charge air clamp , 2 x K077-372-66 clamp , 1 x 275707 governor valve
74176	XS79CZ / L	Lindsay	Call Out		travel to CHM shed - change out alternator !	Sam	22-May-23	CHM - 7165	1 x alternator - Leece Neville , 1 x A3-199-pulley 12 multi 77x75x22
74175	XS79CZ / L	Lindsay	A	514565 km	check fluid levels , grease and brake adjust , replace all 4 drive shocks , replace lower heater tap , replaced doser unit - did over ride test all OK , replaced injector	Tom , Luke	16-May-23		
74038	XS79CZ / L	Lindsay	B	493898 km	change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser ,	Josh , Reece	24-Apr-23	CHM - 6994	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter ,
73865	XS79CZ / L	Lindsay			1 x 5 ltr engine oil	Brown & Hurley / Tamworth	18-Apr-23	Inv - 2848489	
73712	XS79CZ / L	Lindsay			replace wiper blades	Reece	28-Mar-23	CHM - 6821	2 x WW460B125 wiper blades 460 x 12.5mm

73702	XS79CZ / L	Lindsay	A	472653 km	check fluid levels , grease and brake adjust , check all lights work . Fit new exhaust stacks	Luke , Corey	21-Mar-23		
73555	XS79CZ / L	Lindsay	C	457753 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter , blew out diff breathers , change air filters , checked waste gate , repaired wiring for ice Pac , replace missing bolts , replace front diff input seal	Reece , Josh	28-Feb-23	CHM - 6750	1 x UF110 replacement element inline , 1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring , 1 x FF5776 fuel filter , 1 x LF1400NN engine oil filter , 1 x AS2474 air filter , 1 x LF637 oil filter , 1 x LF3335 fleet guard filter oil , 1 x FS19764-10 micron fuel filter , 2 x X011623 air cleaner element
73112	XS79CZ / L	Lindsay		425612 km	inspect icepack fault - top up gas (1773 hrs)	Sam , Josh	10-Jan-23		
72964	XS79CZ / L	Spare / Lindsay			1 x governor Valve	BMG	20-Dec-22	Inv - 582418	governor valve fitted by Poss / Brett
72769	XS79CZ / L	Chris	Call Out		travel to Naracoorte Depot - wind back Cummins motor as to relieve hydraulic issue , then had to jump start truck as flat battery's , top up with water to get to Mount Gambier	Naracoorte Truck & Bus	25-Nov-22	Inv - 53114	
72703	XS79CZ / L	Will			sun visor clip	TTT	23-Nov-22	Inv - 171059	

72579	XS79CZ / L	Chris	B	415020 km	replace heater hose as split , also did test for dropped liner and failed - so sent truck to Cummins Mt Gambier	Cummins / Mt Gambier	3-Nov-22	Inv - 9582740	under warranty - new rings & liners , wash radiator & CAC out , replace thermostat , tune engine , flush AdBlue system ,
72446	XS79CZ / L	Chris	B	401959 km	change engine oil & filters , grease and brake adjust , check all lights work , change gear box oil & filter , replace drums & brake shoes & S-cams	Scott , Mike	20-Oct-22	CHM - 5848	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x LF3335 fleet guard filter oil , 18 ltr x 3416169 Castrol transmax gear box oil , 1 x 2210V7536FW-KW right S-cam , 1 x 2210W7537FW left S-cam , 1 x K1T9078 kit , 2 x 47693S wheel seal , 2 x KSMA3124707QP drive brake shoe kit , 2 x DB017TRP brake drum
72284	XS79CZ / L	Chris	A	390713 km	check fluid levels , grease and brake adjust , check all lights work	Reece , Josh	7-Oct-22		
72035	XS79CZ / L	Lindsay / Chris	C	367820 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter ,	Luke , Mike	8-Sep-22		
72035	XS79CZ / L	Chris	C	367820 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter ,	Luke , Mike	8-Sep-22	CHM - 5695	1 x BS.230.N70 diff filter O-ring , 1 x A3380W1687 filter , 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x UF110 AdBlue filter , 1 x LF3335 fleet guard filter oil , 1 x AS2474 air filter , 1 x LF637 oil filter ,
72633	XS79CZ / L	Lindsay		364166 km	mirror bracket replaced under warranty , replaced LH drive shocker under warranty / These items not covered under warranty - replaced roof light , refit A/C drain hose , replace front drive shocker rubbers	BMG	8-Aug-22	Inv - KWFT352635	

71745	XS79CZ / L	Lindsay	A	358183 km	check fluid levels , grease and brake adjust , top up auto greaser , check all lights work	Luke , Josh	3-Aug-22		
71500	XS79CZ / L YN02DP / L	Lindsay			Rivets , door seal , hinge	Bunnings / M-Bridge	13-Jul-22	Inv - 974843	Paid Lou : trans credit card
71436	XS79CZ / L	Lindsay	B	337978 km	change engine oil & filters , grease and brake adjust , top up auto greaser , replace air filters , replace wiper blades , clutch adjustment	Josh , Sam , Mike	28-Jun-22	CHM - 5148	1 x LF14000NN engine oil filter , 1 x FS19764-10 micron fuel filter , 1 x FF5776 fuel filter , 1 x 3103233 fan belt , 1 x X011623 air cleaner element , 2 x NVTR710-10 wiper blades refill 28', 0.25 PGXLVITAL 20 ltr coolant
71053	XS79CZ / L	Lindsay			1 x puncture repair	West Wyalong	19-May-22		
70878	XS79CZ / L	Lindsay	B	306691 km	change engine oil & filters , grease and brake adjust , top up auto greaser , replace RH rear wheel seal ,	Mike , Josh , Beetle	26-Apr-22	CHM - 4844	1 x LF14000NN engine oil filter , 1 x FS19764 10 micron fuel filter , 1 x DB017TRP - TRP 16.5 x 7 brake drum , 1 x KSMA3124707QP drive brake shoe , 1 x 47693S wheel seal
70811	XS79CZ / L	Lindsay		298941 km	driver complained of air leaks - put trailers over pit could find any on truck or trailers	Sam	11-Apr-22		
70475	XS79CZ / L	Lindsay	A	280950 km	check all fluid levels , grease and brake , check all lights , tighten LH front mud guard	Josh , Scott , Mike	8-Mar-22		

70340	XS79CZ / L	Lindsay			inspect and test fridge - failed cooling unit	Murray Heating & Cooling	17-Feb-22	Inv - 63558	
70114	XS79CZ / L	Lindsay	C	268286 km	change engine oil & filters , grease and brake adjust , top up auto greaser , change diff oil & filter , change air filters , tune up	Luke , Josh , Brett	1-Feb-22	CHM - 4426	1 x LF14000NN engine oil filter , 1 x AS2474 air filter , 1 x A3380W1687 filter , 1 x LF637 oil filter , 1 x 17237 gear box filter , 1 x 25189011 A/C filter , 1 x FS19764-10 micron fuel filter , 1 x HHW0116 AdBlue suction filter , 1 x BS.230N70 diff filter O-ring , 2 x 6203-2RSH idler bearing , 2 x X011623 air cleaner element , .25 x PGXL vital coolant red (20 ltr)
69386	XS79CZ / L	Lindsay	A	216706 km	check fluid levels , grease and brake adjust , adjust turn table and grease ,	Josh , Josh	1-Nov-21		
69131	XS79CZ / L	Lindsay	B	196001 km	change engine oil & filters , grease and brake adjust , top up auto greaser , LH rear drive shock weeping , rewire speedo and connector , replace 4 x new battery's , ice Pac starts randomly ??	Luke , Brett , Josh G , Josh B Bea u repairs / M-Bridge	30-Sep-21	Inv - 6412243878 CH M - 3683	4 x XN70EX battery / 1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter
68829	XS79CZ / L	Lindsay		176380 km	drill out broken stud for road train sign in bull bar	Sam	26-Aug-21		
68514	XS79CZ / L	Lindsay	B	155549 km	change engine oil & filter , grease and brake adjust , check all lights work , check all fluid levels , replace water filter	Luke , Josh G	22-Jul-21	CHM - 3254	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x WF2127 coolant filter , 1 x PGXL vital coolant 20 ltr

68209	XS79CZ / L	Lindsay	A	135691 km	check fluid levels , grease and brake adjust , top up coolant , top up auto greaser	Josh G . Josh B	15-Jun-21	CHM - 3252	1 x PGXL vital coolant 20 lt (red)
68048	XS79CZ / L	Lindsay	A	122308 km	grease and brake adjust , top up auto greaser , drain diff oil & change filter , replace O-ring , found broken wire on icepack shut down solenoid 914 hrs	Josh G , Sam	13-May-21	CHM - 3097	1 x A3380W1687 filter , 1 x BS.230.N70 diff filter O-ring
67692	XS79CZ / L	Lindsay	B		change engine oil & filters , grease and brake adjust , check all lights work , top up auto greaser	Brown & Hurley / Tamworth	29-Apr-21	Imv - 2177862	
67602	XS79CZ / L	Lindsay	A	101630 km	grease and brake adjust , top up auto greaser , check fluid levels , repair ice pac alternator wiring , adjust turn table	Luke , Sam	13-Apr-21	CHM - 3034	
67359	XS79CZ / L	Lindsay	B	78197 km	change engine oil & filters , check lights work , top up auto greaser , grease and brake adjust , weld up mirror brackets , service icepack 664 hrs	Josh G , Luke	9-Mar-21	CHM - 2667	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764-10 micron fuel filter , 1 x FF5018 fuel filter , 1 x LF689 ice pack filter , 1 x AF25550 air filter ,
61939	XS79CZ / L	Lindsay	B	57881 km	change engine oil and filters , change fuel filters , grease and brake adjust , check other fluid levels , check all lights work , re-glue trim in bunk	BMG	5-Feb-21	Inv - KWFT330721	found missing O-ring in A/C - recovered gas fitted new O-ring and Regas test all OK - covered under warranty
61786	XS79CZ / L	Lindsay	A	40632 km	grease and brake adjust , top up auto greaser , check fluid levels ,	Josh B	11-Jan-21		

61528	XS79CZ / L	Lindsay	B	19525 km	first service - Order number given by BMG 1S88396 , change engine oil and filters , grease and brake adjust , top up auto greaser , check all lights work , check all other fluids	Sam , Beetle , Josh G , Luke	3-Dec-20	CHM - 2432	1 x LF14000NN engine oil filter , 1 x FF5776 fuel filter , 1 x FS19764- 10 micron fuel filter , 1 x AS2474 air filter , 1 x 17237 gear box filter , 1 x LF637 oil filter , 1 x A3380W1687 filter , 18 x 3416169 Castrol transmax gear box oil , 1 x BS.230.N70 diff filter O-ring
61320	XS79CZ / L	Lindsay		1190 km	runs wires from battery box to LH locker box , fit 150 amp fuse in battery box	Sam hard Auto	10-Nov-20	Inv - 43859	
61280	XS79CZ / L	New Truck		1189 km	fit up new Suzi coils , EBS cord , 7 pin suzi lead	Josh G , Josh B	5-Nov-20		
61329	XS79CZ / L	Lindsay			install Navman cube	Evolution Autofit / Troy	28-Oct-20	Inv - 118488	