

Repair Order Detail - Customer Copy

2018

RO Number: FS61639

RO Status: CLOSED

Customer: ALL NORTH TRUCKING LTD

ALLNORTHTRUCKING@TELUS.NET

Phone(s): Contact:

Main: (250)261-1569

Cell:

Vehicle: 1NKDL40X07R932331

2007 DEFF

Mileage: 708,610

Payment type:

Waiter: No

Service advisor: 99999

Estimate: 0.00

Tag number:

TCXT	CTCXT	#6: 023 GENERAL OP CODE - CLUTCH SUBLET FLYWHEEL RESURFACING	0.00
Tech(s): 99999			
Pts:	0.00 Lbr:	0.00 Other:	0.00 Total Line F: 0.00
G	TCXT	#7: 042 RAD R&R WITH NEW REPLACE RAD NEW REPLACE RAD	474.00
Tech(s): 223			
X5601-20		1 RADIATOR	2,891.78
M200-70EP		4 BUSHING-R	92.04
07-03286RUB		4 MOUNT-RAD	161.12
374-058		2 LOCKNUT	1.38
K221-2325		2 SPACER-RA	82.72
Pts:	3,229.04 Lbr:	474.00 Other:	0.00 Total Line G: 3,703.04
H	TCXT	#8: 001 GENERAL OP CODE - HVAC SYSTEMS REPLACE A/C LINE REPLACE A/C LINE	79.00
Tech(s): 223			
D9031-1541		1 HARDLINE	270.03
Pts:	270.03 Lbr:	79.00 Other:	0.00 Total Line H: 349.03
I	TCEF	#9: 045 GENERAL OP CODE - ENGINE POWER PLANT REPAIR FOR CHECK ENGINE LIGHT CHECK ENGINE LIGHT	162.00
Tech(s): 223			
Q21-6007S		1 SENSOR	215.55
CN26400		1 TERMINAL-	1.47
CN50200		1 SEAL-PACK	1.45
Pts:	218.47 Lbr:	162.00 Other:	0.00 Total Line I: 380.47
RO	MISC	C MISCELLANEOUS SUPPLIES	499.99
Pts:	0.00 Lbr:	0.00 Other:	499.99 Total Line RO: 499.99

Repair Order Detail - Customer Copy

RO Number: FS61639

RO Status: CLOSED

Customer: ALL NORTH TRUCKING LTD

ALLNORTHTRUCKING@TELUS.NET

Phone(s): Contact:

Main: (250)261-1569

Cell:

Vehicle: 1NKDL40X07R932331

2007 DEFF

Mileage: 708,610

Payment type:

Waiter: No

Service advisor: 99999

Estimate: 0.00

Tag number:

DR6152RXCUM	1	ENGINE-IS	40,591.97
DR6152RXCUM#	1	CORE	10,933.61
FREIGHT	1	FREIGHT	437.90
422-716	8	STRUCTURAL	1.76
4988280CUM	1	GASKET-PU	4.18
G0011-12	1	STRAIGHT	0.35
CT05317	20	TIE-CABLE	4.00
CT05512	20	TIE-CABLE	7.80
HWC12713	2	NUT-HEX S	1.82
3678603CUM	1	O-RING	4.60
500010048C	43	15W40 BULK	183.18
500010048C&	43	EHC	2.15
EC7501	1	COOLANT-T	12.20
EC7501&	1	EHC	1.14
COUPON	1	Y1863	-1.00
9212TRP	1	CLAMP-HOS	1.87
500010048C	3	15W40 BULK	12.78
500010048C&	3	EHC	0.15
DR6152RXCUM*	-1	CORE TBRB	-10,933.61
D13-1001-1	2	BUSHING-E	246.54
K066-421	2	BUSHING-S	135.82
K066-404	2	BUSHING-R	52.42
K066-423	2	BUSHING-E	173.40
AF25247FLG	2	FILTER-AI	144.14
EC7101	2	COOLANT-T	36.34
EC7101&	2	EHC	2.28
EC7501	12	COOLANT-T	146.40
EC7501&	12	EHC	13.68
Pts:	42,469.18	Lbr:	6,804.00
		Other:	0.00
		Total Line D:	49,273.18

E	#5: 023 CLUTCH REPLACEMENT; INCLUDES R/R OF TRANSMISSION AND ADJUSTMENT REPLACE CLUTCH, INPUT SHAFT AND LINKAGE	158.00
TCXT	CTCXT #5: 023 CLUTCH REPLACEMENT; INCLUDES R/R OF TRANSMISSION AND ADJUSTMENT REPLACE CLUTCH, INPUT SHAFT AND LINKAGE	
	Tech(s): 223	
	SB200	1 CLUTC BRK 39.46
	6306LLUA1C3/2E	1 BEARING 18.39
Pts:	57.85	Lbr: 158.00
		Other: 0.00
	Total Line E:	215.85

F #6: 023 GENERAL OP CODE - CLUTCH SUBLET FLYWHEEL RESURFACING

Repair Order Detail - Customer Copy

RO Number: FS61639

RO Status: CLOSED

Customer: ALL NORTH TRUCKING LTD

ALLNORTHTRUCKING@TELUS.NET

Phone(s): Contact:

Main: (250)261-1569

Cell:

Vehicle: 1NKDL40X07R932331

2007 DEFF

Mileage: 708,610

Payment type:

Waiter: No

Service advisor: 99999

Estimate: 0.00

Tag number:

~~~~~				
A	#1: 051 GENERAL OP CODE - HUBOMETER, TACHOMETER, NAV AND GPS TRAVEL TO AND FROM CUSTOMER			
TCTR	CTCTR	#1: 051 GENERAL OP CODE - HUBOMETER, TACHOMETER, NAV AND GPS TRAVEL TO AND FROM CUSTOMER		352.00
	Tech(s):	248		
Pts:	0.00	Lbr:	352.00	Other: 0.00 Total Line A: 352.00
~~~~~				
B	#2: 044 TROUBLESHOOTING FUEL SYSTEMS DIAGNOSE FUEL ISSUES			
TCFS	CTCFS	#2: 044 TROUBLESHOOTING FUEL SYSTEMS DIAGNOSE FUEL ISSUES		352.00
	Tech(s):	248		
Pts:	0.00	Lbr:	352.00	Other: 0.00 Total Line B: 352.00
~~~~~				
C	#3: 045 DIAGNOSE FOR LOW OIL PRESSURE DIAGNOSE FOR LOW OIL PRESSURE			
TCEF	CTCEF	#3: 045 DIAGNOSE FOR LOW OIL PRESSURE DIAGNOSE FOR LOW OIL PRESSURE		810.00
	Tech(s):	223		
Pts:	0.00	Lbr:	810.00	Other: 0.00 Total Line C: 810.00
~~~~~				
D	#4: 045 GENERAL OP CODE- DROP IN CUMMINS - ENGINE POWER PLANT R&R OF CUMMINS DROP IN ENGINE			
TCEF	CTCEF	#4: 045 GENERAL OP CODE- DROP IN CUMMINS - ENGINE POWER PLANT R&R OF CUMMINS DROP IN ENGINE		6,804.00
	Tech(s):	223		
	COUPON	14 Y1863		-14.00
	LF637FLG	1 ELEMENT-O		14.89
	LF637FLG&	1 EHC		0.55
	351-0474	1 HEATER-BL		38.54
	3678606CUM	5 SEAL,O RI		23.55
	3682673CUM	1 GASKET-TH		26.64
	D1030-2650	20 HOSE-RADI		40.40
	CT300LTRP	8 CLAMP-CON		92.48
	80-100-50	4 SILCONE		24.36
	9216TRP	2 CLAMP-HOS		3.90

Repair Order Detail - Customer Copy

Customer Pay	
Labor	9,191.00
Parts	46,244.57
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	499.99
Deductible	0.00
Total Charges	55,935.56
Less Insurance/Adjustment	0.00
Sales Tax	6,712.27
Total	62,647.83

Sales Invoice

Number: 3100
 Issued: 10/11/2022
 Due: 11/10/2022

Deliver To
 site 14 comp 25 RR#1
 Fort St John BC V1J4M6



All North Trucking Ltd.
 site 14 comp 25 RR#1
 Fort St John BC V1J4M6

Ionson Mechanical Ltd.
 Box 621
 Spirit River AB T0H3G0
 Canada
 ionsonmech@gmail.com
 GST/HST 859367294 RT 0001

Item	Qty/Hrs	Price/Rate	Sales Tax	Amount
June 7 - July 11 2022 -take pics and documents for versus valuations on unit -check over unit -pressure wash engine compartment -check codes - Check engine light due to egr system problems -recover ac -drain coolant -remove cooling package -remove fan hub -remove gear-train -remove valve train -remove inj -remove ifsm -remove exh manifold etc -remove cyl head -clean deck -measure protrusions - not very good due to cummins low protrusions -chase head bolt holes in block -clean and prep new head for install -swap components to new head -install head and torque -install ifsm -paint head -clean and reseal injectors and install -replace inj cam and 2 rockers due to hard surfacing damage -install geartrain and setup lash	43.00	130.00	GST 5.00%	5,590.00
SHOP RATE.				

Item		Qty/Hrs	Price/Rate	Sales Tax	Amount
	-install top end and perform vale set				
	-install exh manifold and turbo				
	-re-assemble engine				
	-install cooling package				
	- recharge ac system				
	-refill cooling system				
	-install venturi delete pipe				
	-tie up harnesses properly				
	-install hood spring				
	-install new satellite radio antenna				
	-flush cooling system a few times				
	-replace all coolant lines				
	-refill cooling system				
	-road test unit				
	-remove valve cover and replace jake solenoid				
	-unit not running correctly				
	-run diagnostics				
	-try alternative ecm - not issue				
	-replace inj 3				
	-perform valve set				
	-run unit - good				
	-retune with egr delete tune				
	-Road test unit - Good				
4902789	actuator gasket	2.00	7.02	GST 5.00%	14.04
4024759	engine brake solenoid	1.00	285.29	GST 5.00%	285.29
468-9112-16	thoro flush	1.00	31.01	GST 5.00%	31.01
4101432	871 injector camshaft	1.00	2,848.66	GST 5.00%	2,848.66
4311990	rocker lever	2.00	290.05	GST 5.00%	580.10
HWC06103	Gr5 5/8 - 18 x 3.75 bolt	1.00	15.96	GST 5.00%	15.96
4965698	isx exh. man bolts	12.00	9.44	GST 5.00%	113.28
4928594	exhaust gas back pressure sensor	1.00	215.14	GST 5.00%	215.14
4985492	turbo mounting nuts	4.00	12.31	GST 5.00%	49.24
4318947	thermostat	1.00	98.88	GST 5.00%	98.88
5575513	screw, hex bolt	4.00	10.82	GST 5.00%	43.28
HWC04072	bolt - eye closed M10-1.5x	1.00	32.98	GST 5.00%	32.98
3104392	valve cover gasket	1.00	82.07	GST 5.00%	82.07
3682826	seal - grommets	3.00	4.60	GST 5.00%	13.80
351-0474	block heater	1.00	40.20	GST 5.00%	40.20

Item		Qty/Hrs	Price/Rate	Sales Tax	Amount
SRTMM02	antenna	1.00	49.17	GST 5.00%	49.17
4120858	serpentine belt	1.00	135.97	GST 5.00%	135.97
4962732	APC DOHC new HD cylinder head	1.00	7,000.00	GST 5.00%	7,000.00
4955596	DOHC head gasket kit	1.00	1,049.40	GST 5.00%	1,049.40
used part	good used head bolt	1.00	10.00	GST 5.00%	10.00
310-1	Stage 1 EGR delete - 550HP/1850 Torque	1.00	2,500.00	GST 5.00%	2,500.00
	rad mount isolators	4.00	68.95	GST 5.00%	275.80
47000	Full Tilt isx 870 intake manifold-venturi delete	1.00	750.00	GST 5.00%	750.00
3067979	Vband clamp	1.00	59.79	GST 5.00%	59.79
WF2127	Coolant filter	1.00	36.81	GST 5.00%	36.81
4088665	cm870 fuel injectors	1.00	500.00	GST 5.00%	500.00
Core	- injector -not rebuild-able	1.00	200.00	GST 5.00%	200.00
SILH-063-50	5/8 silicone heater hose	19.00	5.50	GST 5.00%	104.50
f50-1050-1050	coolant hose #16 x 1050 mm	1.00	113.89	GST 5.00%	113.89
SilH-075-50	3/4 silicone heater hose	6.00	7.10	GST 5.00%	42.60
50/50 premix coolant	3.78 litres premixed	13.00	11.25	GST 5.00%	146.25
gd3000	concentrated re ext life coolant	2.00	20.79	GST 5.00%	41.58
shipping from GP	shipping from GP	2.00	33.00	GST 5.00%	66.00
shop supplies	on labour at 5%	1.00	279.50	GST 5.00%	279.50
Comments				Subtotal	23,415.19
KENWORTH TANDEM BOX TRUCK				GST 5.00%	1,170.75
UNIT - 02					
VIN - 1NKDL40XO78932331				Invoice Total	24,585.94
895967 KM					
4833 HRS				Total to Pay	\$24,585.94

Terms and Conditions

Cyl head SN- G0501211004788

No parts available at this time to rebuild bumper latch