

WO Date Created Scheduled Meter Reading End Meter Reading Pate Scheduled Scheduled Scheduled Reading Pate Reading Pate Scheduled Scheduled Pater Reading Pat
12 Monthly pressure vessel inspection 29604 103 inspection 25-Mar-25 25-Mar-25 15972 1 103 inspection 29601 Replace u/s hoses 24-Mar-25 24-Mar-25 15972 1 Replace u/s hoses 29580 Change u/s battery isolator 21-Mar-25 21-Mar-25 15972 1 Change u/s battery isolator 29123 LH steer cylinder leak 18-Dec-24 18-Dec-24 15972 1 LH steer cylinder leak 18-Nov-24 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 16-Oct-24 15968 1 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
29604 103 inspection 25-Mar-25 25-Mar-25 15972 1 103 inspection 29601 Replace u/s hoses 24-Mar-25 24-Mar-25 15972 1 Replace u/s hoses 21-Mar-25 21-Mar-25 15972 29580 Change u/s battery isolator 21-Mar-25 21-Mar-25 15972 1 Change u/s battery isolator 29123 LH steer cylinder leak 18-Dec-24 18-Dec-24 15972 1 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 18-Nov-24 18-Nov-24 2 Reseal fitting to accumulator 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 15968 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 103 inspection 29601 Replace u/s hoses 24-Mar-25 24-Mar-25 15972 1 Replace u/s hoses 29580 Change u/s battery isolator 21-Mar-25 21-Mar-25 15972 1 Change u/s battery isolator 29123 LH steer cylinder leak 18-Dec-24 18-Dec-24 15972 1 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 18-Nov-24 19-Pressure Vessel Inspection 2 Reseal fitting to accumulator 11TS spec 12-Nov-24 12-Nov-24 11TS spec 12-Nov-24 17-Oct-24 15968 1 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
29601 Replace u/s hoses 24-Mar-25 24-Mar-25 15972 1 Replace u/s hoses 29580 Change u/s battery isolator 21-Mar-25 21-Mar-25 15972 1 Change u/s battery isolator 29123 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 Replace u/s hoses 29580 Change u/s battery isolator 21-Mar-25 21-Mar-25 15972 1 Change u/s battery isolator 29123 LH steer cylinder leak 28966 Pressure Vessel Inspection 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 1 ITS spec 12-Nov-24 12-Nov-24 1 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 28753 Replace middle spray valve 1 15968 1 15968 1 15968 1 16-Oct-24 16-Oct-24 15968
29580 Change u/s battery isolator 1 Change u/s battery isolator 29123 LH steer cylinder leak 28966 Pressure Vessel Inspection 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 1 ITS spec 28761 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 28753 Replace middle spray valve 1 Change u/s battery isolator 21-Mar-25 21-Mar-25 18-Dec-24 18-Dec-24 18-Nov-24 18-Nov-24 18-Nov-24 17-Oct-24 17-Oct-24 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector
1 Change u/s battery isolator 29123 LH steer cylinder leak 18-Dec-24 18-Dec-24 15972 1 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 17-Oct-24 17-Oct-24 15968 Repair transmission selector 17-Oct-24 16-Oct-24 15968
29123 LH steer cylinder leak 18-Dec-24 1 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 1 ITS spec 1 ITS spec 28761 Replace spray valve solenoid 1 Replace spray valve solenoid 2 Replace spray valve solenoid 1 Replace spray rocker switch 28756 Repair transmission selector 1 Repair transmission selector 28753 Replace middle spray valve 1 15968
1 LH steer cylinder leak 28966 Pressure Vessel Inspection 18-Nov-24 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 17-Oct-24 17-Oct-24 15968 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
28966 Pressure Vessel Inspection 18-Nov-24 1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 1 Replace spray valve solenoid 2 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 Pressure Vessel Inspection 2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
2 Reseal fitting to accumulator 28934 ITS spec 12-Nov-24 12-Nov-24 1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
28934 ITS spec 12-Nov-24 12-Nov-24 1 1 ITS spec 17-Oct-24 17-Oct-24 15968 18eplace spray valve solenoid 17-Oct-24 17-Oct-24 15968 18eplace spray rocker switch 17-Oct-24 17-Oct-24 15968 18epair transmission selector 17-Oct-24 17-Oct-24 15968 18epair transmission selector 17-Oct-24 16-Oct-24 15968 18eplace middle spray valve 16-Oct-24 16-Oct-24 15968
1 ITS spec 28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
28761 Replace spray valve solenoid 17-Oct-24 17-Oct-24 15968 1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 Replace spray valve solenoid 2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
2 Replace spray rocker switch 28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
28756 Repair transmission selector 17-Oct-24 17-Oct-24 15968 1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 Repair transmission selector 28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
28753 Replace middle spray valve 16-Oct-24 16-Oct-24 15968
1 Replace middle spray valve assembly



			•			
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
28746	Rust repairs	14-Oct-24	14-Oct-24	15968		
	1 Rust repairs					
28739	Repair cannon wiring	11-Oct-24	11-Oct-24	15968		
	1 Repair cannon wiring					
28736	Secure spray valve hoses	10-Oct-24	10-Oct-24	15968		
	1 Secure hoses to body					
28733	Rust repairs	10-Oct-24	10-Oct-24	15968		
	1 Rust repairs					
28709	Tyre report	02-Oct-24	02-Oct-24			
	1 Tyre report					
28684	Defects	24-Sep-24	24-Sep-24	15968		
	1 Replace u/s dog bone bushes and	d suspension pads				
	2 Replace out of date seat belt					
	3 Replace u/s reverse light					
	4 Replace leaking steer and hydrau	ılic oil gauge				
	5 Replace u/s camera					
	6 Replace u/s bonnet switch					
	7 Replace u/s/missing safety sticke	ers/decals				
	8 Replace bump stops					
	9 HVAC repairs					
1	0 Replace leaking steer and hydrau	ılic oil gauge				
28576	Replace cannon hoses	27-Aug-24	18-Jun-24	15958		
	1 Replace hoses					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
28442	2000 hour service	10-Jul-24	10-Jul-24	15958		
2000	Ohr Service					
28260	Replace rubbed hyd hose on water tank	10-May-24	03-May-24	15954		
	1 Repalce hose					
28228	Replace failed AC hose	30-Apr-24	09-Apr-24	15948		
	1 Replace hose and regas system					
28106	Replace failed hyd hoses	02-Apr-24	14-Mar-24	15919		
	1 Replace hoses					
28090	Replace failed hyd cannon hose	27-Mar-24	27-Feb-24	15762		
	1 Replace failed hyd hose					
27944	Replace failed hyd cooler hose	13-Feb-24	05-Feb-24	15730		
	1 REplace failed hose					
27854	Replace failed reverse camera	23-Jan-24	23-Jan-24	15593		
	1 Replace reverse camera					
27817	Replace failed artic hose	15-Jan-24	15-Jan-24	15561		
	1 Replace hose					
27772	Replace leaking diff lock hose	19-Dec-23	19-Dec-23	15498		
	1 Replace hose					
27771	250hr Service	19-Dec-23	19-Dec-23			
250	nr Service					
27769	Water spray controller shorting out fuses	19-Dec-23	19-Dec-23	15438		
	1 Repair fault rubbed wire					



					Trate: ca
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading
27708	Replace corroded hyd cooler bracket	04-Dec-23	24-Nov-23	15438	
	1 Replace bracket				
27683	Leaking spray pump hose	29-Nov-23	29-Nov-23	15384	
	1 Repair hose				
27626	500hr Service	16-Nov-23	16-Nov-23	15409	
500	hr Service				
27625	250hr Service	16-Nov-23	16-Nov-23		
250	hr Service				
27617	Clean rocks out of sprays	16-Nov-23	26-Oct-23	15285	
	1 Clean out sprays				
27616	Replace split hydraulic hoses	16-Nov-23	24-Oct-23	15264	
	1 Replace hoses				
27605	Replace O-Ring on hyd hose	14-Nov-23	17-Oct-23	15240	
	1 Replace O-Ring				
27563	Replace failed injector	03-Nov-23	03-Nov-23	15152	
	1 Replace failed fuel injector				
27510	Replace steer stop pads	23-Oct-23	23-Oct-23	15023	
	1 Replace steer stops				
27357	1000hr Service	14-Sep-23	14-Sep-23	15023	
100	Ohr Service				
27351	Replace failed fuel sender	12-Sep-23	12-Sep-23	15023	
	1 Replace sender unit				



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27331	Steering stops worn out	08-Sep-23	08-Sep-23	15004		
1	Relace steering stops					
27330	Leaking brake cooling tube	08-Sep-23	08-Sep-23	15004		
1	Replace brake cooling tube					
2	Replace brake cooling tube					
27329	Leaking hoist hydraulic supply tube	08-Sep-23	08-Sep-23	15004		
1	Replace hydraulic tube					
27289	Replace door switch	29-Aug-23	29-Aug-23	14968		
1	Replace switch					
27288	Replace AC filter guard	29-Aug-23	29-Aug-23	14968		
1	1 Replace guard					
27287	Main control valve slight leak	29-Aug-23	29-Aug-23	14968		
1	1 Monitorleak repair if required					
27285	Cylinder head weeping	29-Aug-23	29-Aug-23	14968		
1	Monitor leak investigate repair op	otions if weep dev	elops			
27284	Rear lateral control rod outer bushes worn	28-Aug-23	28-Aug-23	14968		
1	Replace bushes					
27279	Replace leaking hydraulic steer hoses	28-Aug-23	28-Aug-23	14954		
1	Repalce hoses					
27278	Aircon repairs	28-Aug-23	28-Aug-23	14875		
1	1 Repair AC					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27197	250hr Service	02-Aug-23	02-Aug-23	14803		
250	hr Service					
27196	No power to water pump engage solenoid	02-Aug-23	02-Aug-23	14643		
	1 Repair bad crimp on wire & Replac	ce voltage reduce	r			
27165	Remove rocks from spray heads	26-Jul-23	26-Jul-23	14540		
	1 Remove rocks, clean sprays, check	suction for debri	S			
27006	Replace blown LHS top batter spray control hose	23-Jun-23	23-Jun-23	14608		
	1 Replace blown hose					
26951	Replace key	06-Jun-23	06-Jun-23	14506		
	1 Replace key					
26949	Repair faulty Air Con	06-Jun-23	06-Jun-23	14506		
	1 Repair AC					
26948	Repair leaking spray heads	06-Jun-23	06-Jun-23	14506		
	1 Repair leaking spray heads					
26947	500hr Service	06-Jun-23	06-Jun-23	14506		
500	hr Service					
26946	Replace diff filter	06-Jun-23	06-Jun-23	14506		
	1 Replace filter					
26904	Diagnose and repair active fault for blocked filter	30-May-23	30-May-23	14297		
	1 Repair faulty switch					
26874	Repair safety devices	22-May-23	22-May-23			
	1 Safety devices					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26873	Repair steer hose	22-May-23	22-May-23			
1	Steer hose - ABE					
26758	12 Monthly pressure vessel inspection	11-Apr-23	11-Apr-23	14293		
12 M	onthly pressure vessel inspection					
26744	Dipstick u/s - transmission	04-Apr-23	04-Apr-23			
1	Trans dipstick					
26743	Mirror u/s	04-Apr-23	04-Apr-23			
1	Mirror					
26550	Blown hose at water pump motor	06-Feb-23	06-Feb-23			
1	. Hyd hose					
26397	Repair water cannon actuator	02-Dec-22	02-Dec-22			
1	Repair water cannon actuator					
26389	Repair a/c	30-Nov-22	30-Nov-22			
1	Repair a/c					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26357	Complete brake application test	23-Nov-22	23-Nov-22	14273		
	Complete brake application test a	nd record results				Start the truck and run up to operational temperature Find a flat level area to perform the brake application test Check surroundings as truck may move Release the park brake and put the truck in DRIVE Shut the engine down using the EMERGENCY STOP button in the cab Apply the brake pedal and record the number of brake pedal applications achieved before the Park Brake Automatically applies/Park brake light on dash illuminates Perform the test 3 times Test 1 Number of applications Test 2 Number of applications Test 3 Number of applications
26226	Replace out of pressure test date extinguishers	29-Sep-22	29-Sep-22	14273		
	1 Replace extinguishers					
25654	Pressure vessel inspection	25-Mar-22	25-Mar-22			
12 N	Nonthly pressure vessel inspection					
25516	Repair LHS rear spray not shutting off	11-Feb-22	11-Feb-22			
	Repair LHS rear spray not shutting	off				
25469	Monthy Tyre inspection & pressure check	25-Jan-22	25-Jan-22			
	1 Monthy Tyre inspection & pressur	e check				
25444	Front A-frame bearing requires replacement	19-Jan-22	19-Jan-22			
	Front A-frame bearing requires re	placement				



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25443	Alternator and belt tensioner bearings are worn	19-Jan-22	19-Jan-22			
:	Alternator and belt tensioner bear	rings are worn				
25442	Fuel Transfer pump leaking at tell-tale hole	19-Jan-22	19-Jan-22			
:	1 Fuel Transfer pump leaking at tell-	tale hole				
25441	rear Axle drive shaft Universal joints replace	19-Jan-22	19-Jan-22			
	rear Axle drive shaft Universal join	ts replace				
25407	Diagnose and repair Short circuit in cannon Wiring	21-Dec-21	21-Dec-21			
:	Diagnose and repair Short circuit i	n cannon Wiring				
25397	Replace U/S LHS Mirrors	17-Dec-21	17-Dec-21	14215		
:	1 Replace U/S LHS Mirrors					
25330	Reseal Leaking Steering cylinders	15-Nov-21	15-Nov-21			
:	1 Reseal Leaking Steering cylinders					
25296	Diagnose and repair Blinker circuit faults	03-Nov-21	03-Nov-21			
	Diagnose and repair Blinker circuit	faults				
25213	6 month fire Extinguisher inspection	30-Sep-21	30-Sep-21			
	6 Month fire extinguisher inspecti	on				
25164	Repair brake cooling oil leaks- Tubes & hose	08-Sep-21	08-Sep-21			
	Repair brake cooling oil leaks- Tub	es & hose				



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25051	Repair wiring in steer column and blinker fault	26-Jul-21	26-Jul-21			
	1 Repairrubbed wiring in steer colu	mn				
	2 Repair blinker fault					
24892	Inspect Machine to possibly sell	11-May-21	11-May-21			
	1 Inspect Machine to possibly sell					
24750	12 Monthly Fire Extinguisher Inspection	25-Mar-21	25-Mar-21			
12 N	Monthly fire extinguisher inspection					
24741	12 Monthly pressure vessel inspection	24-Mar-21	23-Mar-21			
12 N	Monthly pressure vessel inspection					
24721	Repair blown hose RH spray	15-Mar-21	15-Mar-21			
	1 Repaired Blown Hose on RHS rear	spray cylinder				
24663	Indicator and hazard circuit inop	24-Feb-21	24-Feb-21	14115		
	1 Blinker and hazard circuit inop					
24631	Repair blown hyd hose on rear of tank	04-Feb-21	04-Feb-21			
	1 Repair blown hyd hose on rear of	tank				
24628	Repair leaking exhaust	03-Feb-21	03-Feb-21	14102		
	1 Repair leaking exhaust pipe					Diagnose Exhaust leak at muffler clamp, R&R exhaust joint clamp and re-align to stop leak 5/02 Inspect for exhaust leaks - hood raise fault - identify clamps & seals required.



Replace faulty hyd hose and fue 12-Feb-21 12-Feb-21 14102 14					• •		
Replace faulty hyd hoses Paper P							Notes
2 replace faulty fuel return hose 12-Feb-21 12-Feb-21 14102	24626		12-Feb-21	12-Feb-21	14102		
24624 Repair beacon wiring 12-Feb-21 14102 1 Repair beacon wiring 2 replace failed bonnet switch 2 replace failed bonnet switch 4 replace faile	:	1 Replace faulty hyd hoses					
Remove & replace water hyd pump Remove & replace hyd oil. Remove & replace water hyd pump Remove & replace hyd oil. Remove & replace hyd oil ooler Remove & replace water hyd pump Remove & replace hyd oil ooler Remove & replace water hyd pump Remove & replace hyd oil ooler Remove & replace water hyd pump Remove & replace hyd oil ooler Remove & replace water hyd pump Remove & replace hyd oil ooler Remove & r	:	2 replace faulty fuel return hose					
2	24624	Repair beacon wiring	12-Feb-21	12-Feb-21	14102		
1	:	1 Repair beacon wiring					
Inspect machine 250hr service 28-Jan-21 28-Jan-21 14040 14215	:	2 replace failed bonnet switch					
250hr service 28-Jan-21 28-Jan-21 14040 14215	24608	Inspect machine	08-Feb-21	08-Feb-21	14081		
250hr Service - Dont Use Wouldn't initialise 250hr Service - Dont Use Wouldn't initialise 250hr Service - Dont Use Wouldn't initialise 250hr Service - Wouldn't initialise 250		1 Inspect machine					
24573 250hr Service - Dont Use Wouldn't initialise 250hr Service 24568 Remove & replace water hyd pump 1 Remove & replace water hyd pump 22-Jan-21 22-Jan-21 14028 Rear hyd pump 24567 Investigate oil pressure gauge fault - broken wire 24568 Remove leaking brake oil cooler - 18-Jan-21 18-Jan-21 14020 11 14020 11 Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - 18-Jan-21 18-Jan-21 14020 19/01 Continue with change out of hyd oil cooler - start flushing cooling system. 20/01 flush system after hyd cooler failure - run & test	24575	250hr service	28-Jan-21	28-Jan-21	14040	14215	
Wouldn't initialise 250hr Service 24568 Remove & replace water hyd pump 1 Remove & replace water hyd pump 1 Remove & replace water hyd pump 20-Jan-21 20-Jan-21 14020 1 Investigate oil pressure gauge fault 1 Investigate oil pressure gauge fault 24548 Remove leaking brake oil cooler oil into coolant 1 Remove leaking brake oil cooler oil into coolant 24542 Replace faulty fire extinguisher 1 Replace faulty fire extinguisher 1 Respect fault fire extinguisher 1 Respect faulty fire extinguisher 2 Respect faulty fire extinguisher 2 Respect faulty fire extinguisher 2 Respect faulty fire extin		1 250hr service					
Remove & replace water hyd pump Rear hyd pump - replace hyd oil. Remove & replace water hyd pump Rear hyd pump - replace hyd oil. Repaired & tested. Repaired & tested. 18-Jan-21 18-Jan-21 14020 19/01 Continue with change out of hyd oil cooler - start flushing cooling system. 20/01 flush system after hyd cooler failure - run & test	24573		28-Jan-21	28-Jan-21	14040		
pump 1 Remove & replace water hyd pump 1 Rear hyd pump - replace hyd oil. 24567 Investigate oil pressure gauge fault 1 Investigate oil pressure gauge fault - broken wire 24548 Remove leaking brake oil cooler - 18-Jan-21 18-Jan-21 14020 Remove leaking brake oil cooler - oil into coolant 24548 Remove leaking brake oil cooler - oil into coolant 24548 Remove leaking brake oil cooler - oil into coolant 24548 Remove leaking brake oil cooler - oil into coolant 24548 Remove leaking brake oil cooler - oil into coolant 24549 Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 14020	250h	hr Service					
Investigate oil pressure gauge fault - broken wire Repaired & tested. Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 24542 Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 14020	24568		22-Jan-21	22-Jan-21	14028		
fault Investigate oil pressure gauge fault - broken wire Repaired & tested. Remove leaking brake oil cooler - 18-Jan-21 18-Jan-21 14020 oil into coolant Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant Remove leaking brake oil cooler - oil into coolant Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 14020		1 Remove & replace water hyd pun	ıp				Rear hyd pump - replace hyd oil.
Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 24542 Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 18-Jan-21 14020 19/01 Continue with change out of hyd oil cooler - start flushing cooling system. 20/01 flush system after hyd cooler failure - run & test	24567		20-Jan-21	20-Jan-21	14020		
oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 1 Remove leaking brake oil cooler - oil into coolant 20/01 flush system after hyd cooler failure - run & test 24542 Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 14020	:	1 Investigate oil pressure gauge fau	lt - broken wire				Repaired & tested.
system. 20/01 flush system after hyd cooler failure - run & test 24542 Replace faulty fire extinguisher 18-Jan-21 18-Jan-21 14020	24548	_	18-Jan-21	18-Jan-21	14020		
		1 Remove leaking brake oil cooler -	oil into coolant				system.
1 Replace faulty fire extinguisher	24542	Replace faulty fire extinguisher	18-Jan-21	18-Jan-21	14020		
		1 Replace faulty fire extinguisher					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24513	Defect repairs from 14000hr service	11-Jan-21	11-Jan-21	13996		
1	Hose over Artic U/S-P/N 349-2875	5				Brayden Avery replaced 2/11/21
2	Brake supply hose to front diff U/	S				Jake Cross Replaced 2/11/21
3	front diff lock hose U/S P/N-202-2	2046				Jake Cross Replaced 2/11/21
2	4 Lower radiator hose U/S					No repair required yet
5	Rear Axle drive shaft Uni joints we	orn				New W/O- 25441/1
6	Fuel Transfer pump leaking at tell	-tale hole				New W/O-25442/1
7	Rear fan pump Case drain hose U	/S				No repair required D.M
8	B Fuel hose U/S- P/N- 127-2254					Replaced ABE 7/9/21
g	Alternator & belt tensioner are w	orn				New W/O-25443/1
10	P5 wheel end leaking (Minor)					No Repair required (Monitor)
11	Suspension seat is worn out P/N-	379-1003				15/12 Inspect seat wear supply parts list - check SIS for parts available.
12	Lower hitch bearing is Worn					No Repair required yet Note only D.M
13	Front A-Frame bearing is worn					New W/O-25444/1
14	Exhaust leak at front Muffler					Brayden Avery repaired 5/9/21
15	Battery box cover plate is cracked	l out				No repair required D.M
24512	Replace POS 1 &2 tyres	11-Jan-21	11-Jan-21	14020		
1	Replace POS 1 &2 tyres					
24492	Replaced rear faulty flashing light	17-Dec-20	17-Dec-20			
1	Replaced rear faulty flashing light					



		• •				
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24472	Remove & repair rear sprays, repair wiring to cannon	14-Dec-20	14-Dec-20	13986		
2	1 Remove & repair rear sprays					U/S Diaphram
2	Repair wiring to cannon					Test - no connection, inspect wiring at control module 15/12 Repair electrical harness to cannon.
24458	2000hr Service	10-Dec-20	10-Dec-20	13986	13996	
2000	Ohr Service					
24403	Replace leaking POS 5 tyre	27-Nov-20	27-Nov-20			
-	1 Replace leaking POS 5 tyre					
24389	Replace front windscreen - Cracked	24-Nov-20	24-Nov-20			
-	1 Replace front windscreen					16/12 Fit new windscreen
24300	Tyre inspection	02-Nov-20	02-Nov-20	13855		
-	1 Tyre inspection					
24172	Operator Input Defect - Inspect bonnet	24-Sep-20		13770		
1	1 Bonnet won't open with toggle sv	vitch at times				D.M inspected 11/11 8507hrs, No faults found with switch
24124	Defect repairs from 13750hr service	15-Sep-20	15-Sep-20	13740		
-	Oil leak at Drop box input shaft (n	ninor)				
2	Oil leaking from front diff input se	eal (minor)				
3	Seat Suspension is worn out					
24114	250hr Service	10-Sep-20	10-Sep-20	13732	13740	
250h	nr Service					
24107	Repair leaking cannon control hose	07-Sep-20	07-Sep-20	13718		
	Repair leaking cannon control hos	se				



				. •		
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
24095	Test pilot & system pressures, Test power to solenoid	04-Sep-20	04-Sep-20	13705		
	1 Test pilot & system pressures					Adjust pilot
	2 Test power to solenoid - repair co	onnection at volt o	onvertor			
24085	Replace hoist solenoid & disassemble hoist valve & inspect	03-Sep-20	03-Sep-20	13705		
	1 Replace hoist solenoid					
	2 Disassemble hoist valve & inspec	t				
	3 Diagnose low water flow					
24071	Install ignition timer cut out switch	31-Aug-20	31-Aug-20			
	1 Install ignition timer cut out switch	ch				
24058	Replace faulty batteries	26-Aug-20	26-Aug-20	13685		
	1 Replace faulty batteries					Inspect & test batteries & charge rate.
24050	Jump start machine	24-Aug-20	24-Aug-20	13682		
	1 Jump start machine					25/08 Jump start machine
24047	Jump start & run up	21-Aug-20	21-Aug-20	13667		
	1 Jump start & run up					
23856	Remove exhaust lagging to inspect A/C, alt belts & pulleys	07-Jul-20	07-Jul-20	13667		
	1 Remove exhaust lagging to inspec	ct A/C & alt belts 8	& pulleys			belts require replacing
23786	Inspect machine	30-Jun-20	30-Jun-20	13667		
	1 Inspect machine					



				• •		
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23752	Fit safety stickers, repair rust on chassis & tank door acce	24-Jun-20	24-Jun-20	13667		
	1 Fit safety decals					
	2 Repair rust on chassis					
	3 Weld flat bar on RH wheel fender	for tank door acc	ess			
23744	Fit step grip to steps & clean out machine at radiator	25-Jun-20	25-Jun-20	13667		
	1 Fit step grip to steps					
	2 Replace key					
	3 Clean out machine at radiator					Pulled of cover near radiator & cleaned.
23713	Fire extinguisher inspection	17-Jun-20	17-Jun-20			
	1 Fire extinguisher inspection					
23677	Install exhaust lagging	11-Jun-20	11-Jun-20	13667		
	1 Supply and fit exhaust lagging					
23676	Repair engine coolant, exhaust leaks	11-Jun-20	11-Jun-20	13667		
	1 Repair engine coolant, exhaust lea	ıks				13667hrs
23675	Repair both front guards	11-Jun-20	11-Jun-20	13667		
	1 Repair both front guards		13667hrs Repair both front guards - rusted out Drilled out broken bolts out of guards, cleaned & painted guards & tread plates. 16/06 Prep & painted flares, fitted tread plates, tapped & drilled mounting threads, Fitted RHS guard. 18/6 fit steps, removed rust and resprayed			
	2 Fit new safety decals to front guar	ds				18/6 fitter stickers to step
23651	103 inspection and repairs	10-Jun-20	10-Jun-20	13667		



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
	1 103 inspection					13667hrs Completed 103 inspection, Check movement in articulation
	2 Fit park brake door alarm			10/06 13667hrs Started park brake door alarm install 11/06 Completed and tested park brake door alarm		
	Repair LHS steer cylinder bearing					10/06 13667hrs Removed LHS steer cylinder bearing 11/06 Fitted new pin and bearing Installed cylinder
23585	Replace leaking hyd hose at spray control valve	28-May-20	28-May-20	13667	13667	
	1 Replace leaking hyd hose at spray	control valve				Removed & replaced hose to spray valves due to oil leak at crimp.
23584	Replaced rusted water fitting	28-May-20	28-May-20	13667	13667	
	1 Replaced rusted water fitting					removed rusted water fitting and replaced with new.
23564	6 Monthly fire extinguisher inspection	25-May-20				
	1 Portable fire extinguisher inspecti	on				
23534	Supply 2x 29.5R25 Michelin tyres	21-May-20	21-May-20	13667		
	1 Supply 2x 29.5R25 Michelin tyres					
23411	UHF speaker faulty	07-May-20	07-May-20	13620		
	1 Repair UHF					Swap out UHF and repair faulty unit
23317	Replace RHS top batter spray housing - cracked	16-Apr-20	16-Apr-20	13534		
	1 Replace RHS top batter spray hou	sing - cracked				Replace internals of centre spray on rear
23153	5 Yearly Fire Risk Assesment review	12-Mar-20	12-Mar-20	13439		
	1 Conduct 5 yearly Fire RA Review					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23144	March maintenance work order	01-Mar-20	01-Mar-20	13446		
	1 Safety work					10/03 Clean up isolator terminals & tighten loose leads.
	2 Start up fault - couldn't find fault					operator mentioned not starting, checked and couldn't find fault.
	3 Replace POS1 final drive plug					1/04 fit final rive plug - 13491hrs
	4 Body work					25/03 Replace steering chocks in hitch - smashed. 31/03 Replace hitch steer pads & remove broken bolt -13491hrs
23087	500hr Service	26-Feb-20	26-Feb-20	13429	13477	
500	hr Service					
23082	12 Monthly pressure vessel inspection	27-Feb-20	28-Feb-20			
12 [Monthly pressure vessel inspection					
22943	Electrical fault in spray switches	10-Jan-20	10-Jan-20	12421		
	1 Replace spray switches					18/12 found green death in wiring harness cleaned and swapped wires, switches on order
22937	250hr Service	08-Jan-20	08-Jan-20	13223	13264	
	1 250hr Service					
22932	Jan Maintenance	08-Jan-20	01-Jan-20	13226		
	1 Frame & Body					23/01 Replace rear spray diaphragms and test operation 24/01 Adjust seals on RHS batter spray - water leak. 27/01 Free up centre spray plunger - stuck down. 28/1 replace blocked spray head and test
	2 Hyd work					14/01 Re-seal hyd leaks - one near spray valves & water pump.
	3 Engine					16/1 prime up fuel due to not starting
22923	Repair flashing beacon	20-Dec-19	14-Dec-19	13194		
	1 Repair beacon					14/12 Repair beacon plug



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22851	POS 4 Brake oil supply hose failed	02-Dec-19	02-Dec-19	13121		
1	Replace failed hose					13/12 Replace hyd hose leaking at crimp for engine fan.
2	Replace beacon bracket					
22825	12 Monthly fire extinguisher inspection	25-Nov-19	25-Nov-19	13075		
12 N	lonthly fire extinguisher inspection					
22750	Nov maintenance work order	01-Nov-19	01-Nov-19	12976		
1	. Hyd work					1/11 Replace after cooler fan drive hose - leaking.
2	Maintenance					12/11 fill sample bottles
3	Frame & Body					12/11 replace broken sprays
2	Electrical					29/11 Replace faulty rocker switches for water sprays & water pump.
5	Final drives/brakes					30/11 Replace blown pos 4 brake hose.
22748	Aftercooler fan drive hose leaking	01-Nov-19	01-Nov-19	12976		
1	Replace hose					
22727	1000hr Service	21-Oct-19	21-Oct-19	12924	12976	
1	1000hr Service					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22676	Oct maintenance work order	01-Oct-19	01-Oct-19	12797		
1	Body work					2/10 Paint repairs 10/10 Inspect crack in water body - take photos 15/10 Assist Keldan with the repair for crack in the body. 16/10 Tighten adaptor fitting to go from 3 inch cam lock to 2 inch. 17/10 Carry out repairs to seat & seat suspension.
2	Hyd work					15/10 Replace blown hyd hose on water pump
3	B Electrical work				16/10 Swap switch for rocker sprays & test operation 17/10 Replace failed spray rocker switches 18/10 Collect pump switches 21/10 Fit new cannon switches	
22635	250hr Service	17-Sep-19	17-Sep-19	12700	12769	
250h	r Service					
22613	Sep Maintenance	01-Sep-19	01-Sep-19	12700		
1	. Engine work					
2	Electrical					6/9 Repair RH batter spray fault 22/9 Check lights & replace blown headlight globe
22547	Aug Maintenance work order	01-Aug-19	01-Aug-19	12534		
1	Final drives/brakes					9/8 Replace broken uni on hitch shaft. 10/8 Replace hitch shaft uni joints
2	Engine work					28/8 Connect ET to diagnose not start issue, fuel blockage
22488	500 Hr Service	10-Jul-19	10-Jul-19	12515	12515	
500h	r Service					
22440	June Maintenance Work	01-Jun-19	01-Jun-19	12314		
1	. Body work			17/6 Replace failed rear sprays. Replace failed spring on RH batter spray		
2	2. AC work					18/6 Replace u/s AC fan.



		WO Date	Date	Beginning	End Meter	
		Created	Scheduled	Meter Reading	Reading	Notes
22388	250hr service	17-May-19	17-May-19	12223	12272	
1	250hr service					Completed 22/5/19 12272 Hrs M Thompson
2	Replace light Globes					
22313	Repair cannon wiring	04-Apr-19	04-Apr-19	12057		
1	Repair cannon wiring					Repair wiring to cannon actuator on rear of water cart body
22247	Engine oil evac valve failed	11-Mar-19	11-Mar-19	12016		
1	Engine oil evac valve failed					
2	Replace ecolgy valve from hyd tai	nk				Replace ecolgy valve from hyd tank
3	Repair crack in rear of water tank					Remove spray bar, reseal joint between pump and spray bar, ilogate spray mounts to align joint.
4	Replace o ring brake cooling hose					
22195	February Pressure Vessel inspections - Mt Pleasant	12-Feb-19	12-Feb-19	11889		
1	. February Pressure Vessel inspecti	ons - Mt Pleasant				
22184	Repair leaking hyd fitting	07-Feb-19	07-Feb-19	11908		
1	Repair leaking hyd fitting					Repair loose leaking hyd fitting on hyd motor.
22177	2000 Hr Service	07-Feb-19	07-Feb-19	11898	12016	
2000	hr Service					
22102	250 Hr Service	09-Jan-19	09-Jan-19	11770	11770	
250h	r Service					
22097	Inspect for defects & prep for Thiess	09-Jan-19	09-Jan-19	11756		
1	Inspect for defects					
2	2 Hydraulic works					Replace LHS artic hoses . Replace hoist pump hose
3	Body work					Cannon issue - Check actuator & switch - Monitor



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22045	Overhaul LHF Suspension cyl	06-Dec-18				
	1 Overhaul LHF Suspension cyl					
22020	Replace failed POS 1 strut	22-Nov-18	22-Nov-18	11658		
	1 Replace failed POS 1 strut					Replace strut.Overhaul LHF Suspension cyl
21996	Replace Front LHS Suspension cylinder + 250hr Service	15-Nov-18	15-Nov-18	11658		
	1 Replace Front LHS Suspension cyl	inder				АН
	2 250hr Service					
	3 Tighten AC belt					
21993	Heavy plant tyre inspections - Marathon	31-Oct-18	31-Oct-18	11641		
	1 Heavy plant tyre inspections - Ma	ırathon				
21985	Repair RHR spray mounting & clamp	05-Nov-18	05-Nov-18	11641		
	1 Repair RHR spray mounting & cla	mp				
21934	Replace failed AM/FM radio	22-Oct-18	22-Oct-18	11565		
	1 Replace failed AM/FM radio					Replace failed AM/FM radio
	2 Adjust sprays					
21928	Replace failed bonnet actuator	17-Oct-18	17-Oct-18	11552		
	1 Replace failed bonnet actuator					Replaced failed bonnet actuator 19/10/18
	2 Fit new hinge on battery cover					Replace hinge on battery isolator cover
21870	Replace body position sensor	24-Sep-18	24-Sep-18	11480		
	1 Replace body position sensor					Replace body position sensor
	2 Obtain steer oil sample					Obtain steer oil sample
	3 Resecure dump brake					Search for & refit screw in dump brake lever



	WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
21851 500 Hr Service	18-Sep-18	18-Sep-18	11419		
500hr Service					
21798 Re flash engine ECM	29-Aug-18	29-Aug-18	11325		
1 Re flash engine ECM					
21768 Tyre replacements	17-Aug-18	17-Aug-18	11260		
1 Tyre replacements					Replace Pos 1 & 2 Tyres with new form Ditchfield stock at Mt Thorley. Remove & scrap worn Pos 6 & replace with run out. Pos 2 to go on Pos 3 #667
21751 Repair loose hyd fitting	10-Aug-18	10-Aug-18	11227		
1 Repair loose hyd fitting					
21740 Tighten loose spray head & unblock	07-Aug-18	07-Aug-18	11194		
1 Tighten loose spray head & unbl	ock				
2 Repair coolant leak at header ta	nk				
3 Remove hose reel					
21725 250 Hr Service	08-Aug-18	08-Aug-18	11196		
1 250 Hr Service					Completed 14/8/18 11246 Hrs M Lane
21721 Check for electrical faults - non found	26-Jul-18		11085		
1 Check for electrical faults - non f	ound				
21665 Repair vision link	18-Jul-18	18-Jul-18	11027		
1 Repair vision link					Westrac fit new Vision link
21654 Replace water pump hyd hose	16-Jul-18	16-Jul-18	11006		
1 Replace water pump hyd hose					
2 Replace failed spray head housing	ng				Replace spray head cap & adjust hyd control pressure relief.
3 Remove hose reel 21725 250 Hr Service 1 250 Hr Service 21721 Check for electrical faults - non found 1 Check for electrical faults - non f 21665 Repair vision link 1 Repair vision link 21654 Replace water pump hyd hose 1 Replace water pump hyd hose	08-Aug-18 26-Jul-18 found 18-Jul-18 16-Jul-18	18-Jul-18	11085		Westrac fit new Vision link



Beginning (Texated Scheduled Forested (Texated Scheduled Feading Pacific Reading) End Meter Reading Pacific P				• •			
1000hr Service 21574							Notes
21574	21595	1000 Hr Service	26-Jun-18	26-Jun-18	10843		
1 Crack test wheel rims 21573 Replace burst hyd hose 16-Jun-18 16-Jun-18 10759 1 Replace burst hyd hose Replace burst hyd hose. 21556 Replace leaking hyd hoses at steering tank 1 Replace leaking hyd hoses at steering tank 2 Replace plant ID number falling off 21553 Replace RHS mirror 06-Jun-18 06-Jun-18 10726 1 Replace RHS mirror 05-Jun-18 05-Jun-18 10717 1 Replace RHS mirror 05-Jun-18 05-Jun-18 10717 1 250 Hr Service 05-Jun-18 05-Jun-18 10717 1 250 Hr Service 15-May-18 15-May-18 10490 1 Replace failed hyd hoses 15-May-18 15-May-18 10490 2 Installed canon assembly 2 Installed canon assembly 3 Repair Isolators 30-Apr-18 30-Apr-18 10416 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 30-Apr-18 30-Apr-18 10416	100	Ohr Service					
21573 Replace burst hyd hose 16-Jun-18 16-Jun-18 10759 Replace burst hyd hose. 21556 Replace leaking hyd hoses at steering tank 1 Replace Place plant ID number falling off 1 Replace RHS mirror 06-Jun-18 10726 Mirror fell off 21553 Replace RHS mirror 06-Jun-18 10717 Mirror fell off 21545 250 Hr Service 05-Jun-18 05-Jun-18 10717 Completed 11/6/18 10755 Hrs C Hodges 21501 Replace failed hyd hoses 15-May-18 10490 Completed 11/6/18 10755 Hrs C Hodges 21547 Repair isolators 30-Apr-18 30-Apr-18 10416 Completed 11/6/18 10755 Hrs C Hodges 21457 Repair isolators 30-Apr-18 30-Apr-18 10416 Completed 11/6/18 10755 Hrs C Hodges 21557 Repair isolators 30-Apr-18 30-Apr-18 10416 Completed 11/6/18 10755 Hrs C Hodges 2167 Repair isolators 30-Apr-18 30-Apr-18 10416 Completed 11/6/18 10755 Hrs C Hodges 2168 Repair isolators 30-Apr-18 <t< td=""><td>21574</td><td>Crack test wheel rims</td><td>18-Jun-18</td><td>18-Jun-18</td><td>10759</td><td></td><td></td></t<>	21574	Crack test wheel rims	18-Jun-18	18-Jun-18	10759		
1 Replace burst hyd hose Replace burst hyd hose. 21556 Replace leaking hyd hoses at steering tank 1 Replace leaking hyd hoses at steering tank 2 Replace plant ID number falling off 21553 Replace RHS mirror 06-Jun-18 06-Jun-18 10726 1 Replace RHS mirror 06-Jun-18 05-Jun-18 10726 1 Replace RHS mirror Mirror fell off 21545 250 Hr Service 05-Jun-18 05-Jun-18 10717 1 250 Hr Service 1 Seplace failed hyd hoses 15-May-18 15-May-18 10490 1 Replace failed hyd hoses 21457 Repair isolators 30-Apr-18 30-Apr-18 10416 2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		1 Crack test wheel rims					
21556 Replace leaking hyd hoses at steering tank 12-Jun-18 12-Jun-18 10757	21573	Replace burst hyd hose	16-Jun-18	16-Jun-18	10759		
Replace leaking hyd hoses at steering tank		1 Replace burst hyd hose					Replace burst hyd hose.
2 Replace plant ID number falling off 21553 Replace RHS mirror 1 Replace RHS mirror 21545 250 Hr Service 1 Replace failed hyd hoses 15-May-18 15-May-18 10490 1 Replace failed hyd hoses 21545 Repair isolators 30-Apr-18 30-Apr-18 10416 2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416	21556		12-Jun-18	12-Jun-18	10757		
Replace RHS mirror D6-Jun-18 D6-Jun-18 D7-Jun-18 D7-Jun-		1 Replace leaking hyd hoses at stee	ring tank				
Replace RHS mirror		2 Replace plant ID number falling of	ff				
21545 250 Hr Service 05-Jun-18 05-Jun-18 10717	21553	Replace RHS mirror	06-Jun-18	06-Jun-18	10726		
250 Hr Service Completed 11/6/18 10755 Hrs C Hodges 21501 Replace failed hyd hoses 15-May-18 10490 2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics Sepair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		1 Replace RHS mirror					Mirror fell off
21501 Replace failed hyd hoses 15-May-18 10490 1 Replace failed hyd hoses 30-Apr-18 30-Apr-18 10416 2 Installed canon assembly 3 Repair blown hose to batter spray 4 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416	21545	250 Hr Service	05-Jun-18	05-Jun-18	10717		
1 Replace failed hyd hoses 21457 Repair isolators 30-Apr-18 30-Apr-18 10416 2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		1 250 Hr Service					Completed 11/6/18 10755 Hrs C Hodges
21457 Repair isolators 30-Apr-18 30-Apr-18 10416 2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416	21501	Replace failed hyd hoses	15-May-18	15-May-18	10490		
2 Installed canon assembly 3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		1 Replace failed hyd hoses					
3 Repair blown hose to batter spray 4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416	21457	Repair isolators	30-Apr-18	30-Apr-18	10416		
4 Replace worn joy stick for gear selector 5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		2 Installed canon assembly					
5 Repair cannon electrics 21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		3 Repair blown hose to batter spray	/				
21450 500 Hr Service 30-Apr-18 30-Apr-18 10416		4 Replace worn joy stick for gear se	lector				
		5 Repair cannon electrics					
500hr Service	21450	500 Hr Service	30-Apr-18	30-Apr-18	10416		
	500	Ohr Service					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
21397	250 Hr Service	09-Apr-18	09-Apr-18	10253		
2501	nr Service					
21304	Prep for Mt Pleasant	21-Feb-18	21-Feb-18	10095		
	1 Safety work		Pressure vessel inspections by Joeys Air Tanks. Fit safety stickers. Fit exhaust & turbo wrap. Fit reflective tape for compliance.			
	2 Inspect machine					103 Inspection . Wash & inspect truck for defects
	3 Body work			Replace unit numbers. Replaced steering stops. Repair spray heads. remove rear spray units, housing & pipes. Replace 1 housing. Replace all internals & diaphragms. Set spray angles. Fit new cannon valve assembly		
	4 Electrical fault		Inspect brake light fault. Fit new brake lights both sides Replace 24v-12v reducer. Diagnose & rewire estop & idle timer circuits . Repair wiring to LHS headlight & blinker.			
	5 Hydraulic work					Replace hyd hose from fan pump to motor
	6 Engine work					Replace exhaust segment. Replace radiator sight glass.
21260	Replace rear dog bone bushes	25-Jan-18	25-Jan-18	10090		
	Replace rear dog bone bushes					New bearings pressed in at Grafton Westrac
21151	AC - Replace failed condenser	02-Nov-17	02-Nov-17	10006		
	1 AC - Replace failed condensor					AC - Replace failed condenser.
	Replacefaulty 24v - 12v reducer					Fit 24v to 12v reducer .
21041	Water spray fault	12-Sep-17	12-Sep-17	10006		
	1 Diagnose water spray fault					Remove sticky solenoid, clean , lube & reassemble. Test ok
21008	UHF issues	29-Aug-17	29-Aug-17	9947		
	1 UHF issues					Transmitting but not receiving. Swap temporarily with #252 radio
20991	2000 Hr Service	30-Aug-17		10005		
2000	Ohr Service					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes		
20955	Replace rusted bypass hose at water pump	18-Aug-17	18-Aug-17	9888				
	1 Replace rusted bypass hose at wa	iter pump						
20916	Low power fault - replace fuel filters	03-Aug-17	03-Aug-17	9821				
	1 Low power fault - replace fuel filt	ers		Replaced fuel filters. Diagnose failed injector No 3 . Replace injector.				
						Westrac assist - 12/08/17 - 9882hrs -Inv# SO33608.		
20841	Replace worn spray head parts	13-Jul-17	13-Jul-17	9743				
	1 Replace worn spray head parts							
	2 Replace hyd hoses across artic							
20808	250 Hr Service	29-Jun-17	29-Jun-17	9747				
250	hr Service							
20799	Investigate hyd oil leak & brake cooling hose	26-Jun-17	26-Jun-17	9720				
	1 Investigate hyd oil leak			Needs new hyd hose.				
	2 Replace LHS brake cooling hose				Westrac SO 33273			
20755	Repair failed AC bracket & replace compressor	08-Jun-17	08-Jun-17	9677				
	1 Repair failed AC bracket & replace	e compressor		Parts were taken from #655 when AC bracket in #656 collapsed resulting in damage. Ordered parts to be install back in #655 when they come in. Westrac SO 33117 & Westrac SO 33258				
	2 Replace radiator safety cap							
3 Repllace cabin pins								



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes		
20687	Complience requirements for Drayton	11-May-17	11-May-17	9488				
	1 Ball stud inspections							
	2 Rim crack testing					Crack test 6 x rims. Fit 2 x Mich 29.5 R25 XADN tyres. Fit new rims		
	3 Pressure vessel inspection							
	4 Supply 2 new tyres							
20677	Inflate Pos 3 Tyre	20-Apr-17	20-Apr-17	9456				
	1 Inflate Pos 3 Tyre							
20659	Adjust sprays	29-Apr-17	29-Apr-17	9488				
	1 Adjust sprays							
20640	500 Hr Service	20-Apr-17	20-Apr-17	9569				
500	hr Service							
20623	Repair power to guage cluster	10-Apr-17	10-Apr-17	9410				
	1 Repair power to guage cluster					Found fault in relay. Repair & restore power to cluster.		
20614	Replace battery isolator	03-Apr-17	03-Apr-17	9397				
	1 Replace faulty isolator					Westrac replace battery isolator Inv SO 32589		
20568	Inspect for defects	07-Mar-17	07-Mar-17	9377				
	1 Replace u/s batteries							
	2 Replace blockes fuel filters							
	3 Exhaust repairs			Replace exhaust muffler seal & clamp. All bolts were seized. Hold down bolts snapped. Had to drill out. Westrac repair exhaust pipe Inv SO 32558				
	4 Replace transmission hose			Westrac replaced leaking transmission hose . Inv SO 32464				
	5 Replace fuel filters							
	6 Replace hyd hitch hose					Hose replaced by Westrac Inv SO 32111		



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
20536	Reseal HMU + defects	13-Feb-17	13-Feb-17			
	1 Reseal HMU + defects					
	2 Replace leaking axle over cooling	hose				
	3 Replace broken clamp over hitch	pivot				
	4 Replace fan belt & tensioner					
20535	Repair water cannon issues	17-Feb-17	17-Feb-17	9321		
	1 Repair corroded wiring for cannot	n	Diagnose & repaired corroded wiring to spray actuators.			
	2 Free cannon pivot points		Free up seized pivot points on cannon valve & clean out debris from spray nozzles.			
20534	Replace Air Conditioner	20-Feb-17	20-Feb-17	9320		
	1 Replace Air Conditioner		AC mounting failed. Replace AC . Replace AC compressor & charge . Evac 1.950 kg & recharge 2.0 kg A134 Gas			
	2 Replace transmission filter hose					
20505	250 Hr Service	08-Feb-17	08-Feb-17	9311		
	1 250 Hr Service					Completed 8/2/17 9311 Hrs
20453	Low power fault - fuel starvation.	19-Jan-17	19-Jan-17	9185		
	1 Low power fault - fuel starvation.		Drain fuel tank & clean out. Replace fuel filters & bleed up.			
20363	Find gas leak on LHS front strut	25-Nov-16	25-Nov-16	9069		
	1 Find gas leak on LHS front strut - I	Regas				
	2 Start fault - E Stop					
20342	Replace failed starter motor	18-Nov-16	18-Nov-16	9028		
	1 Replace failed starter motor		Westrac SO 31682			



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
20334	Low charge - Batteries	14-Nov-16	14-Nov-16	9021		
1	Jump start machine					
2	Replace batteries					
20308	1000 Hr Service	09-Nov-16	09-Nov-16	8972		
_	1000 Hr Service					Completed 15/11/16 9021 Hrs Westrac SO31650
20241	Regas front strut	17-Oct-16	17-Oct-16			
=	Regas front strut					
20210	Inspect AC fault	07-Oct-16	07-Oct-16			
	Inspect AC fault					
20045	Fit rego plates to to machine	15-Jul-16	15-Jul-16			
	Fit rego plates to to machine					Fit rego plates at Nabiac