

JOB_NO	< DATE	EQUIPMENT	NAME	CURR_ODO	SERVICE	WORK	DEPOT	INSTRUC	COST
210278	09/17/2018	PM93	XN51DX	0	SERSHE		INT	T610 vin 463498 No maint contract	0
542626	10/19/2018	PM93	XN51DX	12000	1STSERV	PM	INT	Completed.	0
259823	03/26/2019	PM93	XN51DX	0	SLP		RUT		0
257413	07/16/2019	PM93	XN51DX	0	EL		RUT	Won't start. Batteries replaced, 1 covered by warranty.	0
259829	07/16/2019	PM93	XN51DX	0	BAT		RUT	Batteries replaced under warranty	0
259824	07/22/2019	PM93	XN51DX	159753	B	SERVICE	RUT		0
274685	08/10/2019	PM93	XN51DX	170765	A	SERVICE	RUT	Completed, HHM	120
263528	08/19/2019	PM93	XN51DX	178180	B	SERVICE	RUT	Service completed by HHM 24-8-19	0
266151	09/11/2019	PM93	XN51DX	200000	BESERV	SERVICE	RUT	Service completed by Cummins Newc.	1340
266154	09/11/2019	PM93	XN51DX	200000	BELTS	PM	RUT	Engine belts replaced.	0
266156	09/11/2019	PM93	XN51DX	200000	VALVESET	PM	RUT	Engine Tune up carried out by Cummins Newcastle.	0
267038	09/20/2019	PM93	XN51DX	0	SLP	IN	RUT	SLP Inspection done by H&O.	175
274682	09/20/2019	PM93	XN51DX	191172	BT	SERVICE	RUT	Completed, HHM	165
279714	09/24/2019	PM93	XN51DX	0	BREAK	TYRE	RUT	Tyre replaced on drive pos9? Sublet Highway Tyres Doverton	905.65
275800	10/09/2019	PM93	XN51DX	204579	A	SERVICE	RUT	Completed HHM	110
272982	10/18/2019	PM93	XN51DX	0	B	SERVICE	RUT		0
275464	11/01/2019	PM93	XN51DX	0	A	SERVICE	RUT	Completed HHM. Horton fan wobbles when engaged. Fan runout. Monitor	120
277940	11/15/2019	PM93	XN51DX	225532	BT	SERVICE	RUT	Completed HHM	165
278555	11/15/2019	PM93	XN51DX	0	EL	EBS	RUT	Wheel sensor fault. Repaired by G&R	0
280986	11/29/2019	PM93	XN51DX	234300	TA	SERVICE	RUT	Completed HHM. Had to wait for truck.	210
281165	12/11/2019	PM93	XN51DX	240000	BESERV	SERVICE	RUT	Completed by Cummins Newcastle	952.96
285880	12/21/2019	PM93	XN51DX	246571	TYRE	TYRE	RUT	Tyre replaced pos 3 - runout	60
291938	01/01/2020	PM93	XN51DX	0	SLP	IN	RUT	Completed by Durhams 31-01-20. Fit up supplied Ebsray pump.	405.14
286413	01/03/2020	PM93	XN51DX	254968	BT	SERVICE	RUT	Completed by HHM	220
300639	01/20/2020	PM93	XN51DX	0	BREAK	TYRE	INT	KUMHO x 1	790
290174	01/21/2020	PM93	XN51DX	261735	A	SERVICE	RUT	Completed by HHM	165
292853	01/21/2020	PM93	XN51DX	261735	TYRE	TYRE	RUT	Michelin Tyres replaced 3,4,5,6	2605.5
292696	02/04/2020	PM93	XN51DX	0	B	SERVICE	RUT	Completed by HHM topped up greaser	165
296974	02/05/2020	PM93	XN51DX	0	R&M	PUMP	RUT	Ebsray pump blocked with floculant. Disassemble and unblock. Fit new seal kit	2330
296388	02/13/2020	PM93	XN51DX	274315	A	SERVICE	INT	Completed by HHM	165
268791	02/21/2020	PM93	XN51DX	0	C	SERVICE	RUT		0
296223	02/21/2020	PM93	XN51DX	279743	ANNUAL	IN	RUT	Completed by HHM	110
299043	02/29/2020	PM93	XN51DX	274304	TYRE	TYRE	INT	Flip Steer pos 1,2	110
297487	03/02/2020	PM93	XN51DX	280000	BESERV	SERVICE	RUT	Completed by Cummins	878.5
300842	03/05/2020	PM93	XN51DX	0	R&M	EL	INT	No power at trailer plug	41.25
306208	03/11/2020	PM93	XN51DX	0	TYRE	TYRE	INT	Fit new tyre Pos 7,8,9,10	2605.5
300897	03/18/2020	PM93	XN51DX	293390	A	SERVICE	RUT	Tension loose wheel nuts on 3rd axle; replace worn wiper blades, top up auto greaser	165
302859	03/30/2020	PM93	XN51DX	301772	B	SERVICE	RUT	Completed by HHM	247.5
305706	04/17/2020	PM93	XN51DX	159984	A	SERVICE	RUT	Please check batteries fluid levels, Replace cab fire extinguisher, grease steering shaft uni's, drai	210
309040	04/18/2020	PM93	XN51DX	0	R&M	MISC	INT	Pressure protection valve 70PSI	44.36
309224	04/21/2020	PM93	XN51DX	0	R&M	MISC	INT	Cartride torque rod x 4	279
307593	04/27/2020	PM93	XN51DX	0	BT	SERVICE	RUT	Completed HHM	270
308634	05/11/2020	PM93	XN51DX	320000	BESERV	SERVICE	RUT	Completed Cummins 323797km	1031.35
311585	05/23/2020	PM93	XN51DX	329471	B	SERVICE	RUT	Completed by HHM	180
314644	05/27/2020	PM93	XN51DX	0	TYRE	TYRE	INT	Pos 1,2 2 x 295/80R22.5	1224
316712	06/04/2020	PM93	XN51DX	335058	A	SERVICE	INT	Completed by HHM	110
318230	06/22/2020	PM93	XN51DX	345460	R&M	BRAKES	RUT	Brake pads replaced axle 2	137.5
318232	06/22/2020	PM93	XN51DX	0	BT	SERVICE	RUT		0
318225	07/03/2020	PM93	XN51DX	352089	A	SERVICE	RUT	Completed by HHM	110
318019	07/05/2020	PM93	XN51DX	0	SLP	IN	RUT	Completed Durhams.	178
319976	07/15/2020	PM93	XN51DX	357833	B	SERVICE	RUT	Completed by HHM	165

322176	07/17/2020	PM93	XN51DX	0 BAT	BAT	INT	4 x Battery endurance 12V	485.76
318295	07/20/2020	PM93	XN51DX	360000 BESERV	SERVICE	RUT	Completed Cummins. 357845km	883.53
318296	07/20/2020	PM93	XN51DX	0 BAT	PM	RUT	Fitted by Cummins	485.76
323835	08/03/2020	PM93	XN51DX	369567 A	SERVICE	RUT	Completed by HHM	275
327372	08/10/2020	PM93	XN51DX	369572 TYRE	ROT	INT	Pos 3,4,5,6,7,8,9,10 - rotate	96
325248	08/17/2020	PM93	XN51DX	376179 BT	SERVICE	RUT	Completed by HHM	297.07
326479	08/20/2020	PM93	XN51DX	0 R&M	EL	RUT	Number plate light not working and tighten driving lights	0
330651	08/27/2020	PM93	XN51DX	380240 A	SERVICE	INT	Completed by HHM	110
330619	09/11/2020	PM93	XN51DX	387600 B	SERVICE	RUT	Completed by HHM	165
338092	09/22/2020	PM93	XN51DX	0 R&M	H & F	RUT	Rebuild pump	2290
334693	09/24/2020	PM93	XN51DX	394237 R&M	PUMP	INT	Instal new EBS ray pump	2980
334694	10/10/2020	PM93	XN51DX	411195 BT	SERVICE	RUT	Completed by HHM	275
332894	10/12/2020	PM93	XN51DX	400000 BESERV	SERVICE	RUT	COMPLETED BY CUMMINS, 398461KM	1196.5
332895	10/12/2020	PM93	XN51DX	400000 D	SERVICE	RUT	Completed by Cummins	1276.18
332896	10/12/2020	PM93	XN51DX	400000 ALT	PM	RUT		599.85
332897	10/12/2020	PM93	XN51DX	400000 VALVESET	PM	RUT	COMPLETED BY CUMMINS	760
332900	10/12/2020	PM93	XN51DX	400000 BELTS	PM	RUT	Belts replaced cummins	344
334488	10/12/2020	PM93	XN51DX	400000 R&M	TURBO	RUT	CAC mounting isolators wornout- replaced Cummins	129.78
330702	10/21/2020	PM93	XN51DX	411195 R&M	WB	INT	RH & LH S Steer wheel bearings tensioned	110
338132	10/26/2020	PM93	XN51DX	412947 A	SERVICE	RUT	Completed by HHM	110
340295	11/09/2020	PM93	XN51DX	420548 B	SERVICE	RUT	Completed by HHM	165
340317	11/09/2020	PM93	XN51DX	0 R&M	BRAKES	RUT	Brake pads replaced axles 1 & 3	567.5
342668	11/23/2020	PM93	XN51DX	0 A	SERVICE	RUT	DIAGNOSE OIL LEAK FROM PTO	110
346764	11/26/2020	PM93	XN51DX	432215 R&M	BRAKES	INT	Reports of brake vibration - couldn't fault - 1st axle RHS wheel bearing loose - tightened	625
346789	11/30/2020	PM93	XN51DX	434298 R&M	BRAKES	INT	Anti seize back and sides of brake pads - refit	247.5
345267	12/04/2020	PM93	XN51DX	440000 BESERV	SERVICE	RUT	Completed Cummins 437835km.	903.53
350924	12/07/2020	PM93	XN51DX	0 B	SERVICE	INT	Completed CUMMINS	903.53
347589	12/16/2020	PM93	XN51DX	445486 B	SERVICE	RUT	Completed HHM	165
347590	12/16/2020	PM93	XN51DX	0 R&M	WB	RUT	RH steer hub oil dirty replace	0
350873	12/16/2020	PM93	XN51DX	445486 R&M	COOL	INT	Bottom heater tap hose replaced	275
350875	12/16/2020	PM93	XN51DX	445486 R&M	WB	INT	Steer hub oils refilled	275
354480	12/18/2020	PM93	XN51DX	445481 TYRE	ROT	INT	Pos 1,2,3,4,5,6,7,8,9,10 - Rotate	130
348101	01/11/2021	PM93	XN51DX	454919 A	SERVICE	RUT	COMPLETED HHM	150
357408	01/21/2021	PM93	XN51DX	461247 B	SERVICE	INT	Completed HHM	165
353196	01/25/2021	PM93	XN51DX	0 B	SERVICE	RUT		0
359817	01/25/2021	PM93	XN51DX	0 SLP	IN	INT	Completed by Durhams	158.5
355624	02/08/2021	PM93	XN51DX	472597 A	SERVICE	RUT	Completed HHM	110
355642	02/08/2021	PM93	XN51DX	472597 R&M	MIN ENG	RUT	Check all engine mounts are tight. Apply small amount of grease to bonnet mounts on firewall.	82.5
355644	02/08/2021	PM93	XN51DX	472597 R&M	HYD	RUT	Reeve mesh from ebsray inlet and drill 1/8" holes in it to increase flow and refit	82.5
355647	02/08/2021	PM93	XN51DX	0 R&M	EL	RUT	No reverse light - LAWLERS	0
355736	02/08/2021	PM93	XN51DX	0 R&M	BRAKES	RUT		700
355851	02/08/2021	PM93	XN51DX	0 R&M	COOL	RUT	Heater tap coolant leak	161.76
357186	02/15/2021	PM93	XN51DX	477573 R&M	CL	RUT	Check clutch adjustment. Adjust clutch if possible.	8317.7
508821	02/15/2021	PM93	XN51DX	0 R&M	CL	RUT	CARRIED OUT ADJUSTMENTS ON THE CLUTCH DUE TO THE DRIVERS REPORTS HAVING ISSUES WITH CHANGING GEARS,	360
356990	02/22/2021	PM93	XN51DX	480000 BESERV	SERVICE	RUT	Completed Cummins.	883.53
364009	02/22/2021	PM93	XN51DX	481222 R&M	AIR	INT	Replaced damaged airline fittings on PTO	27.5
361169	02/23/2021	PM93	XN51DX	481267 R&M	DL	INT	Uni joints have excessive movement	712.5
363954	02/23/2021	PM93	XN51DX	481219 B	SERVICE	INT	Completed Cummins	883.53
363743	03/04/2021	PM93	XN51DX	487453 BAT	PM	RUT	Batteries replaced Lawlers	981.34
361155	03/08/2021	PM93	XN51DX	489485 ANNUAL	IN	RUT	Completed HHM	55
361156	03/08/2021	PM93	XN51DX	489485 C	SERVICE	RUT	Completed HHM	330
363737	03/19/2021	PM93	XN51DX	497641 B	SERVICE	RUT	Completed HHM	270

365081	03/26/2021	PM93	XN51DX	0 R&M	AIR	RUT	Air leak in chassis near LHFD	55
365082	03/26/2021	PM93	XN51DX	0 R&M	MISC	RUT	Auto greaser leaking at reservoir	55
366137	03/31/2021	PM93	XN51DX	507854 A	SERVICE	RUT	Completed HHM	110
369123	04/01/2021	PM93	XN51DX	496636 BREAK	TR	INT	Pos 9 - puncture repair	400
366147	04/06/2021	PM93	XN51DX	0 R&M	WB	RUT	Drive hubseal leaking	0
369481	04/06/2021	PM93	XN51DX	0 R&M	AIR	INT	Rectify air leak	158.41
369120	04/09/2021	PM93	XN51DX	0 R&M	WB	INT	Leaking hubs seals on RHRD hub seal. replace hub seal	388.2
367138	04/15/2021	PM93	XN51DX	513794 BT	SERVICE	RUT	Completed HHM	220
367140	04/15/2021	PM93	XN51DX	0 R&M	AIR	RUT	Truck loosing air. Check over for air leaks. Possible around gearbox.	0
371840	05/03/2021	PM93	XN51DX	520000 BESERV	SERVICE	RUT	Completed Cummins	932.05
373106	05/17/2021	PM93	XN51DX	533357 B	SERVICE	RUT	Completed hhm	270
373131	05/17/2021	PM93	XN51DX	533357 R&M	MISC	RUT	Wiper blades replaced.	72.5
373132	05/17/2021	PM93	XN51DX	533357 R&M	AIR	RUT	Inspect truck for air leaks and fit ball valve to air dryer exhaust	424.67
376112	05/31/2021	PM93	XN51DX	543465 A	SERVICE	RUT	Completed HHM	210
377317	05/31/2021	PM93	XN51DX	543465 R&M	COOL	INT	Replace heater tap on engine, refilled coolant	90
377576	05/31/2021	PM93	XN51DX	541298 TYRE	TYRE	INT	Pos 1,2,3,4,5,6,7,8,9,10 - 2 x 295/80R22.5BS + 8 x 11R22.5 BS	5293.4
382413	06/08/2021	PM93	XN51DX	0 R&M	DL	INT	Topped up rear diff oil	27.5
377303	06/10/2021	PM93	XN51DX	549939 BT	SERVICE	RUT	Completed. HHM	247.5
380252	06/28/2021	PM93	XN51DX	560000 BESERV	SERVICE	RUT	Service completed Cummins. 559376km	883.5
398970	06/28/2021	PM93	XN51DX	559365 A	SERVICE	INT	Completed HHM. Fitted wheel nut indicators	270
382398	07/12/2021	PM93	XN51DX	567715 B	SERVICE	RUT	Completed HHM	170
382401	07/12/2021	PM93	XN51DX	0 R&M	AIR	RUT	Repair air leaks on truck	0
385362	07/23/2021	PM93	XN51DX	574241 A	SERVICE	RUT	Completed HHM	110
396757	08/06/2021	PM93	XN51DX	581885 R&M	TOW	INT	Adjusted turntable	27.5
388620	08/09/2021	PM93	XN51DX	581885 BT	SERVICE	RUT	Completed HHM	220
392165	08/09/2021	PM93	XN51DX	581889 TYRE	TR	INT	Pos 8 - puncture repair	45
391406	08/16/2021	PM93	XN51DX	583000 BAT	R&M	RUT	Batteries replaced by Shane & Jordan	0
390106	08/23/2021	PM93	XN51DX	590007 A	SERVICE	RUT	Completed HHM	150
400789	09/02/2021	PM93	XN51DX	596075 TYRE	ROT	INT	Pos 1,2,3,4,5,6,7,8,9,10 - rotate tbr tyre	120
401369	09/03/2021	PM93	XN51DX	0 SLP	IN	INT	Completed Dur Fab	158.5
391465	09/10/2021	PM93	XN51DX	0 B&T	SERVICE	RUT		0
391466	09/10/2021	PM93	XN51DX	600000 BESERV	SERVICE	RUT	Completed Cummins.	1000
391467	09/10/2021	PM93	XN51DX	600000 VALVESET	SERVICE	RUT	Completed Cummins	600
391528	09/10/2021	PM93	XN51DX	600000 TUR	PM	RUT	Replaced Cummins	3575.9
391530	09/10/2021	PM93	XN51DX	600000 COMPRESS	PM	RUT	Replaced Cummins	2743.07
391531	09/10/2021	PM93	XN51DX	600000 W/PUMP	PM	RUT	Replaced Cummins	1325.82
391540	09/10/2021	PM93	XN51DX	600000 EM	PM	RUT	AD BLUE PUMP REPLACED.	0
391544	09/10/2021	PM93	XN51DX	600000 PM	MIN ENG	RUT	ENGINE BRAKES SERVICED	938.46
395487	09/10/2021	PM93	XN51DX	600000 B&T	PM	RUT	Belts and Tensioners replaced.	2524.93
400845	09/13/2021	PM93	XN51DX	0 B	SERVICE	INT	Completed CUMMINS	1120
400846	09/13/2021	PM93	XN51DX	0 MID	PM	INT	Replaced turbo, turbo studs and nuts, air compressor and governor valve, water pump, engine brake sp	10928.29
396818	09/20/2021	PM93	XN51DX	605936 A	SERVICE	RUT	Completed HHM	150
399918	10/05/2021	PM93	XN51DX	615966 BT	SERVICE	RUT	Please find invoice	
Completed HHM		220 F						
410887	10/08/2021	PM93	XN51DX	615966 R&M	EX	INT	Tighten exhaust dump pipe bolts to spec. Removed & blow out diff breathers and hoses and refit. Blow	123.75
410888	10/08/2021	PM93	XN51DX	615966 R&M	TOW	INT	Adjusted turntable	123.75
401860	10/18/2021	PM93	XN51DX	620481 A	SERVICE	RUT	Please find invoice	
Completed hhm		110 F						
405917	10/29/2021	PM93	XN51DX	625906 B	SERVICE	RUT	Completed HHM	165
411566	11/10/2021	PM93	XN51DX	0 R&M	COOL	INT	REPLACE RADIATOR	2145.45
407195	11/15/2021	PM93	XN51DX	635387 A	SERVICE	RUT	Completed HHM	110
411065	11/22/2021	PM93	XN51DX	0 R&M	WB	INT	Seals, kit pinion nut and hub cap	131.25

412336	11/22/2021	PM93	XN51DX	641783 R&M	DL	INT	INSTALL NEW PINION SEAL,	220
411028	11/29/2021	PM93	XN51DX	646224 BT	SERVICE	RUT	Completed HHM	270
416804	11/29/2021	PM93	XN51DX	646224 R&M	EL	INT	Removed damaged casing on trailer plug. Refit new casing.	30
423632	12/06/2021	PM93	XN51DX	0 R&M	STARTER	INT	Paccar Starter	524.21
414945	12/13/2021	PM93	XN51DX	654931 A	SERVICE	RUT	Completed HHM	110
425338	12/13/2021	PM93	XN51DX	0 R&M	EL	INT	plug	10.42
418517	12/31/2021	PM93	XN51DX	666574 B	SERVICE	RUT	Completed HHM	165
429963	01/07/2022	PM93	XN51DX	669347 TYRE	ROT	INT	Pos 3,4,5,6,7,8,9,10 - rotate tbr tyre	115.35
419983	01/12/2022	PM93	XN51DX	650724 BESERV	SERVICE	RUT	Completed Cummins	1391.5
431429	01/13/2022	PM93	XN51DX	0 SLP	IN	INT	Completed DUURHAMS	808.25
431465	01/14/2022	PM93	XN51DX	0 R&M	BRAKES	INT	Caliper & mounting kit	1650.83
431466	01/14/2022	PM93	XN51DX	0 R&M	SUS	INT	shock absorber rear	347.27
431467	01/14/2022	PM93	XN51DX	0 R&M	EX	INT	Flex exhaust pipe, gasket & clamp	377.32
432040	01/14/2022	PM93	XN51DX	674319 A	SERVICE	INT	HHM	165
432041	01/14/2022	PM93	XN51DX	674319 R&M	BRAKES	INT	Reline to 1st drive axle, replace 1st axle RH caliper	319
432042	01/14/2022	PM93	XN51DX	674319 OP	PUMP	INT	Fit EBS ray pump	682
432043	01/14/2022	PM93	XN51DX	0 R&M	SUS	INT	Replace worn shock on 1st driveLHS	104.5
432044	01/14/2022	PM93	XN51DX	0 R&M	EX	INT	Fit new exhaust piece	242
432045	01/14/2022	PM93	XN51DX	0 R&M	AIR	INT	Replaced leaking air fitting	180
432046	01/14/2022	PM93	XN51DX	0 R&M	MIN ENG	INT	Replace inter cooler bushes	300
431657	01/19/2022	PM93	XN51DX	0 R&M	BRAKES	INT	Pad kit	425.32
482272	01/19/2022	PM93	XN51DX	676741 BREAK	TYRE	INT	11R22.5 HIFLY POS 7	861.3
422639	01/24/2022	PM93	XN51DX	680427 BT	SERVICE	RUT	BT SERVICE	306
429862	01/24/2022	PM93	XN51DX	678040 TYRE	TR	INT	Pos 7 - fit tbr tyre	37.05
424168	01/31/2022	PM93	XN51DX	684855 R&M	WB	RUT	Completed hhm	515
431598	01/31/2022	PM93	XN51DX	0 R&M	AC	INT	Checked AC , batteries and charge system for lithium due to clicking noise	1576.83
431315	02/02/2022	PM93	XN51DX	0 R&M	WB	INT	Seal & gasket axle shaft	35.71
422985	02/07/2022	PM93	XN51DX	690000 BESERV	SERVICE	RUT	CUMMINS BE SERVICE. 687872km	895.83
429316	02/21/2022	PM93	XN51DX	696356 B	SERVICE	RUT	Completed HHM	240
429378	02/21/2022	PM93	XN51DX	0 R&M	WB	RUT	RHR Hubslea leak	0
433189	02/21/2022	PM93	XN51DX	0 R&M	DL	INT	UJ kit 100	43.38
437206	02/21/2022	PM93	XN51DX	696390 R&M	WB	INT	Cleaned axle hubs fit caliper brakes and boosters	779.72
432894	02/24/2022	PM93	XN51DX	0 R&M	EBS	RUT	ABS Elec Suzi Coil	176.39
438272	03/03/2022	PM93	XN51DX	0 R&M	BRAKES	RUT	STRIP LED LAMP FRONT	62.36
432635	03/07/2022	PM93	XN51DX	706587 ANNUAL	SERVICE	RUT	COMPLETED. HHM REPLACE HEADER TANK STEER HUB OIL	927.5
437183	03/08/2022	PM93	XN51DX	704395 R&M	TYRE	INT	PUNCTURE REPAIR TBR	46
447344	03/15/2022	PM93	XN51DX	0 R&M	EL	INT	Open circuit - repaired. Starter motor replaced. Brake faults	1058.05
450524	03/16/2022	PM93	XN51DX	713136 TYRE	TYRE	INT	Pos 1,2 - 295/80R22.5 BS R154	1116.34
447329	03/17/2022	PM93	XN51DX	0 R&M	WA	INT	Front wheel alignment	286.36
435600	03/18/2022	PM93	XN51DX	713201 BT	SERVICE	RUT	REPLACE WIPERS	220
438846	04/04/2022	PM93	XN51DX	719925 A	SERVICE	RUT	COMPLETED BY HHM	180
447164	04/04/2022	PM93	XN51DX	719925 R&M	EX	RUT	TIGHTEN EXHAUST SYSTEM	30
444110	04/19/2022	PM93	XN51DX	730000 BESERV	SERVICE	RUT	Completed CUMMINS	2019.04
447047	04/19/2022	PM93	XN51DX	729755 B	SERVICE	INT	COMPLETED BY HHM	60
445822	04/22/2022	PM93	XN51DX	0 R&M	EL	INT	Wheel spin light staying on	264.5
444943	04/29/2022	PM93	XN51DX	735272 A	SERVICE	RUT	Completed HHM	110
449519	05/16/2022	PM93	XN51DX	0 R&M	DL	INT	Oil Seal Kit & Hex flange kit	107.96
451723	05/16/2022	PM93	XN51DX	743413 R&M	EL	RUT	Secured PTO lines and loose wiring/plug	27.5
451724	05/16/2022	PM93	XN51DX	743413 PM	EX	RUT	Tighten exhaust pipe to y piece	27.5
451725	05/16/2022	PM93	XN51DX	743413 PM	TR	RUT	Tension all drive wheel nuts	27.5
449726	05/17/2022	PM93	XN51DX	743413 BT	SERVICE	RUT	Completed HHM	275
450001	05/17/2022	PM93	XN51DX	743427 R&M	DL	RUT	trans output shaft seal	350

455645	05/17/2022	PM93	XN51DX	0 PM	TR	INT	Rotate TBR Tyre POS 3,4,5,6,7,8,9,10	98
452421	05/26/2022	PM93	XN51DX	749524 A	SERVICE	RUT	Completed HHM	110
457851	05/26/2022	PM93	XN51DX	749524 R&M	HYD	RUT	Tension to spec the inlet & outlet bolts	27.5
457852	05/26/2022	PM93	XN51DX	749524 R&M	HYD	RUT	Secured PTO lines	27.5
455237	06/09/2022	PM93	XN51DX	757161 B	SERVICE	RUT	Completed HHM	201.25
455977	06/14/2022	PM93	XN51DX	759014 BREAK	EL	INT	Jump Start	593.18
460907	06/14/2022	PM93	XN51DX	0 R&M	EL	INT	No brake lights	437.53
459985	06/27/2022	PM93	XN51DX	767033 A	SERVICE	RUT	COMPLETED HHM	210
460242	06/27/2022	PM93	XN51DX	0 R&M	WB	RUT	RECTIFY LEAKING HUB SEAL	0
480732	06/27/2022	PM93	XN51DX	767033 R&M	WB	RUT	REPLACED RHR DRIVE HUB SEAL. CLEANED DIFF BREATHERS	300
466188	07/01/2022	PM93	XN51DX	768164 PM	TR	SYD	ROTATE TBR TYRE POS 1,2	24.5
474824	07/04/2022	PM93	XN51DX	770883 R&M	EBS	RUT	ALL WIRING INSPECTED,OK.FOUND FUSE BLOWN. INSPECTED RADAR IN BULLBAR, WAS DAMAGED. FITTED SECOND HA	677.5
458390	07/11/2022	PM93	XN51DX	770000 BESERV	SERVICE	RUT	COMPLETED CUMMINS	919.87
480737	07/11/2022	PM93	XN51DX	0 SLP	IN	INT	COMPLETED DURHAMS	161
464917	07/18/2022	PM93	XN51DX	0 R&M	AIR	RUT	AIR LEAKS FROM UNDER CAB ON AIR TANK	28.75
465827	07/22/2022	PM93	XN51DX	799968 A	SERVICE	RUT	COMPLETED HHM	143.75
469074	08/05/2022	PM93	XN51DX	788007 B	SERVICE	RUT	COMPLETED HHM	201.25
471939	08/22/2022	PM93	XN51DX	798456 A	SERVICE	RUT	Completed by HHM	158.13
472151	08/22/2022	PM93	XN51DX	0 R&M	WB	RUT	REPLACED THE RHS STEER HUB SEAL. BEARINGS AND CUPS	253
478210	08/25/2022	PM93	XN51DX	793711 R&M	AC	INT	HARD START A/C OPERATION	1115.97
480544	09/09/2022	PM93	XN51DX	0 R&M	WB	INT	Gasker hub cap & kit wheel	147.4
480597	09/12/2022	PM93	XN51DX	806916 R&M	EM	INT	DOSIG UNIT BLOCKED.	1800.98
480598	09/12/2022	PM93	XN51DX	806916 BESERV	SERVICE	INT	Completed CUMMINS	1800.98
479241	09/19/2022	PM93	XN51DX	0 A	SERVICE	RUT	A SERVICE - BONNET BUSHES TO BE WORN,, WEAPING PINIONS, MOUNTS WEARING. LEAKING GEARBOX AND PUMP	270
483004	10/03/2022	PM93	XN51DX	822652 B	SERVICE	RUT	Completed HHM	201.25
484156	10/05/2022	PM93	XN51DX	0 B	SERVICE	RUT		0
484219	10/05/2022	PM93	XN51DX	0 R&M	ST	BRI	Power steering box replacement at CQD Eagle Farm	455.17
488159	10/05/2022	PM93	XN51DX	0 R&M	ST	BRI	Re-conditioned steering box - Supply only - Jamie picked up - \$300 core charge outstanding	1968.75
490994	10/12/2022	PM93	XN51DX	0 R&M	WB	INT	KIT FG 941 WHEEL BR	145.38
487121	10/17/2022	PM93	XN51DX	832959 A	SERVICE	RUT	Completed HHM	230
487125	10/17/2022	PM93	XN51DX	0 R&M	BRAKES	RUT	Drive brakes getting low replace as required.	0
495415	10/17/2022	PM93	XN51DX	0 R&M	GLASS	RUT	Fit front windscreen	700
490367	10/31/2022	PM93	XN51DX	842372 BT	SERVICE	RUT	COMPLETED BY HHM	450
490368	10/31/2022	PM93	XN51DX	0 R&M	CL	RUT	Adjust clutch	0
490369	10/31/2022	PM93	XN51DX	0 R&M	AIR	RUT	Bad air leak new air dryer	0
491948	10/31/2022	PM93	XN51DX	0 R&M	EL	INT	Auto greaser not working	345.4
488853	11/07/2022	PM93	XN51DX	850000 BESERV	SERVICE	RUT	Completed Cummins	1200
488856	11/07/2022	PM93	XN51DX	850000 D	PM	RUT	Completed Cummins	1200
488857	11/07/2022	PM93	XN51DX	850000 VALVESET	PM	RUT	Completed Cummins	600
488858	11/07/2022	PM93	XN51DX	850000 BELTS	PM	RUT	Completed Cummins	450
495382	11/07/2022	PM93	XN51DX	846871 ALT	PM	RUT	Alternator replaced.	800
495383	11/07/2022	PM93	XN51DX	846871 R&M	EM	RUT	Aftertreatment light on. Found to be faulty NOX sensor, replaced.	977.08
504534	11/25/2022	PM93	XN51DX	856239 B	SERVICE	INT	Completed HHM	230
508101	11/29/2022	PM93	XN51DX	846702 R&M	DL	RUT	Front diff power divider nest replaced as bolt fell out on oil change.	4223.13
508104	11/29/2022	PM93	XN51DX	846702 R&M	TURBO	RUT	Intercooler split. replaced intercooler and mounting kit	2995.62
512420	11/29/2022	PM93	XN51DX	846702 R&M	DL	RUT	Front diff power divider rebuild. Bolt found in oil out power divider nest.	7218.8
504539	12/12/2022	PM93	XN51DX	0 R&M	MISC	INT	autosol 1kg tin	54.29
511628	12/12/2022	PM93	XN51DX	0 TYRE	TYRE	INT	11R22.5 148/145L BS M866	5447.12
501592	12/16/2022	PM93	XN51DX	0 BT	SERVICE	RUT		0
512319	12/21/2022	PM93	XN51DX	872530 R&M	ST	RUT	Power steer pump failed. Replace pump B&H Toowoomba	1851.4
509292	12/29/2022	PM93	XN51DX	873188 PM	TR	INT	Pos 2 flip on rim	44
503903	12/30/2022	PM93	XN51DX	862465 BAT	PM	RUT		1092.25

503904	12/30/2022	PM93	XN51DX	862465 R&M	STARTER	RUT		1207.95
505178	01/16/2023	PM93	XN51DX	890000 BESERV	SERVICE	RUT	CUMMINS SERVICE + ENGINE MOUNTS	934.22
515326	01/16/2023	PM93	XN51DX	0 SLP	IN	RUT	SLP INSPECTION	216
514755	01/17/2023	PM93	XN51DX	0 A	SERVICE	INT	Completed Trucksmart	74
515350	01/19/2023	PM93	XN51DX	0 R&M	AC	RUT	CODENSER SENSOR	3586.25
517749	01/30/2023	PM93	XN51DX	0 R&M	BRAKES	INT	PAD KIT	368.06
523624	01/31/2023	PM93	XN51DX	0 TYRE	TYRE	RUT	925/80R22.5 BS R154 POS 1,2	1209.28
516243	02/13/2023	PM93	XN51DX	0 R&M	COOL	INT	RADIATOR LEAKING	4928.1
516247	02/13/2023	PM93	XN51DX	0 R&M	AIR	INT	CHECK FOR AIR LEAK	1019.72
515133	02/20/2023	PM93	XN51DX	904657 BT	SERVICE	RUT	COMPLETED BY TRUCKSMART	148
516676	02/20/2023	PM93	XN51DX	0 R&M	TOW	INT	Greaseless insert	462.79
517326	02/21/2023	PM93	XN51DX	904657 R&M	MISC	RUT	CARRY OUT REPAIR TO AUTO GREASER LINE ON KING PIN	111
517327	02/21/2023	PM93	XN51DX	904657 R&M	TOW	RUT	REPAIR TEFLON PLATE	74
521933	03/09/2023	PM93	XN51DX	0 R&M	COOL	INT	HOSE COOLANT AND CLAMP	100
520125	03/10/2023	PM93	XN51DX	0 R&M	COOL	RUT	Top radiator hose replaced	0
535829	03/14/2023	PM93	XN51DX	0 BREAK	COOL	RUT	Bottom radiator hose clamp failed at Westbrook	1050
521937	03/20/2023	PM93	XN51DX	924115 R&M	R&M	RUT	spanner wxle net 4" 6 hex	-624.46
522434	03/20/2023	PM93	XN51DX	924115 R&M	BRAKES	RUT	Axle 3 brake reline	-51.38
522620	03/20/2023	PM93	XN51DX	924137 BAT	BREAK	RUT	Batteries replaced @ Wickham	1066.28
531189	03/20/2023	PM93	XN51DX	0 R&M	R&M	RUT	Replace Oil Pressure Sensor - onsite by Cummins	748.55
529935	03/27/2023	PM93	XN51DX	930000 BESERV	SERVICE	RUT	Completed	1224.26
530204	03/28/2023	PM93	XN51DX	0 R&M	SUS	INT	torque rod assy	1076.36
530253	03/29/2023	PM93	XN51DX	0 R&M	EL	INT	REMOVED AND REPLACED START ISOLATOR DUE TO ORIGINAL ONE FAILING	235.09
531244	03/31/2023	PM93	XN51DX	0 R&M	EL	RUT	Adjusted steerings on Charger controls and test. - Onsite Lawlers	427.9
526201	04/06/2023	PM93	XN51DX	932473 R&M	COOL	RUT	coolant level fault g&r	344.9
526204	04/06/2023	PM93	XN51DX	0 R&M	BODY	RUT	bonnet leaning to one side - g&r	0
535720	04/06/2023	PM93	XN51DX	0 R&M	TYRE	RUT	Rotate and Fit TBR Tyre x 8 POS3-10	125.4
526841	04/13/2023	PM93	XN51DX	935417 BT	SERVICE	RUT		0
527001	04/13/2023	PM93	XN51DX	935417 R&M	BRAKES	RUT	Pogo stcik broken , replaced. + Fitted wiper blades	-150
540587	04/27/2023	PM93	XN51DX	0 R&M	EL	RUT	Investigate and repair electrical Issue with starter.	1949.76
532693	05/05/2023	PM93	XN51DX	950242 R&M	WB	RUT	Repalce LHS 1st Drive Hub seal	-173.81
532695	05/05/2023	PM93	XN51DX	950242 R&M	SUS	RUT	4 x Drive Axle Shock absorber Replacement	1181.15
534582	05/12/2023	PM93	XN51DX	0 R&M	BRAKES	RUT	Replace all glad hand rubbers	0
533735	05/15/2023	PM93	XN51DX	953224 B	SERVICE	RUT		24.45
534584	05/19/2023	PM93	XN51DX	0 R&M	EL	RUT	Driving lights blow fuse when turned on - Lawlers to Inspect 19/05	979.79
549731	05/30/2023	PM93	XN51DX	962122 TYRE	ROT	RUT	Rot Steer Tyres	-60
533070	06/05/2023	PM93	XN51DX	970000 BESERV	SERVICE	RUT		1027.64
540208	06/05/2023	PM93	XN51DX	966062 BT	SERVICE	RUT		-150
540241	06/05/2023	PM93	XN51DX	0 ANNUAL	IN	RUT	Completed	0
543648	06/19/2023	PM93	XN51DX	0 OP	SAFETY	RUT	Install Guardian Seeing Eye Machine. Install not included in price	0
549952	07/05/2023	PM93	XN51DX	0 R&M	CL	RUT	Adjust Clutch	-120
544803	07/10/2023	PM93	XN51DX	0 SLP	IN	RUT	SLP Inspection	245.85
548560	07/10/2023	PM93	XN51DX	983975 B	SERVICE	RUT	Completed	-240
551949	07/19/2023	PM93	XN51DX	0 OP	SAFETY	RUT	Guardian Seeing machine supply and install	528
559636	08/03/2023	PM93	XN51DX	0 R&M	EL	RUT	HVAC Unit - R+R - Lawlers	5042.64
548981	08/04/2023	PM93	XN51DX	1010000 BESERV	SERVICE	RUT	B Service Cummins	2861.46
548982	08/04/2023	PM93	XN51DX	1010000 VALVESET	PM	RUT	Valve Set Cummins	0
548983	08/04/2023	PM93	XN51DX	1010000 BELTS	PM	RUT	Engine Belts Replaced	0
552818	08/07/2023	PM93	XN51DX	0 R&M	MIN ENG	RUT	Top C&C Mounts	157.59
552819	08/07/2023	PM93	XN51DX	0 R&M	DL	RUT	Gear Pump Leak - Repair	0
552820	08/07/2023	PM93	XN51DX	0 R&M	MIN ENG	RUT	Breather Extention	0
556270	08/07/2023	PM93	XN51DX	0 BT	SERVICE	RUT	Completed	0

563066	09/04/2023	PM93	XN51DX	1012703 B	SERVICE	RUT	Completed	275
563070	09/04/2023	PM93	XN51DX	0 R&M	BRAKES	RUT	Front Rotors - Inspect / Repair	0
581171	09/07/2023	PM93	XN51DX	0 BREAK	MIN ENG	INT	R+R injector 6	3666.49
566004	09/14/2023	PM93	XN51DX	0 R&M	COOL	RUT	Coolant Leak - Repair	1840.88
567798	09/20/2023	PM93	XN51DX	0 R&M	BODY	RUT	Bonnet Mounts - Replace	57.07
575636	09/22/2023	PM93	XN51DX	0 R&M	CL	INT	Clutch servo replaced by Shane	1003.96
570294	09/29/2023	PM93	XN51DX	1024536 BT	SERVICE	RUT	Wash down / inspect / Repair / Advise List Below / Completed	110
577596	10/20/2023	PM93	XN51DX	1032300 TYRE	TYRE	INT	ROTATE TYRE POS: 3 - 10	125.4
578250	11/01/2023	PM93	XN51DX	1042145 B	SERVICE	RUT	Completed	110
576574	11/27/2023	PM93	XN51DX	1050000 BESERV	SERVICE	RUT	Engine B Service @ Cummins	1737.56
584304	11/27/2023	PM93	XN51DX	0 BT	SERVICE	INT	T/Table Inspection Only - B Service Completed by OEM	110
588168	12/11/2023	PM93	XN51DX	0 R&M	DL	INT	Diff Oil - Replace	1558.22
590060	12/13/2023	PM93	XN51DX	0 R&M	EL	RUT	7 Pin Plug R+R	0
590581	12/22/2023	PM93	XN51DX	0 B	SERVICE	RUT	Completed	0
592850	12/29/2023	PM93	XN51DX	0 BATE	BAT	RUT	Batteries Replaced - Lawlers	1697.91
596739	01/08/2024	PM93	XN51DX	0 R&M	MIN ENG	INT	Engine Misfire - Investigation + Rerpair	3899.92
595109	01/09/2024	PM93	XN51DX	0 R&M	MIN ENG	INT	High Oil Temp Fault - Cummins	2301.26
595531	01/11/2024	PM93	XN51DX	0 R&M	MIN ENG	INT	Engine Missfire - Rectify	165
589832	01/22/2024	PM93	XN51DX	0 SLP	IN	INT	SLP Inspection @ Depot	239.5
596750	01/22/2024	PM93	XN51DX	1082978 BT	SERVICE	INT	Completed	275
601486	02/05/2024	PM93	XN51DX	1088714 TYRE	TR	INT	Drive rotoation, Puncture repair pos 4, Steer rotation	198.5
602626	02/05/2024	PM93	XN51DX	0 R&M	COOL	INT	Mounting Kit CAC	238.41
601113	02/06/2024	PM93	XN51DX	0 R&M	COOL	RUT	Remove and Replace Radiator , New coolant	1165.47
593799	02/18/2024	PM93	XN51DX	1090000 BESERV	SERVICE	INT	Engine B Service @ Cummins	1502.5
608232	02/22/2024	PM93	XN51DX	0 R&M	SAFETY	RUT	Wingman Fault - Lawlers	269.8
612933	03/06/2024	PM93	XN51DX	0 BREAK	COOL	INT	Overheating / Fan not engaging	1607.87
610157	03/18/2024	PM93	XN51DX	1113872 BT	SERVICE	INT	Completed	290.89
611343	03/18/2024	PM93	XN51DX	1113572 R&M	PRESET	RUT	Front LHS W/Bearing Found To Be Pitted And Unusable, Replace Both	1119.94
612514	03/19/2024	PM93	XN51DX	0 TYRE	TYRE	RUT	Tyres x 2 POS 1/2	1328.26
611761	03/20/2024	PM93	XN51DX	0 R&M	WB	INT	Replace Hub Covers x 2 Steer #2535936	137.5
612544	04/15/2024	PM93	XN51DX	1130000 BESERV	SERVICE	RUT	Engine B Service @ Cummins #1210861	1000
619947	04/18/2024	PM93	XN51DX	1128200 TYRE	TYRE	RUT	Tyres x 8 POS 3-10	4140.12
623475	05/13/2024	PM93	XN51DX	0 ANNUAL	IN	INT	Completed	1129.76
623571	05/13/2024	PM93	XN51DX	0 R&M	AIR	INT	Air Leaks Under Cab - Repair	558.63
630303	06/12/2024	PM93	XN51DX	1163541 B	SERVICE	INT	Completed	451.43
630587	06/24/2024	PM93	XN51DX	1170000 BESERV	SERVICE	INT	Engine B Swervice @ Cummins	0
640277	07/18/2024	PM93	XN51DX	0 BESERV	SERVICE	INT	Engine B Service @ W/Shop	701.59
640548	07/22/2024	PM93	XN51DX	0 SLP	IN	INT	SLP @ by Durhams	238.5
646586	07/26/2024	PM93	XN51DX	1185158 R&M	EL	INT	Attend to E-Stop, Trailer ABS and Horton Fan Issues - Lawler Auto Elec	1006.4
649820	08/26/2024	PM93	XN51DX	0 R&M	AIR	INT	Attend to a whistlingf Air leak from under the cab	186.79
649837	08/26/2024	PM93	XN51DX	0 R&M	COOL	INT	RxR Leaking coolant hose	530.2
653114	09/06/2024	PM93	XN51DX	0 DEC	OP	INT	Decomission Truck - Remove Hydraulics, MT Data, Guardian and all Property	605