

For Maintenance Recorded Between: 1/01/2006 and 21/05/2026

Asset ID	Asset Description	Date Acquired	Maintenance Date	Maintenance Performed By	Maintenance Description	Maintenance Cost
363	<i>320DRR Excavator Sam - No.2</i>	<i>18/12/2018</i>	2/01/2018	Tyrone	Repair hydraulic pump and case drain. Panel beat engine door. Tyrone 8hrs	\$548.00
			3/01/2018	Burson	Replacement strobe lights.	\$399.33
			3/01/2018	Tyrone	Fitted UHF radio. Tyrone 3hrs	\$205.50
			3/01/2019	William Adams	Decals for rear engine door	\$49.60
			7/01/2019	Enzed Geelong	Replacement hydraulic couplings	\$227.00
			11/04/2019	William Adams	Replacement decals	\$67.10
			30/04/2019	Tyrone	Fitted safety hand rails. Tyrone 6hrs	\$411.00
			7/05/2019	Tyrone	Replaced hydraulic couplings. Tyrone 1hr	\$68.50
			15/07/2019	GM Risk assessments	Machine Risk Assessment	\$128.50
			4/11/2019	Associated Cold Tread	Replacement batteries - 2 x MF95D31R	\$350.00
			23/12/2019	WilliamAdams	Invoice# PR070179635 - Engine door and decal.	\$1,572.16
			13/01/2020	Tyrone	Service @ 7601hrs - Carried out 500hr service. Replaced engine oil, filters and washed down engine and pump bays. Tyrone 10hrs	\$838.00
			13/01/2020	William Adams	Invoice# PR070179885 - Filters for service.	\$201.96
			10/09/2020	Otway Touring Solutions	Machine Risk Assessment - annual assessment.	\$137.50
			8/10/2020	Otway Touring Solutions	Machine risk assessment and fire extinguisher check.	\$154.00
			5/11/2020	Warren Miller	Repair solenoid failure. Woll 2hrs.	\$200.00
			11/11/2020	Burson Colac	Parts supply - relay	\$24.53
			12/11/2020	Warren Miller	Service@ 8160hrs. Carried out 500hr service. Replace all filters, engine oil, final drives oil and swing drive oil. Adjusted tracks. Cleaned radiator and cabin filters. Replaced faulty relay for tilt solenoid issue. Fitted auxillary hydraulics to boom.	\$2,000.00
			19/11/2020	William Adams	Filters for service - 326-1644; 131-8822; 093-7521; 51-8670; 1R-0751	\$273.00
			23/11/2020	Colac Hydrhose	Hydraulic fittings forauxillary hydraulic line.	\$753.98
			4/12/2020	Warren Miller	Fitted auxillary hydraulic line fittings - Woll 2hrs	\$200.00
			8/12/2020	Colac Hydrhose	Hydraulic fittings	\$193.03
			15/12/2020	Warren Miller	Fitted new hydraulic fittings.	\$100.00
			16/12/2020	Colac Hydrhose	Hydraulic fittings	\$33.00
			6/02/2021	Warren Miller	Replaced hydraulic hose. Woll 4hrs	\$400.00
			18/03/2021	Warren Miller	Repaired wiring fault - replaced faulty switch. Woll 8hrs	\$800.00
			30/06/2021	William Adams	Parts supply - filter for service	\$44.17
			26/08/2021	Otway Touring Solutions	Mobile plant static risk assessment carried out.	\$132.00
			12/11/2021	Colac Hydrhose	Hydraulic coupling O ring and retaining thread.	\$29.96
			7/12/2021	Phillip Kurzman	Replaced blown hydraulic hose. Topped up hydraulic oil and washed machine. Phillip 3hrs	\$495.00
			7/12/2021	Colac Hydrhose	Replacement hydraulic coupling.	\$44.40
			14/01/2022	William Adams	Parts supply - windscreen glass	\$242.40
			18/01/2022	Warren Miller	Replaced windscreen. Woll 5hrs	\$500.00
			19/01/2022	Colac Windscreens	Replacement windscreen glass	\$330.00
			8/03/2022	Warren Miller	Replaced hydraulic filters and fitted valve kit. Ordered new tacho sensor. Woll 4hrs	\$400.00
			17/03/2022	William Adams	Invoice#P2PR0115056 - Speed sensor	\$150.66
			25/03/2022	MaxiParts	Parts supply - Castrol fuel treatment.	\$143.40
			25/03/2022	William Adams	Invoice# P2PR0118929 - Parts supply - windscreen glass.	\$673.93
			12/04/2022	William Adams	Invoice# P2PR0126554 - Roller	\$384.70
			26/05/2022	Warren Miller	Service @ 8650hrs. Carried out 1000hr major service. Replace engine oil and filters. Replaced fuel, hydraulic, cabin and boom return filters. Drained and cleaned fuel lines. Drained hydraulic oil and replaced. Replaced top roller assembly. Cont...	

27/05/2022	Warren Miller	Cont.... Straightened RHS side panel and resprayed counter weight. Woll 25hrs	\$3,780.50
15/06/2022	William Adams	Invoice#P2PR0151985 - Filters for next service	\$245.25
27/06/2022	H.I.S Hose	Parts supply - H5000 series Hydraulic coupling	\$146.55
25/07/2022	Warren Miller	Fixed ignition switch	\$100.00
3/10/2022	Otway Touring Solutions	Machine static risk assessments and fire extinguisher check.	\$142.95
30/03/2023	William Adams	Invoice#P2PR0263816 - Filters for next service.	\$66.08
12/05/2023	Warren Miller	Replace fan hub - Woll 8hrs	\$800.00
16/10/2023	Otway Touring Solutions	Machine risk assessment and fire extinguisher check	\$137.50
10/11/2023	Warren Miller	Service @ 9100hrs. Carried out 500hr service. Changed engine oil, filters, fuel filters. Checked and topped up hydraulic oil and coolant fluid. Tightened aircon belt. Woll 2hrs Patrick 6hrs	\$616.50
10/11/2023	William Adams	Parts supply - tank 245-9205	\$278.93
17/11/2023	William Adams	Parts supply: 1 x 327-6618, 1 x 326-1644 and 1 x 546-0006	\$464.99
15/12/2023	William Adams	Parts supply - Glass part# 453-4794	\$901.01
7/06/2024	William Adams	Parts supply - Filters for serviceP2PR0426176	\$22.54
18/07/2024		Replaced windscreen. Woll 2hrs	\$240.00
26/07/2024	Warren Miller	Fitted new hydraulic couplings. Woll 1.5hrs	\$165.00
1/08/2024	Warren Miller	Repaired recoil in cabin. Woll 2hrs	\$220.00
1/10/2024	William Adams	Parts supply - Windscreen glass	\$897.95
22/10/2024	Warren Miller	Fault diagnosis - Woll 2hrs	\$220.00
30/10/2024	William Adams	Parts supply - seal # 2H-3928 x 7	\$92.63
31/10/2024	William Adams	Parts supply - shim and seals	\$622.06
4/11/2024	Patrick Cunnington	Service @ 9600hrs - Carried out 500hr interval service. Changed engine oil, oil filters, fuel filters, 3 x hydraulic filters. Replaced slew drive oil and hub oils. Patrick 13.5hrs Brylee 8.5hrs Woll 2hrs	\$2,139.40
6/11/2024	William Adams	Diagnosis and repair of wiring for hydraulic fault.	\$3,487.70
19/11/2024	Warren Miller	Replaced blown O ring. Woll 3hrs Brylee 3hrs	\$834.00
27/11/2024	Colac Hydrhose	Onsite replacement of hydraulic hose	\$609.48
17/12/2024	William Adams	Parts supply - V Belt	\$63.56
19/12/2024	Brylee Sheedy	Replaced airocn belt - Brylee 2hrs	\$176.00
5/01/2025	Water Supply Specialists	9kg Fire extinguisher	\$215.00
12/02/2025	Brylee Sheedy	Field service - Re-gassed aircon and fitted new net aircon drive belt. Brylee 3hrs	\$308.00
20/02/2025	Brylee Sheedy	Remove and refit windscreen Brylee 3hrs	\$264.00
21/02/2025	Colac Windscreens	Fitted new windscreen glass	\$220.00
4/03/2025	Colac Hydrhose	Replacement hydraulic hose	\$428.02
11/03/2025	William Adams	Parts supply - filters for next service	\$242.37
30/04/2025	Woll and Brylee	Replace pulley idler - Woll 1hr Brylee 3hrs	\$374.00
1/05/2025	William Adams	Parts supply - Pulley idler	\$1,171.46
26/06/2025	Tyrepower	Replacement batteries x 2	\$530.00
27/06/2025	Brylee Sheedy	Refitted track - Brylee Sheedy and Woll	\$495.00
12/08/2025	Brylee Sheedy	Service @ 10112hrs - Carried out 500hr interval service. Changes engine oil and filters. Replaced fuel filter, hub oils and slew oil. Replaced cabin filters and air filter. Patrick 4hrs Brylee 5hrs	\$1,007.60
12/08/2025	William Adams	Parts supply - Hose and door catch	\$311.50
22/08/2025	William Adams	Filters for next service	\$397.86
8/10/2025	Colac Hydrhose	Replaced blown hydraulic hose	\$292.20
21/10/2025	Otway Touring Solutions	Machine risk assessment	\$159.50
30/03/2026	All Earthmoving Parts	Parts supply - track chains and sprockets	\$8,900.32
16/04/2026	William Adams	Cat sticker	\$112.20
23/04/2026	William Adams	Decal sticker	\$345.95
23/04/2026	William Adams	Identification sticker	\$376.41

23/04/2026	William Adams	Information sticker	\$54.36
24/04/2026	Warren Miller	Replaced track chains and sprockets. Respray under carriage. - Brylee 2hrs Woll 110hrs	\$13,610.00
27/04/2026	William Adams	Parts supply - Bumper assembly	\$584.33
1/05/2026	Bunnings	Rust guard paint	\$139.00
11/05/2026	Brylee Sheedy	Re-spray panels - Woll Brylee 2hrs	\$200.00
12/05/2026	Outlaw Blasting	Sand blast and prime excavator panels	\$550.00
12/05/2026	Haymes	Grey etch prime paint	\$305.20
			<i>Sum Of MaintenanceCost:</i>
			\$62,531.17