

For Maintenance Recorded Between: 1/01/2006 and 21/05/2026

Asset ID	Asset Description	Date Acquired	Maintenance Date	Maintenance Performed By	Maintenance Description	Maintenance Cost
215	4WD Toyota Hilux - Dark Grey 30/3/07 - URQ942	29/03/2007	26/03/2007	Colac Auto Replacements	Invoice No. 217800 Beacon Light	\$123.00
			27/03/2007	Colac Toyota	Invoice No. 31945 (Part) Seat Cover	\$245.00
			29/03/2007	BM-Tronics	Invoice No. Supply and install mobile phone cradle and antenna	\$576.00
			29/03/2007	Tyrer Engineering	Invoice No. 2455 Extra Tie Downs	\$132.00
			4/04/2007	Colac Auto Replacements	Invoice No. 218023 Lights, brake controller	\$632.40
			5/04/2007	Colac Electronics	Invoice No. 55209 Install UHF Radio	\$70.00
			26/04/2007	Colac Toyota	Invoice No. R51140 1000km service	\$68.95
			16/07/2007	Colac Toyota	Invoice No. 32678 Parklamp Indicator	\$33.00
			4/09/2007	Colac Toyota	Invoice No. R52680 Service 10,000km	\$154.15
			15/01/2008	NGF Solutions Pty Ltd	Invoice No. 822 (Part) mobile phone car kit installation	\$125.00
			20/02/2008	Colac Toyota	Invoice No. R54733 Service 20,000 km as per Toyota Schedule	\$218.75
			3/04/2008	Colac Toyota	Tax Invoice No. 34272 Lens Rear Comb	\$73.15
			20/05/2008	Toyota Total Care	Roadside Assist Renewal	\$40.00
			9/10/2008	Colac Toyota	Job card # 58008	\$359.90
			18/05/2009	Colac Toyota	50,000km service,	\$476.80
			18/05/2009	Cold Tread	4 New Tyres Inv 25117	\$1,260.00
			5/01/2010	Colac Toyota	60,000km service	\$235.10
			25/09/2010	Wayne	Service Oil and filter change	
			10/11/2010	Associated Cold Tread Tyres	4 tyres	\$1,200.00
			9/02/2011	Wayne	90,000kms service incl Oil & Filter Change	\$87.38
			6/06/2011	Colac Toyota	100,000km Service, Replace front rotors & pads, Front steering arm & wheel alignment	\$1,276.10
			12/09/2011	Colac Toyota	110,000km Service	\$186.55
			9/11/2011	Colac Toyota	Replace Rear Wheels Bearings Inv R72915	\$397.25
			17/05/2012	Colac Toyota	130,000 Kms Service	\$394.90
			1/03/2013	Toyota	150,000km Service Timing Belt	\$414.52
			6/04/2013	Colad Tread	Supply & Fit 4 new Tyres BFG All Terrain	\$1,240.00
			20/04/2016	Steven Kurzman	Service @196000kms, Replace Oil & Filter, Grease Driveline	\$110.00
			10/06/2016	Associated Cold Tread	Repair to Puncture on 1 Tyre	\$37.00
			5/09/2016	Williams Auto Care	Replaced fuel injectors and fuel filter.	\$2,233.58
			3/10/2016	Steven K	10k service @ 240037. Replaced engine oil & filter, fuel filter and installed new flashing safety light. Cleaned car inside & out.	\$264.00
			20/01/2017	Associated Cold Tread	Replace 2 x tyres	\$522.00
			26/04/2017	Associated Cold Tread	Puncture repair	\$37.00
			26/04/2017	Cool Drive	Invoice # 5655181 Oil filters x 2	\$85.76
			2/05/2017	Steven Kurzman	Service @ 211470 Replace oil, oil filter and greased.	\$200.00
			3/08/2017	Simon	Front brakes replaced. Parts supplied by Burson.	\$245.44
			16/08/2017	Simon	Replacement part - rear taillight lens.	\$55.39
			16/11/2017	Associated Cold Tread	Replacement battery	\$175.00
			9/02/2018	Associated Cold Tread	Tyre puncture repair	\$37.00
			23/02/2018	Burson	Oil filter and oil for next service.	\$144.49
			1/03/2018	Tyrone	Service @ 223195 20,000 km interval service.	\$548.00
			15/03/2018	Associated Cold Tread	Replacement battery	\$365.00

10/05/2018	Associated Cold Tread	Replacement of 4 x tyres and repair to spare.	\$1,212.00
4/06/2018	Colac toyota	Replacement mat set and cable assembly	\$143.11
1/08/2018	Tyrone	Service @ 230,000 kms - Oil filter & oil, replace rear brake shoes and adjust. Tyrone - 6.5hrs	\$445.25
2/08/2018	Burson	Parts supply - Brake shoes and brake fluid	\$120.06
7/03/2019	Associated Cold Tread	Strip and refit tyre to replacement wheel.	\$21.00
7/03/2019	Colac Toyota	Replacement wheel nuts and studs.	\$84.55
7/03/2019	Tyrone	Replaced LHS rear wheel, wheel studs and nuts. Tyrone 4hrs.	\$274.00
8/05/2019	Tyrone	Service @ 240,000kms. Major service per manual - Replaced engine oil, oil filter, checked front & rear diff oils, checked gearbox and trans	\$530.25
15/01/2020	Warren Miller	Repairs to oversize sign on ute. Woll 2hrs	\$137.00
4/04/2020	Burson	Parts supply - oil filter	\$8.76
4/04/2020	Burson	Parts supply - oil filter	\$8.76
7/04/2020	Warren Miller	Minor repairs - replaced tail light and number plate light. Repair RHS mudguard. Striaghten exhaust. Fit new hand piece to UHF.	\$300.00
13/07/2020	Burson	Clutch kit and oil filte.	\$552.98
18/08/2020	Warren Miller	Service cont... Replaced both headlight assemblies. Fitted two new rear shockers. Replaced park light globes. Greased vehicle. Ordered new rear springs and bushes.	
18/08/2020	Warren Miller	Service @ 250,000kms - carried out 10,000hr service. Replaced engine oil and filter. Changed fuel filter. Replaced front discs and brake pads. Replaced clutch and uni joints to tailshaft. Refill gearbox and transfer case with new oil. Woll 36hrs	\$3,717.00
20/08/2020	Burson	Parts supply - head lights, brake pads, brake rotors, shock absorber and uni joint.	\$980.04
24/08/2020	Burson	Parts supply - oil filter.	\$21.53
26/08/2020	Burson	Parts supply - Replacement leaf springs and bush kit.	\$575.71
27/08/2020	Burson	Parts supply - Filter and fuel filter cartridge.	\$32.30
1/09/2020	Steven Kurzman	Replaced suspension springs and repaired toolbox, auxillary fuel tank. Steven 12hrs	\$1,200.00
1/09/2020	Warren Miller	Treated tray for rust and painted - Woll 16hrs	\$1,600.00
2/09/2020	Colac Toyota	Parts supply - oil filter	\$26.77
2/09/2020	Burson Colac	Rust converter paint for tray.	\$36.58
15/10/2020	Warren Miller	Cleaned hubs to fix vibration and fitted aircompressor to ute tray. Woll 8hrs	\$800.00
17/11/2020	Burson Colac	Parts supply - Ryco oil filter	\$8.76
18/11/2020	Warren Miller	Remove and clean S.C.R Woll 2hrs	\$200.00
22/12/2020	Burson	Parts supply - Reversing alarm components.	\$97.25
31/12/2020	Andrew	Fitted reversing alarm interlinked with amber beacon. Andrew 2hrs	\$160.00
7/01/2021	Hip Pocket	Fire blanket 1.8m x 1.8m	\$39.60
19/01/2021	Colac Toyota	2 x rear light lens	\$96.05
27/01/2021	Burson	Parts supply - oil filter, fuel filter and uni joint.	\$56.75
27/01/2021		Parts supply - oil filter, fuel filter and universal joint.	
4/02/2021	Associated Cold Tread Colac	4 x replacement tyres	\$772.00
18/05/2022	Associated Coldtread	Replaced tyre	\$450.00
23/06/2022	Colac Toyota	Parts supply - Clutch master cylinder	\$197.32
28/06/2022	Burson	Parts supply - relay and connector.	\$74.04
30/09/2022	Colac Toyota	Filters for servicing	\$117.14
5/10/2022	Warren Miller	Service @ 270,000kms. Carried out 10,000km interval service per logbook. Replaced engine oil & filter. Fitted replacement fishing light. Straighten belly guard.	\$248.00
4/11/2022	Burson	Parts supply - Clutch slave cylinder.	\$72.05
11/11/2022	Warren Miller	Replaced clutch cylinder	\$100.00
30/05/2023	Warren Miller	Replaced alternator - Woll 2hrs	\$200.00
31/05/2023	Colac Electric Motor Co.	Replacement alternator.	\$616.00

3/08/2023	Burson	Replacement shock absorbers x 2 for rear.	\$299.20
3/08/2023	Warren Miller	Repairs to injection pump. Woll 2hrs	\$200.00
23/08/2023	Burson	Parts supply - oil filter and pollen filter.	\$54.62
1/11/2023	Burson	Replacement UHF radio	\$550.00
28/12/2023	Burson	AM/FM Helical antenna kit	\$71.50
24/01/2024	Colac Toyota	Parts supply: oil seal	\$19.09
26/03/2024	Burson	Parts supply - wheel bearing kit	\$197.89
3/04/2024	Patrick and Woll	Replaced wheel bearings. Patrick 11hrs Woll 6hrs	\$993.30
23/05/2024	Patrick Cunnington	Service @ 290,000kms. Carried out 10,000km service. Changed engine oil and filter. Changed fuel filter. Checked cabin filter, air filter, front diff oil, air filter, transfer case oil level and transmiision oil level. Checked light. Patrick 6.5hrs	\$237.90
10/04/2025	Brylee Sheedy	Service @ Brylee 3hrs	\$300.00
22/05/2025	Burson	Aerpro AM/FM reception booster	\$33.00
30/05/2025	Tyrepower	Replaced 4 x tyres	\$880.00
2/06/2025	Burson Colac	Parts supply - water pump, wheel bearing kit, flange sealant, timing belt kit and Coopersfilter service kit.	\$542.11
2/06/2025	Brylee Sheedy	Service @ 300500kms. Replaced engine oil and filter. Replaced air filter, fuel filter, timing belt kit and water pump. Brylee 10hrs	\$926.20

Sum Of MaintenanceCost:

\$36,716.98