

Asset Serial Number	Make	Model	Sample Meter	Hour meter unit of measure	Sample Date	Fluid Sample	Lab report number	Lifetime Fuel Consumed Value	Severity	Recommendation	Hours Value
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	ENGINE	T120-55308-0227	147,451.18	No Action Required	All test results appear normal. Continue to sample at consistent intervals. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation; please contact Darron Rowley, Phone (02) 4964 5057. Email Darron.Rowley@westrac.com.au.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	FINAL DRIVE REAR LEFT	T120-55308-2313	147,451.18	No Action Required	Oil information was not reported, please supply oil, brand, type and grade information. For the reported fluid hours. All test results for this sample are acceptable, continue to sample at the recommended interval. ** For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Nikayla Howe, nikayla.howe@westrac.com.au, Ph 02 4964 5056.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	PUMP COUPLING	T120-55308-2243	147,451.18	Monitor Component	The iron appears slightly elevated. Check any contamination capturing devices fitted for debris. All other test results appear normal. Continue to sample at consistent intervals. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Darron Rowley, Phone (02) 4964 5057. Email Darron.Rowley@westrac.com.au.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	HYDRAULIC SYSTEM	T120-55308-1433	147,451.18	No Action Required	All test results appear normal. Continue to sample at consistent intervals. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation; please contact Darron Rowley, Phone (02) 4964 5057. Email Darron.Rowley@westrac.com.au.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	FINAL DRIVE REAR RIGHT	T120-55309-2137	147,451.18	Action Required	The PQ index, iron, aluminium and silicon are elevated possibly due to dirt entry and the oil is unsuitable for particle count testing. Check magnetic plug for abnormal ferrous material, if not already done. Check seals and breathers for dirt entry points. As the oil has reportedly been changed. Resample 125hrs after repairs or adjustments. ** For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Nikayla Howe, nikayla.howe@westrac.com.au, Ph 02 4964 5056.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	24/10/2025 00:00	RADIATOR	T120-55309-3018	147,451.18	No Action Required	All test results appear normal. Continue to sample at consistent intervals. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation; please contact Darron Rowley, Phone (02) 4964 5057.	8,000.00
YBN00611	CAT	336-07	7,463.78	h	16/01/2024 00:00	SWING DRIVE	T120-55024-2532	147,451.18	No Action Required	Insufficient oil information was reported Please supply exact oil, brand, type and grade information. All test results for this sample appear acceptable, continue to sample at the recommended interval. ** For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Nikayla Howe, nikayla.howe@westrac.com.au, Ph 02 4964 5056.	7,500.00