

Asset Serial Number	Make	Model	Sample Meter	Sample Date	Fluid Sample	Lab report number	Severity	Recommendation	Hours Value
YEP00542	CAT	336E L	7,742.00	16/09/2025 00:00	FINAL DRIVE REAR RIGHT	T120-55269-2427	No Action Required	<p>For the reported fluid hours. All test results for this sample are acceptable, continue to sample at the recommended interval. **</p> <p>For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Nikayla Howe, nikayla.howe@westrac.com.au, Ph 02 4964 5056.</p>	8,250.00
YEP00542	CAT	336E L	7,742.00	14/04/2025 00:00	ENGINE	T120-55112-0235	Action Required	<p>The lead appears elevated. Suggest inspecting the used engine oil filter(s) / screens for debris, if not already done. The elevated copper is possibly leaching from the cooler core--no failure.</p> <p>Suggest resample within 125 hrs to confirm the effectiveness of any adjustments or repairs. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Darron Rowley. Phone (02) 4964 5057. Email Darron.Rowley@westrac.com.au.</p>	8,000.00
YEP00542	CAT	336E L	7,742.00	14/04/2025 00:00	FINAL DRIVE REAR LEFT	T120-55113-2301	Monitor Component	<p>The PQ index and iron are slightly high and the oil is unsuitable for particle count testing. Check magnetic plug for abnormal ferrous material, if not already done. All other test results appear to be acceptable. Continue to sample at recommended interval. **</p> <p>For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation, please contact Nikayla Howe, nikayla.howe@westrac.com.au, Ph 02 4964 5056.</p>	8,000.00