



2018 JOHN DEERE 410E ARTICULATED DUMP TRUCK

1DW410ETEHF684334

URT-19

Uujo Contracting



10680



Signal



Off



25.22



Location

Overview

Maintenance

Diagnose & Repair

UUJO CONTRACTING LTD.

PO BOX 56

ROSE PRAIRIE, BC V0C2H0

(250) 827-3776

[Conversation History](#)[Customer Notes](#)

Machines (7) 2 PIPs 2 DTCs 8 EAs

[Warranty Information](#)

9 Expired

[Components and Option Codes](#)

Alerts

2 DTCs

5 Expert Alerts

Open (7)

In Progress (0)

Deferred & Dismissed (0)

Completed (0)

Type to Filter

Sort

Occurrence (Newest) ▾

Filters

Type ▾

Severity ▾

Showing 7 of 7 items

Onboard Weighing LHS Strain Gauge Failure



Information

Category

Total Occurrences

Last Occurrence

Solution

[Interactive Solution](#)

[Show Details](#)

RFC 002172.09

Information

OTHER RFC 002172.09 Communication system message missing. - Troubleshooting required.

Total Occurrences	Last Occurrence
3	Jul 17, 2026, 6:21 PM MDT 10679.50

JDL 002850.02

Information

OTHER JDL 002850.02 JDLink communications antenna fault. - Troubleshooting required.

Total Occurrences	Last Occurrence
1	Jul 17, 2026, 5:01 PM MDT 10679.40

Onboard Weighing LHS Strain Gauge Failure

High

Category	Total Occurrences	Last Occurrence
Expert Alert - Uptime	77	Dec 4, 2025, 2:36 PM MST 10252.00

Solution

[223544](#)

[Show Details](#)

MTG Antenna Not Working Correctly

High

Category	Total Occurrences
Expert Alert - Performance	2

Last Occurrence

Solution

Nov 24, 2025, 7:10 AM MST | 10218.90

[Interactive Solution](#)

[Show Details](#)

Missing DPF Fault Flag

Critical

Category

Expert Alert - Uptime

Total Occurrences

1

Last Occurrence

Apr 23, 2025, 3:53 PM MDT | 10043.20

Solution

[Interactive Solution](#)

[Show Details](#)

Onboard Weighing Strain Gauge or Harness Failure

High

Category

Expert Alert - Uptime

Total Occurrences

2

Last Occurrence

Feb 13, 2025, 10:26 AM MST | 9808.10

Solution

[223546](#)

[Show Details](#)

> PIPs - Product Improvement Programs

> Cases and Solutions

> Manuals and Instructions

> Aftermarket Recommendations

▼ Work Orders

Type to Filter

Sort

Repair Date (Newest)

Showing 45 of 45 items

WO 1951400

Completed

Repair Complete

Nov 25, 2025

Invoice Date

Nov 28, 2025

Usage

10209 Hours

Failed Part

Location

766530 - Fort St John

Segments (2)

> TROUBLESHOOT COOLING FAN CODE 1639.8	4.75 Labor Hours
> TRAVEL TO AND FROM SITE	3.25 Labor Hours

WO 1950061

✔ Completed

Repair Complete	May 15, 2025	Invoice Date	May 31, 2025
Usage	10042 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (6)

> MACHINE INSPECTION *cfmi25	4.5 Labor Hours
> WASH UNIT	9.75 Labor Hours
> REPLACE WINDOW	0 Labor Hours
> REPAIR LIGHTS	0.75 Labor Hours
> INSPECTION OIL SAMPLES /OVERLIMIT	0 Labor Hours
> INSPECTION PARTS DISCOUNT	0 Labor Hours

WO 1948780

✔ Completed

Repair Complete	Oct 28, 2024	Invoice Date	Oct 31, 2024
Usage	9780 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (1)

> DIAGNOSE NO JD LINK

2.5 Labor Hours

WO 1948009

✔ Completed

Repair Complete	Jul 12, 2024	Invoice Date	Jul 19, 2024
Usage	9418 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

> FUEL LEAK ON FILLER NECK

6.25 Labor Hours

> TRAVEL

2.25 Labor Hours

WO 1947860

✔ Completed

Repair Complete	Jun 28, 2024	Invoice Date	Jul 16, 2024
Usage	9394 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

> UNIT KEEPS GOING INTO LIMP MODE

28.25 Labor Hours

> BIN WEIGHING SYSTEM SCALE INOPERABLE

0 Labor Hours

WO 1947549

✔ Completed

Repair Complete	May 21, 2024	Invoice Date	May 27, 2024
Usage	9348 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

- > TRAVEL0 Labor Hours
- > T/S ENGINE NOISE11.5 Labor Hours

WO 1945791

✔ Completed

Repair Complete	Oct 10, 2023	Invoice Date	Oct 13, 2023
Usage	8575 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

- > 500 HOUR SERVICE PLUS AIR / CAB FILTERS3.5 Labor Hours
- > TRAVEL1.75 Labor Hours

WO 1944343

✔ Completed

Repair Complete	May 2, 2023	Invoice Date	May 6, 2023
Usage	7251 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (3)

- > 500 HR SERVICE4.5 Labor Hours
- > CHECK OVER MACHINE1 Labor Hours
- > TRAVEL2.5 Labor Hours

WO 1944194

✔ Completed

Repair Complete	Apr 17, 2023	Invoice Date	Apr 20, 2023
Usage	7132 Hours	Failed Part	---

Location

766530 - Fort St John

Segments (2)

> DIAGNOSE CODES	2.5 Labor Hours
> TRAVEL	2 Labor Hours

WO 1943278

✔ Completed

Repair Complete	Jan 20, 2023	Invoice Date	Jan 26, 2023
Usage	6969 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

> 21TX059F - FT4 ADT SM, HARNESS &#	0.5 Labor Hours
> PIP TRAVEL	2.5 Labor Hours

WO 1942608

✔ Completed

Repair Complete	Nov 8, 2022	Invoice Date	Nov 16, 2022
Usage	6845 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

> DEF CODES / DERATE	7 Labor Hours
> TRAVEL TO AND FROM MACHINE	1.5 Labor Hours

WO 1941834

✔ Completed

Repair Complete	Aug 23, 2022	Invoice Date	Aug 31, 2022
Usage	6463 Hours	Failed Part	---

Location

766530 - Fort St John

Segments (9)

- > REPAIR STEERING BUSHINGS 9.5 Labor Hours
- > CHECK MACHINE OVER FOR REPAIRS NEEDED 5.75 Labor Hours
- > REPAIR CAB GLASS 0 Labor Hours
- > TROUBLESHOOT TRANS OVERHEAT 16 Labor Hours
- > OIL LEAK UNDER CAB 5.75 Labor Hours
- > INSTALL STEPS 1.25 Labor Hours
- > INSTALL HANDLE 0.5 Labor Hours
- > INSPECT ARTICULATOR POINT 1.5 Labor Hours
- > REPAIR BIN WARM FLANGE 2 Labor Hours

WO 1941679

✔ Completed

Repair Complete

Jul 21, 2022

Invoice Date

Jul 29, 2022

Usage

6450 Hours

Failed Part

Location

766530 - Fort St John

Segments (3)

- > DIAGNOSE STEERING LOOSE / NOISY 1.25 Labor Hours
- > SERVICE AS NEEDED 2.25 Labor Hours
- > TRAVEL TO AND FROM MACHINE 3.75 Labor Hours

WO 1941170

✔ Completed

Repair Complete	May 18, 2022	Invoice Date	May 27, 2022
Usage	6213 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (1)

> DRAIN HYD TANK & FILL WITH BIO OIL - SAV	3.75 Labor Hours
--	------------------

WO 1941154

✔ Completed

Repair Complete	May 17, 2022	Invoice Date	May 21, 2022
Usage	6213 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (1)

> DIAGNOSE / REPAIR EGR	6.5 Labor Hours
-------------------------	-----------------

WO 1940932

✔ Completed

Repair Complete	Apr 25, 2022	Invoice Date	Apr 29, 2022
Usage	6139 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (1)

> ENGINE SERVICE / CAB FILTERS	3.5 Labor Hours
--------------------------------	-----------------

WO 1939509

Completed

Repair Complete	Nov 29, 2021	Invoice Date	Dec 23, 2021
Usage	5768 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (6)

> TURBO CODES / DERATE	8.5 Labor Hours
> WTY TRAVEL	12.75 Labor Hours
> MONITOR INTERMITTENT NOT POWERING UP	0.5 Labor Hours
> CORE CREDITS FOR WARRANTY	0 Labor Hours
> CHARGES NOT COVERED BY WTY	0 Labor Hours
>	0 Labor Hours

WO 1938744

Completed

Repair Complete	Sep 3, 2021	Invoice Date	Sep 11, 2021
Usage	5744 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (1)

> EGR CODES	0.75 Labor Hours
-------------	------------------

WO 1938530

Completed

Repair Complete	Jul 29, 2021	Invoice Date	Aug 20, 2021
Usage	5365 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

- > FUEL LEAK2 Labor Hours
- > TRAVEL0 Labor Hours

WO 1938413

✔ Completed

Repair Complete	Jul 16, 2021	Invoice Date	Jul 23, 2021
Usage	5164 Hours	Failed Part	---
Location	766530 - Fort St John		

Segments (2)

- > BIN STUCK IN THE AIR3.5 Labor Hours
- > TRAVEL4 Labor Hours

Show More (25 Remaining)

> Tickets

> Machine Notes