

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
6555	COD	5/28/2026			

Item	Description	Quantity	Rate	Amount
Complaint: REPLACE CLUTCH				
Cause: Customer request				
Labor	Correction: Transmission / Clutch / REMOVED AND REPLACED CLUTCH. ADJUSTED LINKAGE AS NEEDED. HAD TRANNY MOUNTS AT BACK SO HAD TO SUPPORT THE ENGINE TO GET THE TRANNY OUT. - Completed: 5/27/2026	15.00000	\$129.00	\$1,935.00
Parts	CLUTCH, E-Z PADEL 2050 TORQUE - 308925-25	1.00000	\$1,298.776	\$1,298.78
Parts	FLYWHEEL MACHINING - FLYWHEEL MACHINING	1.00000	\$140.00	\$140.00
Parts	CLUTCH BRAKE - BAC SB200	1.00000	\$79.6775	\$79.68
Parts	MISC - FITTINGS	5.00000	\$12.18056	\$60.90
Parts	SYN-GEAR XDM 75W-90 - CHV-22-3030-15	3.00000	\$18.345	\$55.04
Subtotal				\$3,569.40

Complaint: REPLACE FRONT BUMPER				
Cause: Customer request				
(Inspection)				
Labor	Correction: Chassis / Chassis / REPLACED FRONT BUMPER, DRILLED NEW MOUNTING HOLES AND WELDED CRACKED - Completed: 5/27/2026	1.50000	\$129.00	\$193.50
Subtotal				\$193.50

Complaint: HYDRAULIC LEAKS				
Cause: Customer request				
(Inspection)				
Labor	Correction: Chassis / Chassis / REMOVED AND REPLACED LEAKING HYDRAULIC HOSE, HAD TO GO TO MAKE NEW ONE. - Completed: 5/27/2026	1.50000	\$129.00	\$193.50
Parts	PRE-MADE HIGH PRESSURE HOSE - HYDRAULIC HOSE ASS	2.98100	\$100.00	\$298.10
Subtotal				\$491.60

Unit: VIN: 2M2AM07C1LC001188		Labor	\$2,322.00
1990 Mack RB		Parts	\$1,932.50
Chassis: 98,050 Kilometers		Shop Supplies	\$340.36
		Pre-Charge Subtotal	\$4,594.86
		GST	\$229.74
		(5% of \$4,594.86)	
		PST	\$321.64
		(7% of \$4,594.86)	