



12308 100 Street, Grande Prairie, AB T8V 4H7

Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865

User

Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220

KendraH

Service Direct Line: (780) 830-4200

SO # S106933

Status

Printed 10/17/2025 8:20:00 AM

SERVICE ORDER CUSTOMER COPY

Amount 0.00

0.00

0.00

Customer No 386

Ritchie Bros Auctioneers 721076 Rge Rd 51

County Of Grande Prairie No. 1, AB T8X 4G1

Home (780) Cell

(780) 538-1100 Bus Today

Email grande_prairie_csms@rbauction.com

Type Term Cash

Advisor	Kendra Hare	Promised	10/09/2025 6:00 PM	Tag#	7123
Shop	S1	Opened	10/09/2025 1:05 PM	Location	
Сор		Cashiered		PO#	

License Odom In Odom Out In Service Date Stock No 257012 257014 04/24/2019 920582 Year Make Model Mode! Number Colour 2019 **GMC** SIERRA 1500 TK10743 GAZ SUMMIT Vehicle ID No Selling Dealer **Extended Warranty Delivery Date** 1GTU9DEDXKZ289879 04/23/2019 Engine 5.3L ECOTEC3 V8 Fleet # 920582

Request Description

DIAG Customer concerned the chekc engine light is coming back on and engine is misfiring,

DIAG Customer concerned the chekc engine light is coming back on and engine is misfiring,

1 0442 Low Original

please see history and advise

DIAG Customer concerned the chekc engine light is coming back on and engine is misfiring, please see history and advise

Rate 210.00 Est Parts

Ses LAMP is not currently on, scanned for codes and no relating codes current or Est Labour history.

Correction Monitored

Monitored engine misfire data and all cylinder read 0 counts current and history. Found possible relating bulletin 18-NA-292: Malfunction Indicator Lamp (MIL) Illuminated with DTC P0300-This condition may be caused by a software anomaly. Checked for programming updates and found updates available for the ECM. Will need to start here-Reprogrammed ECM, code: 11YN299109175. Ran vehicle again in the AM and ses lamp is not on. Had shuttle driver road test vehicle again and ses lamp did turn on and was flashing but then shut off again before returning to the shop. Scanned for codes and has p0300 engine misfire detected stored in history. Monitored misfire data and only has history misfire counts present 756counts at cylinder #8. Had shuttle driver road test while monitoring data with scan tool confirmed when condition occurs misfire is present and internal engine noise is present. When accelerating and rev reaches 3000rpm can hear bottom end engine rattle and intermittently ses lamp will set with p0300. Will require engine replacement, also noticed on road test rough down shift and due to mileage suggest transmission replacement. *Advise customer it is possible catalytic convertor may require replacement as well due to fault with engine at this point there is no codes indicating failure but unsure how much damage has occurred to the convertors due to engine fault.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in where for the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or else-on the purpose of testing and/or inspection. Until payment in full of the within account. I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full.

Date:	Signature:





Year

2019

386

12308 100 Street, Grande Prairie, AB T8V 4H7

Phone: (780) 532-8865 | Fax: (780) 539-7510 | Toll Free: (888) 532-8865

Parts Direct Line: (780) 539-3745 | Parts Fax: (780) 830-4220

Service Direct Line: (780) 830-4200

SO # S106933

Status

Customer No

721076 Rge Rd 51

Ritchie Bros Auctioneers

Printed 10/17/2025 8:20:01 AM

County Of Grande Prairie No. 1, AB T8X 4G1

Type

Term Cash

grande_prairie_csms@rbauction.com

(780) 538-1100 Bus

SERVICE ORDER CUSTOMER COPY

Page

Advisor Promised Kendra Hare

Opened Shop S1 Cashiered

10/09/2025 6:00 PM Tag# 7123 10/09/2025 1:05 PM Location

PO#

KendraH

License

Make

GMC

Odom in **Odom Out** 257012 257014

SIERRA 1500

Selling Dealer

Model

In Service Date 04/24/2019 Model Number TK10743

Stock No 920582 Colour **GAZ SUMMIT**

Vehicle ID No 1GTU9DEDXKZ289879

Extended Warranty Fleet # 920582

User

Delivery Date 04/23/2019

Engine 5.3L ECOTEC3 V8

Nate 587-298-1424

Nate advised called them with the estimate as it will be billed through Ritchie Bros not

Enterprise

Home

Cell

Email

dropped off no appointment

Labour	0.00
Parts	0.00
Fees	0.00
Supplies	0.00
Sub-Total	0.00
GST	0.00
Total Invoice	0.00

Recommended/Deferred Services

Code

Description

ESE

engine replacement, includes diagnosis up to this point, reset procedures after repalcement and AC system recharge.

Reason: they have declined at this time

ESE

Transmission replacement, includes line flush

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that to the extent permitted by law, you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets highways or elsewhere for the purpose of testing and/or inspection. Until payment in full of the within account, I hereby acknowledge the existence of a repair lien in favor of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer, until the within account is paid in full. While the vehicle is in my possession it shas at all times be subject to repossession on demand by the dealer until the within account is paid in full

ate: Signature