

Maintenance Date	Plant	Maintenance Short Description	Maintenance Supplied By	Meter Reading	Cost	Notes
09/21/2025	PR-17 Truck - Tipper (XN99RF)	Full service	TJ Woods	70,099 km	1,469.46	Carry out a full service as required. Change the engine oil & filter. Replace the fuel & air filters. Check & adjust all fluid levels. Jack up all axles, check & adjust all brakes, check all wheel bearings for movement. Check & grease all steering, suspension & driveline components. Check all lights. General check over
07/13/2025	PR-17 Truck - Tipper (XN99RF)	Fix Jake brake	TJ Woods	68458 km	3,865.08	Test drive and inspect Jake brake fault locate damaged internal harness , remove interior floor plate remove tappet cover remove internal harness , remove external harness and have repaired were necessary by Trent Ryan , replace internal harness reassemble and test Jake operation
04/27/2025	PR-17 Truck - Tipper (XN99RF)	Full service 60k	TJ Woods	60382 km	2,146.10	Carry out a full service as required. Change the engine oil & filter. Replace the fuel & air filters. Check & adjust all fluid levels. Jack up all axles, check & adjust all brakes, check all wheel bearings for movement. Check & grease all steering, suspension & driveline components. Check all lights. General check over
11/10/2024	PR-17 Truck - Tipper (XN99RF)	Check fuel pressure	TJ Woods	52020 km	640.2	Carry out pressure checks on fuel system , full check over on system diagnose faulty fuel pump
08/30/2024	PR-17 Truck - Tipper (XN99RF)	Release brakes	TJ Woods	50436 km	347.6	Release brakes, jack axle 2 and 3 remove brake backing plates and pry locked brakes off and adjust all brakes refit backing plates
08/16/2024	PR-17 Truck - Tipper (XN99RF)	Replaced failed UHF radio	Ryan Mobile Auto Electrics	50266 km	639	
07/26/2024	PR-17 Truck - Tipper (XN99RF)	B Service	TJ Woods	49,722 km	2,253.90	Check engine light on. Plug scan tool in run diagnostics. Found to be a faulty engine speed sensor. Remove and replace both engine speed sensors check operation. Remove dash centre manufacturer a support bracket secure dash order broken dash pieces. Jack all axles check all wheels for wheel end play and adjust brakes. Carry out "B" service change engine oil & filter. Replace the fuel & air filters. Pressure test cooling system locate leak at bypass hose from thermostat housing to water pump. Change clamps on hose & top up coolant. Replace wiper blades. Remove steering shaft and replace lower 2 steering unit joints grease shaft
06/23/2024	PR-17 Truck - Tipper (XN99RF)	Replace failed drivers door window regulator/motor assembly	Ryan Mobile Auto Electrics	47558 km	269.44	Includes 1 x side marker lamp replaced on Dog Trailer
05/24/2024	PR-17 Truck - Tipper (XN99RF)	Full Service	TJ Woods	40337 km	1,058.18	Carry out full service as required. Change the engine oil & filter. Replace the fuel & air filters. Check & adjust all fluid levels. Jack up all axles, check & adjust all brakes, check all wheel bearings for movement. Check & grease all steering, suspension & driveline components. Check all lights. General check over
05/21/2024	PR-17 Truck - Tipper (XN99RF)	Full Mechanical inspection	TJ Woods	43016 km	2,199.46	Carry out full mechanical inspection note repairs for later date , Remove left cab skirt to gain access to top of gear box and replace range change solenoid reassemble and test operation. Carry out diagnostics to further listed faults and order part as required. Supply & fit a new throttle & speed sensors. Replace the engine brake switch.
04/19/2024	PR-17 Truck - Tipper (XN99RF)	Carry out full service	TJ Woods	40337 km	1,120.47	Carry out a full service as required. Change the engine oil & filter. Replace the fuel and air filters. Check and adjust all fluid levels. Jack up axles, check and adjust all brakes, check all wheel bearings for movement. Check & grease all steering, suspension & driveline components. Check all lights. General check over.
04/15/2024	PR-17 Truck - Tipper (XN99RF)	Carry out "B" service	T.J.Woods mobile Mechanical Repairs	40337 km		
04/08/2024	PR-17 Truck - Tipper (XN99RF)	Pre-Pit inspection	TJ Woods	39000 km	211.75	Carry out a pre pit inspection. Jack up all axles check & adjust all brakes, check all wheel bearings for movement. Check all steering & suspension components. Check all lights
03/19/2024	PR-17 Truck - Tipper (XN99RF)	Check & adjust all brakes. Check over for a RMS inspection	T.J.Woods mobile Mechanical Repairs	37137 km		
03/08/2024	PR-17 Truck - Tipper (XN99RF)	Replace the cabin fan	TJ Woods	34,454 km	289.85	
02/24/2024	PR-17 Truck - Tipper (XN99RF)	Replace cabin fan	T.J.Woods mobile Mechanical Repairs	34454 km		
02/18/2024	PR-17 Truck - Tipper (XN99RF)	R&R rear lower trailing arms. Fit new bushes to arms. Replace all top torque rod bushes. Replace all drive shocks.	TJ Woods	33,313 km	1,659.90	
02/07/2024	PR-17 Truck - Tipper (XN99RF)	Replace all rear trailing arm & torque rod bushes. Replace all drive shocks	T.J.Woods mobile Mechanical Repairs	33132 km		
11/09/2023	PR-17 Truck - Tipper (XN99RF)	Carry out "B" service	T.J.Woods mobile Mechanical Repairs	25322 km		
10/19/2023	PR-17 Truck - Tipper (XN99RF)	Repair the AdBlue system	T.J.Woods mobile Mechanical Repairs	22860 km		
09/21/2023	PR-17 Truck - Tipper (XN99RF)	Replace the turbo. Carry out a valve adjustment. Replace fan belts & tensioner	T.J.Woods Mobile Mechanical Repairs	20840 km		
09/12/2023	PR-17 Truck - Tipper (XN99RF)	Check & clear engine codes. Replace the manifold pressure switch	T.J.Woods	19064 km		
07/28/2023	PR-17 Truck - Tipper (XN99RF)	Replace the radiator hoses	T.J.Woods Mobile Mechanical Repairs	14202 km		
06/13/2023	PR-17 Truck - Tipper (XN99RF)	Carry out a "B" service. Repair coolant leak. Replace heater taps	T.J.Woods	10119 km		
05/12/2023	PR-17 Truck - Tipper (XN99RF)	Replace the sender unit. Repair windscreen washer. Repair coolant leak	T.J.Woods	0 km		
03/31/2023	PR-17 Truck - Tipper (XN99RF)	Repair door catch. Repair air leaks	T.J.Woods	1641 km		
03/02/2023	PR-17 Truck - Tipper (XN99RF)	Carry out a "B" service	T.J.Woods	997898 km		
02/04/2023	PR-17 Truck - Tipper (XN99RF)	Replace front springs, shocks & U-bolts	T.J.Woods	996931 km		
10/24/2022	PR-17 Truck - Tipper (XN99RF)	"A" service	T.J.Woods	992043 km		
09/11/2022	PR-17 Truck - Tipper (XN99RF)	Repair the wiring to the R/H head light	T.J.Woods Mobile mechanical repairs	990487 km		
08/28/2022	PR-17 Truck - Tipper (XN99RF)	Repair a coolant leak	T.J.Woods Mobile mechanical repairs	989551 km		
07/03/2022	PR-17 Truck - Tipper (XN99RF)	Fit a new wiper assembly	T.J.Woods Mobile mechanical repairs	986950 km		
01/16/2022	PR-17 Truck - Tipper (XN99RF)	"A" service Replace the brakes on axle 3. Replace brake booster L/H axle 3	T.J.Woods	975975 km		
12/20/2021	PR-17 Truck - Tipper (XN99RF)	service	VINCE HAGARTY	975000 km		CHANGED ENGINE OIL & FILTER, X2 FUEL FILTERS GREASE & ADJUST BRAKES NEXT SERVICE DUE 990000KM
09/21/2021	PR-17 Truck - Tipper (XN99RF)	Engine service	Justin JB Mechanical	9700812 km		Carry out engine service safety check all ok next service 980,000 km
08/25/2021	PR-17 Truck - Tipper (XN99RF)	Repairs	Justin JB Mechanical	11111 km		Replaced AC idler pulley and belt Replaced 2 x front boosters Replaced air line from front regulator to booster Inspect battery

05/05/2021	PR-17 Truck - Tipper (XN99RF)	Engine service and defect repairs	Nick mcd	960447 kms	Engine service carried out All engine filters changed Greased Adjusted brakes Carry out mechanical audit Repair intercooler damage Renew air conditioning condenser due to damage
02/27/2021	PR-17 Truck - Tipper (XN99RF)	Service	Nick McDonald	955621 km	Engine service carried out All filters changed Engine oil changed Greased Adjusted brakes Mechanical audit carried out
11/19/2020	PR-17 Truck - Tipper (XN99RF)	Maintenance	Digger mechanical	945190 km	Fixed air leak on fire wall and done a hot set next service due 1,1045,190 km
11/13/2020	PR-17 Truck - Tipper (XN99RF)	Defect repair bullbar lights	Ryan Auto electrical	1 km	Bull bar lights wired in Diagnose faulty engine oil temp gauge. Find sender faulty - parts ordered.
09/12/2020	PR-17 Truck - Tipper (XN99RF)	Service	Josh Barrett	940263 km	Minor service carried out. Engine oil and filters changed. All others fluids checked and greased. Next service 950,000kms
09/05/2020	PR-17 Truck - Tipper (XN99RF)	Defect repairs	Nick McDonald	940055 km	Repaired faulty Rhs indicator wiring on mudguard Checked operation of all lights
07/18/2020	PR-17 Truck - Tipper (XN99RF)	service	Nick McDonald Mechanical	930000 km	Changed engine oil & filter, fuel filters, adjust brakes & grease next service due 940,000 km
04/17/2020	PR-17 Truck - Tipper (XN99RF)	Service	LAESENS TRUCKS	915665 km	Changed engine oil & filter, fuel filters, air filters, diff oils & filter, gearbox oil & filter next service due 930,000 km