

Unit #8 - 1T0450JXPB0198481

DATE	HOURS	REPAIR
MAY 22/12	259	Extend blade lift cylinders
NOV 6/12	540	Repair for sdm & tcu codes
OCT 31/12		Repair damage to canopy roof
JUL 12/13	437	Repair possible alternator alignment issue
SEP 20/13	468	Repair for fuel leak at fuel rail
MAY 28/14	582	Repair for broken blade link & twisted blade Install track spring guards
AUG 21/14	636	Replace damaged fan shroud Repair oil leak at oil pan
JAN 12/15	687	Repair for failed muffler
MAR 12/15	702	Repair for fuel leak at engine
MAR 31/15	702	Repair no electrical function
NOV 25/15	743	Replace failed right hand track spring Repair for counter rotating right hand track
AUG 17/16	812	Supply & install inside blade cutting edge
MAR 20/17	899	Replace broken track spring on left hand side
DEC 29/17	973	Repair for excessive play in blade lift arms
MAY 29/18	1004	Replace broken dipstick
JUL 16/18	1066	Repair for fuel leak
AUG 26/19	1303	Repair for water pump leak Repair for broken track spring & failed idler Extract broken timing cover bolts & stripped w/pump bolt Extract broken cooling package bolt
SEP 19/19	1314	Repair engine oil leak
APR 20/20	1396	Repair for fuel leak at steel line connection at the fuel transfer pump Repair oil leak at timing cover area
NOV 23/20	1482	Repair for failed operator seat suspension
AUG 31/22	1550	Repair for broken rh track adjuster spring Extract broken master link hardware x 3