instantAccess
The Access Specialists

Instant Access Australia Pty Limited
1/2 Cyanamid Street, Laverton North, VIC 3026
ABN: 20 001 872 500
Phone: 03 9223 6666
Email: info@instantaccess.com.au

Report Number:	INST – 167
Report Date:	17.10.2022

Elevating Work Platform

MAJOR EXAMINATION

Manufacturer: JLG

Model: 2646ES

Serial Number: 1200003360

Owner: Instant Access

Instant Access Australia Pty Limited
1 / 2 Cyanamid Street, Laverton North, VIC 3026
ABN: 20 001 872 500
Phone: 03 9223 6666
Email: info@instantaccess.com.au

Proud Member of:

EWPA
Elevating Work Platform Association

Table of Contents

ITEM No - 1. GENERAL 3

ITEM No - 2. SAFETY ITEMS 4

ITEM No - 3. INDICATORS / ALARMS 5

ITEM No - 4. CONTROLS 6

ITEM No - 5. FUNCTIONS & SPEEDS 7

ITEM No - 6. HYDRAULICS 8

ITEM No - 7. ELECTRICS 9

ITEM No - 8. MECHANICAL CONDITION 10

ITEM No - 9. STRUCTURAL CONDITION 11

ITEM No - 10. TESTS 12

ITEM No - 11. *ADDITIONAL FOR* SELF-PROPELLED MEWPs 13

ITEM No - 12. *ADDITIONAL FOR* PEDESTRIAN-CONTROLLED MEWPs 14

LIST OF SIGNIFICANT REPAIRS 15

TEST CERTIFICATE 16

MAJOR INSPECTION DECLARATION 17

Major Inspection Checklist

instantAccess

Manufacturer:	JLG	Owner:	Instant Access
Model:	2646ES	Asset Number:	3360
Serial Number:	1200003360	Hour Meter:	636.10
Date of Manufacture:	2005	Odometer Reading:	N/A
Date of Commission:	26.07.2005	Design Registration No:	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
1.	GENERAL			
1.1	Verification of serial number	Pass	Pass	
1.2	Completion of manufacturer's safety upgrades	Pass	Pass	
1.3	Modification to the latest standard (as far as reasonably practicable)	Pass	Pass	
1.4	Manufacturer's manuals present.	Pass	Pass	
1.5	Manufacturer's specification plates (including rated capacity, slope and wind)	Pass	Pass	
1.6	Logbooks	Pass	Pass	

Major Inspection Checklist

instantAccess

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
2.	**SAFETY ITEMS**			
2.1	Operating decals, installed and legible	**Pass**	**Pass**	
2.1.1	General operating instructions	**Pass**	**Pass**	
2.1.2	Emergency operating instructions	**Pass**	**Pass**	
2.2	Emergency retrieval systems operate correctly	**Pass**	**Pass**	
2.3	Safety interlocks	**Pass**	**Pass**	
2.3.1	Stabiliser Interlocks	**N/A**	**N/A**	
2.3.2	Boom Interlocks	**N/A**	**N/A**	
2.3.3	Motion Interlocks (if fitted)	**Pass**	**Pass**	
2.4	Hazard warning decals fitted (as applicable)	**Pass**	**Pass**	

Major Inspection Checklist

instantAccess

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
3.	**INDICATORS / ALARMS**			
3.1	Level indicators / alarms function correctly	**Pass**	**Pass**	
3.2	Load indicators / limiters function correctly (if fitted)	**Pass**	**Pass**	
3.3	Hour meter operational	**Pass**	**Pass**	
3.4	Motion alarms	**Pass**	**Pass**	
3.5	Other Indicators / Alarms	**N/A**	**N/A**	

Major Inspection Checklist

instantAccess

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
4.	CONTROLS			
4.1	Lower controls return to off and correctly labelled	Pass	Pass	
4.2	Lower controls isolate upper controls	Pass	Pass	
4.3	Upper controls return to off and correctly labelled	Pass	Pass	
4.4	Stabiliser controls (if fitted)	N/A	N/A	
4.5	Emergency stop / dead man functions correctly	Pass	Pass	
4.6	Other Controls	N/A	N/A	

Major Inspection Checklist

instantAccess

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
5.	**FUNCTIONS & SPEEDS**			
5.1	Functions operate correctly	**Pass**	**Pass**	
5.2	Speeds set to specification	**Pass**	**Pass**	
5.3	Platform levelling system operates correctly	**N/A**	**N/A**	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
6.	HYDRAULICS			
6.1	All hydraulic hoses in serviceable condition and routed correctly	Pass	Pass	
6.2	System relief valves set to specification	Pass	Pass	
6.3	Loading holding valves operate correctly	Pass	Pass	Replaced Lowering Holding Valve
6.4	Accumulators inspected in accordance with AS / NZS 3788	N/A	N/A	
6.5	Hydraulic cylinders in serviceable condition	Pass	Pass	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
7.	**ELECTRICS**			
7.1	Electrical looms adequately installed and protected	**Pass**	**Pass**	
7.2	Electrical switches secured and operational	**Pass**	**Pass**	
7.3	Work lights function correctly (if fitted)	**N/A**	**N/A**	
7.4	Rotating beacons operate correctly (if fitted)	**Pass**	**Pass**	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
8.	**MECHANICAL CONDITION**			
8.1	Chains / wire ropes adequate condition on tensioned	N/A	N/A	
8.2	Sprockets / sheaves guarded as necessary	N/A	N/A	
8.3	Braking systems operational and hold load	Pass	Pass	
8.4	Pivot points adequately lubricated, secured and no excessive clearance	Pass	Pass	
8.5	Slew bearing condition within tolerance	N/A	N/A	
8.6	Slew drive condition satisfactory	N/A	N/A	
8.7	Slew lock fitted and operational	N/A	N/A	
8.8	Counterweights secured	Pass	Pass	
8.9	Guarding Adequate	Pass	Pass	
8.10	Wear pads within tolerance	Pass	Pass	

Major Inspection Checklist

instantAccess

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
9.	**STRUCTURAL CONDITION**			
9.1	Structural free from deformation	**Pass**	**Pass**	
9.2	Critical areas free of cracks	**Fail**	**Pass**	**Repairs to deck carried out by Robert Lange Engineering**
9.3	Corrosion absent and surface condition protected	**Pass**	**Pass**	
9.4	Platform condition and guardrails adequate	**Pass**	**Pass**	
9.5	Platform gates self-closing and latching	**Pass**	**Pass**	
9.6	Platform floor condition adequate	**Pass**	**Pass**	
9.7	Travel rests satisfactory (boom type MEWPs)	**N/A**	**N/A**	
9.8	Personnel access adequate and slip resistant	**Pass**	**Pass**	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
10.	**TESTS**			
10.1	Function Test	**Pass**	**Pass**	
10.2	Load Test	**Pass**	**Pass**	
10.3	Braking Test	**Pass**	**Pass**	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
11.	***ADDITIONAL FOR*** **SELF-PROPELLED MEWPs**			
11.1	Drive brakes hold MEWP on rated gradient	**Pass**	**Pass**	
11.2	Drive wheels axles and tyres adequate condition and correct specification	**Pass**	**Pass**	**Replaced 4 wheels**
11.3	Wheel nuts correctly torqued	**Pass**	**Pass**	
11.4	Extendible or oscillating axles function correctly and interlocked	**N/A**	**N/A**	
11.5	Slope alarm operates correctly	**Pass**	**Pass**	
11.6	Motion alarms operate correctly (if fitted)	**Pass**	**Pass**	
11.7	Audible warning device operational	**Pass**	**Pass**	
11.8	Engine, fuel and exhaust systems appropriately guarded sealed and serviceable	**N/A**	**N/A**	
11.9	Batteries adequately secured and with correct specification	**Pass**	**Pass**	
11.10	On board battery charger secured and adequately isolated from chassis	**Pass**	**Pass**	
11.11	Safety prop installed, labelled and functional (scissor type MEWPs)	**Pass**	**Pass**	
11.12	Condition of lifting eyes and tie-down adequate	**Pass**	**Pass**	
11.13	Harness anchor points satisfactory (boom type MEWPs)	**N/A**	**N/A**	

Item No.	Item to be checked	Initial (Pass / Fail)	Final (Pass / Fail)	Notes
12.	***ADDITIONAL FOR*** **PEDESTRIAN-CONTROLLED MEWPs**			
12.1	Parking brake holds load on rated gradient	N/A	N/A	
12.2	Batteries adequately secured and correct specification	N/A	N/A	
12.3	Onboard battery charger secured and adequately isolated from chassis	N/A	N/A	

10 Year Major Inspection
List of Significant Repairs

instantAccess

Manufacturer:	JLG	Owner:	Instant Access
Model:	2646ES	Asset Number:	3360
Serial Number:	1200003360	Hour Meter:	636.10
Date of Manufacture:	2005	Odometer Reading:	N/A
Date of Commission:	26.07.2005	Design Registration No:	

Additional Repairs Completed

As per Service Work Order 201/533273

10 Year Major Inspection
TEST CERTIFICATE

instantAccess

REFERENCE – AS/NZS 148.10 2011 – ELEVATING WORK PLATFORMS

Machine Model:	**2646ES**
Serial Number:	**1200003360**
Rated Load (SWL):	**450 Kg**

CLAUSE 3.6 PERFORMANCE REQUIREMENTS

3.6.3.1.1	Stability Test (static) Static Test Load: 450 Kg	Complies: OK
3.6.4	Overload Test Overload Test Load: 500 Kg	Complies: OK
3.6.5	Functional Test Rated Load: 450 Kg	Complies: OK

10 Year Major Inspection
TEST CERTIFICATE

instantAccess

DECLARATION BY INSPECTING ORGANISATION

I hereby certify that the Elevating Work Platform identified above has been inspected in accordance with the requirements of AS2550.10 and has been found to be in a safe serviceable condition at the time of inspection.

Inspecting Organisation: **Instant Access**

Authorised Representative: **Peter Grimaud**

Company ABN: 20 001 872 500 **Date:** 17.10.22

The following inspection and test reports form part of the major inspection requirements and have been completed.

REPORT	DESCRIPTION	ORGANISATION	REPORT NUMBER
1.	Examination of structural mechanical components	Tru-Test Inspection Services	TT22-213-079
2.	Non- destructive testing of critical structural mechanical components	Tru-Test Inspection Services	TT22-213-079
3.	Function test	Instant Access	INST-167
4.	Load test	Instant Access	INST-167
5.	Stability test	Instant Access	INST-167
6.	Electrical insulation acceptance test	N/A	N/A
7.	Accumulator inspection	N/A	N/A
8.	Other	Robert Lange Engineering	Inv # 66561

TRU·TEST INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs



Photo 1

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)




Photo 2

TEST PERSONNEL: B. Knowles	
Signatory: B. Knowles	Sign:
Report Date: 2 Sep 2022	

TRU·TEST INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)




Photo 3

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST
INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)



Photo 4

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)



Photo 5

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)



Photo 6

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST
INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)



Photo 7

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST
INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)



Photo 8

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		

TRU·TEST
INSPECTION SERVICES

Report No.:	TT22-213-079
Test Date:	2 Sep 2022

Photographs (cont'd)




Photo 9

TEST PERSONNEL: B. Knowles		
Signatory: B. Knowles	Sign:	
Report Date: 2 Sep 2022		