Car Service Salisbury

1 Stanbel Road
Salisbury Plains SA 5108
ABN 30 008 264 319
Tel: 8250 0583 Fax: 8281 6568
Email: accounts@carservicesalisbury.com
Website: www.carservicesalisbury.com
Au 38172

Tax Invoice

Inv. No.	34185	Date	04/08/25	Order No.	-	Sales ID	-

Client Details

Hispec Transport

Vehicle Details

Rego: 436 ET5 **Odo:** 127721
Make/Model: GMC SIERRA 2500 HD
Year: 2018
VIN: 1GT12EY2JF261465
Next service: Premium Service
Due: 17/01/26 **Kms:** 137176

Account	12138	Home	-	Work	-	Mobile	0412 979 093

Work done

Diag - No Power Steer
Vehicle Toweed In For No Power Steering And Brakes Start Vehicle And Found Power Steering And Brakes Ok
Road Test Vehicle Along Main North Road At 80kph No Faults At This Time
Note Found Upper Radiator Hose Sucking In And Colapsing Requires New Upper Rad Hose
Supply And Fit New Rad Hose Top Up Coolant Run And Road Test Again
Unable To Fault At This Time

Services, Parts & Labour

Mechanical

Qty	Description	Unit Price	Total (Ex)	Tax	Total (Inc)
1	Diagnosis Test Time	$363.64	$363.64	$36.36 GST	$400.00
1	Radiator Hose	$190.91	$190.91	$19.09 GST	$210.00
	Total Diagnosis Test Time		**$554.55**	**$55.45**	**$610.00**
			$554.55	**$55.45**	**$610.00**

Financial Summary

Total (Ex. Tax)	$554.55	Terms	
Tax Total	$55.45	Paid	
Total (Inc. Tax)	**$610.00**	**Balance**	

We Are Proud Of All Our Repairs, If You Are, Please Tell Others, If You A
We Would Like To Thank You For Your Business And Assure You Of Our P

Bsb - 105-012
Account - 120 441 740
Abn -

bankSA

CAR SERV SALISBURY
1 STANBEL RD
SALISBURY PLA SA 5109

TID	**P3608095**
MID	06849343
DATE/TIME	**05/08/25 13:05**
RRN	**051305022555**
STAN 022555	AUTH R71348
CARD ... 4577	CR(T)
MASTERCARD	
Mastercard	
AID	A0000000041010
TVR 0000048001	ATC 004A
ARQC	0F6DC425D6DB6935
PURCHASE	**AUD 610.00**
APPROVED	**0000**

Car Service Salisbury

1 Stanbel Road
Salisbury Plains SA 5108
ABN 30 008 264 319
Tel: 8250 0583 Fax: 8281 6568
Email: accounts@carservicesalisbury.com
Website: www.carservicesalisbury.com
Au 38172

436ETS

Tax Invoice

Inv. No.	34071	Date	17/07/25	Order No.	-	Sales ID	-

Client Details

Hispec Transport

Vehicle Details

Rego: 436 ET5 **Odo:** 127176
Make/Model: GMC SIERRA 2500 HD
Year: 2018
VIN: 1GT12EY2JF261465
Next service: Premium Service
Due: 17/01/26 **Kms:** 137176

Account	12138	Home	-	Work	-	Mobile	0412 979 093

Work done

Premium Service & 65 Point Repco Authorised Service Inspection. Including: Change Engine Oil & Oil Filter & Check Air Filter, Check Battery & All Other Levels & Top Up As Required, Check Tyres & Lights Etc, Visual Check Of Hoses, Belts, Exhaust, Suspension, Shockers & Under Car Components. Check Wheel Bearings For Play. Remove Road Wheels & Inspect Brakes For Wear / Leaks, Inspect Brake Fluid.
Checked Vehicle For Power Steer Leak, Found Power Steer Hose Fallen Off, Refitted Hose With 2 New Clamps & Topped Up Fluid Level, Bled Systemof Air , Degreased Oil From Vehicle & Road Tested - Ok.

Inspection report: https://tinyurl.com/ythy66h4

Services, Parts & Labour

Mechanical

Qty	Description	Unit Price	Total (Ex)	Tax		Total (Inc)
1	Premium Service	$436.36	$436.36	$43.64	GST	$480.00
1	Air Filter	$127.27	$127.27	$12.73	GST	$140.00
10	Dhd 15w-40	$12.46	$124.55	$12.45	GST	$137.00
1	Oil Filter	$53.64	$53.64	$5.36	GST	$59.00
2	Adblue 10l	$6.37	$12.73	$1.27	GST	$14.00
1	Waste Management Fee	$18.18	$18.18	$1.82	GST	$20.00
1	Workshop Supplies	$18.18	$18.18	$1.82	GST	$20.00
	Total Premium Service		**$790.91**	**$79.09**		**$870.00**
1	Check Power Steering Leak	$290.91	$290.91	$29.09	GST	$320.00
2	Penrite Premium Fully Synthetic Transmission Fluid L V	$17.27	$34.55	$3.45	GST	$38.00
2	Degreaser	$4.54	$9.09	$0.91	GST	$10.00
2	Hose Clamp	$3.63	$7.27	$0.73	GST	$8.00
	Total Check Power Steering Leak		**$341.82**	**$34.18**		**$376.00**
			$1,132.73	**$113.27**		**$1,246.00**

Vehicle report

(future) Diff Oil Condition & Leaks: Rear Right Axle Seal Leaking.
(future) Exhaust System: Exhaust Leaks Present, Will Require Exhaust Specialist
(urgent) Tread Depth Lf (mm): Worn On Inner Edge
(urgent) Tread Depth Rf (mm): Worn On Inner Edge
(urgent) Wheel / Rim Condition: Rear Right Wheel Missing 1x Lug Nut. Requires Replacement
(future) Dash Warnings & Instruments: Tyre Pressure System Warning On Dash, Aftermarket Wheels Fitted To Vehicle

BSA

Financial Summary

Total (Ex. Tax)	$1,132.73	Terms	Cash on delivery
Tax Total	$113.27	Paid	$0.00
Total (Inc. Tax)	**$1,246.00**	**Balance**	**$1,246.00**

We Are Proud Of All Our Repairs, If You Are, Please Tell Others, If You Are Not Please Tell Us First.
We Would Like To Thank You For Your Business And Assure You Of Our Personal Attention At All Times.

Bsb - 105-012
Account - 120 441 740
Abn -

CAR SERVICE SALISBURY

1 STANBEL RD
SALISBURY PLAIN 5109
Phone: 08 8250 0583
Email: admin@carservicesalisbury.com

AUTO-TECH SMARTQUOTE

Customer

Hispec Transport

0412 979 093

nmaione@hsic.com.au

Vehicle

GMC SIERRA 2500 HD D 6.6L LML OHV 32v Turbo Diesel Direct Inj. V8 296kW Crew Cab Utility AWD [07/14 ON]

Rego. 436 ET5

VIN 1GT12EY2JF261465

Odo. 127,176km

RAS 65 Point Check

Urgent

Job		Action	Ref
Wheels & Tyres			
Tread Depth LF (mm)	✗	Worn on inner edge	1.1
Tread Depth RF (mm)	✗	Worn on inner edge	1.2
Wheel / Rim Condition	✗	Rear right wheel missing 1x lug nut. Requires replacement	1.3


Future

Job		Action	Ref
Underbody			
Diff Oil Condition & Leaks	✗	Rear right axle seal leaking.	2.1
Exhaust System	✗	Exhaust leaks present, will require exhaust specialist	2.2
Interior & Exterior			
Dash Warnings & Instruments	✗	Tyre pressure system warning on dash, aftermarket wheels fitted to vehicle	


Other

Job		Action	Ref
Road Test			
Noise & Vibrations	✓	All tyres very noisy	
Engine / Power Train Operation	✓		
Air Conditioning Temperature	✓		
Under Bonnet			
Vehicle Service History	✓		
Engine Oil	✓		
Automatic Transmission Fluid (ATF)	✓		
Power Steering Fluid	✓		
Engine Coolant	✓		
Coolant Leaks - Pressure Test	✓		
Cooling System Hoses	✓		
Drive Belts	✓		
Fuel System Service	✓		
Brake Master Cylinder	✓		


Rear Brake Discs Rotors / Drums	✓		
Rear Calipers / Wheel Cylinders	✓		
Interior & Exterior			
Park Brake Operation	✓		
Windscreen Wipers & Washers	✓		
Windscreen Glass	✓		
All Lights & Horn Tone	✓		
Steering Wheel Grip	✓		
Trim & Interior Fitting	✓		
Body, Paint & Panel	✓		
Bonnet Supports / Clips / Bushes	✓		
Other Items			
Other Items	✓	Air filter was dirty, replaced.	4.1




1.1



1.2



1.3



2.1