

**Richfield**

2890 Brecksville Road
Richfield, OH 44286
(800) 362-7490

Ashland | Canton | Cleveland | Columbus | Richfield | Zanesville

***** Customer Review *****

Date / Time: 7/23/2026 11:38:42AM
Repair Order: 100202
Customer: 600000
Branch: RCH
Invoice Total: \$6,130.73

Credit Card

Page 1 of 3

Bill To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Ship To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Customer P/O

Created By

Completion Date

SSeem

Unit Number: LJ369130

Model Year: 2020

Make/Model: Kenworth T680

Type: TRUCK

VIN: 1XKYDP9XXLJ369130

Meter: 479511 Miles

ECM Reading:15559

Task: 1 N/C Labor No Charge Service Labor Department: Service

Complaint: CHECK AND ADVISE ON CEL/SEE PREVIOUS REPAIR

Correction: found same code for the fuel rail pressure relief valve. followed troubleshooting, could not find a failure. reviewed previous repair, tech does not state he reset the valve. processed reset. will need a test drive to confirm.

Supp.	Part	Description / Ref Number		U/M	Quantity	Price	Ext Price
1000	K37-1012	PACCAR FUEL ELEMENT	Part	EA	1.00	56.33	56.33
1000	2277129PE	FILTER-FUEL	Part	CA	1.00	82.37	82.37

Task 1 Subtotals:	Parts:	\$138.70
	Labor:	\$71.70
	Task 1 Totals:	\$210.40

Task: 2 051-Diag General accessories - Diagnosis/Inspection Department: Service

Complaint: CUSTOMER STATES UNIT NEEDS A NEW 5TH WHEEL SOLENOID

Correction: 4/22/2026 11:37:20 AM 13547 13547- Looked into the 5th wheel slide issue and found nothing wrong with the cylinder, i beleive its the EOA for the 5th wheel slide thats bad.

5/22/2026 11:09:01 AM 13629 replaced eoa valves tried to program but had back offices problems

Supp.	Part	Description / Ref Number		U/M	Quantity	Price	Ext Price
1000	5602-05-020	SERVICE KIT, MSB, PTC VARIANT	Part	EA	3.00	68.11	204.33
1000	5603-01-020	KIT-BASE1, NYLON-END CAPS/ORINGS NOT INC	Part	EA	1.00	222.40	222.40
1000	AC1001C	CARTRIDGE-OIL COALESCING	Part	EA	1.00	125.46	125.46
1000	5602-07-020	SERVICE KIT, MSB, PTC VARIANT END CAP	Part	EA	1.00	63.25	63.25
1000	CT05317	Tie-Cable 50Lb 15.5" Blk	Part	CA	7.00	0.95	6.65
1000	G38-1036-0404	FITTING-90 DEG ELBOW STEM J24	Part	EA	3.00	8.50	25.50
	SUBLET	SUBLET-MISC	Misc		1.00	340.20	340.20

Task 2 Subtotals:	Parts:	\$647.59
	Labor:	\$800.00
	Miscellaneous:	\$340.20
	Task 2 Totals:	\$1,787.79

Task: 3 011-Diag Axles (front non-driven) - Diagnosis/Inspection Department: Service

Complaint: CHECK STEER AXLE KING PINS AND STEERING COMPONENTS, ALIGNMENT SHOP STATED UNIT NEEDS KING PINS

Cause: king pins are out of spec



Richfield

2890 Brecksville Road
Richfield, OH 44286
(800) 362-7490

Ashland | Canton | Cleveland | Columbus | Richfield | Zanesville

***** Customer Review *****

Date / Time: 7/23/2026 11:38:42AM
Repair Order: 100202
Customer: 600000
Branch: RCH
Invoice Total: \$6,130.73

Credit Card

Page 2 of 3

Bill To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Ship To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Customer P/O

Created By

Completion Date

SSeem

Correction: 4/25/2026 12:24:35 PM 13614 13614-put truck on stands and took both front tires off. backed off calipers and removed the pads and then the caliper. Went to driver side and removed the drag link and tie rod from spindle removed the wedges and caps for king pin and hit it out. Did the same to the passenger side.

5/21/2026 12:21:59 PM 13629 installed kit pin gave it grease found grease seals where put in backwards pulled king pin back out filed seals reinstalled installed calipers installed brakes installed drag link and tie rod installed wheels done

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Ext Price
1000	503700ETN	Kit-King Pin	Part	EA	1.00	643.91
1000	J20-6011	Draglink	Part	EA	1.00	506.99
6994	1971A	MULTI PURPOSE SOLVENT	Part	EA	2.00	7.00
7304	RE12	FREE ALL 11 OZ	Part	EA	1.00	9.95
1000	503700ETN	Kit-King Pin	Part	EA	1.00	429.05
1000	N514-1	NUT-HEX SLTD 7/8-14NF GR8	Part	CA	2.00	53.16
		PLN				
1000	10005LUC	GREASE-LITHIUM RED N TACKY	Part	CA	1.00	6.78
		14OZ CRTG				

Task 3 Subtotals:	Parts:	\$1,717.00
	Labor:	\$2,000.00
	Task 3 Totals:	\$3,717.00



Richfield

2890 Brecksville Road
Richfield, OH 44286
(800) 362-7490

Ashland | Canton | Cleveland | Columbus | Richfield | Zanesville

***** Customer Review *****

Date / Time: 7/23/2026 11:38:42AM
Repair Order: 100202
Customer: 600000
Branch: RCH
Invoice Total: \$6,130.73

Credit Card

Page 3 of 3

Bill To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Ship To: AMERICAN EAGLE COMPANY
6224 RIDGE POND RD
CENTREVILLE, VA 20121

Customer P/O

Created By

Completion Date

SSeem

Payment Method

Credit Card

Totals

Total Parts:	\$2,503.29
Total Core Chg:	\$0.00
Total Core Ret:	\$0.00
Total EHC:	\$0.00
Total Labor:	\$2,871.70
Total Miscellaneous:	\$340.20
Total Shop Supply Fee:	\$27.89
Invoice Subtotal:	\$5,743.08
Total Tax:	\$387.65
Invoiced Total:	\$6,130.73

DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

I HEREBY AUTHORIZE the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages. NOTICE: You are entitled to inspect or receive any components, parts or accessories replaced or removed by the shop.

CUSTOMER SIGNATURE _____

PLEASE PRINT NAME _____ DATE _____