

Monte,

I forgot to include the current major component hours on the Cat 5230 excavator. Please see the list below.

Caterpillar 5230

S/N 7LL23

92,826 Machine ho

Component	Current Hrs
Engine	3,659
Undercarriage	25,566
Pump Drive	6,589
Main Imp pumps	1,049
Left Final	11,386
Right Final	11,386
Revolving Frame Brg	10,760
Front Swing Trans	2,402
Left Rear Swing Trans	1,294
Right Rear Swing Trans	2,402
Front Swing Motor	2,402
Left Rear Swing Motor	1,294
Right Rear Swing Motor	2,402
Left Stick Cyl	4,070
Right Stick Cyl	4,356
Left Boom Cyl	705
Right Boom Cyl	6,515
Right bucket cyl	2,402
Left bucket cyl	744
Main Control Valve	1,280

5230 Spare parts list:

- 1 – Boom Cylinder – needs rebuilt
- 2 – Stick Cylinders – need rebuilt
- Bucket power link – needs rebuilt
- Used main control valve – used part
- 2 – swing drives (p/n 134-3675) – need rebuilt
- Drive tumbler – spare part could be used
- Upper track roller bearing – spare part
- Complete upper track roller - new
- Swing brake (p/n 110-6198) – needs rebuilt
- Rock Bucket – ready for use
- 5 – teeth for bucket - new
- 2 – Side frames - Left and Right (No Tracks) – need rebuilt
- Misc new parts in warehouse – hoses etc.

Parts needed to put into service:

- Front swing brake – p/n 110-6198
- Left side muffler – p/n 112-6590
- Hose to muffler – p/n 5P1473 (230cm)
- Hydraulic return hose – p/n 134-6361 (In SCM Stock)
- Replace D-ring seal at left side hoist cylinder hard line