

# Experian AutoCheck Report

Report run: 03/16/2026 11:18:38 EDT

## 2017 Ford F-250 Super Duty King Ranch / Lariat / Platinum / Crew Cab 4D (6.2L V8 SMT Flex Fuel)

VIN:	1FT7W2B68HEE95671
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	9 year(s)
Estimated In Service:	09/25/2017
Last Reported Odometer:	72,281 (09/10/2021)

**One Owner**  
**AutoCheck**  
**Vehicle Usage**  
 Personal



### Vehicle History at a Glance

<p><b>State Title Brand</b></p> <p><b>CLEAN</b></p>	<p><b>Auction Brand / Issues</b></p> <p><b>NO ISSUE</b></p>	<p><b>Accident / Damage</b>        No Accidents or Damage Reported</p> <p><b>NO ISSUE</b></p>
<p><b>Open Recall Check</b></p> <p><b>2 OPEN RECALL(S)</b></p>	<p><b>Insurance Loss / Transfer</b></p> <p><b>NO ISSUE</b></p>	<p><b>Odometer Check</b>        Last reported odometer:        72,281 (09/10/2021)</p> <p><b>NO ISSUE</b></p>
<p><b>Certified Pre-Owned</b></p> <p><b>NO CPO INFO AVAILABLE</b></p>	<p><b>Service / Repair</b>        4 Service Record(s) Reported</p> <p><b>NO ISSUE</b></p>	<p><b>Additional History</b>        Lien Reported</p> <p><b>EVENTS REPORTED</b></p>



**This vehicle is eligible for Buyback Protection**

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

### Accident & Damage

**Your Vehicle Checks Out** There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage

## Open Recall Check



### Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 02/17/2022

Recall Type - Safety

NHTSA / OEM Recall No. - 22v087 / 22S09

Campaign Description - Safety Recall: LOOSE/SAGGING UNDERBODY INSULATOR  
Status: Remedy Available

Recall Date - 08/30/2022

Recall Type - Safety

NHTSA / OEM Recall No. - 22V644 / 22S51

Campaign Description - Safety Recall: REAR VIEW CAMERA REPLACEMENT DUE TO A FOGGY IMAGE  
Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ford Dealer](#) to schedule repair.

## Odometer Check



### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



#### State Title Odometer Check

No issues reported



#### Auction Odometer Check

No issues reported



#### Odometer Calculation Check

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2017 Ford F-250 Super Duty King Ranch / Lariat / Platinum / XL / XLT (1FT7W2B68HEE95671) Report Run Date: 03/16/2026 11:18:38 EDT

2017

## Vehicle Prep and Other Pre-Titling Events

Preparation Date: 09/2017

Event Date	Location	Odometer	Data Source	Details
09/25/2017			Independent Source	Vehicle Manufactured and Shipped to Dealer
11/06/2017	NE	103	Motor Vehicle Dept.	Odometer Reading from DMV

2017

## Owner 1

Location: NE

Owned From: 11/2017

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
11/09/2017	NORFOLK, NE		Motor Vehicle Dept.	Title(Lien Reported)
12/08/2017	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
09/06/2018			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
09/26/2018			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
11/19/2018	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
06/21/2019	NE	30,313	Service Record	Vehicle Recall Service Performed Electrical System Serviced Lights or Signals Serviced
07/24/2019	NE	34,998	Service Record	Lights or Signals Serviced Tires or Wheels Service Performed
09/27/2019	NE	35,950	Service Record	Vehicle Inspected Vehicle Recall Service Performed Lights or Signals Serviced

Event Date	Location	Odometer	Data Source	Details
04/30/2020			Manufacturer	<p>Manufacturer Service Bulletin Mfr. Recall 20N04 Customer SAT/Owner Notification Program: STEERING LINKAGE DAMPER LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 20N04 Customer SAT/Owner Notification Program: STEERING LINKAGE DAMPER LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 20N04 Customer SAT/Owner Notification Program: STEERING LINKAGE DAMPER LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p>
11/16/2020	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
11/20/2020	NORFOLK, NE		Motor Vehicle Dept.	Title(Lien Reported)
06/30/2021			Manufacturer	<p>Manufacturer Service Bulletin Mfr. Recall 20M04 Customer Satisfaction Program - Multi Repair: POWER DOOR LOCK ACTUATOR FAILURE LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 20M04 Customer Satisfaction Program - Multi Repair: POWER DOOR LOCK ACTUATOR FAILURE LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 20M04 Customer Satisfaction Program - Multi Repair: POWER DOOR LOCK ACTUATOR FAILURE LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p>
09/10/2021	NE	72,281	Service Record	Electrical System Serviced
11/15/2021	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
02/17/2022			Manufacturer	<p>Manufacturer Recall NHTSA Recall 22v087 / Mfr. Recall 22S09 Safety Recall: LOOSE/SAGGING UNDERBODY INSULATOR LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Available</p>
08/30/2022			Manufacturer	<p>Manufacturer Recall NHTSA Recall 22V644 / Mfr. Recall 22S51 Safety Recall: REAR VIEW CAMERA REPLACEMENT DUE TO A FOGGY IMAGE LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Available</p>
11/14/2022	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal

Event Date	Location	Odometer	Data Source	Details
06/20/2023			Manufacturer	<p>Manufacturer Service Bulletin Mfr. Recall 22M03 Customer Satisfaction Program - Multi Repair: REPLACE FRONT AND OR SIDE CAMERAS IF FOGGY LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 22M03 Customer Satisfaction Program - Multi Repair: REPLACE FRONT AND OR SIDE CAMERAS IF FOGGY LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall 22M03 Customer Satisfaction Program - Multi Repair: REPLACE FRONT AND OR SIDE CAMERAS IF FOGGY LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p>
11/14/2023	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
11/15/2024	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal
11/17/2025	NORFOLK, NE		Motor Vehicle Dept.	Registration Event/Renewal

#### AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### Buyback Protection Terms and Conditions

This vehicle (1FT7W2B68HEE95671) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpterm](http://www.autocheck.com/bbpterm) or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

#### Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.