



Invoice

DATE	INV. #
3/18/2022	15673

300 NE 32ND STREET
Fort Worth, Texas 76106
(817) 624-2610
www.evansfleet.com

BILL TO:
KINGDOM TRUCKING

DATE IN	TERMS	UNIT #	MILEAGE	VIN / SERIAL #	MAKE/ENGINE	LICENSE PLATE	
3/18/2022	Due on r...	2002	1172869	9J227096	2009 KW T660		
DESCRIPTION					QTY	RATE	AMOUNT
INSTALL ALL 6 INJECTORS - PUT 6 NEW INJECTORS IN ENGINE THAT WAS SENT TO REPLACE THE ONE THAT BLEW UP FROM REVIVA					2	110.00	220.00
INJECTOR					6	997.82	5,986.92T
Subtotal							6,206.92
SHOP SUPPLIES						3.00%	186.21T
Sales Tax						8.25%	509.28
CUSTOMER SIGNATURE					PAYMENTS/CREDITS		
					\$0.00		
					TOTAL		
					\$6,902.41		

Any invoice over the amount of \$1,000.00 is subject to a 2% late payment charge every day after two weeks from date of invoice until full amount is paid. A 3% processing fee will be added to all invoices paid by credit card.

Please Note:

Warranty on labor is 30 DAYS from date on this invoice. Warranty on parts may vary. Warranty work on labor has to be performed by Precision Diesel Repair in our facility and cannot exceed the original cost of repairs.



Invoice

DATE	INV. #
3/25/2021	14055

300 NE 32ND STREET
Fort Worth, Texas 76106
(817) 624-2610
www.evansfleet.com

BILL TO:
KINGDOM TRUCKING

DATE IN	TERMS	UNIT #	MILEAGE	VIN / SERIAL #	MAKE/ENGINE	LICENSE PLATE	
10/13/2020	Due on r...	2002		227096	2008 KW WHT	R488038	
DESCRIPTION					QTY	RATE	AMOUNT
TOWED IN - REMOVE TRANSMISSION SO WE COULD REMOVED ENGINE					12	95.00	1,140.00
REMOVE RADIATOR TO REMOVED ENGINE					8	95.00	760.00
REMOVED ENGINE AND REPLACE WITH LONG BLOCK. SWAP OVER ALL PARTS NOT INCLUDED WITH LONG BLOCK					30	95.00	2,850.00
CUMMINS ISX ENGINE					1	19,937.50	19,937.50T
MOUNT-ENGINE RUBBER					2	37.16	74.32T
BOLT-HEX M 20-2.50X1					2	30.42	60.84T
WASHER-ROUND M20X37					2	3.97	7.94T
BUSHING SNUMB BAR					2	60.65	121.30T
BUSHING ENG REAR					2	110.07	220.14T
WASHER-ROUND M20X37					4	3.97	15.88T
A/C DRIER					1	40.40	40.40T
TRI HOSE 2.50" ID X					1	80.25	80.25T
TRI HOSE 2.50" ELB-R					1	103.78	103.78T
BOLT					2	17.50	35.00T
STRAP KIT WITH BOLTS					1	28.59	28.59T
NUT-HEX SL NYL M20					2	17.56	35.12T
A/B UNION 1/4					1	10.37	10.37T
BLUE HARDLINE GROMMETS					2	3.46	6.92T
WATER PIPE SEAL FOR CUMMINS ENGINE					1	4.86	4.86T
A/C COMPRESSOR					1	236.17	236.17T
V-BELT/MICRO BELT					1	32.72	32.72T
DRIVE BELT/ MICRO V BELT					1	67.20	67.20T
EXHAUST BACKPRESSURE SENSOR/EGR SENSOR					1	209.03	209.03T
SEAL O-RING					1	6.05	6.05T
SEAL GROMMET					4	5.12	20.48T
WASHER SEAL					2	4.00	8.00T
BRAKE CLEANER					7	6.43	45.01T
SHOP OIL 15W-40 (QUART)					52	4.69	243.88T
POLYFREEZE GLOBAL GOLD ANTIFREEZE (QUART)					55	3.50	192.50T
5/8 " HOSE					6	1.71	10.26T
3/4" HOSE					11	1.43	15.73T
CUSTOMER SIGNATURE					PAYMENTS/CREDITS		
					TOTAL		

Any invoice over the amount of \$1,000.00 is subject to a 2% late payment charge every day after two weeks from date of invoice until full amount is paid. A 3% processing fee will be added to all invoices paid by credit card.

Please Note:

Warranty on labor is 30 DAYS from date on this invoice. Warranty on parts may vary. Warranty work on labor has to be performed by Precision Diesel Repair in our facility and cannot exceed the original cost of repairs.



Invoice

DATE	INV. #
3/25/2021	14055

300 NE 32ND STREET
Fort Worth, Texas 76106
(817) 624-2610
www.evansfleet.com

BILL TO:
KINGDOM TRUCKING

DATE IN	TERMS	UNIT #	MILEAGE	VIN / SERIAL #	MAKE/ENGINE	LICENSE PLATE	
10/13/2020	Due on r...	2002		227096	2008 KW WHT	R488038	
DESCRIPTION					QTY	RATE	AMOUNT
1" HOSE					2	5.95	11.90T
PAG OIL					1	12.44	12.44T
D134A RE C20A FREON (PER POUND)					4	11.99	47.96T
BRASS FITTING 1/4"					1	8.27	8.27T
3/4 ' HOSE CLAMP					4	3.79	15.16T
5/8" HOSE CLAMP					4	3.97	15.88T
Subtotal							26,731.85
SHOP SUPPLIES						3.00%	801.96T
Sales Tax						8.25%	1,879.66
CUSTOMER SIGNATURE					PAYMENTS/CREDITS		
					\$0.00		
					TOTAL		
					\$29,413.47		

Any invoice over the amount of \$1,000.00 is subject to a 2% late payment charge every day after two weeks from date of invoice until full amount is paid. A 3% processing fee will be added to all invoices paid by credit card.

Please Note:

Warranty on labor is 30 DAYS from date on this invoice. Warranty on parts may vary. Warranty work on labor has to be performed by Precision Diesel Repair in our facility and cannot exceed the original cost of repairs.



Invoice

DATE	INV. #
3/18/2022	15674

300 NE 32ND STREET
Fort Worth, Texas 76106
(817) 624-2610
www.evansfleet.com

BILL TO:
KINGDOM TRUCKING

DATE IN	TERMS	UNIT #	MILEAGE	VIN / SERIAL #	MAKE/ENGINE	LICENSE PLATE	
3/18/2022	Due on r...	2002		9J227096	2009 KENWORTH		
DESCRIPTION					QTY	RATE	AMOUNT
CLAIM #70505F REMOVE OIL PAN AND GET PICS OF METAL INSIDE. ALSO TAKE SEVERAL PICS OF OUTSIDE OF MOTOR. TRUCK WAS TOWED IN FOR MOTOR LOCKED UP AND BLOCK CRACKED. INSPECTED TRUCK AND FOUND THAT ONE OF THE RODS BROKE AND CUT THE BLOCK DOWN BOTH SIDES AND ALSO CUT THE OIL PAN IN HALF. CALLED RIVIVA TO START CLAIM AND PULLED ENGINE OUT OF THE TRUCK. REPLACE ENGINE WITH ENGINE SUPPLIED BY REVIVA AND HAD TO SWAP ALL COMPONENTS OVER. HAD TO REPLACE THE STARTER, ENGINE HARNESS, FUEL PUMP AND 2 SENSORS DUE TO THEY GOT DAMAGED WHEN THE ROD BROKE. ONCE THE ENGINE WAS IN, TEST DROVE AND ALL WAS IN GOOD WORKING ORDER.					60	110.00	6,600.00
SEAL, O RING					1	13.34	13.34T
SEAL, O RING					1	17.60	17.60T
GASKET, CAMSHAFT COVER					1	11.02	11.02T
GASKET - ADAPTER					1	13.92	13.92T
SEAL, O RING					1	10.19	10.19T
GASKET-ACC DRIVE SU					1	16.95	16.95T
FUEL PUMP GASKET					1	29.27	29.27T
SEAL-RECTANGULAR STRIP					1	47.00	47.00T
GASKET-GEAR HOUSING					1	83.19	83.19T
SEAL, CROMMET					2	3.56	7.12T
O-RING SEAL					1	5.24	5.24T
SEAL-GROMMET					2	4.41	8.82T
SEALING WASHER					2	3.47	6.94T
HARNESS ETR CNT MDL WRG					1	1,311.69	1,311.69T
FUEL PUMP					1	526.96	526.96T
STEEL COOLANT LINE FROM THERMOSTAT HOUSING TO TURBO					1	111.99	111.99T
SENSOR, PRESSURE					1	111.22	111.22T
TEMPERATURE SENSOR					1	25.56	25.56T
DISCHARGE LINE					1	259.28	259.28T
FUEL FLTR					1	17.71	17.71T
BLACK RTV SILICONE GASKET MAKER					1	9.38	9.38T
ULTRA-HIGH TEMP RED RTV SILICON / GASKET MAKER					1	9.74	9.74T
CUSTOMER SIGNATURE					PAYMENTS/CREDITS		
					TOTAL		

Any invoice over the amount of \$1,000.00 is subject to a 2% late payment charge every day after two weeks from date of invoice until full amount is paid. A 3% processing fee will be added to all invoices paid by credit card.

Please Note:

Warranty on labor is 30 DAYS from date on this invoice. Warranty on parts may vary. Warranty work on labor has to be performed by Precision Diesel Repair in our facility and cannot exceed the original cost of repairs.



Invoice

DATE	INV. #
3/18/2022	15674

300 NE 32ND STREET
Fort Worth, Texas 76106
(817) 624-2610
www.evansfleet.com

BILL TO:
KINGDOM TRUCKING

DATE IN	TERMS	UNIT #	MILEAGE	VIN / SERIAL #	MAKE/ENGINE	LICENSE PLATE	
3/18/2022	Due on r...	2002		9J227096	2009 KENWORTH		
DESCRIPTION					QTY	RATE	AMOUNT
NON-CHLORINATED BRAKE CLEANER					2	7.23	14.46T
TRANS FLUID/ ATF / AUTOMATIC TRANSMISSION FLUID					2	9.79	19.58T
SPIN ON FUEL FILTER					1	23.73	23.73T
SHOP OIL 15W-40 (QUART)					46	4.99	229.54T
POLYFREEZE GLOBAL GOLD ANTIFREEZE (QUART)					44	4.07	179.08T
BRAKE CLEANER					7	7.23	50.61T
STARTER					1	332.56	332.56T
OIL FILTER FOR CUMMINS ISX					1	49.26	49.26T
LARGE HOSE CLAMP					1	7.41	7.41T
U-JOINT STRAP AND BOLT KIT					1	21.28	21.28T
FILTER-AIR KW T660					1	166.24	166.24T
HARDWARE KIT - 2 LARGE BOLTS WITH NUTS AND WASHERS AND 4 MEDIUM BOLTS WITH NUTS AND WASHERS					1	11.90	11.90T
Subtotal							10,359.78
SHOP SUPPLIES						3.00%	310.79T
Sales Tax						8.25%	335.82
CUSTOMER SIGNATURE					PAYMENTS/CREDITS		
					\$0.00		
					TOTAL		
					\$11,006.39		

Any invoice over the amount of \$1,000.00 is subject to a 2% late payment charge every day after two weeks from date of invoice until full amount is paid. A 3% processing fee will be added to all invoices paid by credit card.

Please Note:

Warranty on labor is 30 DAYS from date on this invoice. Warranty on parts may vary. Warranty work on labor has to be performed by Precision Diesel Repair in our facility and cannot exceed the original cost of repairs.