



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED]

Invoice to:

[REDACTED]
[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

YORKTON

REPRINT

Date	Time	Page
09/10/21	22:14:30 (B)	01
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No. [REDACTED]	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240		1161				

SEGMENT# 1 C 01631 N/A 08/11/21 08/11/21

Replace engine oil/filter

CORRECTION: _____

August 31/ 2021

Ran engine to warm the oil. Drain valve broke when tried to open it. Removed reinforcement panel under the engine (had to cut one of the bolts off) and then removed floor panel below the engine. Removed drain hose; unthreaded drain valve to drain the engine oil.

September 1/ 2021

Changed engine oil filter and refilled the crankcase.

Vacuumed debris from around the edges where the floor panel bolts in. Straightened floor panel, drilled holes out for the reinforcing plate so bolts would fit properly and welded bolts into place to make installing the plate easier. Secured the floor panel into place followed by bolting the second plate in.

Ran engine to fill the filter and topped up the oil level.

ADDITIONAL DESCRIPTION: _____

***** please advise Perry if anything else is required prior to this unit leaving the shop*

15W40BULK	15W40 CK4	32	4.06	129.92
5801415504	OIL FILTER	1	94.10	94.10
87105048	OIL PAN DRAIN	1	81.70	81.70
			PARTS	305.72
			LABOR	435.00
17300000	SEGMENT TOTAL==>			740.72

SEGMENT# 2 C 01631 N/A 08/11/21 08/11/21

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	02
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No.	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240		1161				
check all air filters, CLEAN OR ADVISE REPLACEMENT							
CORRECTION: _____							
August 31/ 2021							
Removed cab and recirculation filters and blew them out.							
Vacuumed out the cab filter canister, pre-cleaner box and							
and the engine air filter canister. Replaced both engine							
air filters as the secondary filter was very dirty.							
84305930			OUTER AIR 9230	1	228.16	228.16	
84305935			INNER AIR, 9230	1	255.41	255.41	
					PARTS	483.57	
					LABOR	159.50	
			17300000		SEGMENT TOTAL==>	643.07	

SEGMENT# 3 C 01631 N/A 08/11/21 08/31/21

Replace hyd filters and top off all fluids

CORRECTION: _____

August 31/ 2021

Removed and replace hydraulic and PTO filters. Ran unit to fill the filters and topped up the oil levels.

HYDFLUIDBULK	PREMIUM HYD	10	3.86	38.60
254353A1	HYD-CHARGE	1	157.00	157.00
51508555	FILTER HYDRAUL	1	132.00	132.00
84523925	FILTER HYD	1	67.92	67.92
			PARTS	395.52
			LABOR	145.00
	17300000		SEGMENT TOTAL==>	540.52

SEGMENT# 4 C 01631 N/A 08/11/21

Adjust belts & chains

COMPLAINT: _____

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature) _____ (date) _____

(signature) _____ (date) _____



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	03
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No.	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#

153971 COMBINE
8240

HRS PIN/EIN

1544 YFG230256
1161

WARRANTY DATE

HRS

Fold - - - -

loose belts and chains

CAUSE: _____

normal use

CORRECTION: _____

adjusted all belts and chains to spec

SEGMENT# 6 C 01631 NA

08/11/21 08/30/21

PAINT TABLE AUGER

CORRECTION: _____

Brought in combine

Filled and adjusted paint gun

Painted auger

Also painted auger on 9240 combine

Ser # YEG227409--2342 /1877 hrs

Cleaned paint gun after finishing

Drove combines back in line up

B17564VOC

GLOSS RED QT.

1

35.96

35.96

B17692VOC

THINNER, QUART

1

28.75

28.75

PARTS

64.71

LABOR

290.00

17300000

SEGMENT TOTAL==>

354.71

SEGMENT# 7 C 01631 NA

08/11/21 08/30/21

fix stationary Blade

CORRECTION: _____

September 1/ 2021

Removed 2 sets of stationary knives. Disassembled one that had broken and bent sections and installed new ones. Couple sections knocked out of position on the other that needed to be loosened and put back into place. Bolted the 2

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	04
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No.	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240		1161				
assemblies back into place.							
47952760			CHOPPER KNIVES	1	66.25	66.25	
					PARTS	66.25	
					LABOR	319.00	
		17300000		SEGMENT TOTAL==>		385.25	

SEGMENT# 8 C 01631 NA 08/11/21 08/30/21

replace all chopper knives

CORRECTION: _____

September 1/ 2021

Loosened and removed the chopper belts and removed all the rotating chopper knives. Installed all new knives, thread locked and torqued the retaining bolts.

47677377	KIT, CHOPPER BL	10	125.28	1252.80
			PARTS	1252.80
			LABOR	400.00
	17300000	SEGMENT TOTAL==>		1652.80

SEGMENT# 9 C 01631 NA 08/11/21 08/30/21

change incline Auger (bubble up)

CORRECTION: _____

September 2/ 2021

Unbolted support bracket at the end of the auger and hoisted the auger out of the tube. Lifted the auger down with the forklift, removed the lock collar and bearing and removed the bracket.

Cleaned output shaft splines and coated them with anti-seize. Lifted the new auger up to the hopper and lowered it into the tube. Installed the support bracket, bearing and locked it into place with the collar.

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature) _____ (date) _____

(signature) _____ (date) _____



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	05
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No. [REDACTED]	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240	1161					
87106615			AUGER BUBBLE UP	1	1266.88	1266.88	
87605590			BEARING, BUBBLE	1	66.97	66.97	
					PARTS	1333.85	
					LABOR	290.00	
		17300000			SEGMENT TOTAL==>	1623.85	

SEGMENT#10 C 01631 NA 08/11/21 08/30/21

gusset tailings processor

COMPLAINT: _____

August 31/ 2021

Top front corner of processor housing mounting plate
cracking.

CORRECTION: _____

August 31/ 2021

Loosened lines from valve block to cleaning fan motor,
removed line support clamps and bracket and pulled lines
out of the way. Buffed paint in the top, front mounting
corner of the processor housing.

Made 2 gussets and welded them into place. Cleaned and
painted the repaired area. Put lines, bracket and clamps
back into place that were previously removed.

17300000	LABOR	580.00
	SEGMENT TOTAL==>	580.00

SEGMENT#11 C 01631 NA 08/11/21 08/30/21

replace missing guides and table auger fingers

CORRECTION: _____

September 2/ 2021

Removed and replaced 16 pick-up table auger finger guides
as well as 3 bent or broken auger fingers.

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature) (date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	06
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No. [REDACTED]	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240	1161					
322357		WSHR, M6 SPRING		32	.37	11.84	
42032		M6 X 25 8.8 HCS		10	.28	2.80	
84194057		AUGER FINGER		3	47.79	143.37	
84287636		GUIDE, 3016 FIN		16	7.19	115.04	
					PARTS	273.05	
					LABOR	526.35	
	17300000			SEGMENT TOTAL==>		799.40	

SEGMENT#12 C 01631 NA 08/11/21 08/30/21

check feeder slip clutch

CORRECTION: _____

August 30/ 2021

Removed safety shield, unbolted and removed the driveline from the feeder gearbox output side. Blocked beater and checked torque - 500 lbs ft.

Found oil leak on gearbox - drain plug was finger tight.

September 2/ 2021

Reinstalled drive line and all safety shields. Topped up oil level in the gearbox.

17300000	LABOR	153.65
	SEGMENT TOTAL==>	153.65

SEGMENT#13 C 01631 NA 08/11/21 08/30/21

check shaft seal

CORRECTION: _____

August 30/ 2021

Oil leak on feeder gearbox was due to a loose drain plug.

17300000	LABOR	2.90
	SEGMENT TOTAL==>	2.90

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature) (date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	07
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No.	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240		1161				
SEGMENT#14 C 01631 NA		08/11/21	09/02/21				
REPAIR TOP SIEVE							
CORRECTION:							
September 2/ 2021							
Removed top, left sieve retaining bolts, disconnected the control linkage and pulled the sieve out. Cleaned debris from the sides and between the fingers of the sieve. Straightened all the fingers that were bent and slid the sieve back into place. Installed the retaining bolts and reconnected the control linkage.							
				LABOR		176.90	
17300000				SEGMENT TOTAL==>		176.90	

SEGMENT#15 C 01631 NA 08/11/21 09/02/21

REPAIR LEAKING SPREADER MOTOR

CORRECTION:

September 3/ 2021

Unbolted and removed the spreader paddle from the right side spreader motor. Removed shield from over top of the spreader motors and disconnected the hydraulic lines.

Unbolted and removed the motor.

Cleaned the motor body off and removed the output shaft/endcap off. Pushed the output shaft/ bearing assembly out of the housing. Polished the groove out of the shaft where the seal runs. Removed and replaced pressure and dust seals in the end cap. Pushed the shaft assembly back into the end cap and bolted it back onto the motor.

Bolted the motor back in to place and connected the hydraulic lines. Installed spreader paddle and straw shield over top of the motors.

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

INVOICE

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	08
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No. [REDACTED]	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240	1161					
47430062			KIT, SERVI	1	120.96	120.96	
					PARTS	120.96	
					LABOR	348.00	
		17300000		SEGMENT TOTAL==>		468.96	

SEGMENT#16 C 01631 NA 08/11/21 09/02/21

CHANGE ENGINE BREATHER FILTER

CORRECTION: _____

September 2/ 2021

Removed breather tube, unbolted and removed the cover.

Removed and replaced the filter, cleaned the cover,
replaced the seal and bolted the cover back into place.

Clamped the breather tube onto the cover.

504387088	GASKET, BREATHER	1	38.84	38.84
5801856860	FILTER, BREATHER	1	154.78	154.78
			PARTS	193.62
			LABOR	145.00
17300000		SEGMENT TOTAL==>		338.62

SEGMENT#17 C 01631 NA 08/11/21 09/02/21

REPLACE BOTH CHOPPER BELTS

CORRECTION: _____

September 2/ 2021

Loosened off chopper drive belts and removed the outer
belt. Removed safety shield and removed shift handle
allowing the inner belt to be removed. Also, the chopper
shift bearing was dry so pushed some grease into it with a
grease needle.

September 3/ 2021

Installed both new chopper belts and bolted the shift

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



**ROCKY
MOUNTAIN
EQUIPMENT**

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

INVOICE

Please Remit To:

Box 280, Hwy 9 South
#1 Rocky Mountain Way
Yorkton, Sask. S3N 2V7
Tel: (306) 783-8508
Fax: (306) 786-7880

Ship to:

[REDACTED] YORKTON

Invoice to:

[REDACTED]

Branch

Date	Time	Page
09/10/21	22:14:30 (B)	09
Account No.	Phone No.	Reference No.
[REDACTED]	[REDACTED]	W36165
Ship Via	Purchase Order	
	G.S.T. No. [REDACTED]	
Credit Card No.	Salesperson	
	M66	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY	DATE	HRS	Fold - - - -
153971	COMBINE	1544	YFG230256				
	8240		1161				
linkage and support bracket back into place. Tensioned the belts and installed the safety shield.							
48114650		V-BELT		1	205.20	205.20	
84540703		BELT KIT		1	234.36	234.36	
					PARTS	439.56	
					LABOR	145.00	
	17300000			SEGMENT TOTAL==>		584.56	

***** WORK ORDER TOTALS *****
 INTERNAL CUSTOMER
 PARTS 4929.61
 LABOR 4116.30
 DISPOSAL FEE 82.32
 SHOP SUPPLIES 349.88
 INTERNAL TOTAL 9478.11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature) (date)