



Hwy 21 North, Box 1810
 Maple Creek, SK S0N 1N0
 Phone: (306) 662-2233
 Fax: (306) 662-3049
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Foam Lake, SK	(306) 272-3345
Kyle, SK	(306) 375-2302	Moosomin, SK	(306) 435-3301
Leader, SK	(306) 628-3889	Preeceville, SK	(306) 547-2007
Unity, SK	(306) 228-2696	Russell, MB	(204) 773-2149
North Battleford, SK	(306) 445-4468	Wynyard, SK	(306) 554-2536
Humboldt, SK	(306) 682-2572	Kamsack, SK	(306) 542-2814
Kelvington, SK	(306) 327-4355	Swan River, MB	(204) 734-3466
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: 23113

Deliver To:

SERVICE INVOICE

[Redacted]

Bus Phone: *
 Prv Phone: *

[Redacted]

Bus Phone: [Redacted]
 Prv Phone: [Redacted]

Invoice Number: [Redacted]
Invoice Date: 04/20/2017
Location: 02
Work Order Number: [Redacted]
Payment Type: Account
 Page: 1 of 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 9560RT	45	1RW9560RCDP904052	524717	

Service Reminders:

JGEN01- Warranty

COMPLAINT:

01 FUEL LEAK ON FUEL TANK

CORRECTION:

SENDER LEAKING



INSPECTED SENDING UNIT, SAW LARGE CRACK IN HEAD OF SENDING UNIT. REMOVED AND REPLACED WITH NEW SENDING UNIT. TURNED ON TRACTOR AND CONFIRMED THAT IT WAS SENDING SIGNAL TO TRACTOR.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE301595	Fuel Sender	1.00	157.54	\$157.54	N

Miscellaneous Charges:

Labor: \$161.00 Parts: \$157.54 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$318.54

Customer PO No:
Tax Exempt No: Onfile
Advisor: [Redacted]

Labor: \$161.00
Parts: \$157.54
OL&M: \$0.00
Misc: \$0.00
GST: \$0.00
PST: \$0.00
Grand Total: \$318.54

TERMS AND CONDITIONS

Received by:

Date: