



Fired-Up Automotive Performance and Service  
 Box 691, 191 - 3rd Street NE  
 Black Diamond, AB T0L0H0  
 (403) 933-4701

Invoice

Plate AB 2006 F350  
 Description White 2006 Ford F-350 Super Duty XLT V8 6.0L  
 VIN P  
 VIN 1FTWX33P86EC43969  
 Odometer 176,520

Service

EGR Delete Kit

remove exhaust gas re-circulation valve

Labor

6 Hour

\$750.00 \*G

EGR60EX - Flopro - Ford 6.0L EGR Up Pipe

1 Unit

\$155.84 / Unit

\$155.84 G

EGR62 - Flopro - EGR62 EGR Cooler Delete

1 Unit

\$178.10 / Unit

\$178.10 G

9200RU4915 - Antifreeze - Extended Life Red

2 Litre

\$6.93 / Litre

\$13.86 G

Sub \$1,097.80

Total Parts

\$347.80

Total Labor

\$750.00

Total Before Taxes & Miscellaneous Charges

\$1,097.80

(\* ) Shop supplies include material and service items too small to itemize individually for service or repairs performed on vehicle.

7 %

\$25.00 G

(G) Canadian Goods and Services Tax (GST)

5 %

\$56.14

Grand Total

\$1,178.94

GST # 839102167RT0001

LIMITED GUARANTEE: Our work is performed in a careful workmanlike manner.  
 ANY WARRANTY WORK MUST BE PRE-APPROVED THROUGH FIRED-UP AUTOMOTIVE.

WE DO NOT assume any responsibility for vehicles, or any contents or articles left in vehicles delivered to our service centre for service, storage, or otherwise. please remove all personal contents from the vehicle.

I AGREE TO PAY 3% INTEREST PER MONTH(26.82% PER ANNUM) ON ALL UNPAID ACCOUNTS OVER 30 DAYS FROM DATE OF INVOICE.

WE DO NOT assume any responsibility for lost or misplaced hubcaps after vehicle has left the parking lot.

**IF TIRES HAVE BEEN REMOVED PLS RE-TORQUE WITHIN 100 KMS**