



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/28/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/SPRAYER4830 F Internal

COMPLAINT:
 01 GREENLIGHT SERVICE INSPECTION SPRAYER

CORRECTION:

Labor: \$1,599.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,599.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/GLOPCLEAN4830 F Internal

COMPLAINT:
 02 GREENLIGHT/RECONDITIONING CLEANING
 INCLUDES SALES WASH DISCOUNT

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	0.00	-540.00	(\$540.00)	N
SERVACCESS	SERVICE ACCESSORIES	1.00	83.52	83.52	\$83.52	N
Labor: \$1,392.00	Parts: \$0.00	OL&M: \$0.00	Misc: (\$456.48)	Sub-Total: \$935.52		

/1201684830 F Internal

COMPLAINT:
 03 WET SYSTEMS, INSPECT AND WINTERIZE

CORRECTION:

FILLED RINSE TANK WITH WATER TESTED ALL SOLUTION SYSTEM OPTIONS ON TANK, SPRAYER OUT WATER, FILLED RINSE TANK WITH 7 PAILS OF WINTERIZER AND THEN PUMPED IT OVER TO PRODUCT TANK, WINTERIZED ALL SOLUTION TANK OPTIONS AND THEN SPRAYED OR WINTERIZER. OPENED ALL TANK VALVES AND BOOM SECTION VALVES

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 3/28/2025	Location: [REDACTED]	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: [REDACTED]	Page: 2 of 13
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1201684830 F Internal

Z0010-20L	18.9L Standard SCE Winterizer(-50 Degee)	7.00	38.95	38.95	\$272.65	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50	Parts: \$272.65	OL&M: \$0.00	Misc: \$26.55	Sub-Total: \$741.70		

/1409684830 F Internal

COMPLAINT:
04 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:
UPDATED ALL SOFTWARE AND CLEARED STORED CODES.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43		

Gen5- Internal

COMPLAINT:
05 DIAGNOSE CODE ECU 002005.14 - INCORRECT CAN RECEIVED FROM SOURCE ADDRESS 5

CORRECTION:
AFTER SOFTWARE UPDATES CODE MOVED TO STORED. CYCLED KEY FEW TIMES AND CODE DID NOT COME BACK.
HOOKED UP EDL AND FIRED MACHINE UP, ECU CODE DID NOT COME BACK

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62		



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 3 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1100004830 G Internal

COMPLAINT:
 06 CLEAN BATTERY CABLES AND CONNECTIONS

CORRECTION:
 REMOVED BATTERY CABLES, SCRUBBED AND CLEANED EACH ONE, REINSTALLED BATTERY CABLES

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$0.00		OL&M: \$0.00		Misc: \$4.25
						Sub-Total: \$75.05

/1100184830 Internal

COMPLAINT:
 07 REPLACE ENGINE AIR FILTERS

CORRECTION:
 REMOVED ENGINE AIR FILTERS, WIPED OUT AIR BOX AND INSTALLED NEW AIR FILTERS, MARKED HOURS ON COVER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE181915	Secondary Air Filter	1.00	132.38	132.38	\$132.38	N
RE196945	Primary Air Filter	1.00	210.01	210.01	\$210.01	N
Labor: \$35.40		Parts: \$342.39		OL&M: \$0.00		Misc: \$2.12
						Sub-Total: \$379.91

/1401594830 F Internal

COMPLAINT:
 08 CHANGE CAB AIR FILTERS

CORRECTION:
 REMOVED AND REPLACED BOTH CAB FILTERS. MARKED HOURS ON COVER



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 4 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1401594830 F Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE199681	Activated Carbon Filter Fresh Air	1.00	544.94	544.94	\$544.94	N
RE199682	Activated Carbon Air Filter Recirculatio	1.00	276.35	276.35	\$276.35	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.72	3.72	\$3.72	N

Labor: \$61.95 Parts: \$821.29 OL&M: \$0.00 Misc: \$3.72 Sub-Total: \$886.96

/1100594830 F Internal

COMPLAINT:
 09 CLEAN BOOM, MAIN, INLET & FOAM STRAINERS, CLEAN FLOWMETER

CORRECTION:
 REMOVED AND CLEANED FLOW METER. REINSTALLED FLOW METER REMOVED SOLUTION STRAINERS, RINSED THE AND PLACED THEM IN TOOL BOX

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N

Labor: \$354.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$21.24 Sub-Total: \$375.24

/14037004830 F Internal

COMPLAINT:
 10 CHANGE HYDRO/HYDRAULIC OIL FILTERS - NO HRS MARKED

CORRECTION:
 REMOVED AND REPLACED HYDRAULIC AND HYDROSTATIC FILTERS. MARKED HOURS ON NEW FILTERS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AN203010	Hydraulic Oil Filter	3.00	117.74	117.74	\$353.22	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/28/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/14037004830 F Internal							
EF50	ENVIRO FEE	3.00	0.50	0.50	\$1.50	N	
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N	
Labor: \$177.00		Parts: \$353.22		OL&M: \$0.00		Misc: \$12.12	
						Sub-Total: \$542.34	

GEN11- Internal
 COMPLAINT:
 11 REPAIR LEAK ON REAR HYDROSTATIC PUMP ON RIGHT HAND SIDE

CORRECTION:
 CLEANED AREA ON SIDE OF REAR HYDROSTATIC PUMP, REMOVED LEAKING HOSE CLAMP CLEANED AREA AGAIN, INSTALLED NEW HOSE CLAMP, REMOVED A LEAKING FLANGE FITTING, REMOVED OLD FLAT O-RING, INSTALLED NEW O-RING AND REINSTALLED FLANGE, CLEANED AREA

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
T78313	O-Ring	1.00	7.99	7.99	\$7.99	N	
TY22539	Hose Clamp #16 (C 3/4" O 1 1/2")	1.00	2.60	2.60	\$2.60	N	
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind	
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N	
Labor: \$177.00		Parts: \$10.59		OL&M: \$0.00		Misc: \$10.62	
						Sub-Total: \$198.21	

/1200754830 F Internal
 COMPLAINT:
 12 REPLACE HYDROSTATIC PUMP DRIVE SHAFT U-JOINTS

CORRECTION:
 REMOVED SHIELDS TO ACCESS DRIVE SHAFT UNBOLTED DRIVE SHAFT FROM FLY WHEEL AND FROM HYDRAULIC PUMP. SLID DRIVE SHAFT OUT FROM SPRAYER AND PUT ON BENCH. REMOVED U-JOINTS AND INSTALLED NEW U-JOINTS WITH NEW SNAP RINGS. GREASED DRIVE SHAFT BEFORE INSTALLING. REINSTALLED DRIVE SHAFT BACK ON SPRAYER. BOLTED UP DRIVE SHAFT TO FLYWHEEL AND PUMP. REINSTALLED SHIELDS AND RAN SPRAYER CHECKED DRIVE SHAFT AND IS GOOD.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 6 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1200754830 F Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN207249	Cross And Bearing	2.00	360.57	360.57	\$721.14	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 37.17	<u>Net Price</u> 37.17	<u>Extended Price</u> \$37.17	<u>Taxed Ind</u> N
Labor: \$619.50		Parts: \$721.14		OL&M: \$0.00		Misc: \$37.17
						Sub-Total: \$1,377.81

GEN13- Internal

COMPLAINT:
 13 REPAIR LEAK ON RIGHT HAND SIDE OF HYDRAULIC PUMP

CORRECTION:
 CLEANED AREA AND FOUND A LEAKING HOSE CLAMP ON THE HYDRAULIC PUMP SUPPLY LINE, ORDERED CLAMP AND REPLACED THE LEAKING ONE WITH A NEW ONE, CLEANED AREA

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN209543	Hose Clamp	1.00	51.56	51.56	\$51.56	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 10.62	<u>Net Price</u> 10.62	<u>Extended Price</u> \$10.62	<u>Taxed Ind</u> N
Labor: \$177.00		Parts: \$51.56		OL&M: \$0.00		Misc: \$10.62
						Sub-Total: \$239.18

/1414154830 F Internal

COMPLAINT:
 14 R&R AND RECONDITION LEFT HAND STEERING CYLINDER

CORRECTION:
 REMOVED LEAKING STEERING CYLINDER FROM MACHINE, WASHED IT OFF, DISASSEMBLED AND INSPECTED CYLINDER, BORE AND ROD LOOKED GOOD, RE-SEALED COMPLETE CYLINDER AND THEN REASSEMBLED. REINSTALLED CYLINDER ON MACHINE, TIGHTENED HARDWARE AND INSTALLED NEW COTTER PINS



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/28/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 7 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1414154830 F Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7083	Cotter Pin M3.2 X 50	2.00	0.81	0.81	\$1.62	N
14H875	Castle Nut 7/8" NF	1.00	12.86	12.86	\$12.86	N
AN206314	Seal Kit	1.00	221.13	221.13	\$221.13	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N

Labor: \$708.00 Parts: \$235.61 OL&M: \$0.00 Misc: \$42.48 Sub-Total: \$986.09

GEN15- Internal

COMPLAINT:

15 REPLACE FRONT AND REAR LEFT HAND PARK BRAKE SUPPLY HOSES TO PLANETARIES

CORRECTION:

REMOVED WEATHER CRACKED HOSES FROM MACHINE, INSTALLED CAPS ON FITTINGS. RINSED HOSES AND BROUGHT THEM TO PARTS TO HAVE NEW ONES MADE, ROUTED AND INSTALLED THE FRONT AND REAR PARK BRAKE HOSES, REINSTALLED P-CLAMPS THAT WERE REMOVED AND INSTALLED ANY ZIPTIES THAT WERE CUT. TIGHTENED UP FITTINGS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7396	Flange Locking Nut M8	3.00	1.74	1.74	\$5.22	N
X1JS43-4-4	HOSE FITTING FEMALE ORF LONG	2.00	24.17	24.17	\$48.34	N
X1JS43-6-4	HOSE FITTING FEMALE ORF LONG	2.00	22.63	22.63	\$45.26	N
X797-4-RL	1/4" 6000psi Hydraulic Hose	39.00	9.66	9.66	\$376.74	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N

Labor: \$531.00 Parts: \$475.56 OL&M: \$0.00 Misc: \$31.86 Sub-Total: \$1,038.42



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 8 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1200104830 F Internal

COMPLAINT:

16 SET AXLE TREAD ADJUST SHIM GAP

CORRECTION:

WHILE THE FRONT AXLE WAS ON JACK STANDS, ADJUSTED FRONT AXLE SHIM GAP AS PER THE SERVICE MANUAL, LOWERED MACHINE AND MOVED JACK AND STANDS TO THE REAR OF THE MACHINE, ADJUSTED REAR AXLE AS PER SERVICE MANUAL.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
N317903	SCREW	1.00	17.75	17.75	\$17.75	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N
Labor: \$708.00		Parts: \$17.75	OL&M: \$0.00	Misc: \$42.48	Sub-Total: \$768.23	

/1246144830 Internal

COMPLAINT:

17 REPLACE ALL SUSPENSION SCISSOR PINS AND BUSHINGS

CORRECTION:

JACKED UP FRONT OF MACHINE AND SET IT ON JACK STANDS, DISASSEMBLED SCISSOR SUSPENSION, CLEANED PARTS IN VARSOL, POUNDED OUT OLD BUSHINGS AND INSTALLED NEW ONES, CLEANED UP OLD SHIMS, WASHERS AND NUTS, INSTALLED NEW BUSHINGS AND PINS, INSTALLED OLD SHIMS PLUS SOME NEW ONES TO FILL ANY GAPS, TIGHTENED DOWN SCISSOR SUSPENSION AND INSTALLED NEW COTTER PINS. DID THE FRONT AXLE AND THEN LOWERED MACHINE AND THEN SWITCHED TO THE BACK AXLE, FOLLOWED THE SAME STEPS ON REBUILDING THE SCISSOR SUSPENSION IN THE REAR

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7032	Cotter Pin M5 X 50	24.00	1.07	1.07	\$25.68	N
14M7181	Castle Nut M24	1.00	15.10	15.10	\$15.10	N
N209346	Chassis Suspension Shim	12.00	8.18	8.18	\$98.16	N
N302245	Suspension Tie Rod	12.00	181.30	181.30	\$2,175.60	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 9 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1246144830 Internal						
N302247	Cylindrical Alloy Bushing with Hole	48.00	31.11	31.11	\$1,493.28	N
N302269	Plain Bushing	12.00	49.29	49.29	\$591.48	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$2,124.00	Parts: \$4,399.30	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$6,619.30		

/1403164830 F Internal
 COMPLAINT:
 18 ADJUST TOE-IN TO 1/4" AS PER SPECIFICATION AFTER SUSPENSION REPAIR

 CORRECTION:
 MEASURED FRONT AXLE TOW-IN AFTER REBUILDING FRONT SUSPENSION ALL GOOD

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75	Parts: \$0.00	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$140.72		

GEN19- Internal
 COMPLAINT:
 19 REPAIR RUSTING TRIM AROUND CAB DOOR - FIRST THING SEEN COMING UP THE LADDER

 CORRECTION:
 REMOVED RUST AND LOOSE PAINT. PRIMED AREA AND REPAINTED.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$187.62		



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/28/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 10 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

GEN20- Internal

COMPLAINT:

20 REPAIR LEAKING HOSE CLAMPS ON HYDRAULIC RESERVOIR

CORRECTION:

REMOVED 3 LEAKING CLAMPS OFF OF HYDRAULIC RESERVOIR. CLEANED AREA WHERE LEAK WAS, GOT NEW CLAMPS FROM PARTS AND INSTALLED NEW CLAMPS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY22467	Hose Clamp #20 (C 13/16" O 1 3/4")	1.00	2.60	2.60	\$2.60	N
TY22539	Hose Clamp #16 (C 3/4" O 1 1/2")	2.00	2.60	2.60	\$5.20	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$7.80	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$101.61	

GEN21- Internal

COMPLAINT:

21 DIAGNOSE AND REPAIR LEAK ON STEERING MOTOR

CORRECTION:

THE BRAKE VALVE WAS LEAKING NOT THE STEERING VALVE, REMOVED BRAKE VALVE FROM BOTTOM OF CAB, CLEANED BRAKE VALVE INSPECTED VALVE AND FOUND THAT THE PISTON SEAL WAS LEAKING, REMOVED PISTON AND INSPECTED, CLEANED PISTON UP, INSTALLED NEW PISTON SEAL IN BRAKE VALVE AND THEN REINSTALLED THE PISTON, REINSTALLED THE VALVE BACK ONTO THE BOTTOM OF CAB

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AN205522	Seal Kit	1.00	73.23	73.23	\$73.23	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$73.23	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$354.66	



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 11 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/100702524830 Internal

COMPLAINT:

22 CYLINDER, OUTER BOOM FOLD - REMOVE & RECONDITION LH

CORRECTION:

REMOVED BOOM CYLINDER, DISASSEMBLED AND RESEALED CYLINDER. REINSTALLED BOOM CYLINDER ON MACHINE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AHC16983	Hydraulic Cylinder Rod Seal Kit	1.00	39.87	39.87	\$39.87	N
AHC19323	Hydraulic Cylinder Kit	1.00	183.50	183.50	\$183.50	N
AN205474	Magnet	1.00	123.43	123.43	\$123.43	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$346.80		OL&M: \$0.00		Misc: \$26.55
						Sub-Total: \$815.85

/101500604830 F Internal

COMPLAINT:

23 BOOM SOLUTION VALVE, R&R - SECOND SECTION TO RIGHT OF LEFT HAND BOOM - LEAKING

CORRECTION:

DISASSEMBLED LEAKING SIDE OF SECTIONAL CONTROL VALVE, FOUND THAT THE 2 SEALING O-RINGS WERE FLAT AND ROCK HARD, GOT 2 NEW ONES FROM PARTS, CLEANED HOUSING OF VALVE AND THEN GREASED UP NEW O-RINGS AND INSTALLED THEM, REASSEMBLED THE VALVE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
N208343	O-RING	2.00	5.95	5.95	\$11.90	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
Labor: \$221.25		Parts: \$11.90		OL&M: \$0.00		Misc: \$13.28
						Sub-Total: \$246.43



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/28/2025 Location: Work Order Number: Payment Type: Page: 12 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

GEN24- Internal

COMPLAINT:

24 REPLACE ALL NOZZLE BODY DIAPHRAGMS - DRIP DOWN UNTIL BOOM PRESSURE BLEEDS DOWN

CORRECTION:

TOOK SPRAYER OUT OF SHOP AND UNFOLDED BOOM ON PAD. REPLACE ALL NOZZLE BODY DIAPHRAGMS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
N304457	DIAPHRAGM	60.00	14.92	14.92	\$895.20	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
Labor: \$531.00		Parts: \$895.20	OL&M: \$0.00	Misc: \$31.86	Sub-Total: \$1,458.06	

/1401634830 F Internal

COMPLAINT:

25 GREASE UNIT COMPLETE INCLUDING DRIVELINE

CORRECTION:

GREASED COMPLETE UNIT

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.87	10.87	\$10.87	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/28/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 13 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 4830 SELF-PROPELLED SPRAYER		1N04830XCC0023024	1N04830XCC0023024	

/1401634830 F Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$10.87	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$292.30	

Customer PO No: [REDACTED]
Tax Exempt No: [REDACTED]
Advisor: [REDACTED]

Labor:	\$11,743.65
Parts:	\$9,046.86
OL&M:	\$0.00
Misc:	\$38.75
Grand Total:	<u>\$20,829.26</u>

*** DOCUMENT COPY ***



GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	148743			USED AG EQUIPMENT
05 40	382	1	822630			INTERNAL LABOR-AG
00 00	178	15	822630			WORK IN PROCESS PARTS -MJ
05 40	482	1	822630			COS INTERNAL LABOR-AG
05 40	544	1	822630			SUPPLIES EXPENSE
05 40	398	1	822630			PROMOTIONS-WASHING
05 30	372	2	822630			OTHER MFR PARTS-CNTR
00 00	172	5	822630			OTHER PARTS-MOOSE JAW
05 30	366	2	822630			JD PARTS-COUNTER
00 00	166	5	822630			JD PARTS-MOOSE JAW
05 30	375	3	822630			PARTS SPECIAL HANDLING
05 30	472	2	822630			OTHER MFR PARTS-CNTR
05 30	466	2	822630			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: