



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/21/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/SPRAYER4830 F Internal

COMPLAINT:
 01 GREENLIGHT SERVICE INSPECTION SPRAYER

CORRECTION:

Labor: \$1,599.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,599.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

/GLOPCLEAN4830 F Internal

COMPLAINT:
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST
 INCLUDES SALES WASH DISCOUNT

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	0.00	-540.00	(\$540.00)	N
SERVACCESS	SERVICE ACCESSORIES	1.00	72.00	72.00	\$72.00	N
Labor: \$900.00	Parts: \$0.00	OL&M: \$0.00	Misc: (\$468.00)	Sub-Total: \$432.00		

/1201684830 F Internal

COMPLAINT:
 03 WET SYSTEMS, INSPECT AND WINTERIZE

CORRECTION:
 WINTERIZED SYSTEM

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
Z0010-20L	18.9L Standard SCE Winterizer(-50 Degee)	7.00	38.95	38.95	\$272.65	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: [REDACTED]

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/21/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 2 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1201684830 F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N	
Labor: \$442.50		Parts: \$272.65		OL&M: \$0.00		Misc: \$26.55	
						Sub-Total: \$741.70	

/1409684830 F Internal
 COMPLAINT:
 04 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:
 DOWNLOADED AND UPDATED ENGINE SOFTWARE

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N	
Labor: \$265.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$15.93	
						Sub-Total: \$281.43	

/1100004830 G Internal
 COMPLAINT:
 05 CLEAN BATTERY CABLES AND CONNECTIONS AND REPLACE BATTERY BOLTS

CORRECTION:
 REMOVED CABLES FROM BATTERY, REMOVED RUSTY CORRODED BATTERY CONNECTION BOLTS. CLEANED CONNECTIONS AND INSTALLED NEW BOLTS, REINSTALLED BATTERY CONNECTIONS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
TY25908	BATTERY BOLT AND NUT	2.00	1.52	1.52	\$3.04	N	
Labor: \$70.80		Parts: \$3.04		OL&M: \$0.00		Misc: \$4.25	
						Sub-Total: \$78.09	



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 3 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1100184830 Internal
 COMPLAINT:
 06 REPLACE ENGINE AIR FILTERS

CORRECTION:
 REMOVED OLD ENGINE AIR FILTERS, CLEANED OUT AIR INTAKE WITH WINDOW CLEANER AND A RAG, INSTALLED NEW ENGINE AIR FILTERS AND MARKED HOURS ON COVER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE181915	Secondary Air Filter	1.00	132.38	132.38	\$132.38	N
RE196945	Primary Air Filter	1.00	210.01	210.01	\$210.01	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 2.12	<u>Net Price</u> 2.12	<u>Extended Price</u> \$2.12	<u>Taxed Ind</u> N
Labor: \$35.40		Parts: \$342.39		OL&M: \$0.00		Misc: \$2.12
						Sub-Total: \$379.91

/1401594830 F Internal
 COMPLAINT:
 07 CHANGE CAB AIR FILTERS

CORRECTION:
 REMOVED AND REPLACED BOTH CAB FILTERS, MARKED HOURS ON COVER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE199681	Activated Carbon Filter Fresh Air	1.00	544.94	544.94	\$544.94	N
RE199682	Activated Carbon Air Filter Recirculatio	1.00	276.35	276.35	\$276.35	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 3.72	<u>Net Price</u> 3.72	<u>Extended Price</u> \$3.72	<u>Taxed Ind</u> N
Labor: \$61.95		Parts: \$821.29		OL&M: \$0.00		Misc: \$3.72
						Sub-Total: \$886.96



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/21/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/100200504830 F Internal

COMPLAINT:

08 EXHAUST MANIFOLD GASKETS - R&R

CORRECTION:

GOT ENGINE MANIFOLD HEATED UP, REMOVED MANIFOLD HEAT SHIELD. SPRAYED ALL MANIFOLD MOUNTING BOLTS WITH PENETRATING OIL, SOAKED BOLTS 5 OR SO TIMES WHILE I WORKED ON OTHER STUFF, WORKED ALL THE MANIFOLD BOLTS, EGR BOLTS, AND TURBO BOLTS BACK AND FORTH WITH SPRAYING WITH OIL AND GOT ALL THE RETAINING BOLTS OUT WITH OUT BREAKING ANY. PLACED MANIFOLD ON BENCH AND INSPECTED FOR CRACKS ALL GOOD, REMOVED ALL RUST AND OLD GASKET MATERIAL OFF OF MOUNTING SURFACES. CLEANED SIDE OF CYLINDER HEAD OFF WITH BRAKE CLEAN AND THEN BUFFED ALL GASKET MOUNTING SURFACES ON CYLINDER HEAD, EGR, AND TURBO FLANGED, USED PENETRATING OIL AND A TAP TO CLEAN ALL THE RUSTY THREADS. CLEANED AND INSPECTED MANIFOLD SLEEVES AND REINSTALLED THEM ON THE CYLINDER HEAD, INSTALLED NEW GASKETS AND THEN LIFTED MANIFOLD INTO POSITION. INSTALLED NEW TURBO GASKET AND EGR GASKET. INSTALLED ALL NEW BOLTS AS THE OLD WERE VERY RUSTY, TORQUED ALL HARDWARE AS PER SERVICE MANUAL. REINSTALLED HEAT SHIELD.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R519484	CAP SCREW	1.00	5.22	5.22	\$5.22	N
R519486	CAP SCREW	12.00	29.96	29.96	\$359.52	N
R519487	GASKET	1.00	17.40	17.40	\$17.40	N
R519488	GASKET	6.00	22.23	22.23	\$133.38	N
R519489	GASKET	1.00	27.35	27.35	\$27.35	N
R520672	CAP SCREW	2.00	14.94	14.94	\$29.88	N
R528364	Cap Screw	3.00	12.24	12.24	\$36.72	N
R539762	Flange Nut	1.00	7.49	7.49	\$7.49	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	66.38	66.38	\$66.38	N

Labor: \$1,106.25 Parts: \$616.96 OL&M: \$0.00 Misc: \$66.38 Sub-Total: \$1,789.59

/10020130A4830 F Internal

COMPLAINT:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 5 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/10020130A4830 F Internal
 09 OIL PAN GASKET, R&R

CORRECTION:

WARMED UP ENGINE AND DRAINED ENGINE OIL, REMOVED OIL PAN, BROUGHT PAN TO WASH BAY AND WASHED IT OFF, REMOVED ALL GASKET MATERIAL OFF OF PAN AND CLEANED PAN AGAIN, REMOVED ALL GASKET MATERIAL FROM BOTTOM SIDE OF ENGINE BLOCK, BUFFED AND CLEANED BLOCK SURFACE, APPLIED 587 LOCTITE SEALANT ON AREAS AS PER THE SERVICE MANUAL. REINSTALLED OIL PAN ON MACHINE AND TORQUED HARDWARE AS PER SERVICE MANUAL REMOVED OLD ENGINE OIL FILTER AND INSTALLED NEW ONE. REFILLED ENGINE OIL, FIRED UP AND CHECKED LEVEL, ALL GOOD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ116644	Gasket	1.00	165.09	165.09	\$165.09	N
R502513	Seal - Engine Oil Filter	1.00	11.06	11.06	\$11.06	N
RE504836	Engine Oil Filter	1.00	40.37	40.37	\$40.37	N
TY26673	3.78L 15W40 PLUS 50 II	3.00	37.78	37.78	\$113.34	N
TY26679	18.9L 15W40 PLUS 50 II	1.00	170.86	170.86	\$170.86	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	4.00	0.50	0.50	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N
Labor: \$619.50	Parts: \$500.72	OL&M: \$0.00	Misc: \$42.17	Sub-Total: \$1,162.39		

GEN10- Internal

COMPLAINT:

10 REPLACE LEAKING HOSE CLAMPS ON HYDRAULIC RESERVOIR

CORRECTION:

CLEANED AREA AND LINES WHERE RESERVOIR WAS LEAKING, REMOVED OLD HOSE CLAMPS, GOT NEW ONES AND INSTALLED THEM ON LINES CLEANED AREA AGAIN



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 6 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

GEN10- Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY22467	Hose Clamp #20 (C 13/16" O 1 3/4")	1.00	2.60	2.60	\$2.60	N
TY22539	Hose Clamp #16 (C 3/4" O 1 1/2")	2.00	2.60	2.60	\$5.20	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 10.62	<u>Net Price</u> 10.62	<u>Extended Price</u> \$10.62	<u>Taxed Ind</u> N

Labor: \$177.00 Parts: \$7.80 OL&M: \$0.00 Misc: \$10.62 Sub-Total: \$195.42

/14037004830 F Internal

COMPLAINT:
 11 CHANGE HYDRO/HYDRAULIC OIL FILTERS - NOT MARKED

CORRECTION:
 REMOVED OLD HYDRAULIC FILTERS, INSTALLED NEW ONES, MARKED HOURS ON THEM

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN203010	Hydraulic Oil Filter	3.00	117.74	117.74	\$353.22	N
<u>Miscellaneous</u> EF50	<u>Description</u> ENVIRO FEE	<u>Quantity</u> 3.00	<u>List Price</u> 0.50	<u>Net Price</u> 0.50	<u>Extended Price</u> \$1.50	<u>Taxed Ind</u> N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

Labor: \$177.00 Parts: \$353.22 OL&M: \$0.00 Misc: \$12.12 Sub-Total: \$542.34

GEN12- Internal

COMPLAINT:
 12 REPLACE LEAKING HYDRAULIC LINES NEAR PRIORITY VALVE AND LOAD SENSE VALVE BLOCK

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 7 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

GEN12- Internal

REMOVED TWO LEAKING LINES FROM PRIORITY VALVES, LEAKING FROM CRIMP ON HYDRAULIC LINES. GOT PARTS TO MAKE 2 NEW ONES, I REMOVED AND REPLACED THE O-RINGS ON THE FITTINGS AND THEN ROUTED AND INSTALLED THE TWO NEW LINES, TIGHTENED FITTINGS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T77858	#12 Flat Face O-Ring	4.00	3.66	3.66	\$14.64	N
X1J943-12-12	HOSE END FEM ORF 90DEG SHORT	2.00	87.08	87.08	\$174.16	N
X1JS43-12-12	HOSE FITTING FEMALE ORF LONG	2.00	63.37	63.37	\$126.74	N
X487-12-RL	3/4" 4000psi Hydraulic Hose	6.00	25.37	25.37	\$152.22	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00	Parts: \$467.76	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$843.00		

/1200104830 F Internal

COMPLAINT:

13 SET AXLE TREAD ADJUST SHIM GAP

CORRECTION:

FRONT END WAS ON STANDS FOR SEG 14, WHILE MACHINE WAS ON STANDS I ADJUSTED THE FRONT AXLE SHIM GAP, THEN LOWERED MACHINE AND MOVED JACK STANDS TO THE REAR OF MACHINE, ADJUSTED REAR AXLE SHIM GAP AS PER MANUAL, LOWERED MACHINE DOWN AND PUT AWAY JACK AND JACK STANDS

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N
Labor: \$708.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$42.48	Sub-Total: \$750.48		

/1246144830 Internal

COMPLAINT:

14 REPLACE ALL SUSPENSION SCISSOR PINS AND BUSHINGS



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 8 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1246144830 Internal

CORRECTION:

DISASSEMBLED AND REMOVED EACH SCISSOR ASSEMBLY OFF OF EACH CORNER OF THE MACHINE, REMOVED ALL OLD BUSHING AND PINS, CLEANED PARTS AND AS MANY NUTS AND WASHERS I COULD, INSTALLED NEW BUSHINGS AND INSTALLED SHIMS WHERE THEY WERE NEEDED, ASSEMBLED EACH SCISSOR ASSEMBLY ON THE MACHINE, THE BACK RIGHT HAND SIDE WAS THE WORST, PINS WERE SEIZED AND HAD TO REMOVED BACK TIRE TO GET BETTER ACCESS, ONES SCISSOR ASSEMBLY WAS REINSTALLED I REINSTALLED THE TIRE AND TORQUED LUG NUTS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7032	Cotter Pin M5 X 50	9.00	1.07	1.07	\$9.63	N
14M7181	Castle Nut M24	3.00	15.10	15.10	\$45.30	N
N209346	Chassis Suspension Shim	8.00	8.18	8.18	\$65.44	N
N302245	Suspension Tie Rod	12.00	181.30	181.30	\$2,175.60	N
N302247	Cylindrical Alloy Bushing with Hole	48.00	31.11	31.11	\$1,493.28	N
N302269	Plain Bushing	12.00	49.29	49.29	\$591.48	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$2,124.00	Parts: \$4,380.73	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$6,600.73		

/1403164830 F Internal

COMPLAINT:

15 ADJUST TOE-IN TO 1/4" AS PER SPECIFICATION AFTER SUSPENSION REPAIRS

CORRECTION:

MEASURED FRONT AXLE TOW IN AFTER COMPLETING ALL AXLE REPAIRS AND THEY MEASURED PERFECT

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 9 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1403164830 F Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$0.00	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$140.72	

GEN16- Internal
 COMPLAINT:
 16 REPLACE SOLUTION SUPPLY HOSE TO LEFT HAND FENCE ROW NOZZLE

CORRECTION:
 REMOVED NOZZLE AND ALL ZIP TIES FROM SOLUTION HOSE, ROUTED IN NEW HOSE BESIDE THE OLD ONE, THEN
 REMOVED THE OLD ONE, REINSTALLED NEW ZIP TIES, AND REUSED CLAMPS AND FENCE ROW NOZZLE BODY

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY24411	3/8" Sprayer Hose 200PSI (Per FT)	35.00	5.11	5.11	\$178.85	N
Miscellaneous	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$178.85	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$366.47	



GEN17- Internal
 COMPLAINT:
 17 REPLACE RIGHT HAND OUTER BOOM PIVOT BOLT WITH PROPER ONE

CORRECTION:
 UNFOLDED MACHINE OUTSIDE, USED FORKLIFT TO SUPPORT OUTER BOOM, REMOVED BOLT THAT WAS TOO LONG, GOT
 BOOM ALIGNED AND INSTALLED PROPER BOLT, TIGHTENED HARDWARE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7594	Hex Lock Nut M20	1.00	9.28	9.28	\$9.28	N
19M9162	Hex Head Cap Screw M20 X 90 GR10.9	1.00	17.21	17.21	\$17.21	N
Miscellaneous						



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 10 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

GEN17- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N	
Labor:	Parts:	OL&M:	Misc:	Sub-Total:	\$177.00	\$26.49	\$0.00 \$10.62 \$214.11

GEN18- Internal
 COMPLAINT:
 18 WELD HANDRAIL ON CATWALK - BOTTOM MOUNT CRACKED

CORRECTION:
 DISCONNECTED BATTERY CABLES, REMOVED HAND RAIL FROM CATWALK TO ACCESS CRACKS BETTER, GRINDED OUT CRACKS AND FILLED THEM BACK UP WITH WELD. GRINDED DOWN WELDS AND PAINTED AREA, PUT AWAY WELDER AND REINSTALLED HAND RAIL. TIGHTENED ALL HARDWARE RECONNECTED BATTERY CABLES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7032	Cotter Pin M5 X 50	18.00	1.07	1.07	\$19.26	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor:	Parts:	OL&M:	Misc:	Sub-Total:	\$354.00	\$19.26 \$0.00 \$21.24 \$394.50

/1200754830 F Internal
 COMPLAINT:
 19 REPLACE DRIVE SHAFT U-JOINTS - VERY VISIBLY WORN, CAN FEEL VIBRATION IN FLOOR

CORRECTION:
 REMOVED DRIVE LINE SHIELDS, REMOVED DRIVE LINE FROM MACHINE, WAS STUBBORN COMING OUT, PLACED DRIVE LINE ON BENCH AND REPLACED U-JOINTS, GREASED DRIVE LINE, REINSTALLED DRIVE LINE ON MACHINE. TORQUED HARDWARE AS PER SERVICE MANUAL AND THEN REINSTALLED DRIVE LINE COVERS, TIGHTENED HARDWARE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN207249	Cross And Bearing	2.00	360.57	360.57	\$721.14	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
 Prv Phone:

[REDACTED]

Bus Phone:
 Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 11 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1200754830 F Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17			N
Labor: \$619.50	Parts: \$721.14	OL&M: \$0.00	Misc: \$37.17	Sub-Total: \$1,377.81				

/1401634830 F Internal
 COMPLAINT:
 20 GREASE UNIT COMPLETE INCLUDING DRIVELINE

CORRECTION:
 GREASED CHASSIS AND DRIVE LINE IN SHOP, MOVED MACHINE OUTSIDE AND UNFOLDED BOOMS, GREASES BOOMS AND CENTER RACK



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26575	3.78L COOL-GARD PREMIX	1.00	26.65	26.65	\$26.65	N
TY6341	SD POLYUREA GREASE	2.00	10.87	10.87	\$21.74	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF91	ENVIRO FEE	1.00	0.91	0.91	\$0.91	N





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number: [REDACTED]
 Invoice Date: 3/21/2025
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: 12 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2009 JD 4830 SELF PROPELLED S		N04830X008226	N04830X008226	

/1401634830 F Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93			N
Labor: \$265.50	Parts: \$48.39	OL&M: \$0.00	Misc: \$16.84	Sub-Total: \$330.73				

Customer PO No:
 Tax Exempt No:
 Advisor: [REDACTED]

Labor:	\$10,366.65
Parts:	\$8,760.69
OL&M:	\$0.00
Misc:	(\$19.96)
Grand Total:	\$19,107.38

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	148745	USED AG EQUIPMENT
	05	40	382	1	821287	INTERNAL LABOR-AG
	00	00	178	15	821287	WORK IN PROCESS PARTS -MJ
	05	40	482	1	821287	COS INTERNAL LABOR-AG
	05	40	544	1	821287	SUPPLIES EXPENSE
	05	40	398	1	821287	PROMOTIONS-WASHING
	05	30	372	2	821287	OTHER MFR PARTS-CNTR
	00	00	172	5	821287	OTHER PARTS-MOOSE JAW
	05	30	366	2	821287	JD PARTS-COUNTER
	00	00	166	5	821287	JD PARTS-MOOSE JAW
	05	30	375	3	821287	PARTS SPECIAL HANDLING
	05	30	472	2	821287	OTHER MFR PARTS-CNTR
	05	30	466	2	821287	JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: