



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/HEADEROPFD75 Internal

COMPLAINT:
 01 RECONDITIONING INSPECTION HEADER

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	32.94	32.94	\$32.94	N
Labor: \$549.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$32.94
						Sub-Total: \$581.94

/GLOPCLEANFD75 Internal

COMPLAINT:
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	43.20	43.20	\$43.20	N
Labor: \$720.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$43.20
						Sub-Total: \$763.20

Gen3- Internal

COMPLAINT:
 03 DIAGNOSE CENTER FEED DRAPER NOT MOVING

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 2 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

Gen3- Internal

RAN HEADER CENTER DRAPER DIDN'T MOVE, REMOVED CENTER DRAPER TENSION, TRIED REMOVING MOTOR WITHOUT REMOVING ANYTHING ELSE TO CHECK SPLINES, COULDN'T GET OUT FRAMES WERE BENT. REMOVED LOCKING COLLAR PRIED TO ONE SIDE, STILL COULDN'T GET OUT, LOCKED HEADER AND LOWERED CENTER DRAPER LOWER THAN OUTSIDE FRAME, MOTOR WAS EASY TO REMOVE FROM THERE, SPLINES ON MOTOR AND ROLLER WERE BROKE OFF, REMOVED SPLICE FROM CENTER DRAPER AND REMOVED FROM HEADER, REMOVED BEARING HARDWARE AND OUTSIDE FLANGE, CUT OUTER RACE OFF BEARING, REMOVED ROLLER FROM HEADER, INSTALLED NEW ROLLER AND BEARING AND FLANGES AND TIGHTEN HARDWARE, MARKED HYDRAULIC LINES, REMOVED HYDRAULIC LINES FROM MOTOR REPLACED MOTOR WITH NEW AND INSTALL HYDRAULIC LINES ON CORRECT FITTINGS, INSTALLED MOTOR SPLINES INTO ROLLER AND MOTOR HARDWARE AND TIGHTEN, CENTER ROLLER AND INSTALL LOCKING COLLAR AND TIGHTEN, INSTALL CENTER DRAPER, RATCHET STRAP ROLLERS TOGETHER TO SPLICE IT EASIER, SPLICE CENTER DRAPER AND TIGHTEN ALL NUTS, SET CENTER DRAPER TENSION, MADE SURE NO TOOLS OR PARTS ON HEADER, RAN AT LOW SPEED FOR A MINUTE, CENTER DRAPER TENSION GOOD, RAN HEADER AND CHECKED OVER EVERYTHING AND OPERATED LIGHTS AND EVERYTHING RAN GOOD

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AE26161	PRESSED FLANGE 3 HOLE	1.00	15.86	15.86	\$15.86	N
AFH209882	Ball Bearing	2.00	57.29	57.29	\$114.58	N
AFH210098	KNIFE NUTS (135626)	1.00	21.55	21.55	\$21.55	N
E76584	PRESSED FLANGE	1.00	26.87	26.87	\$26.87	N
FH318972	Feed Deck Strap	2.00	9.85	9.85	\$19.70	N
MCD133891	Drive Roller Rubber	1.00	1,278.71	1,278.71	\$1,278.71	N
MCD245122	MOTOR-HYD *MPM*	1.00	1,470.92	1,470.92	\$1,470.92	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	82.31	82.31	\$82.31	N

Labor: \$1,371.75 Parts: \$2,948.19 OL&M: \$0.00 Misc: \$82.31 Sub-Total: \$4,402.25

/170058FD75 Internal

COMPLAINT:
 04 REPAIR LIGHT (RH REAR TURN SIGNAL ASSEMBLY BROKEN



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 3 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/170058FD75 Internal

CORRECTION:

RECEIVED NEW LIGHT HOUSING AND SPLICED INTO OLD WIRING, HAD TO BEND MOUNT A FEW TIMES TO GET ALL BOLT HOLES ALIGNED, FOUND THAT PIVOT BOLT WAS VERY LOOSE, TIGHTENED UP

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19H1914	Hex Bolt 1/4" X 1" GR5 NC	1.00	0.99	0.99	\$0.99	N
AFH209720	Tail Lamp	1.00	146.01	146.01	\$146.01	N
MCD138150	LAMP - CLEARANCE	1.00	79.32	79.32	\$79.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$226.32		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$320.13

/170476FD75 Internal

COMPLAINT:

05 REPLACE POLY ON THE INBOARD SKID SHOES (PER SHOE) MIDDLE WHITE

CORRECTION:

REMOVED TWO KNIFE GUARDS, CARRIAGE HEADS STRIPPED, GRIND OFF AND REMOVED NUT, REMOVED POLY, REPLACED WITH NEW AND INSTALLED HARDWARE, TIGHTEN HARDWARE, INSTALL KNIFE GUARDS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03H1765	Carriage Bolt 3/8" X 3/4" GR5	2.00	1.91	1.91	\$3.82	N
14M7275	Hex Nut M12	1.00	1.74	1.74	\$1.74	N
T25018	Screw	1.00	11.73	11.73	\$11.73	N
MCD151551	POLY PAN	1.00	77.74	77.74	\$77.74	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 4 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/170476FD75 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.72	3.72	\$3.72	N
Labor: \$61.95		Parts: \$95.03	OL&M: \$0.00	Misc: \$3.72	Sub-Total: \$160.70	

/150306FD75 Internal
 COMPLAINT:
 06 REPLACE WHEEL BEARING - REAR LH

CORRECTION:
 REMOVED WHEEL AND HUB, REMOVED BEARING CAP, LOOSENED CASTLE NUT, TO REMOVE OLD RACES. INSTALLED NEW RACES AND BEARINGS IN HUB AND INSTALLED ASSEMBLY.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FH328532	Bearing Cone w/ Seal	1.00	49.78	49.78	\$49.78	N
JD8187	Bearing Cone (LM67048)	1.00	13.33	13.33	\$13.33	N
JD8271	Bearing Cup - LM29710	1.00	12.84	12.84	\$12.84	N
MCD7900	BEARING CUP 2 1/4 OD .07KG	1.00	10.51	10.51	\$10.51	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$86.46	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$274.08	

GEN7- Internal
 COMPLAINT:
 07 REPLACE LH REAR WHEEL SWING BUSHINGS

CORRECTION:
 REMOVED SWING BUSHING PINS, LOOSENED ALL BOLTS FOR MOUNTING, PRIED AND MOVED ARM OUT FROM MOUNT, REMOVED OLD BUSHINGS, CLEANED WITH EMERY CLOTH AND INSTALLED NEW BUSHINGS, REINSTALLED ARM AND TIGHTENED ALL MOUNTING BOLTS AND ARM PIN



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

GEN7- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7030	Cotter Pin M5 X 40	1.00	0.99	0.99	\$0.99	N
19M7720	Hex Head Cap Screw M16 X 80 GR10.9	1.00	10.55	10.55	\$10.55	N
34H279	Spring Pin 3/16" X 13/16"	1.00	0.92	0.92	\$0.92	N
K40015	Lock Nut 5/8"	1.00	2.62	2.62	\$2.62	N
MCD133992	BUSHING - PLASTIC	2.00	9.68	9.68	\$19.36	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$34.44		OL&M: \$0.00		Misc: \$15.93
						Sub-Total: \$315.87

/120349FD75 Internal

COMPLAINT:
 08 TIGHTEN WHEEL BEARINGS (EACH) REAR RH WHEEL

CORRECTION:
 REMOVE TIRE, REMOVE CAP AND COTTERPIN, TIGHTEN NUT TILL HAS LITTLE DRAG, INSTALL COTTER PIN, INSTALL CAP, INSTALL TIRE AND TIGHTEN, CHECK PLAY WAS GOOD

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31
						Sub-Total: \$93.81

GEN9- Internal

COMPLAINT:
 09 REPLACE FRONT WHEEL SWING BUSHINGS

CORRECTION:
 CHECKED FOR PLAY AND JUST NEEDED TO MAKE ADJUSTMENTS, ADJUSTED THE SWING ARM PROPERLY.



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 6 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

GEN9- Internal

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43		

/142678FD75 Internal

COMPLAINT:
 10 REPLACE POLY ON CENTER OF ADAPTER

CORRECTION:
 REMOVED HARDWARE FROM HOOKS, METAL PLATE BENT IN HOOKS STUCK, REMOVED ALL HARDWARE AND GOT ALL SEALS OUT AND POLY FELL OUT, BENT METAL PLATE OUT, REMOVED FROM HOOKS, INSTALLED METAL PLATE AND SEALS ON NEW POLY, LIFTED METAL PLATE ONTO HOOKS, INSTALLED HARDWARE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
E63526	NUT	1.00	2.81	2.81	\$2.81	N
MCD245675	PAN - POLYETHYLENE	1.00	287.99	287.99	\$287.99	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00	Parts: \$290.80	OL&M: \$0.00	Misc: \$10.62	Sub-Total: \$478.42		

/10171020FD75 Internal

COMPLAINT:
 11 REMOVE DRUM AND REPAIR DENTS

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/27/2024 Location: Work Order Number: Payment Type: Page: 7 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/10171020FD75 Internal

REMOVED SHIELDS, REMOVED TENSION, REMOVED 4 BOLTS FROM DRUM, TO REMOVE DRUM AND BRING INSIDE, REMOVED COVERS. HEATED DRUM AND STRAIGHTEN THREE DENTS, WRECKED A FINGER SEAL WHILE HEATING DRUM, REMOVED PIN AND PULLED UP FINGER, REMOVED HARDWARE FROM SEAL, REMOVED SEAL REPLACED WITH NEW AND TIGHTEN HARDWARE, LOWERED FINGER AND PUT PIN THROUGH. INSTALLED COVERS, INSTALLED DRUM AND HARDWARE AND TIGHTEN, INSTALLED IDLER AND TIGHTEN, INSTALLED TENSIONER AND SET CORRECT TENSION, INSTALLED DRUM SHIELDS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7205	Carriage Bolt M16 X 40	1.00	5.18	5.18	\$5.18	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	79.65	79.65	\$79.65	N
Labor: \$1,327.50		Parts: \$5.18		OL&M: \$0.00		Misc: \$79.65
						Sub-Total: \$1,412.33

/120583FD75 Internal

COMPLAINT:
 12 REPLACE FEED DECK FLOOR

CORRECTION:

REMOVED 3 SEALS, REMOVED FACE PLATE MOUNTING HARDWARE TO REMOVE FACE PLATE AND SET ASIDE. HELPED OTHER TECH REMOVING DRUM TO MAKE MORE ROOM FOR REMOVING FEED DECK, ONCE DRUM WAS REMOVED HAD TROUBLES REMOVING FEED DECK FROM BACK AS CRACK IN OLD FEED DECK CAUGHT ON SEALS AND PANELS, CUT EDGE OFF OLD FEED PLATE AS WAS TAKING TOO LONG AS RISKED CUTTING SEALS, TRIED INSTALLING FEED DECK FROM MOUNTING PLATE END. COULDN'T GET IN FROM BACK TRIED INSTALLING FROM BOTTOM, TRIED INSTALLING FROM FRONT WAS ABLE TO TWIST DECK INTO HOLDERS REMOVED 4 BOLTS FROM EACH SIDE OF CANOLA SAVER TO GET DECK INTO PLACE, INSTALLED DECK AND INSTALLED 2 MISSING DECK BOLTS, REINSTALLED CANOLA SAVER SEALS, HELPED REINSTALL DRUM TO GET TO MOUNTING FACE PLATE BACK ONTO HEADER, ONCE DRUM WAS INSTALLED, BEGAN ROUTING AND INSTALLING HYDRAULIC HOSES TO FACE PLATE, ONCE INSTALLED, INSTALLED FEED DECK USING FORKLIFT, INSTALLED MOUNTING BOLTS AND HARDWARE AND TORQUED FACE PLATE

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7375	Carriage Bolt M10 X 30	1.00	2.38	2.38	\$2.38	N
E59406	FLANGE NUT	2.00	2.04	2.04	\$4.08	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/27/2024 Location: Work Order Number: Payment Type: Page: 8 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/120583FD75 Internal

MCD220852	PAN - FEED DECK STAINLESS	1.00	743.05	743.05	\$743.05	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
Labor: \$1,062.00		Parts: \$749.51		OL&M: \$0.00		Misc: \$63.72
Sub-Total: \$1,875.23						

/120101FD75 Internal

COMPLAINT:
 13 ADJUST DRUM AUGER FINGER TIMING/HEIGHT

CORRECTION:
 ADJUSTED DRUM TIMING/HEIGHT. LIFTED HEADER UP AND FINGERS CONTACTED FEED FLOOR, RE ADJUSTED HEIGHT AGAIN, ADJUSTED ALL THE WAY UP ON BOTH SIDES.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75		Parts: \$0.00		OL&M: \$0.00		Misc: \$7.97
Sub-Total: \$140.72						

GEN14- Internal

COMPLAINT:
 14 REPLACE ORING ON TOP FITTING FOR GEARCASE DRIVE MOTOR

CORRECTION:
 REMOVED FILTER SHIELD TO GET TO FITTING, REMOVE FITTING, REMOVE O-RING, REPLACED WITH NEW AND INSTALLED WITH WHITE GREASE, TIGHTEN FITTING, INSTALLED SHIELD

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
F3171R	O-Ring	1.00	5.43	5.43	\$5.43	N
R26906	O-Ring	1.00	5.84	5.84	\$5.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 9 of 14
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

GEN14- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N		
Labor: \$44.25		Parts: \$11.27	OL&M: \$0.00	Misc: \$2.66	Sub-Total: \$58.18			

/1204657FD75 Internal
 COMPLAINT:
 15 REPLACE HYDRAULIC FILTER- TOP UP OIL

CORRECTION:
 REMOVED HYDRAULIC FILTER AND TOPPED UP ANY LOST HYDRAULIC OIL

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26675	9.46L 15W40 PLUS 50 II	1.00	89.73	89.73	\$89.73	N
MCD320360	FILTER-HYD C/W 2X SEALS	1.00	105.95	105.95	\$105.95	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80		Parts: \$195.68	OL&M: \$0.00	Misc: \$5.25	Sub-Total: \$271.73	

/KDOIL2FD75 Internal
 COMPLAINT:
 16 CHANGE OIL IN KNIFE DRIVE GEARCASES (BOTH DRIVES)

CORRECTION:
 DRAINED OIL, FILLED WITH NEW

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26812	3.78L 85W140 GL-5	2.00	51.94	51.94	\$103.88	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 10 of 14
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/KDOIL2FD75 Internal							
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00		N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62		N
Labor: \$177.00		Parts: \$103.88		OL&M: \$0.00		Misc: \$11.62	
				Sub-Total: \$292.50			

/150436FD75 Internal
 COMPLAINT:
 17 CHANGE OIL IN CHAIN GEARCASE

CORRECTION:
 DRAINED OIL, PLUGGED DRAIN OFF AND FILLED UNTIL RAN STEADY OUT OF PLUG.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31	
				Sub-Total: \$93.81			

GEN18- Internal
 COMPLAINT:
 18 REPLACE ORINGS ON BOTTOM LH FITTING FOR MULTICOUPLER

CORRECTION:
 LEAKING FROM MIDDLE FITTING, REMOVED FITTING, REMOVED O-RING REPLACED WITH NEW AND INSTALLED WITH WHITE GREASE, INSTALLED AND TIGHTEN FITTING

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R26906	O-Ring	1.00	5.84	5.84	\$5.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 11 of 14
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

GEN18- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N		
Labor: \$88.50	Parts: \$5.84	OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$99.65				

GEN19- Internal
 COMPLAINT:
 19 REPLACE LH KNIFE HEAD

CORRECTION:
 REMOVED THREE KNIFE GUARDS, REMOVED ALL NUTS FROM KNIFE HEAD, TOOK AWHILE TO GET OUT AND IN, INSTALLED NEW KNIFE HEAD, INSTALLED NUTS AND TIGHTEN, INSTALLED KNIFE GUARDS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AFH209370	Knifehead	1.00	304.50	304.50	\$304.50	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75	Parts: \$304.50	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$445.22		

/170770FD75 Internal
 COMPLAINT:
 20 REPLACE CENTER UPPER CROSS AUGER BEARINGS AND CENTER UJOINTS

CORRECTION:
 REMOVED CROSS AUGER FROM RIGHT SIDE AND PULLED OFF U-JOINT, REMOVED ONTO DRAPER, REMOVED HARDWARE FOR CENTER BEARING HOUSING AND LOWERED LEFT CROSS AUGER WITH HOUSING, REMOVED HOUSING FROM CROSS AUGER, CHANGED BEARING AND U-JOINT, INSTALLED HOUSING INTO CROSS AUGER AND LIFTED INTO BRACKET AND TIGHTEN HARDWARE, LIFTED RIGHT CROSS AUGER ONTO U-JOINT AND LIFTED AND TIGHTEN OUTSIDE HARDWARE ON BRACKET

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AFH218818	Universal Joint	1.00	332.15	332.15	\$332.15	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 12 of 14
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/170770FD75 Internal

JD9353	Ball Bearing	2.00	103.83	103.83	\$207.66	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00		Parts: \$539.81		OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$915.05

/170511FD75 Internal

COMPLAINT:
 21 CHECK HEADER LEVEL, FLOAT, AND BALANCE

CORRECTION:
 PUT HITCH ON HEADER AND REMOVED COVERS AND CHECKED HEADER FLOAT AND BALANCE, HAD TO ADJUST HEADER FLOAT, FOLLOWED PROCEDURE AND GOT IN SPEC, PUT COVERS BACK ON, PUT HITCH BACK INTO TRANSPORT POSITION

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50		Parts: \$0.00		OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$281.43

/120348FD75 Internal

COMPLAINT:
 22 CHECK AND ADJUST TIRE PRESSURES

CORRECTION:
 CHECKED TIRE PRESSURES AND FILLED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00	Misc: \$5.31	Sub-Total: \$93.81



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/27/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 13 of 14
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/140621FD75 Internal
 COMPLAINT:
 23 GREASE HEADER

CORRECTION:
 GREASED HEADER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



SOUTH COUNTRY
 E Q U I P M E N T



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 11/27/2024
 Location:
 Work Order Number:
 Payment Type:
 Page: 14 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305709-17	305709-17	

/140621FD75 Internal SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80	Parts: \$10.31	OL&M: \$0.00	Misc: \$4.25	Sub-Total: \$85.36		

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$7,667.55
Parts:	\$5,607.22
OL&M:	\$0.00
Misc:	\$462.08
Grand Total:	\$13,736.85

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147918			USED AG EQUIPMENT
05 40	382	1	802622			INTERNAL LABOR-AG
00 00	178	15	802622			WORK IN PROCESS PARTS -MJ
05 40	482	1	802622			COS INTERNAL LABOR-AG
05 40	544	1	802622			SUPPLIES EXPENSE
05 30	366	2	802622			JD PARTS-COUNTER
00 00	166	5	802622			JD PARTS-MOOSE JAW
05 30	372	2	802622			OTHER MFR PARTS-CNTR
00 00	172	5	802622			OTHER PARTS-MOOSE JAW
05 30	375	3	802622			PARTS SPECIAL HANDLING
05 30	466	2	802622			JD PARTS-COUNTER
05 30	472	2	802622			OTHER MFR PARTS-CNTR

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: