



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 1 of 12
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/HEADEROPFD75 Internal

COMPLAINT:

01 RECONDITIONING INSPECTION HEADER

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N
Labor: \$549.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$37.17
						Sub-Total: \$586.17

/GLOPCLEANFD75 Internal

COMPLAINT:

02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	36.00	36.00	\$36.00	N
Labor: \$720.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$36.00
						Sub-Total: \$756.00

Gen3- Internal

COMPLAINT:

03 REPAIR WIRING HARNESS FOR LIGHT CONNECTOR AT FRONT WHEELS FOR HITCH. REPAIR WIRING AND REPLACE HITCH CONNECTOR

CORRECTION:

REMOVED HITCH FROM HEADER. HAD TO GET A NEW PLUG CONNECTOR. BROUGHT HITCH INSIDE. GOT NEW PINS AND INSTALLED IN NEW CONNECTOR. PUT CRIMP CONNECTORS ON BROKEN WIRES ON HEADER END, HAD TO SPLICE IN SOME MORE WIRE. INSTALLED HITCH MADE SURE CONNECTORS PLUGGED IN AND ALL WIRING WAS GOOD. TAPED WIRES UP NICE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 11/28/2024 Location: [Redacted] Work Order Number: [Redacted] Payment Type: [Redacted] Page: 2 of 12
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

Gen3- Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
57M7546	Elec. Conne	4.00	2.45	2.45	\$9.80	N
57M7630	ELECTRICAL	1.00	10.57	10.57	\$10.57	N
57M7677	Elec. Connector	1.00	1.02	1.02	\$1.02	N
57M8165	ELEC. CONN	6.00	2.99	2.99	\$17.94	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N

Labor: \$619.50 Parts: \$39.33 OL&M: \$0.00 Misc: \$37.17 Sub-Total: \$696.00

Gen4- Internal

COMPLAINT:
 04 REPLACE FRONT WHEEL SWING BUSHINGS

CORRECTION:
 REPLACED THE LEFT SIDE PLASTIC BUSHING, IT WAS MISSING, RIGHT SIDE IS STILL IN AND GOOD.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FH318957	Bushing	1.00	4.78	4.78	\$4.78	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

Labor: \$265.50 Parts: \$4.78 OL&M: \$0.00 Misc: \$15.93 Sub-Total: \$286.21

/150306FD75 Internal

COMPLAINT:
 05 REPLACE WHEEL BEARINGS. BOTH FRONT

CORRECTION:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 3 of 12
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/150306FD75 Internal

REMOVED BOTH WHEELS AND BOTH HUBS. BOTH NUTS WERE LOOSE, PULLED HUBS OFF. CLEANED SHAFTS AND INSPECTED LOOKED GOOD. CLEANED HUBS AND INSPECTED WERE GOOD AS WELL. REPLACED BEARINGS AND RACES. PACKED WITH GREASE. INSTALLED HUB ON HEADER. TIGHTENED TO SPEC. INSTALLED WHEELS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
11M7030	Cotter Pin M5 X 40	2.00	0.99	0.99	\$1.98	N
FH328532	Bearing Cone w/ Seal	2.00	49.78	49.78	\$99.56	N
JD8187	Bearing Cone (LM67048)	2.00	13.33	13.33	\$26.66	N
JD8271	Bearing Cup - LM29710	2.00	12.84	12.84	\$25.68	N
MCD7900	BEARING CUP 2 1/4 OD .07KG	2.00	10.51	10.51	\$21.02	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
Labor: \$354.00	Parts: \$174.90	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$550.14		

Gen6- Internal

COMPLAINT:

06 REPLACE RH REAR TRANSPORT ARM SWING BUSHING

CORRECTION:

REMOVED ARMS TO GET AT BUSHINGS FOR BOTH TRANSPORT AXLES. BOLTS WERE WORN. BUSHINGS DIDNT LOOK BAD. INSTALLED NEW BOLTS AND LOCK NUTS ON BOTH AND NO MORE SLOP IN THEM.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
08H4705	Hex Bolt 5/8" X 7 1/2" GR8 NC	1.00	21.68	21.68	\$21.68	N
FH318895	Bushing	2.00	10.16	10.16	\$20.32	N
K40015	Lock Nut 5/8"	1.00	2.62	2.62	\$2.62	N
MCD188467	NUT-FLANGE	1.00	2.30	2.30	\$2.30	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 11/28/2024	Location: [REDACTED]	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: [REDACTED]	Page: 4 of 12
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

Gen6- Internal

MCD252305	BOLT-HEX HD FINE ASME B18.2.1	1.00	5.38	5.38	\$5.38	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
Labor: \$265.50	Parts: \$52.30	OL&M: \$0.00	Misc: \$15.93	Sub-Total: \$333.73		

GEN7- Internal

COMPLAINT:
07 REPLACE KNIFE SECTIONS (FIVE)

CORRECTION:
REMOVED BROKEN GUARDS AND REPLACED WITH NEW.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AFH215684	MACDON COARSE SECTION 9SPI	5.00	2.71	2.71	\$13.55	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
Labor: \$132.75	Parts: \$13.55	OL&M: \$0.00	Misc: \$7.97	Sub-Total: \$154.27		

GEN8- Internal

COMPLAINT:
08 REPLACE LENS- RH ORANGE SIGNAL LIGHT

CORRECTION:
REPLACED BROKEN ORANGE LENS WITH THE NEW LENS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AFH210250	Lens	1.00	18.19	18.19	\$18.19	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 5 of 12
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

GEN8- Internal									
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N			
Labor: \$44.25		Parts: \$18.19		OL&M: \$0.00		Misc: \$2.66		Sub-Total: \$65.10	

/170058FD75 Internal
 COMPLAINT:
 09 REPLACE LH TAIL LIGHT HOUSING

CORRECTION:
 TOOK OLD HOUSING OFF AND UNPLUGGED LIGHTS FROM HARNESS, INSTALLED NEW HOUSING AND PLUGGED LIGHTS IN.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N			
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31		Sub-Total: \$93.81	

/170474FD75 Internal
 COMPLAINT:
 10 REPLACE SKID SHOES UNDER CUTTERBAR (3 BLACK)

CORRECTION:
 UNBOLTED THE GUARD BOLTS AND PRIED THE POLY OFF THAN REPLACED WITH NEW.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
FH318499	WEAR PLATE (129297)	3.00	19.72	19.72	\$59.16	N			
Labor: \$79.65		Parts: \$59.16		OL&M: \$0.00		Misc: \$4.78		Sub-Total: \$143.59	

/170475FD75 Internal
 COMPLAINT:



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/28/2024 Location: Work Order Number: Payment Type: Page: 6 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/170475FD75 Internal
 11 REPLACE POLY ON THE OUTBOARD SKID SHOES (RH SIDE- WHITE)

CORRECTION:
 REMOVED WHITE POLY BY TAKING FIVE BOLTS OUT AND USING A PRY BAR TO PRY POLY OFF, PUT NEW POLY ON AND INSTALLED NEW BOLTS BUT USED OLD NUTS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03H1540	Carriage Bolt 5/16" X 3/4" GR5	4.00	1.50	1.50	\$6.00	N
FH318495	SHOE, RH (165386)	1.00	155.41	155.41	\$155.41	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.72	3.72	\$3.72	N
Labor: \$61.95		Parts: \$161.41	OL&M: \$0.00	Misc: \$3.72	Sub-Total: \$227.08	

/170770FD75 Internal
 COMPLAINT:
 12 REPLACE CENTER UPPER CROSS AUGER BEARINGS AND U-JOINT

CORRECTION:
 USED FORLIFT WITH SLINGS TO HOLD AUGER UP, UNFASTENED ALL THE BOLTS AND PULLED THE AUGERS APART. REMOVED THE HOUSING WITH THE BEARINGS AND PULLED THE U JOINT OUT, NOTICED THAT THE ONE OF THE SHAFTS WAS ROUNDED OUT. REPLACED SHAFT. TOOK HOUSING TO SHOP AND HIT THE BEARINGS OUT. INSTALLED NEW BEARING AND U JOINTS ALL TOGETHER AND HAD ANOTHER TECH HELP LIFT OTHER END OF AUGER TO PUSH U JOINT SHAFT INTO THE OTHER AUGER. BOLTED BEARING HOUSING BACK UP TO HEADER. BOLTED OTHER END OF AUGER BACK TO THE HEADER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
12H301	1/2" Lock Washer	2.00	0.97	0.97	\$1.94	N
19H1801	Hex Bolt 3/8" X 2" GR5 NC	1.00	2.86	2.86	\$2.86	N
19H1924	Hex Bolt 7/16" X 3/4" GR5 NC	2.00	1.72	1.72	\$3.44	N
AFH218818	Universal Joint	1.00	332.15	332.15	\$332.15	N



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/28/2024 Location: Work Order Number: Payment Type: Page: 7 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/170770FD75 Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
E59406	FLANGE NUT	1.00	2.04	2.04	\$2.04	N
FH318981	Shaft	1.00	138.01	138.01	\$138.01	N
JD9353	Ball Bearing	2.00	103.83	103.83	\$207.66	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 21.24	<u>Net Price</u> 21.24	<u>Extended Price</u> \$21.24	<u>Taxed Ind</u> N
Labor: \$354.00		Parts: \$688.10		OL&M: \$0.00		Misc: \$21.24
Sub-Total: \$1,063.34						

/1204657FD75 Internal
 COMPLAINT:
 13 REPLACE HYDRAULIC FILTER

CORRECTION:
 INSTALLED NEW FILTER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
MCD320360	FILTER-HYD C/W 2X SEALS	1.00	105.95	105.95	\$105.95	N
<u>Miscellaneous</u> SERVACCESS	<u>Description</u> SERVICE ACCESSORIES	<u>Quantity</u> 1.00	<u>List Price</u> 4.25	<u>Net Price</u> 4.25	<u>Extended Price</u> \$4.25	<u>Taxed Ind</u> N
Labor: \$70.80		Parts: \$105.95		OL&M: \$0.00		Misc: \$4.25
Sub-Total: \$181.00						

/KDOIL2FD75 Internal
 COMPLAINT:
 14 CHANGE OIL IN KNIFE DRIVE GEARCASES (BOTH DRIVES)

CORRECTION:
 DRAINED AND FILLED GEARCASES WITH NEW OIL

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 8 of 12
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/KDOIL2FD75 Internal		Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26812	3.78L 85W140 GL-5	2.00	51.94	51.94	\$103.88	N
<u>Miscellaneous</u>	<u>Description</u>					
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
Labor: \$177.00		Parts: \$103.88		OL&M: \$0.00		Misc: \$11.62
				Sub-Total: \$292.50		

/150436FD75 Internal
 COMPLAINT:
 15 CHANGE OIL IN CHAIN GEARCASE

CORRECTION:
 DRAINED, FILLED GEARCASE WITH NEW OIL

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
Labor: \$88.50		Parts: \$0.00		OL&M: \$0.00		Misc: \$5.31
				Sub-Total: \$93.81		

/150398FD75 Internal
 COMPLAINT:
 16 REPLACE WING FLOAT ARM NEEDLE BEARINGS

CORRECTION:





Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 11/28/2024 Location: Work Order Number: Payment Type: Page: 9 of 12
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/150398FD75 Internal

TOOK THE THREE BOLTS OFF THE WING BELL CRANK, PULLED THE BOLTS OUT. REMOVED THE WING BELL. NOTICED THE BRACKET THAT HOLDS THE WING BELL WAS SEVERELY BENT. USED THE TORCH TO HEAT IT UP AND A CRESCENT WRENCH TO BEND IT STRAIGHT.

HAD THE WING BELL IN THE VICE AND USED A PUNCH TO GET THE BEARING AND SEALS OUT. DID THIS FOR BOTH BEARINGS. USED A SOCKET THE SAME SIZE AS THE BEARING AND HIT IT IN WITH A HAMMER. USED THE RIGHT SIZE SEAL PRESSER TO PUSH THE SEALS IN, GREASED BEARINGS TO MAKE SURE THEY WERE LINED UP WITH GREASE ZERK. GOT ALL NEW HARDWARE FOR THE BOLTS THAT WERE WORE.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19H1732	Hex Bolt 3/8" X 1 1/4" GR5 NC	2.00	1.77	1.77	\$3.54	N
19H1782	Hex Bolt 3/4" X 2 1/4" GR5 NC	1.00	8.09	8.09	\$8.09	N
19H3170	Hex Bolt 5/8" X 4 1/2" GR8 NC	2.00	16.19	16.19	\$32.38	N
AFH209220	Seal Kit	4.00	18.25	18.25	\$73.00	N
MCD304307	BEARING-GAGE ROLL NEEDLE 38MM	4.00	21.22	21.22	\$84.88	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N
Labor: \$708.00		Parts: \$201.89	OL&M: \$0.00	Misc: \$42.48	Sub-Total: \$952.37	

/1203440AFD75 Internal

COMPLAINT:
 17 REPLACE CENTER DRAPER

CORRECTION:
 LET TENSION OFF DRAPER, UNBOLTED THE SPLICES, PULLED THE DRAPER OUT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
MCD304454	DRAPER-1988 (78.3in.) WX1712 LG	1.00	1,128.31	1,128.31	\$1,128.31	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 10 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/1203440AFD75 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
Labor: \$442.50		Parts: \$1,128.31	OL&M: \$0.00	Misc: \$26.55	Sub-Total: \$1,597.36	

/120583FD75 Internal
 COMPLAINT:
 18 REPLACE FEED DECK FLOOR- ADJUST DRUM HEIGHT

CORRECTION:
 TOOK ALL THE BOLTS OUT FOR THE FACE PLATE AND USED FORK LIFT TO SET IT ON THE GROUND. TOOK BOLTS AND NUTS OFF THE SEAL ON THE SIDES, REMOVED SEALS. TOOK TWO CARRIAGE BOLTS OFF THAT HELD FLOOR ON. USED PRY BAR TO GET FLOOR OUT(TOOK IT OUT THROUGH FRONT). INSTALLED NEW FLOOR, PUT IN TWO CARRIAGE BOLTS, PUT IN THE SIX BOLTS THAT HOLD THE SEALS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY22462	Hose Clamp #4 (C 1/4" O 5/8")	1.00	2.12	2.12	\$2.12	N
MCD220852	PAN - FEED DECK STAINLESS	1.00	743.05	743.05	\$743.05	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	63.72	63.72	\$63.72	N
Labor: \$1,062.00		Parts: \$745.17	OL&M: \$0.00	Misc: \$63.72	Sub-Total: \$1,870.89	

/120486FD75 Internal
 COMPLAINT:
 19 SET FLOAT ON WINGS

CORRECTION:
 ADJUSTED HEADER FLOAT AND BALANCE. RIGHT SIDE OF HEADER HANGS DOWN A LITTLE LOWER. ADJUSTED BEST AS POSSIBLE.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 11/28/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 11 of 12
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/120486FD75 Internal					
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24 N
Labor: \$354.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$21.24	Sub-Total: \$375.24

/140621FD75 Internal
 COMPLAINT:
 20 GREASE HEADER

CORRECTION:
 GREASED HEADER



SOUTH COUNTRY
 E Q U I P M E N T

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337
 Highway 39 N.
 Weyburn, SK, S4H 2K1
 Phone: 306-842-4686
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 11/28/2024
 Location:
 Work Order Number:
 Payment Type:
 Page: 12 of 12

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
MACDON 2017 MACDON FD75-45FT FLEX DRAPER		305710-17	305710-17	

/140621FD75 Internal SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N
Labor: \$70.80	Parts: \$0.00	OL&M: \$0.00	Misc: \$4.25	Sub-Total: \$75.05		

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$6,508.20
Parts:	\$3,496.92
OL&M:	\$0.00
Misc:	\$388.54
Grand Total:	\$10,393.66

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	147919			USED AG EQUIPMENT
05 40	382	1	802813			INTERNAL LABOR-AG
00 00	178	15	802813			WORK IN PROCESS PARTS -MJ
05 40	482	1	802813			COS INTERNAL LABOR-AG
05 40	544	1	802813			SUPPLIES EXPENSE
05 30	366	2	802813			JD PARTS-COUNTER
00 00	166	5	802813			JD PARTS-MOOSE JAW
05 30	372	2	802813			OTHER MFR PARTS-CNTR
00 00	172	5	802813			OTHER PARTS-MOOSE JAW
05 30	375	3	802813			PARTS SPECIAL HANDLING
05 30	466	2	802813			JD PARTS-COUNTER
05 30	472	2	802813			OTHER MFR PARTS-CNTR

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: