



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 1 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/SPRAYERR4045 F Internal**  
 COMPLAINT:  
 01 GREENLIGHT SERVICE INSPECTION SPRAYER

CORRECTION:

<b>Labor:</b> \$1,599.00	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$0.00	<b>Sub-Total:</b> \$1,599.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

**/GLOPCLEANR4045 F Internal**  
 COMPLAINT:  
 02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	0.00	-540.00	(\$540.00)	N
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N

<b>Labor:</b> \$4,093.16	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> (\$444.00)	<b>Sub-Total:</b> \$3,649.16
--------------------------	----------------------	-------------------------	-------------------------	------------------------------

**/10150110R4045 F Internal**  
 COMPLAINT:  
 03 SPRAY SYSTEM FLUSH

CORRECTION:

FILLED RINSE TANK, DID 3 HIGH FLOW SOLUTION SYSTEM RINSE CYCLES ADDING IN ERASE SPRAYER CLEANER IN ON THE SECOND RINSE. FILLED RINSE TANK 1 MORE TIME AND DID ANOTHER 3 RINSE CYCLES ADDING IN 2 OUNCES OF DE-FOAMING AGENT TO SPRAYER ON THE SECOND RINSE CYCLE, AFTER ALL RINSE CYCLES I PARKED MACHINE IN SHOP

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 12/23/2024 Location: Work Order Number: Payment Type:  Page: 2 of 18
--------------------------	--------------------------	-----------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	

**/10150110R4045 F Internal**

PM739QT	GUNDOWN ELITE DEFOAMER	1.00	36.29	35.52	\$35.52	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
<b>Labor: \$442.50</b>		<b>Parts: \$35.52</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$26.55</b>
				<b>Sub-Total: \$504.57</b>		

**/120168R4045 F Internal**  
 COMPLAINT:  
 04 WET SYSTEMS, INSPECT AND WINTERIZE

CORRECTION:  
 Add John Deere Winterizer Fluid along with  
 Run sprayer wet system until winterization fluid is running  
 NOTE: Sprayer wet system must be completely cleaned and flushed  
 IF SPRAYER HAS BOTH CARBON FIBRE AND EXACTAPPLY OPTIONS, AT END OF WINTERIZATION PROCESS ENSURE  
 NOZZLE POSITIONS A AND B ARE COVERED BY NOZZLE OR A CAP FOR ALL BODIES THAT FACE UPRIGHT IN  
 TRANSPORT/STORAGE POSITION. NEVER LEAVE BODY POSITION A AND B OPEN TO ELEMENTS FOR A SPRAYER THAT  
 HAS BOTH OF THESE OPTIONS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
Z0010-20L	18.9L Standard SCE Winterizer(-50 Degee)	5.00	38.95	38.95	\$194.75	N
Z0015-20L	18.9L Premium Winterizer PWM(-50 Degree)	4.00	56.95	56.95	\$227.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	26.55	26.55	\$26.55	N
<b>Labor: \$442.50</b>		<b>Parts: \$422.55</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$26.55</b>
				<b>Sub-Total: \$891.60</b>		

**/110302R4045 F Internal**  
 COMPLAINT:  
 05 REMOVE CB RADIO AND CUSTOMER TOOLS

CORRECTION:



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 3 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/110302R4045 F Internal**  
 BOXED UP ALL TOOLS AND PARTS FROM TOOL BOX. REMOVED CB RADIO AND ANTENNA EXTENSION AND PLACED THEM IN A BOX, LABELED BOXES [REDACTED]

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$187.62</b>	

**/120169R4045 F Internal**  
 COMPLAINT:  
 06 CHANGE ENGINE OIL AND FILTER

CORRECTION:  
 DRAINED ENGINE OIL AND REMOVED OLD FILTER FROM HOUSING INSTALLED NEW FILTER INSTALLED OIL DRAIN PLUG FILLED WITH ENGINE OIL MARKED HOURS ON THE FILTER HOUSING

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE509672	Engine Oil Filter Cartridge	1.00	46.42	46.42	\$46.42	N
TY26674	946ML 15W40 PLUS 50 II	3.00	9.92	9.92	\$29.76	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	89.73	89.73	\$89.73	N
TY26679	18.9L 15W40 PLUS 50 II	1.00	170.86	170.86	\$170.86	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF15	ENVIRO FEE	3.00	0.15	0.15	\$0.45	N
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
<b>Labor: \$132.75</b>		<b>Parts: \$336.77</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$12.92</b>	<b>Sub-Total: \$482.44</b>	



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 12/23/2024 Location: Work Order Number: Payment Type:  Page: 4 of 18
--------------------------	--------------------------	-----------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	

**/140968AR4045 F Internal**

COMPLAINT:  
 07 UPDATE ALL MACHINE CONTROLLERS SOFTWARE. WITH EXACT APPLY.

CORRECTION:  
 UPDATED CONTROLLERS

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	37.17	37.17	\$37.17	N
<b>Labor: \$619.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$37.17</b>	<b>Sub-Total: \$656.67</b>		

**/110018R4045 F Internal**

COMPLAINT:  
 08 REPLACE ENGINE AIR FILTERS

CORRECTION:  
 REPLACED FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN403918	Primary Air Filter	1.00	292.84	292.84	\$292.84	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>	<b>Parts: \$292.84</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$386.65</b>		

**/10020020R4045 F Internal**

COMPLAINT:  
 11 R&R FAN BELT AND BOTH IDLERS  
 \*\*CHECK IF CAN REPLACE BEARINGS IN IDLERS BEFORE CHANGING THEM

CORRECTION:



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 5 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/10020020R4045 F Internal**

REPLACED THE TWO BEARINGS IN THE LEFT HAND SIDE IDLER. THE RIGHT HAND IDLER IS A ONE PIECE UNIT SO BEARINGS COULD NOT BE REPLACED INSTALLED NEW FAN BELT AND TENSIONED PROPERLY

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AL201362	Idler	1.00	183.65	183.65	\$183.65	N
JD29980	Ball Bearing	2.00	8.60	8.60	\$17.20	N
N408570	V-Belt	1.00	138.45	138.45	\$138.45	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	19.65	19.65	\$19.65	N
<b>Labor: \$327.45</b>		<b>Parts: \$339.30</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$19.65</b>
<b>Sub-Total: \$686.40</b>						

**/150519R4045 Internal**

COMPLAINT:  
 12 REPLACE OVERFLOW COOLANT TANK

CORRECTION:  
 UNHOOKED HINGES ON THE HOOD AND HOLD IT FORWARDS, TOOK OFF OLD COOLANT TANK. INSTALLED WITH NEW COOLANT TANK . PUT HOOD BACK TOGETHER.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
F2863R	SNAP RING	1.00	3.69	3.69	\$3.69	N
R555082	Guide	1.00	32.15	32.15	\$32.15	N
RE558224	Radiator Reservoir	1.00	339.01	339.01	\$339.01	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
<b>Labor: \$265.50</b>		<b>Parts: \$374.85</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$15.93</b>
<b>Sub-Total: \$656.28</b>						



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 6 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/10030110R4045 F Internal**

**COMPLAINT:**

13 FUEL FILTER - R&R

**CORRECTION:**

REMOVED AND DRAINED OLD FUEL FILTERS REMOVED WATER SEPARATOR BOWL INSTALLED NEW FUEL FILTER AND WATER SEP FILTER INSTALLED WATER BOWL ON PLUGGED IN SENSOR AND MARKED HOURS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	224.06	224.06	\$224.06	N
DZ130550	Primary Engine Fuel Filter	1.00	220.54	220.54	\$220.54	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	6.69	6.69	\$6.69	N
<b>Labor: \$111.51</b>		<b>Parts: \$444.60</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.69</b>	<b>Sub-Total: \$564.80</b>	

**/110078R4045 Internal**

**COMPLAINT:**

14 REPLACE FUEL TANK BREATHERS (TANK HAS STARTED TO COLLAPSE)

**CORRECTION:**

REMOVED THE GREEN COVER FROM OVER THE AIR BOX AND SET ASIDE LOOSENED OFF P-CLAMP HOLDING THE FUEL TANK BREATHER AND REMOVED BREATHER INSTALLED NEW BREATHER AND TIGHTENED UP P-CLAMP INSTALLED THE GREEN COVER BACK OVER THE AIR BOX AND TIGHTENED HARD WEAR.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H216169	Fuel Tank Vent Filter	1.00	44.63	44.63	\$44.63	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 7 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

<b>/110078R4045 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.72	3.72	\$3.72	N
<b>Labor: \$61.95</b>		<b>Parts: \$44.63</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.72</b>	<b>Sub-Total: \$110.30</b>	

**/120195R4045 Internal**  
 COMPLAINT:  
 15 CLEAN BATTERY POSTS AND CABLES, CLEAN BATTERY BOX

CORRECTION:  
 BLEW BATTERIES WITH A BLOW GUN OFF TO GET THE BIG DEBRIS OFF. UNIDID THE BATTERY POSTS AND PULLED CLAMPS OFF. REMOVED BATTERIES. SCRAPE OFF ALL THE DIRT AND BLEW OUT THE BATTERY BOX WITH AN AIR GUN. CLEANED BATTERY POSTS AND CLAMPS WITH A POST CLEANER. PUT BATTERIES BACK IN THE BOX AND HOOKED CLAMPS BACK UP.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.28	13.28	\$13.28	N
<b>Labor: \$221.25</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$13.28</b>	<b>Sub-Total: \$234.53</b>	



**/140160R4045 Internal**  
 COMPLAINT:  
 16 CHANGE ALL HYDRO/HYDRAULIC FILTERS

CORRECTION:  
 REPLACED ALL THREE HYDRAULIC FILTERS MARKED HOURS ON THE FILTERS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AN203010	Hydraulic Oil Filter	2.00	111.70	111.70	\$223.40	N
AT318160	Hydraulic Oil Filter	1.00	228.75	228.75	\$228.75	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 8 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/140160R4045 Internal**

EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N			
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N			
<b>Labor: \$88.50</b>		<b>Parts: \$452.15</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$7.31</b>		<b>Sub-Total: \$547.96</b>	

**/120457R4045 Internal**  
 COMPLAINT:  
 17 REPLACE HYDRAULIC OIL SIGHT GLASS

CORRECTION:  
 REMOVED GREEN HYD TANK SHIELD LOOSENED OFF THE BOLTS AND REMOVED OLD SIGHT GLASS. INSTALLED NEW SIGHT GLASS AND TIGHTENED BOLTS SNUG SO THAT SIGHT GLASS WOULD NOT LEAK INSTALLED GREEN PLASTIC COVER AND TIGHTENED HARDWARE DOWN.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
AKK16934	Sight Level Gauge	1.00	410.00	410.00	\$410.00	N			
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>			
SERVACCESS	SERVICE ACCESSORIES	1.00	6.90	6.90	\$6.90	N			
<b>Labor: \$115.05</b>		<b>Parts: \$410.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$6.90</b>		<b>Sub-Total: \$531.95</b>	

**GEN18- Internal**  
 COMPLAINT:  
 18 REPLACE ORINGS ON AUTO TRAC VALVE- LEAKING

CORRECTION:  
 HOSE ON TOP OF THE VALVE BLOCK WAS LOOSE. TIGHTENED HOSE AND WILL RUN SPRAYER TO MAKE SURE THAT THE LEAK HAS STOPPED

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 9 of 18
--------------------------	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

<b>GEN18- Internal</b>								
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N		
<b>Labor: \$177.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$10.62</b>	<b>Sub-Total: \$187.62</b>				

**/142796R4045 Internal**  
 COMPLAINT:  
 19 REPLACE FRONT AMBER LIGHTS, BOTH LENSES CRACKED OUT

CORRECTION:  
 REPLACED AMBER LENSES



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK20234	Turn Signal Lamp	2.00	221.60	221.60	\$443.20	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N
<b>Labor: \$88.50</b>	<b>Parts: \$443.20</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$537.01</b>		

**/141600R4045 Internal**  
 COMPLAINT:  
 20 REPLACE MIRROR - FRONT LOWER MIRROR BROKEN

CORRECTION:  
 REMOVED BROKEN MIRROR AND REPLACED WITH A NEW ONE.



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AT157226	REAR VIEW M	1.00	230.64	230.64	\$230.64	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 10 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

<b>/141600R4045 Internal</b>							
SERVACCESS	SERVICE ACCESSORIES	1.00	2.66	2.66	\$2.66	N	
<b>Labor: \$44.25</b>		<b>Parts: \$230.64</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$2.66</b>	
					<b>Sub-Total: \$277.55</b>		

**/120076R4045 Internal**  
 COMPLAINT:  
 21 REPLACE SOLUTION TANK SIGHT TUBE

CORRECTION:  
 REMOVED HOSE CLAMPS FROM SIGHT TUBE AND ELBOW FITTINGS REMOVED SIGHT TUBE AND INSTALLED NEW SIGHT TUBE TIGHTENED HOSE CLAMPS ON SIGHT TUBE AND ELBOWS

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
PMK010-1216	3/4" Clear PVC Bulk Hose (Per FT)	5.00	3.47	3.47	\$17.35	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
<b>Labor: \$88.50</b>		<b>Parts: \$17.35</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.31</b>	
					<b>Sub-Total: \$111.16</b>		

**/120076SR4045 F Internal**  
 COMPLAINT:  
 22 REPLACE RINSE TANK SIGHT TUBE

CORRECTION:  
 REMOVED HOSE CLAMP FROM THE TOP AND PULLED OUT ELBOW, REMOVED CLOUDED SIGHT GLASS AND INSTALLED NEW ONE. INSTALLED ELBOWS ON BOTH ENDS OF THE NEW SIGHT GLASS AND TIGHTENED HOSE CLAMPS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
PMK010-1216	3/4" Clear PVC Bulk Hose (Per FT)	3.00	3.47	3.47	\$10.41	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 11 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

<b>/120076SR4045 F Internal</b>							
SERVACCESS	SERVICE ACCESSORIES	1.00	4.25	4.25	\$4.25	N	
<b>Labor: \$70.80</b>		<b>Parts: \$10.41</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$4.25</b>	<b>Sub-Total: \$85.46</b>		

**/110059R4045 F Internal**  
 COMPLAINT:  
 23 CLEAN BOOM, MAIN, INLET & FOAM STRAINERS, CLEAN FLOWMETER

CORRECTION:  
 WASHED OUT STRAINERS AND STRAINER HOUSINGS. CHECKED THE FLOW METERS BOTH SPUN WITH OUT ISSUE  
 CLEANED OUT THE FLOW METER HOUSINGS AND REINSTALLED THE FLOW METERS. TIGHTENED THE FLOW METERS  
 INTO PLACE.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
<b>Labor: \$354.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$21.24</b>	<b>Sub-Total: \$375.24</b>	

**/110651R4045 F Internal**  
 COMPLAINT:  
 24 TIGHTEN HOSE CLAMPS LEAKING ON PRODUCT TANK

CORRECTION:  
 TIGHTENED HOSE CLAMP

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.19	3.19	\$3.19	N
<b>Labor: \$53.10</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.19</b>	<b>Sub-Total: \$56.29</b>	

**/120010R4045 F Internal**  
 COMPLAINT:



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 12 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/120010R4045 F Internal**  
 25 SET AXLE TREAD ADJUST SHIM GAP

**CORRECTION:**

LOOSENED OFF THE DOG POINT CAP SCREWS AND REMOVED THEM STARTING WITH THE LEFT REAR AXLE ON THE SPRAYER. COATED THEM IN ANTI SIEZE AND REINSTALLED TORQUED TO 100 FT-LB THEN TIGHTENED THE JAM NUT TO 350 FT-LB. REPEATED THESE STEPS ON THE OTHER THREE CORNERS FOLLOWING THE MANUAL

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
KK10593	Screw	1.00	36.89	36.89	\$36.89	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	42.48	42.48	\$42.48	N
<b>Labor: \$708.00</b>		<b>Parts: \$36.89</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$42.48</b>	<b>Sub-Total: \$787.37</b>	

**/140161R4045 F Internal**

COMPLAINT:  
 26 CHANGE PLANETARY HUB OILS ( 250HR SERVICE )

**CORRECTION:**

CHANGED HUB OILS



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26372	946ML 80W140 GL-5 SYNTHETIC	12.00	47.83	47.83	\$573.96	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	12.00	1.00	1.00	\$12.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	21.24	21.24	\$21.24	N
<b>Labor: \$354.00</b>		<b>Parts: \$573.96</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$33.24</b>	<b>Sub-Total: \$961.20</b>	

**/1503912R4045 Internal**

COMPLAINT:



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 13 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/1503912R4045 Internal**  
 27 REPLACE WHEEL MOTOR HOSES- FRONT LEFT SIDE

\*\*ONLY REPLACE 1 HOSE THAT IS LEAKING AT CRIMP

**CORRECTION:**  
 REMOVED HOSE FROM FRONT LEFT MOTOR BY UNDOING ALL THE CLAMPS AND UNDOING THE FLAT FACE COUPLER. UNDOED THE FAT FACE COUPLER AT THE TOP AND BROUGHT THE HOSE TO PARTS. GOT NEW HOSE AND HOOKED UP THE COUPLER ON ONE END AND WORKED ITS WAY UP PUTTING ON THE HOSE CLAMPS AS IT BENDS AROUND. HOOKED UP TOP COUPLER AND MADE SURE ALL THE CLAMPS WERE SITTING RIGHT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK33874	Hydraulic Hose	1.00	875.47	875.47	\$875.47	N
T59014	O-RING	1.00	8.22	8.22	\$8.22	N
T78313	O-Ring	1.00	7.58	7.58	\$7.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N
<b>Labor: \$531.00</b>		<b>Parts: \$891.27</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$31.86</b>
						<b>Sub-Total: \$1,454.13</b>

**/1503911R4045 Internal**  
 COMPLAINT:  
 28 REPLACE WHEEL MOTOR HOSES- FRONT RIGHT SIDE

\*\*ONLY REPLACE ONE HOSE THAT IS LEAKING AT CRIMP

**CORRECTION:**  
 REMOVED OLD HOSE FROM THE FRONT RIGHT WHEEL MOTOR AND REMOVED FROM BRACKETS WENT AND GOT A NEW HOSE AND CONNECTED IT TO THE WHEEL MOTOR THEN THREADED IT UP THROUGH EACH HOSE BRACKET CONNECTED STRAIGHT FLAT FACE FITTING TO THE SPRAYER TIGHTENED ALL THE HOSE CLAMPS BACK DOWN .

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK33874	Hydraulic Hose	1.00	875.47	875.47	\$875.47	N



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 14 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

<b>/1503911R4045 Internal</b>							
T59014	O-RING	1.00	8.22	8.22	\$8.22	N	
T78313	O-Ring	1.00	7.58	7.58	\$7.58	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	31.86	31.86	\$31.86	N	
<b>Labor: \$531.00</b>	<b>Parts: \$891.27</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$31.86</b>	<b>Sub-Total: \$1,454.13</b>			

**/121073R4045 Internal**  
 COMPLAINT:  
 31 REPLACE DRIVESHAFT U JOINTS -

CORRECTION:  
 REMOVED BELLY SHIELDS SO [REDACTED] COULD LOOK AT THE U-JOINTS ON THE DRIVE SHAFT. REMOVED DRIVE SHAFT CAGE AND UNIDID PLASTIC SHIELD REMOVED FLY WHEEL BOLTS AND REAR DRIVE SHAFT BOLTS. SPLIT DRIVE SHAFT AND REMOVED THE BACK HALF, PULLED OUT PLASTIC SHIELD AND REMOVED THE FRONT HALF OF THE DRIVE SHAFT. ONCE DRIVE SHAFT WAS OUT REMOVED SNAP RINGS FROM THE REAR HALF OF DRIVE SHAFT AND STARTED TAKING OUT THE CUPS. REPLACED U-JOINTS AND REINSTALLED DRIVESHAFT. INSTALLED ALL REMOVED SHIELDS TO GAIN ACCESS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
24M7614	Washer	16.00	0.80	0.80	\$12.80	N	
AKK18337	Cross And Bearing Assembly	2.00	185.57	185.57	\$371.14	N	
H173750	Bolt	16.00	4.16	4.16	\$66.56	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N	
<b>Labor: \$1,770.00</b>	<b>Parts: \$450.50</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$96.00</b>	<b>Sub-Total: \$2,316.50</b>			

**/142152R4045 F Internal**  
 COMPLAINT:  
 32 REPLACE FAN SHIELDS- BOTH LH AND RH FAN COVERS ARE DAMAGED



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 15 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/142152R4045 F Internal**

**CORRECTION:**

REMOVED LEFT HAND SHIELD BY TAKING THE TWO BOLTS OUT AND PULLING OFF THE SHIELD. HAD TO REMOVE STEEL VENT AND PUT ON NEW SHIELD, WHEN INSTALLING METAL VENT THE NEW SHIELD HAD A DEFECTED PLASTIC CLIP HOLDER, USED A SCREW DRIVER TO STRETCH THE METAL CLIP OVER THE LARGER PLASTIC CLIP HOLDER. PUT THE REST OF THE METAL CLIPS BACK ON. NOTICED THE OLD SHIELD WAS MISSING A PLASTIC TAB THAT HOLDS THE SHIELD IN PLACE, REPLACED. INSTALLED NEW SHIELD BACK ON TO SPRAYER, METAL BRACKET THAT SHIELD BOLTS TO WAS BENT(BENT IT BACK TO PLACE). BOLTED SHIELD ON.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
KK18672	Screw	1.00	7.36	7.36	\$7.36	N
KK58001	PANEL	1.00	682.44	682.44	\$682.44	N
KK58050	PANEL	1.00	682.44	682.44	\$682.44	N
R288362	Bracket	1.00	21.25	21.25	\$21.25	N
R310377	Push Nut	12.00	3.20	3.20	\$38.40	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N

**Labor: \$265.50      Parts: \$1,431.89      OL&M: \$0.00      Misc: \$15.93      Sub-Total: \$1,713.32**

**GEN33- Internal**

**COMPLAINT:**

33 DIAGNOSE CENTER BOOM RACK BOUNCES WHEN MOVE UP AND DOWN. CHECK ACCUMULATOR AND CHECK VALVE

**CORRECTION:**

TESTED ACCUMULATOR PRESSURE READ GOOD INSPECTED BUSHINGS AND RACK NO OBVIOUS WEAR ON THE PINS

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N

**Labor: \$177.00      Parts: \$0.00      OL&M: \$0.00      Misc: \$10.62      Sub-Total: \$187.62**



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 12/23/2024	<b>Location:</b> [REDACTED]	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> [REDACTED]	<b>Page:</b> 16 of 18
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/150373R4045 Internal**

**COMPLAINT:**

34 REPLACE BREAKAWAY STOP BOLTS & ADJUST. BOTH RH AND LH STOP BOLTS BROKEN

**CORRECTION:**

UNFOLDED REMOVED THE BOLT FROM THE BRACKET INSTALLED NEW BOLT WASHER AND NUTS AND TIGHTENED UNTIL THE BREAK AWAY WAS LEVEL DID THE SAME FOR THE OTHER BREAK AWAY

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7688	Flange Nut M12	2.00	2.30	2.30	\$4.60	N
14M7727	Hex Lock Nut M12	2.00	2.54	2.54	\$5.08	N
19M8322	Hex Head Cap Screw M12 X 80 GR10.9	2.00	7.84	7.84	\$15.68	N
24M7623	WASHER	2.00	2.90	2.90	\$5.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.62	10.62	\$10.62	N
<b>Labor: \$177.00</b>		<b>Parts: \$31.16</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$10.62</b>
						<b>Sub-Total: \$218.78</b>

**/10500040R4045 F Internal**

**COMPLAINT:**

35 FENCE ROW NOZZLE, REPLACE COMPLETE RH NOZZLE AND LINE FROM VALVE TO NOZZLE

**CORRECTION:**

REMOVED RETAINING NUT FROM FENCE ROW END CUT ZIP TIES FROM THE BOOM TUBE SO THAT HOSE COULD COME FREE REMOVED HOSE FROM VALVE AND SLID OUT OF THE LARGE ZIP TIES PUSHED NEW HOSE THROUGH THE LARGE ZIP TIES AND CONNECTED HOSE TO FENCE LINE END PT NEW ZIP TIES ON WHERE OLD ONES WERE CUT OFF PUT TOGETHER THE SPRAY TIP AND INSTALLED ON FENCE LINE END

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK17746	Adapter Fitting	1.00	69.54	69.54	\$69.54	N
PS90020	Nozzle Cap Black	1.00	1.20	1.20	\$1.20	N
TY25743	3/8" Bulk Sprayer Hose (Per FT)	21.00	1.50	1.50	\$31.50	N



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 12/23/2024 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 17 of 18
--------------------------	--------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	[REDACTED]

**/10500040R4045 F Internal**

SPPOC-03	OC-03 OFF CENTRE BRASS TIP	1.00	15.26	15.26	\$15.26	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.97	7.97	\$7.97	N
<b>Labor: \$132.75</b>		<b>Parts: \$117.50</b>		<b>OL&amp;M: \$0.00</b>	<b>Misc: \$7.97</b>	<b>Sub-Total: \$258.22</b>

**/140163R4045 F Internal**  
 COMPLAINT:  
 36 GREASE UNIT COMPLETE INCLUDING DRIVELINE

CORRECTION:  
 GREASED UNIT

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.54	10.31	\$10.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	15.93	15.93	\$15.93	N
<b>Labor: \$265.50</b>		<b>Parts: \$10.31</b>		<b>OL&amp;M: \$0.00</b>	<b>Misc: \$15.93</b>	<b>Sub-Total: \$291.74</b>

**/110216R4045 F Internal**  
 COMPLAINT:  
 37 INSTALL FUEL TO RUN

CORRECTION:  
 FILLED SPRAYER WITH 200L OF FUEL

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



Box 337  
 Highway 39 N.  
 Weyburn, SK, S4H 2K1  
 Phone: 306-842-4686  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone:  
Prv Phone:

Bus Phone:  
Prv Phone:

Invoice Number:  
 Invoice Date: 12/23/2024  
 Location:  
 Work Order Number:  
 Payment Type:  
 Page: 18 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2018 JD R4045 120' HIGH CLEAR		1N04045RHJ0186606	1N04045RHJ0186606	

/110216R4045 F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	5.31	5.31	\$5.31	N	
<b>Labor: \$88.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.31</b>	<b>Sub-Total: \$93.81</b>			

INVOICE CONTAINS \$1.00 DISCOUNT

Customer PO No:  
 Tax Exempt No:  
 Advisor:

<b>Labor:</b>	\$14,662.52
<b>Parts:</b>	\$8,289.56
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$105.00
<b>Grand Total:</b>	\$23,057.08

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1		147299	USED AG EQUIPMENT
05	40	382	1		807349	INTERNAL LABOR-AG
00	00	178	15		807349	WORK IN PROCESS PARTS -MJ
05	40	482	1		807349	COS INTERNAL LABOR-AG
05	40	544	1		807349	SUPPLIES EXPENSE
05	40	398	1		807349	PROMOTIONS-WASHING
05	30	366	2		807349	JD PARTS-COUNTER
00	00	166	5		807349	JD PARTS-MOOSE JAW
05	30	372	2		807349	OTHER MFR PARTS-CNTR
00	00	172	5		807349	OTHER PARTS-MOOSE JAW
05	30	375	3		807349	PARTS SPECIAL HANDLING
05	30	466	2		807349	JD PARTS-COUNTER
05	30	472	2		807349	OTHER MFR PARTS-CNTR

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....