



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 1 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/SPOPS780 Internal
 COMPLAINT:
 01 RECONDITIONING INSPECTION COMBINE

CORRECTION:

| | | | | |
|--------------------------|----------------------|-------------------------|---------------------|------------------------------|
| Labor: \$1,999.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$1,999.00 |
|--------------------------|----------------------|-------------------------|---------------------|------------------------------|

Gen4- Internal
 COMPLAINT:
 04 REPLACE MISSING FEED ACCELERATOR DRIVE COVER (CUSTOMER HAS ORDERED ALREADY)

CORRECTION:

| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|----------------|-----------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 1.59 | 1.59 | \$1.59 | N |
| Labor: \$26.55 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$1.59 | Sub-Total: \$28.14 | | |

Gen5- Internal
 COMPLAINT:
 05 REPLACE MISSING LOWER RE-THRASHER DRIVE SHIELD (DALE TO CHECK WITH CUSTOMER FOR SHIELD)
 (DALE STILL TO GET FROM CUSTOMER)

CORRECTION:

- 1 - HXE103075
- 3 - 14M7298
- 3 - 19M7866

| | | | | |
|----------------------|----------------------|-------------------------|---------------------|--------------------------|
| Labor: \$0.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$0.00 |
|----------------------|----------------------|-------------------------|---------------------|--------------------------|



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 2 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|--------|-------------------|-------------------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/170380S780 Internal

COMPLAINT:
 06 REMOVE HALF LINK FROM FEEDER HOUSE CONVEYOR CHAIN AND ADJUST

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|----------------------|-------------------------|----------------------|----------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$187.62 | | |

/170294S780 Internal

COMPLAINT:
 07 ADJUST FEED ACCELERATOR DRIVE BELT (ALSO PUT IN SLOW SPEED)

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.12 | 2.12 | \$2.12 | N |
| Labor: \$35.40 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$2.12 | Sub-Total: \$37.52 | | |

GEN8- Internal

COMPLAINT:
 08 PAINT FEEDER HOUSE DRIVE CHAIN TENSION BRACKET (HAS HEAT MARKINGS WEAR CHAIN WORE ON IT)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|-------------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| TY25624 | Paint Ag/CCE Green Spray Bomb | 1.00 | 23.54 | 23.54 | \$23.54 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| EF25 | ENVIRO FEE | 1.00 | 0.25 | 0.25 | \$0.25 | N |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 3 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | |
|-----------------------|---------------------|-----------------------|-------------------------|---------------------|----------------------------|---|
| GEN8- Internal | | | | | | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |
| Labor: \$88.50 | | Parts: \$23.54 | OL&M: \$0.00 | Misc: \$5.56 | Sub-Total: \$117.60 | |

/150214S780 Internal
 COMPLAINT:
 09 CLEAN AND PAINT BURNT FEED ACCELERATOR PULLEY

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|---------------------|----------------------|-------------------------|---------------------|---------------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.66 | 2.66 | \$2.66 | N |
| Labor: \$44.25 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$46.91 | |

/11005HS780 Internal
 COMPLAINT:
 10 R&R OR REPLACE FEEDER HOUSE FEED PLATE , --(FEEDER HOUSE OFF)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|--------------------------|-------------------------|----------------------|------------------------------|------------------|
| AXE60027 | Plate | 1.00 | 1,083.24 | 1,083.24 | \$1,083.24 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$1,083.24 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$1,270.86 | |

/120543S780 Internal
 COMPLAINT:
 11 REPLACE FEED ACCELERATOR SUPPORTS RIGHT AND LEFT (OFFSETS), (ALL SUPPORTS SEVERELY DAMAGED)



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 4 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/120543S780 Internal

CORRECTION:

Remove:Upper shieldsAttaching hardwareOffsetsReplace or remove paddles from old offset and install on newInstall in reverse order to specification.Test run.

Paddles could not be removed using normal methods due to excessive damage bolts were inaccessible. 60% of the supports required torch to remove.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|---------------------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| 19M7786 | Flange Head Cap Screw M10 X 30 GR10.9 | 4.00 | 2.63 | 2.63 | \$10.52 | N |
| H137329 | Flange Lock Nut M12 | 33.00 | 3.06 | 3.06 | \$100.98 | N |
| HXE138427 | Wear Plate Strips | 6.00 | 52.33 | 52.33 | \$313.98 | N |
| HXE84113 | Wing Beater Channel RH Support | 4.00 | 407.48 | 407.48 | \$1,629.92 | N |
| HXE84114 | Wing Beater Channel LH Support | 4.00 | 407.48 | 407.48 | \$1,629.92 | N |
| L215374 | Carriage Bolt M12 x 35 | 33.00 | 5.01 | 5.01 | \$165.33 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 53.10 | 53.10 | \$53.10 | N |

Labor: \$885.00 Parts: \$3,850.65 OL&M: \$0.00 Misc: \$53.10 Sub-Total: \$4,788.75

/160048S780 Internal

COMPLAINT:

12 REPLACE FEEDER HOUSE DOOR (LARGE BEND) (TRY TO STRAIGHTEN)

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|---------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |

Labor: \$88.50 Parts: \$0.00 OL&M: \$0.00 Misc: \$5.31 Sub-Total: \$93.81



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 5 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

GEN13- Internal

COMPLAINT:
 13 REPLACE ALL O-RINGS ON LEFT HAND CONTOUR MASTER "T" FITTING

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|-----------------------|-------------------------|----------------------|----------------------------|------------------|
| T77613 | #6 Flat Face O-Ring | 3.00 | 3.35 | 3.35 | \$10.05 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$10.05 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$197.67 | |

GEN14- Internal

COMPLAINT:
 14 REMOVE DUCT TAPE FROM FEEDERHOUSE LIFT CYLINDERS & INSTALL PROPER CLAMPS FOR HOSES

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|------------------------------------|----------------------|-------------------------|---------------------|---------------------------|------------------|
| TY22476 | Hose Clamp #80 (C 4 5/8" O 5 1/2") | 2.00 | 4.23 | 4.23 | \$8.46 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 4.25 | 4.25 | \$4.25 | N |
| Labor: \$70.80 | | Parts: \$8.46 | OL&M: \$0.00 | Misc: \$4.25 | Sub-Total: \$83.51 | |

/141935S780 Internal

COMPLAINT:
 15 REPLACE CAB VENT BEZEL (ONE BROKE)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 6 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/141935S780 Internal

| | | | | | | |
|---------------------------|---------------------|-----------------------|-------------------|-------------------------|-----------------------|---------------------|
| RE209204 | Louver | 1.00 | 45.24 | 45.24 | \$45.24 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 1.59 | 1.59 | \$1.59 | N |
| Labor: \$26.55 | | Parts: \$45.24 | | OL&M: \$0.00 | | Misc: \$1.59 |
| Sub-Total: \$73.38 | | | | | | |

/150505S780 Internal
 COMPLAINT:
 16 CALIBRATE FEEDER HOUSE FORE/AFT

CORRECTION:
 DURING CALIBRATION FEEDER HOUSE FORE/AFT TILT BECAME DISABLED DUE TO LC1.001 516724.07 CODE, LOOKED CODE UP ON SERVICE ADVISOR AND WAS DIRECTED TO DTAC CASE NO 114919. THIS REQUIRED A SOFTWARE UPDATE TO CLEAR THIS CODE, UPDATE REQUIRED 3 ATTEMPTS TO INSTALL CORRECTLY AS WELL AS CONNECTING BATTERY CHARGER TO COMBINE. UPON UPDATE WAS ABLE TO COMPLETE FORE/AFT TILT CALIBRATION AND RESOLVE THE ERROR CODE

| | | | | | | |
|----------------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|---------------------|
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 3.19 | 3.19 | \$3.19 | N |
| Labor: \$354.00 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$3.19 |
| Sub-Total: \$357.19 | | | | | | |

/1414960S780 Internal
 COMPLAINT:
 17 REMOVE MACDON TILT SWITCH AND WIRING

CORRECTION:

| | | | | | | |
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 7 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | |
|------------------------------|---------------------|----------------------|-------------------------|----------------------|----------------------------|---|
| /1414960S780 Internal | | | | | | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$187.62 | |

/110705S780 Internal
 COMPLAINT:
 18 REMOVE TWO WAY RADIO AND ANTENNA

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|----------------------|-------------------------|----------------------|----------------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 13.28 | 13.28 | \$13.28 | N |
| Labor: \$221.25 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$13.28 | Sub-Total: \$234.53 | |

GEN19- Internal
 COMPLAINT:
 19 ATTACH CAB LANDING SAFETY CHAINS

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|--------------------|-----------------------|-------------------------|---------------------|---------------------------|------------------|
| AXE20532 | Clip | 1.00 | 21.76 | 21.76 | \$21.76 | N |
| Labor: \$44.25 | | Parts: \$21.76 | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$68.67 | |

GEN20- Internal
 COMPLAINT:
 20 REPLACE FRONT ACI CONCAVE POSITION SENSOR(SENSOR IS BROKEN & WILL NOT HOLD HARNESS CONNECTOR, WILL REQUIRE LEVEL & CLEARANCE CALIBRATION AFTER)



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|--|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 8 of 25 |
|--------------------------|--------------------------|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

GEN20- Internal

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|------------------------|-------------------------|----------------------|----------------------------|------------------|
| AXE14245 | Sensor | 1.00 | 280.64 | 280.64 | \$280.64 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 15.93 | 15.93 | \$15.93 | N |
| Labor: \$265.50 | | Parts: \$280.64 | OL&M: \$0.00 | Misc: \$15.93 | Sub-Total: \$562.07 | |

GEN21- Internal

COMPLAINT:
 21 INSTALL MISSING CONCAVE LEVELING HARDWARE

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|------------------------------------|-----------------------|-------------------------|---------------------|---------------------------|------------------|
| 14M7299 | Flange Nut M12 | 6.00 | 2.88 | 2.88 | \$17.28 | N |
| 19M7590 | Hex Head Cap Screw M12 X 100 GR8.8 | 2.00 | 8.14 | 8.14 | \$16.28 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.66 | 2.66 | \$2.66 | N |
| Labor: \$44.25 | | Parts: \$33.56 | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$80.47 | |

/10180350S780 Internal

COMPLAINT:
 22 R&R CONCAVE Z-BAR SUPPORT

CORRECTION:

NOTE:-Does not include leveling concaves.Remove dust shields from left front left side of separator.Open concaves fully.Remove pins from eyebolts.Unbolt concave support from concaves.Install new support with new bolts and nuts.Install pins in eyebolts.Install shields.



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--|--|--|
| [Redacted] Bus Phone: Prv Phone: | [Redacted] Bus Phone: Prv Phone: | Invoice Number: [Redacted] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [Redacted] Payment Type: Account Page: 9 of 25 |
|--|--|--|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/10180350S780 Internal

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|--------------------------|-------------------|-------------------------|-----------------------|------------------------------|
| AXE61891 | Support | 1.00 | 1,590.16 | 1,590.16 | \$1,590.16 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 23.90 | 23.90 | \$23.90 | N |
| Labor: \$398.25 | | Parts: \$1,590.16 | | OL&M: \$0.00 | | Misc: \$23.90 |
| | | | | | | Sub-Total: \$2,012.31 |

GEN24- Internal
 COMPLAINT:
 24 WELD CRACK IN TAILINGS UPPER AUGER TUBE & SUPPORT

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|----------------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 15.93 | 15.93 | \$15.93 | N |
| Labor: \$265.50 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$15.93 |
| | | | | | | Sub-Total: \$281.43 |

GEN25- Internal
 COMPLAINT:
 25 GREASE ROTOR GEARCASE WITH HD GREASE AS PER DTAC # 220831

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|-------------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| TY25744 | EXTREME DUTY SYNTHETIC GREASE | 1.00 | 27.08 | 27.08 | \$27.08 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 10 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | | | |
|------------------------|-----------------------|-------------------------|---------------------|----------------------------|--------|---|--|--|
| GEN25- Internal | | | | | | | | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N | | |
| Labor: \$88.50 | Parts: \$27.08 | OL&M: \$0.00 | Misc: \$5.31 | Sub-Total: \$120.89 | | | | |

GEN26- Internal
 COMPLAINT:
 26 TIGHTEN CLAMP ON MAIN PUMP INLET HOSE

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.66 | 2.66 | \$2.66 | N |
| Labor: \$44.25 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$46.91 | | |

/10172010S780 Internal
 COMPLAINT:
 27 R&R STRAW CHOPPER HAMMERS (SEVERELY WORN)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|--------------------------|-------------------------|----------------------|------------------------------|-----------------------|------------------|
| HXE118760 | Lock Nut M10 | 22.00 | 2.82 | 2.82 | \$62.04 | N |
| HXE119246 | Hex Head Bolt M10 X 55 | 22.00 | 5.79 | 5.79 | \$127.38 | N |
| KXE10255 | Knife Kit | 6.00 | 409.78 | 409.78 | \$2,458.68 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 31.86 | 31.86 | \$31.86 | N |
| Labor: \$531.00 | Parts: \$2,648.10 | OL&M: \$0.00 | Misc: \$31.86 | Sub-Total: \$3,210.96 | | |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 11 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/140854S780 Internal

COMPLAINT:

28 TURN STRAW CHOPPER STATIONARY KNIVES

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|--------------------------|-----------------------|-------------------------|---------------------|----------------------------|------------------|
| H215004 | Stationary Chopper Blade | 2.00 | 17.19 | 17.19 | \$34.38 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 7.97 | 7.97 | \$7.97 | N |
| Labor: \$132.75 | | Parts: \$34.38 | OL&M: \$0.00 | Misc: \$7.97 | Sub-Total: \$175.10 | |

/101801701S780 Internal

COMPLAINT:

29 R&R CHOPPER DISCHARGE HOUSING (FLOOR PORTION WORN THROUGH IN MULTIPLE PLACES)

CORRECTION:

REMOVE-SHIELDS-COVERS-GRATES-BRACKETS AND HARDWARE ROTATE HOUSING AROUND ROTOR THEN REMOVE OUT LEFT-HAND SIDE OF MACHINE. REPLACE BRACKETS AND HOUSING AS NECESSARY. ASSEMBLE IN REVERSE ORDER. TEST RUN.

A&I PART DID NOT FIT UP VERY WELL, STRUGGLED WITH BOLT HOLE ALIGNMENT, ATTEMPTED MULTIPLE TIMES TO REALIGN PART AND GET ALL HARDWARE IN WITHOUT SUCCESS. CONSULTED WITH DEAN AND DRILLED NEW BOLT HOLES TO ACCOUNT FOR POOR ALIGNMENT.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|--------------------------|-------------------------|----------------------|------------------------------|------------------|
| A-AXE20855 | Housing | 1.00 | 1,115.29 | 1,115.29 | \$1,115.29 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 31.86 | 31.86 | \$31.86 | N |
| Labor: \$531.00 | | Parts: \$1,115.29 | OL&M: \$0.00 | Misc: \$31.86 | Sub-Total: \$1,678.15 | |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | | |
|-----------------------------------|--------------------------------|------------------------------|--------------------------------------|
| Invoice Number: [REDACTED] | Invoice Date: 4/29/2025 | Location: 02 | Work Order Number: [REDACTED] |
| Bus Phone: | Bus Phone: | Payment Type: Account | Page: 12 of 25 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/120563S780 Internal
 COMPLAINT:
 30 STRAIGHTEN LOUVERS ON TOP CHAFFER

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 7.97 | 7.97 | \$7.97 | N |
| Labor: \$132.75 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$7.97 | Sub-Total: \$140.72 | | |

/180015S780 Internal
 COMPLAINT:
 31 PREFORM INSTALL CALIBRATION OF SIEVE AND CHAFFER

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |
| Labor: \$177.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$5.31 | Sub-Total: \$182.31 | | |

GEN32- Internal
 COMPLAINT:
 32 SET ADJUSTABLE PRECLEANER LOUVERS TO PROPER POSITION

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|-----------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.66 | 2.66 | \$2.66 | N |
| Labor: \$44.25 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$46.91 | | |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 13 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/150339S780 Internal
 COMPLAINT:
 33 REPLACE VACUUM FAN OUTLET TUBE (HOLE WORN THROUGH)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|------------------------|-------------------------|---------------------|----------------------------|------------------|
| HXE103612 | Air Duct | 1.00 | 255.99 | 255.99 | \$255.99 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 7.97 | 7.97 | \$7.97 | N |
| Labor: \$132.75 | | Parts: \$255.99 | OL&M: \$0.00 | Misc: \$7.97 | Sub-Total: \$396.71 | |

/120565S780 Internal
 COMPLAINT:
 34 REPLACE VACUUM DRIVE BELT

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|-----------------------|-----------------------|-------------------------|---------------------|----------------------------|------------------|
| HXE38073 | Vacuum Fan Drive Belt | 1.00 | 40.45 | 40.45 | \$40.45 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 4.25 | 4.25 | \$4.25 | N |
| Labor: \$70.80 | | Parts: \$40.45 | OL&M: \$0.00 | Misc: \$4.25 | Sub-Total: \$115.50 | |

GEN35- Internal
 COMPLAINT:
 35 REPLACE MISSING HARDWARE ON FRONT AUXILIARY DRIVE SUPPORT

CORRECTION:



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 14 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

GEN35- Internal

INSTALLED MISSING BOLT AND NOTICED ANOTHER BOLT IN THE BRACKET APPEARED LOOSE, BOLT HEAD FELL OFF AS SOON AS I TOUCHED IT WITH THE RATCHET. REMOVED L BRACKET AND EXTRACTED BROKEN BOLT. REINSTALLED L BRACKET AND REPLACED BROKEN HARDWARE.

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|----------------------------|
| SERVACCESS | SERVICE ACCESSORIES | 2.00 | 13.28 | 13.28 | \$26.56 | N |
| Labor: \$221.25 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$26.56 |
| | | | | | | Sub-Total: \$247.81 |

/170531S780 Internal

COMPLAINT:
 36 CLEAN ACTIVE VISION CAMERA LENSES

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|---------------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |
| Labor: \$88.50 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$5.31 |
| | | | | | | Sub-Total: \$93.81 |

GEN37- Internal

COMPLAINT:
 37 INSTALL GULL WING LATCH BRACKET (PIN IS IN CAB)

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|---------------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 4.25 | 4.25 | \$4.25 | N |
| Labor: \$70.80 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$4.25 |
| | | | | | | Sub-Total: \$75.05 |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | | |
|-----------------------------------|--------------------------------|------------------------------|--------------------------------------|
| Invoice Number: [REDACTED] | Invoice Date: 4/29/2025 | Location: 02 | Work Order Number: [REDACTED] |
| Bus Phone: | Bus Phone: | Payment Type: Account | Page: 15 of 25 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/110016S780 Internal
 COMPLAINT:
 38 ADJUST TAILINGS PADDLE CHAIN

CORRECTION:
 tailings chain was at the maximum adjustable limit. spun tailings chain to find half links and removed a link. adjusted chain to spec.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|----------------------|----------------------|-------------------------|---------------------|---------------------------|------------------|
| 11M7059 | Cotter Pin M3.2 X 20 | 2.00 | 0.43 | 0.43 | \$0.86 | N |
| Miscellaneous | DESCRIPTION | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.12 | 2.12 | \$2.12 | N |
| Labor: \$35.40 | | Parts: \$0.86 | OL&M: \$0.00 | Misc: \$2.12 | Sub-Total: \$38.38 | |

/110015S780 Internal
 COMPLAINT:
 39 ADJUST CLEAN GRAIN PADDLE CHAIN

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|---------------------|----------------------|-------------------------|---------------------|---------------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.12 | 2.12 | \$2.12 | N |
| Labor: \$35.40 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$2.12 | Sub-Total: \$37.52 | |

/120617S780 Internal
 COMPLAINT:
 42 RETHRESHER DOOR JAMMED. REMOVE, DISASSEMBLE, AND REPAIR

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|-----------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| 03M7184 | Carriage Bolt M8 X 20 | 4.00 | 1.30 | 1.30 | \$5.20 | N |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 16 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|--------|-------------------|-------------------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/120617S780 Internal

| | | | | | | |
|------------------------|---------------------|------------------------|-------------------------|----------------------|----------------------------|------------------|
| 14M7298 | Flange Nut M8 | 4.00 | 1.53 | 1.53 | \$6.12 | N |
| HXE22813 | Plate | 1.00 | 95.11 | 95.11 | \$95.11 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 23.90 | 23.90 | \$23.90 | N |
| Labor: \$398.25 | | Parts: \$106.43 | OL&M: \$0.00 | Misc: \$23.90 | Sub-Total: \$528.58 | |

/1702871S780 Internal
 COMPLAINT:
 43 REPLACE RADIATOR PROPELLER FAN (WAND HAS MADE CONTACT WITH RADIATOR FINS)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|--------------------------------------|-----------------------|-------------------------|---------------------|----------------------------|------------------|
| 19M7864 | Flange Head Cap Screw M8 X 12 GR10.9 | 2.00 | 1.66 | 1.66 | \$3.32 | N |
| 24M7207 | Washer | 1.00 | 0.77 | 0.77 | \$0.77 | N |
| 24M7389 | Washer | 1.00 | 3.67 | 3.67 | \$3.67 | N |
| HXE113942 | Spacer | 1.00 | 22.89 | 22.89 | \$22.89 | N |
| HXE12956 | Bolt | 1.00 | 14.03 | 14.03 | \$14.03 | N |
| HXE154558 | Shim | 1.00 | 11.54 | 11.54 | \$11.54 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |
| Labor: \$88.50 | | Parts: \$56.22 | OL&M: \$0.00 | Misc: \$5.31 | Sub-Total: \$150.03 | |

GEN44- Internal
 COMPLAINT:
 44 REPLACE ETHER DELIVERY LINE (COMPLETELY WORN THROUGH)



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 17 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|--------|-------------------|-------------------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

GEN44- Internal CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|-----------------------|---------------------|------------------------|-------------------|-------------------------|-----------------------|----------------------------|
| HXE21149 | Bulk Hose | 1.00 | 69.72 | 69.72 | \$69.72 | N |
| RE21790 | ELBOW FITT | 2.00 | 21.97 | 21.97 | \$43.94 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.66 | 2.66 | \$2.66 | N |
| Labor: \$44.25 | | Parts: \$113.66 | | OL&M: \$0.00 | Misc: \$2.66 | Sub-Total: \$160.57 |

GEN45- Internal COMPLAINT:

45 PLUG MISSING "KNOCK OUT" HOLE IN REAR WALL OF ROTOR WALLS (FILLS ROTOR BELT ARE WITH DEBRIS)

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|----------------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 21.24 | 21.24 | \$21.24 | N |
| Labor: \$354.00 | | Parts: \$0.00 | | OL&M: \$0.00 | Misc: \$21.24 | Sub-Total: \$375.24 |

/150052S780 Internal COMPLAINT:

46 REPLACE LOADING AUGER DRIVE COUPLER

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------------------------|--------------------------------|---------------------|--------------------------------------|
| Invoice Number: [REDACTED] | Invoice Date: 4/29/2025 | Location: 02 | Work Order Number: [REDACTED] |
| Payment Type: Account | Page: 18 of 25 | | |
| Bus Phone: | Bus Phone: | | |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | | |
|-----------------------------|--------|------------------------|--------|----------------------------|----------|---------------------|--|
| /150052S780 Internal | | | | | | | |
| HXE84650 | Driver | 1.00 | 228.89 | 228.89 | \$228.89 | N | |
| Labor: \$265.50 | | Parts: \$228.89 | | OL&M: \$0.00 | | Misc: \$0.00 | |
| | | | | Sub-Total: \$494.39 | | | |

GEN47- Internal
 COMPLAINT:
 47 REPLACE O-RING IN FITTING ON TOP OF ROTOR DRIVE BELL HOUSING

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> | |
|-----------------------|---------------------|----------------------|-------------------|---------------------------|-----------------------|---------------------|--|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N | |
| Labor: \$88.50 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$5.31 | |
| | | | | Sub-Total: \$93.81 | | | |

GEN48- Internal
 COMPLAINT:
 48 REPLACE MISSING RUBBER SEAL FOR HOPPER SUMP CLEAN OUT

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> | |
|-----------------------|---------------------------------------|-----------------------|-------------------|---------------------------|-----------------------|---------------------|--|
| 19M7783 | Flange Head Cap Screw M10 X 16 GR10.9 | 2.00 | 2.32 | 2.32 | \$4.64 | N | |
| H236753 | Seal | 1.00 | 36.71 | 36.71 | \$36.71 | N | |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 1.59 | 1.59 | \$1.59 | N | |
| Labor: \$26.55 | | Parts: \$41.35 | | OL&M: \$0.00 | | Misc: \$1.59 | |
| | | | | Sub-Total: \$69.49 | | | |

/10040060S780 Internal
 COMPLAINT:



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 19 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/10040060S780 Internal
 49 REPLACE VISIONTRAK SENSOR (ROTOR)

CORRECTION:
 Disconnect wiring harness.Remove cap screws and sensor.Install new sensor and connect harness.
 TRIED BOTH SENSORS, BOTH DIDNT WORK, CHANGED BOTH

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|-------------------------------------|------------------------|-------------------------|----------------------|----------------------------|------------------|
| AXE55969 | Grain Loss Monitoring System Sensor | 2.00 | 306.40 | 306.40 | \$612.80 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 13.28 | 13.28 | \$13.28 | N |
| Labor: \$221.25 | | Parts: \$612.80 | OL&M: \$0.00 | Misc: \$13.28 | Sub-Total: \$847.33 | |

/120014S780 Internal
 COMPLAINT:
 50 GREASE COMBINE

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|---------------------|-----------------------|-------------------------|----------------------|----------------------------|------------------|
| TY6341 | SD POLYUREA GREASE | 1.00 | 10.87 | 10.87 | \$10.87 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$10.87 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$198.49 | |

/150029S780 Internal
 COMPLAINT:
 51 REPLACE CAB FILTERS AND CLEAN PLASTIC GRATE

CORRECTION:



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | | |
|-----------------------------------|--------------------------------|------------------------------|--------------------------------------|
| Invoice Number: [REDACTED] | Invoice Date: 4/29/2025 | Location: 02 | Work Order Number: [REDACTED] |
| Bus Phone: | Bus Phone: | Payment Type: Account | Page: 20 of 25 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/150029S780 Internal

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|------------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| L214634 | Cab Ricirculation Air Filter | 1.00 | 50.16 | 50.16 | \$50.16 | N |
| TA32591 | Cab Fresh Air Filter | 1.00 | 121.88 | 121.88 | \$121.88 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 3.19 | 3.19 | \$3.19 | N |

Labor: \$53.10 Parts: \$172.04 OL&M: \$0.00 Misc: \$3.19 Sub-Total: \$228.33

/120060S780 Internal

COMPLAINT:
 52 REPLACE ENGINE AIR FILTERS

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|----------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| HXE11090 | Primary Air Filter | 1.00 | 462.31 | 462.31 | \$462.31 | N |
| HXE11091 | Secondary Air Filter | 1.00 | 326.21 | 326.21 | \$326.21 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 5.31 | 5.31 | \$5.31 | N |

Labor: \$88.50 Parts: \$788.52 OL&M: \$0.00 Misc: \$5.31 Sub-Total: \$882.33

/141578S780 Internal

COMPLAINT:
 53 REPLACE DEBRIS MANAGEMENT FILTER (AXE42066)

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--|-----------------|-------------------|------------------|-----------------------|------------------|
| AXE42065 | Secondary Air Filter (Debris Management) | 1.00 | 148.04 | 148.04 | \$148.04 | N |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------------------------|--------------------------------|------------------------------|--------------------------------------|
| Invoice Number: [REDACTED] | Invoice Date: 4/29/2025 | Location: 02 | Work Order Number: [REDACTED] |
| Bus Phone: | Bus Phone: | Payment Type: Account | Page: 21 of 25 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/141578S780 Internal

| | | | | | | |
|-----------------------|--|-------------------------|---------------------|----------------------------|-----------------------|------------------|
| AXE42066 | Primary Air Filter (Debris Management) | 1.00 | 231.82 | 231.82 | \$231.82 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 2.12 | 2.12 | \$2.12 | N |
| Labor: \$35.40 | Parts: \$379.86 | OL&M: \$0.00 | Misc: \$2.12 | Sub-Total: \$417.38 | | |

/120000S780 Internal
 COMPLAINT:
 54 CHANGE ENGINE OIL AND FILTER

CORRECTION:

| | | | | | | |
|------------------------|------------------------|-------------------------|----------------------|----------------------------|-----------------------|------------------|
| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| RE572785 | Engine Oil Filter | 1.00 | 151.62 | 151.62 | \$151.62 | N |
| TY26673 | 3.78L 15W40 PLUS 50 II | 1.00 | 37.78 | 37.78 | \$37.78 | N |
| TY26679 | 18.9L 15W40 PLUS 50 II | 2.00 | 170.86 | 170.86 | \$341.72 | N |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| EF100 | ENVIRO FEE | 1.00 | 1.00 | 1.00 | \$1.00 | N |
| EF300 | ENVIRO FEE | 2.00 | 3.00 | 3.00 | \$6.00 | N |
| EF50 | ENVIRO FEE | 1.00 | 0.50 | 0.50 | \$0.50 | N |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 7.97 | 7.97 | \$7.97 | N |
| Labor: \$132.75 | Parts: \$531.12 | OL&M: \$0.00 | Misc: \$15.47 | Sub-Total: \$679.34 | | |

/120018S780 Internal
 COMPLAINT:
 55 REPLACE FUEL FILTERS, AND CLEAN FUEL PRE-SCREEN

CORRECTION:



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 22 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/120018S780 Internal

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|-------------------------------------|------------------------|-------------------------|---------------------|----------------------------|------------------|
| DZ112918 | Secondary Engine Fuel Filter (Long) | 1.00 | 236.20 | 236.20 | \$236.20 | N |
| DZ130550 | Primary Engine Fuel Filter | 1.00 | 232.48 | 232.48 | \$232.48 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| EF100 | ENVIRO FEE | 2.00 | 1.00 | 1.00 | \$2.00 | N |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 7.97 | 7.97 | \$7.97 | N |
| Labor: \$132.75 | | Parts: \$468.68 | OL&M: \$0.00 | Misc: \$9.97 | Sub-Total: \$611.40 | |

/1007009S780 Internal

COMPLAINT:
 56 REPLACE HYDRAULIC FILTERS, INCLUDES RESERVIOR FILTER

CORRECTION:

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|--------------------------------|------------------------|-------------------------|----------------------|----------------------------|------------------|
| A52523 | Ring | 1.00 | 26.30 | 26.30 | \$26.30 | N |
| AH128449 | Hydraulic Oil Filter | 1.00 | 147.41 | 147.41 | \$147.41 | N |
| AN207368 | Hydraulic Oil Filter Element | 1.00 | 195.07 | 195.07 | \$195.07 | N |
| AXE12964 | Hydraulic Oil Reservoir Filter | 1.00 | 177.71 | 177.71 | \$177.71 | N |
| N309233 | O-Ring | 1.00 | 28.00 | 28.00 | \$28.00 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| EF100 | ENVIRO FEE | 3.00 | 1.00 | 1.00 | \$3.00 | N |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 13.28 | 13.28 | \$13.28 | N |
| Labor: \$221.25 | | Parts: \$574.49 | OL&M: \$0.00 | Misc: \$16.28 | Sub-Total: \$812.02 | |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 23 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

/120512S780 Internal
 COMPLAINT:
 57 CHECK AND TOP ALL FLUIDS

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------------|---------------------|----------------------|-------------------|-------------------------|-----------------------|---------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 6.90 | 6.90 | \$6.90 | N |
| Labor: \$115.05 | | Parts: \$0.00 | | OL&M: \$0.00 | | Misc: \$6.90 |
| Sub-Total: \$121.95 | | | | | | |

/170538S780 Internal
 COMPLAINT:
 58 ADJUST ALL BELTS AND CHAINS AS PER IS DEPT GUIDELINES

CORRECTION:
 FOUND BROKEN TENSION INDICATOR ON UPPER FEEDER HOUSE DRIVE BELT AND REPLACED.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------------|---------------------------|-----------------------|-------------------|-------------------------|-----------------------|----------------------|
| HXE47618 | Spring Gauge 5 1/32" Long | 1.00 | 56.37 | 56.37 | \$56.37 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$56.37 | | OL&M: \$0.00 | | Misc: \$10.62 |
| Sub-Total: \$243.99 | | | | | | |

/110377S780 Internal
 COMPLAINT:
 59 RERUN AFTER REPAIRS

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 24 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | |
|-----------------------------|---------------------|----------------------|-------------------------|----------------------|----------------------------|---|
| /110377S780 Internal | | | | | | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 10.62 | 10.62 | \$10.62 | N |
| Labor: \$177.00 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$10.62 | Sub-Total: \$187.62 | |

/101801401S780 Internal
 COMPLAINT:
 61 R&R CONCAVES. LEVEL, ADJUST, AND CALIBRATE (WITH ACI)

CORRECTION:

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------------|---------------------|----------------------|-------------------------|----------------------|------------------------------|------------------|
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 64.17 | 64.17 | \$64.17 | N |
| Labor: \$1,069.50 | | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$64.17 | Sub-Total: \$1,133.67 | |

/10230160S780 Internal
 COMPLAINT:
 62 R&R CLEAN GRAIN ELEVATOR DRIVE BELT

CORRECTION:

Open gull wing door, release tension from belt. Remove clean grain belt shield in hopper. Remove and replace clean grain drive belt. Re-install belt shield in hopper. Tension belt to spec. and test run.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| H223230 | V-Belt | 1.00 | 505.86 | 505.86 | \$505.86 | N |
| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |



609 Main Street N.
 Mossbank, SK S0H 3G0
 Phone: 306-354-2411
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

| | | |
|--------------------------|--------------------------|---|
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | Invoice Number: [REDACTED] Invoice Date: 4/29/2025 Location: 02 Work Order Number: [REDACTED] Payment Type: Account Page: 25 of 25 |
|--------------------------|--------------------------|---|

| | | | | |
|---------------------------------|---------------|-----------------------|-------------------|------------------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE 2018 JD S780 COMBINE | 1971 | 1H0S780SAJ0801004 | 1H0S780SAJ0801004 | # 3 |

| | | | | | | | |
|-------------------------------|------------------------|-------------------------|----------------------|----------------------------|---------|---|--|
| /10230160S780 Internal | | | | | | | |
| SERVACCESS | SERVICE ACCESSORIES | 1.00 | 27.90 | 27.90 | \$27.90 | N | |
| Labor: \$465.00 | Parts: \$505.86 | OL&M: \$0.00 | Misc: \$27.90 | Sub-Total: \$998.76 | | | |

Customer PO No:
Tax Exempt No:
Advisor: [REDACTED]

| | |
|---------------------|-------------|
| Labor: | \$12,233.05 |
| Parts: | \$15,716.61 |
| OL&M: | \$0.00 |
| Misc: | \$600.85 |
| Grand Total: | \$28,550.51 |

*** DOCUMENT COPY ***

GST Registration No: 897357802

| G/L Entries | Br | Dpt | Acct | Sub | Ref | Description |
|-------------|-----|-----|--------|-----|-----|---------------------------|
| 00 00 | 160 | 1 | 148694 | | | USED AG EQUIPMENT |
| 02 40 | 382 | 1 | 832027 | | | INTERNAL LABOR-AG |
| 00 00 | 178 | 12 | 832027 | | | WORK IN PROCESS PARTS -MJ |
| 02 40 | 482 | 1 | 832027 | | | COS INTERNAL LABOR-AG |
| 02 40 | 544 | 1 | 832027 | | | SUPPLIES EXPENSE |
| 02 30 | 375 | 3 | 832027 | | | PARTS SPECIAL HANDLING |
| 02 30 | 366 | 2 | 832027 | | | JD PARTS-COUNTER |
| 00 00 | 166 | 2 | 832027 | | | JD PARTS-MOOSE JAW |
| 02 30 | 466 | 2 | 832027 | | | JD PARTS-COUNTER |

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
 I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: